UNITED STATES



## NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

March 3, 1995

Radiation Services & Consultants, Inc. ATTN: Michael D. Morris, President P. O. Box 2985 Ripley, Oklahoma 74062

SUBJECT: NRC INSPECTION REPORT 030-19005/94-01

This refers to the routine, announced inspection conducted by Mr. Richard A. Leonardi, Jr., of this office on December 19, 1994. The inspection included a review of activities authorized by Byproduct Material License 35-19631-01. At the conclusion of the inspection, the findings were discussed with members of your staff. A telephonic exit briefing was later conducted with you on February 7, 1995.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector determined that the licensee had provided radiation safety consulting services for a limited number of NRC licensees. During this interval, the majority of the licensee's activities involved services related to diagnostic x-ray units which are not regulated by the NRC. Although the licensee possessed several decayed sealed sources, only four sealed sources in the licensee's possession at the time of the inspection required leak testing. A review of leak test records for these sealed sources revealed that leak tests had been performed as required and related records had been retained.

As discussed during the telephonic exit briefing conducted on February 7, 1995, between you and Ms. Linda Howell and Mr. Richard A. Leonardi, Jr. of this office, it is our understanding that you will provide to the Nuclear Materials Licensing Branch information identifying the current status of your company and the correct company name in order to support the license renewal application which is currently under review.

Also reviewed during the inspection were actions taken in response to the violations observed during our previous inspection conducted on January 10, 1989. The inspector verified that corrective actions for these violations had been implemented as stated in your replies dated March 11 and July 3, 1989, and that these actions were effective.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

9503080119 950303 PDR ADOCK 03019005 JEON 10

Radiation Services & Consultants, -2-Inc.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Linda L. Howell, Chief Nuclear Materials Inspection Branch

Docket: 030-19005 License: 35-19631-01

cc: Oklahoma Radiation Control Program Director

Radiation Services & Consultants, -3-Inc.

bcc:
DMB - Original (IE-07)
LJCallan
DWeiss, OC/LFDCB (T-9E10)
DBSpitzburg
LLHowell
FAWenslawski, WCFO
\*RALeonardi
\*NMIB
\*MIS System
\*NMLB file room (5th floor)

\*W/IFS Form

DOCUMENT NAME: 0:\NMIS\RAL\19005RIP.OK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:NMIB	SC:NMIB	
RALeonardi:ww	LLHowell	
02/28795	02/ /95	

OFFICIAL RECORD COPY

Radiation Services & Consultants, -3-Inc.

bcc:
DMB - Original (IE-07)
LJCallan
DWeiss, OC/LFDCB (T-9E10)
DBSpitzburg
LLHowell
FAWenslawski, WCFO
\*RALeonardi
\*NMIB
\*MIS System
\*NMLB file room (5th floor)

\*W/IFS Form

DOCUMENT NAME: 0:\NMIS\RAL\19005RIP.OK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:NMIB	SC:NMIB		
RALeonardi:ww	LLHowell		
02/28/795	02/ /95		

OFFICIAL RECORD COPY