NRC Form (9-83)	. 100		•	~	LIC	ENSEE EVER	NT RE	PORT	(LER)	U.S. NU AJ EJ	CLEAR REGULAT	04Y COMM	MARKON M
TACIN IT?									D	OCKET NUMBER	(2)	PAS	
FACILITY	Sale	em Ge	nerat	ing Stati	on - Un	it 1			0	1510101	0 2 1712	1 OF	0 3
-	,												
	Read	ctor	Trip	From 60%	- LOW L	ow Level N	0. 13	Stea	m Generat	or	100 (8)		
				REPORT DATE	REPORT DATE (7) OTHER F				ES DOCKET NUMBER(S)				
MONTH	DAY	YEAR	YEAM	NUMBER	NUMBER						0 151010	101	11
				_		0000							
01	2 1	84	84	-0 0 4	-00	021/	0 4				0 151010	LOL	
0	RATING	1		PORT IS BUSMITTE	D PURBUANT	TO THE REQUIREME	NTS OF 10	CPR \$ 10	Check one or more of	i the followingi (11)		
NOWE LEVE (19)		<u>ا (</u>	20. 20. 25. 20. 20. 20. 20.	402(a) 406(a)(1)(i) 406(a)(1)(ii) 406(a)(1)(iii) 406(a)(1)(iv) 406(a)(1)(iv)		20.409(a) 90.39(a)(1) 90.39(a)(2) 90.73(a)(2)(1) 90.73(a)(2)(1) 90.73(a)(2)(1)			60.73(a)(2)(v) 60.73(a)(2)(v) 50.73(a)(2)(vii)(A 50.73(a)(2)(viii)(A 50.73(a)(2)(viii)(S 50.73(a)(2)(x)	u u	73,71(c) 73,71(c) 07HER (34 before and 385A)	ectly in Abi n Text, NRC	tract C Form
NAME.					L	ICENSEE CONTACT	POR THIS	LER (12)			TELEPHONE NUN		
NAME										AREA CODE	TELEPHONE NON		
		J. L.	Rupp	p						610 9	313 19 1-	14 B	P 19
		_		COMPLETE	ONE LINE FOR	EACH COMPONENT	FAILURE	DESCAILE	D IN THIS REPORT	T (15)			
CAUSE	SVSTEM	COMP	ONENT	MANUFAC-	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC-	TO NPROS	•	
x	sp	PID	CIV	M 1 2 10	Y			1		111			
	1		1.1	1.1.1.					111	1111			
				BUPPLEME	NTAL REPORT	EXPECTED (14)				EXPECTS	MONT	DAY	YEAR
_						-				SUBMISSI DATE (1)	ON 5)		
ABSTRAC	T ILimit	to 1400 m		SUBMISSION DATE	single-spece type	Written lines (16)				1		11	<u> </u>
	On in 1 in 1 spil fai. sign such Wate trip A s: Extern prob Prob The to rep	Janua No. 1 et va ke in led t nals. tion er le p. 1 imila ensiv blem. vent reac ow th tecti even the a ortak	ry 21 3 Ste lve t a fe o ope Thi press vel d cN47 r occ re tes The the v tor t is min on Sy t inv automa ble in	l, 1984, a am Genera to a Low P eedwater h en automat is caused sure, which decreased was found currence of sting, at e valve have valve from trip is to himum volu ystem fund volved no atic opera h accordan	reacto tor. T ressure leater. ically, No. 11 h led t to the to the to be on Janua that ti is been bindin preven me requi- tioned undue r tion of new with	r trip occ The initiat Feedwater The bypas and would Steam Gene to the low low-low le intermitte ry 7, 1984 me, did no adjusted t g when in t operation ired for a as designe isk to the the React 10CFR50.7	Heat Heat Heat Not Heat Heat Heat Heat Heat Heat Heat Hea	due vent er st ve ar respo Feed cond setpoi bindi docum real t thit th shut p th the the he th or cotect 2) (iv	to a low- was the c ring, due ound the ound to rem water Pum lition in int, which ing when i hented in the interm the interm the travel, osition. the steam ge the steam ge th	low water losure of to a hig heaters obte-manual p to trip the steam a caused f in the shu LER 84-00 hittent b which w The purp enerator f l. The purp the steam a caused f in the shu LER 84-00 hittent b which w The purp enerator f l. The purp the steam a caused f in the shu LER 84-00 hittent b which w the purp	r level f the gh level (lCN47) al contro p on low n generat the react ut positi 02-00. inding ill pose of water lev Reactor intained. blic. Du vent is	or. or. on.	
					84 P'0 S	02240072 R ADOCK	840 0500	217 0272 PDR					

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Salem Generating Station	DOCKET NUMBER	LER NUMBER	PAGE
Unit 1	05000272	84-004-00	2 QF 3

PLANT AND SYSTEM IDENTIFICATION:

.

Westinghouse - Pressurized Water Reactor

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

IDENTIFICATION OF OCCURRENCE:

Reactor Protection System [JC] - Reactor Trip From 60% - Low Low Level No. 13 Steam Generator - (Rx Trip #84-04)

Event Date: 01/21/84

Report Date: 02/17/84

This report was initiated by Incident Report No. 84-014

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 - Rx Power 060 % - Unit Load 0632 MWe

DESCRIPTION OF OCCURRENCE:

At 2240 hours, January 21, 1984, a reactor trip occurred due to a low water level condition in No. 13 Steam Generator. The initiating event was the closure of the inlet valve to 13A, 14A and 15A Low Pressure Feedwater Heater string (11CN27), due to a high level spike in 15A Feedwater Heater. The high level spike occurred while adjusting the controller for the Heater High Level Dump Valve (11HD65), to correct a heater high level condition. The bypass valve around the heaters (1CN47) failed to open automatically. An attempt was made to open 1CN47, using remote-manual control from the control room, but the valve failed to respond. This caused No. 11 Steam Generator Feedwater Pump [SJ] to trip on low suction pressure. The loss of the feedwater pump led to the low water level in No. 13 Steam Generator. Water level decreased to the low-low level setpoint, which caused the reactor trip.

APPARENT CAUSE OF OCCURRENCE:

1CN47 is designed to open automatically upon a 115 psi differential pressure across the heaters or, upon 265 psig suction pressure on the feed pumps. It is also designed to be operated from the control room. The valve failed to respond to automatic or manual control signals. On January 7, 1984, a similar occurrence was experienced; that occurrence was documented in LER 84-002-00. At that time, the differential pressure setpoint was found to be high. The valve was stroked and tested in all possible modes of operation. Remote-manual and automatic operation of the valve was satisfactory.

	-	EVENT	REPORT			a she had a set of a set	
	LICENSEE			(LER)	TEXT	CONTINUATION	
Salem Generat	ing Station	n	DOCKET	NUMBER	R	LER NUMBER	PAGE
Unit 1	•		05000	2720	1.	84-004-00	3 OF 3

APPARENT CAUSE OF OCCURRENCE: (cont'd)

The valve operated smoothly, and no reason could be found for the valve not responding to the manual or the low suction pressure signals. Following this occurrence (January 21,1984), investigation revealed that the valve was experiencing an intermittent binding problem, while in the shut position.

ANALYSIS OF OCCURRENCE:

The purpose of the reactor trip, on low-low steam generator level, is to prevent operation with the steam generator water level below the minimum volume required for adequate heat removal; thereby preventing the loss of the reactor heat sink. The trip is actuated on two out of three low-low water level signals in any steam generator. The setpoint ensures that there is adequate inventory in the steam generators, at the time of the reactor trip, to allow for any possible starting delays of the Auxiliary Feedwater Pumps [BA]; thus preventing steam generator dry-ouc and the Reactor Coolant System [AB] thermal and hydraulic transients that would be associated with a loss of the heat sink. The Reactor Protection System [JC] functioned as designed, and the heat sink was maintained. The Reactor Coolant System has been designed to withstand the thermal and hydraulic effects of four-hundred (400) reactor trips from full power. This trip was well within the design limits of the system. This occurrence involved no undue risk to the health or safety of the public. Because of the automatic actuation of the Reactor Protection system, the event is reportable in accordance with the Code of Federal Regulations, 10CFR 50.73(a)(2)(iv).

CORRECTIVE ACTION:

As previously stated, 1CN47 was intermittently binding when in the shut position. The valve has been adjusted to limit the travel, which will prevent binding when in the shut position. It has been tested in all possible modes of operation. Remote-manual and automatic operation of the valve is satisfactory. Permanent repairs will be effected during the next available outage of sufficient duration.

pre grats &-

General Manager-Salem Operations

JLR:tns

SORC Mtg 84-018



Public Service Electric and Gas Company P.O. Box E. Hancocks Bridge, New Jersey 08038

Salem Generating Station

February 17, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

SALEM GENERATING STATION LICENSE NO. DPR-70 DOCKET NO. 50-272 UNIT NO. 1 LICENSEE EVENT REPORT 84-004-00

This Licensee Event Report is being submitted pursuant to the requirements of 10CFR 50.73(a)(2)(iv). This report is required within thirty (30) days of discovery.

Sincerely yours,

Jos pusho f.

J. M. Zupko, Jr. General Manager -Salem Operations

JR: k11861

CC: Distribution

IE22 1/1

The Energy People

. .