

ILLINOIS POWER COMPANY



1605-L
U-10129

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

February 22, 1984

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Potential Deficiency 55-82-11
10CFR50.55(e)
Incorrect Identification of
Base Material and Weld Procedures
on Piping Hanger Travelers

Dear Mr. Keppler:

In Illinois Power Company letter dated November 14, 1983 (ref: letter D.P. Hall to J.G. Keppler, U-10106), your office was provided an interim report addressing the status of the subject 10CFR50.55(e) investigation. It was anticipated at the time that approximately ninety (90) days would be necessary to complete the investigation and to provide a final report on the issue.

Illinois Power Company is presently involved in the final verification actions necessary to evaluate the adequacy of the investigation and the corrective actions taken. It is anticipated that approximately thirty (30) additional days will be necessary to complete and evaluate the results of this activity, and to provide a final report on the issue.

If you have any questions or comments regarding the status of actions taken on this issue, please contact Illinois Power Company.

Sincerely,

A handwritten signature in dark ink, appearing to read "D. P. Hall".

D. P. Hall
Vice President

RDW/lag

cc: NRC Resident Office
Director - Office of I&E, US NRC, Washington, DC 20555
Illinois Department of Nuclear Safety
INPO Records Center

8402290276 840222
PDR ADOCK 05000461
S PDR

FEB 24 1984

1/0 JES7