

✓

October 30, 1994

Mr. Douglas M. Collins, Chief
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N.W., Suite 2900
Atlanta, Georgia 30323-0199

RE: Docket Number: 030-20510
License Number: 52-21325-01


Dear Mr. Collins:

I refer to your letter dated June 24, 1994, addressed to Dr. René Dietrich and myself. In said letter, you implied that we had not submitted a quality management program, as of that date. On July 22, 1994, we wrote you correcting your oversight on this matter. Since we have not received a reply to our letter, we need to advise you again that, despite the fact that we do not use iodine I-125 or I-131 in any quantity, we did submit a QMP as part of our license renewal submitted in November, 1993.

Since that time, we have modified the QMP that we submitted then, so I am enclosing a copy of the revised program which we intend to use in the event that we start using radioiodine.

Please advise if there is any additional modification required.

Sincerely,


M.M. Palacios de Lozano, M.S.
Consultant Radiological Physicist
Alternate RSO
Hospital San Pablo

000246
9503130209 941030
PDR ADOCK 03020510
C PDR

ML21