

EXHIBIT A

8311010214 831020
PDR ADCK 05000302
S PDR

IE22

SUPPLEMENTARY INFORMATION

REPORT NO.: 50-302/83-040/03L-0

FACILITY: Crystal River Unit 3

REPORT DATE: October 20, 1983

OCCURRENCE DATE: September 22, 1983

IDENTIFICATION OF OCCURRENCE:

The semi-annual surveillance of the sodium hydroxide concentration (NaOH) in the Building Spray Additive System was not performed as required by Technical Specification 4.6.2.2.b.2.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 (73% full power)

DESCRIPTION OF OCCURRENCE:

On September 22, 1983, Florida Power Corporation was reviewing the sodium hydroxide concentration data as a follow-up to LER 83-024. (LER 83-024 identified that FPC has erroneously been equating 1.0 mg per liter with 1.0 ppm.) Responsible personnel were unable to provide objective evidence that the semi-annual concentration determination had been performed as required during July, 1982.

DESIGNATION OF APPARENT CAUSE:

During July, 1982, chemistry control procedures were being revised en masse. Due to the complexity of these revisions, the requirement to perform the NaOH analysis was evidently overlooked.

ANALYSIS OF OCCURRENCE:


The next semi-annual concentration analysis, performed January, 1983, indicated that the concentration was within Technical Specification limits (as they were understood at that time).

CORRECTIVE ACTIONS:

Other chemistry analyses that were required to be performed during July and August, 1982, will be reviewed to identify any additional omissions by January 1, 1984.

FAILURE DATA:

This was the first time that surveillance 4.6.2.2.b.2 was missed and the third report under Specification 3.6.2.2.



83 OCT 27 A10:46

**Florida
Power**
CORPORATION

October 20, 1983
3F1083-17

Mr. James P. O'Reilly
Regional Administrator, Region II
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, GA 30303

Subject: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
Licensee Event Report No. 83-040

Dear Mr. O'Reilly:

Enclosed is Licensee Event Report No. 83-040 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.9(b).

Should there be any questions, please contact this office.

Sincerely,

G.R. Westafer
Manager
Nuclear Operations Licensing and Fuel Management

AEF:jcf

Enclosure

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

IE 22

11