
CONTROL BLOCK: []] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
GT1 FIL C R P 3 2 0 0 + 10 10 0 0 0 0 0 0 0 4 1 1 1 1 1 0 57 CAT SE
CON'T REPORT LING LO 510 - 10 3 10 12 7 11 11 29 813 8 11 12 12 9 8 13 9
[0] 2 At 1525 on November 29, 1983, it was discovered that the decay heat cooler
"B" discharge temperature indicator, DH-2-TI2, was indicating mid-scale,
[150 degrees, and not the actual temperature of 71 degrees, indicated by the
[0]5 plant computer. The meter was removed, checked, cleaned and returned to
[Service at 1800 on November 29, 1983. Only the temperature indication was
lost. This is the second event of this type and the twenty-fifth report
[0]8 Lunder Technical Specification 3.5.2.
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
TO REPORT 8 3 0 610 1013 11 101
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NORDA PRIME COMP. COMPONENT MATHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER SUPPLIER SUPPLIER MANUFACTURER SUPPLIER SUPPLI
40 41 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 110 The cause of this event is undetermined at this time. The meter was checked,
The cause of this event is undetermined at this time. The meter was checked,
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this com-
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted.
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted. The meter was checked, the meter was chec
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted. The meter was checked, the meter was chec
The cause of this event is undetermined at this time. The meter was checked, TI cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted. TI ponent to determine if further corrective action is warranted.
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted. 12 ponent to determine if further corrective action is warranted. 13
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted. 1
The cause of this event is undetermined at this time. The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted.



04 JAN 3 P2:31

Florida Power

December 29, 1983 3F1283-38

Mr. James P. O'Reilly Regional Administrator, Region II Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission IOI Marietta Street N.W., Suite 2900 Atlanta, GA 30303

Subject:

Crystal River Unit 3

Docket No. 50-302

Operating License No. DPR-72 Licensee Event Report No. 83-060

Dear Mr. O'Reilly:

Enclosed is Licensee Event Report No. 83-060 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.9(b).

Sincerely,

P. Y. Baynard

Assistant to Vice President

Nuclear Operations

AEF/feb

Enclosure

cc:

Document Control Desk

U.S. Nuclear Regulatory Commission

Washington, D.C. 20555

TEZZ

SUPPLEMENTARY INFORMATION

REPORT NO.: 50-302/83-060/03L-0

FACILITY: Crystal River Unit 3

REPORT DATE: December 29, 1983

DATE OF OCCURRENCE: November 29, 1983

IDENTIFICATION OF OCCURRENCE:

Decay Heat Temperature Indicator (DH-2-TI2) was inoperable. This malfunction caused "B" Decay Heat Cooler to be considered inoperable contrary to the requirements of Technical Specification 3.5.2.

CONDITIONS PRIOR TO OCCURRENCE:

Mode I (100% Full Power).

DESCRIPTION OF OCCURRENCE:

At 1525 on November 29, 1983, it was discovered that the "B" Decay Heat Cooler discharge temperature indicator, DH-2-TI2, was indicating mid-scale, 150° F, and not the actual temperature of 71° F indicated by the plant computer. The meter was removed, checked, cleaned, and returned to service at 1800 on November 29, 1983.

DESIGNATION OF APPARENT CAUSE:

The cause of this event is undetermined at this time.

ANALYSIS OF OCCURRENCE:

Only the temperature indication was lost. Correct temperature was available via the computer point. The redundant cooler was available maintaining the ability to meet the system's safety function. Furthermore, the cooler was functional. The loss of temperature indication would have presented conflicting information to the operator with regard to how well it was functioning.

CORRECTIVE ACTION:

The meter was checked, cleaned and returned to service. FPC will continue to monitor this component to determine if further corrective action is warranted.

FAILURE DATA:

This is the second event of this type and the twenty-fifth report under Technical Specification 3.5.2.