

DIRECTOR OF REGULATION ACTIVITY REPORT, REPORT NO. 68, NOVEMBER 15, 1967

OYSTER CREEK--Both Jersey Central and the Division of Compliance are actively investigating the problems of cracks near shop welds joining control rod stub tubes to the pressure vessel (see Report No. 67) and porosity indications in field welds joining stub tubes to control rod guide tubes.

8304080206 690106  
PDR ADOCK 05000219  
A PDR