

MAY 6 1971

J. B. Henderson

1. This is to advise you of my conversation with J. Varela, CO:II, at the Turkey Point 3 site.
2. No work on tendon examination being done today.
3. In four days of inspection one tendon has not been completely examined.
4. The radius between the button head and the wire was checked and found to measure only 10 mils. There does not seem to be a specification for this item on this job.
5. Tensioning of the dome tendons started today.

cc: A. Giambusso
 L. Kornblith, Jr.
 R. H. Engelken

L. L. Beratan

50-250, Incident

5/6/71

8305190135 710319
 PDR ADOCK 05000250
 A PDR

OFFICE ▶	CO:TSB				
SURNAME ▶	<i>L. L. Beratan</i> Liberatan: gk				
DATE ▶	5/6/71				