

NOV 13 1972

D. J. Skovholt, Assistant Director for Operating Reactors, L

MILLSTONE 1 - DOCKET NO. 50-245 - DRAWINGS AND PHOTOGRAPHS OF
CRACKED FEEDWATER SPARGERS

In followup to my memorandum to you of November 3, 1972, I am
enclosing the following drawings and photographs relating to the
cracked feedwater spargers at the Millstone 1 facility:

1. Plan view of sparger assemblies.
2. Copy of A GE Drawing of the feedwater spargers.
3. Copies of photographs and recorded visual observations
of the cracking on all four sparger units and a general
view of the sparger end bracket.

If you have any questions regarding these enclosures, please let
us know.

Original signed by
R. H. Engelken

R. H. Engelken, Assistant Director
for Inspection and Enforcement, RO

Enclosures: *no end for yellow*
As Stated

cc:w/enclosure
F. E. Kruesi, RO
A. Giambusso, L
R. R. Maccary, L
D. L. Ziemann, L

*50-245
isgny*

B307090311 740308
PDR ADOCK 05000245
P PDR

OFFICE ▶	RO	RO	RO		
SURNAME ▶	RJMcDermott	JGKepler	RHEngelken		
DATE ▶	11/13/72	11/13/72	11/13/72		