

E. J. Bauser,  
Executive Director  
Joint Committee on  
Atomic Energy

RE: MILLSTONE 1 - DOCKET NO. 50-245  
DRAWINGS AND PHOTOGRAPHS OF CRACKED  
FEEDWATER SPARGERS

In response to your request to Dr. Morris,  
please find enclosed the following drawings  
and photographs relating to the cracked feed-  
water spargers at the Millstone 1 facility:

1. Plan view of sparger assemblies
2. Copy of a G.E. drawing of the feedwater  
spargers
3. Copies of photographs and results of visual  
inspection of the cracking on all four  
sparger units and a general view of the  
sparger end bracket.

If you have any questions regarding these  
enclosures, please let us know.

Enclosures:  
As Stated

bcc: P. A. Morris, RO

R. H. Engelken,  
Assistant Director  
for Inspection and  
Enforcement, RO

11/10/72

*no enclosure  
on yellow*

*50-245  
inquiry*

8307090316 740308  
PDR ADOCK 05000245  
P PDR

OFFICE	RO	RO				
SURNAME	JGKepler:mm	RHEngelken				
DATE	11/10/72	11/10/72				