Carolina Power & Light Company

Raleiga, North Carolina 27602

May 16, 1972

Robinson File No. 2-0-4-a

Mr. Edward J. Block, Acting Director Directorate of Licensing U. S. Atomic Energy Commission Washington, D. C. 20545

H. B. ROBINSON UNIT NO. 2

LICENSE DPR-23

FAILURE TO PERFORM A SURVEILLANCE TEST
ON THE AUXILIARY FEEDWATER SYSTEM

Dear Mr. Block:

During a routine audit of the completed periodic tests, it was noted that Periodic Test No. 22 (Technical Specification Section 4.8.1 to 4.8.3), involving the Auxiliary Feedwater System, had not been performed as scheduled on April 18, 1972. This test was successfully performed on May 2, 1972 which was six days over the 25% adjustment time as stated in Technical Specifications, Section 4.0.

In an effort to prevent a re-occurrence of this violation, the periodic test status board will be monitored more closely and the duty shift foreman will cross-check the periodic tests to be performed on his shift against a master list which designates specific due dates for each periodic test.

This is reported in accordance with Technical Specification 6.6.3.d. The Company Nuclear Safety Committee will investigate this violation in accordance with Section 6.1.4.2.g.5.

Yours very truly,

Manager

Bulk Power Supply

JBM: mc

2738