

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
0	1	N	Y	N	M	P	1										4	1	1	1	1	0	1			
7	8	9					14	15								25	26					31	32			

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
0	1	M	I	L	L	0	5	0	-	0	2	2	0	1	2	1	2	7	5	0	1	0	7	7	5
7	8	57	58	59	60	61							68	69					74	75					80

[illegible]

02	During routine surveillance testing, RE-04C indicated a trip at 3.25 psig rather	80
03	than 3.5 ± .053 psig.	80
04		80
05		80
06	AOR 75-38	80
	SYSTEM CAUSE PRIME	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	I	A	E	I	N	S	T	R	U	N	B	0	8	0	N
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Could find no apparent reason for the drift, however, routine surveillance is	
7 8 9		
09	sufficient to locate these problems.	80
7 8 9		
10		80
7 8 9		

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		80
11	E	050				b				
7	8	9	10	12	13	44	45	46		80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE		
12	Z	Z								
7	8	9	10	11		44	45			80
PERSONNEL EXPOSURES										

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	d	Z

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	

OFFENSE CONSEQUENCES Probable

1	5	None
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		8302180068 760107

17	PUBLICITY	PDR ADOCK 05000220	80
	None	PDR	

ADDITIONAL FACTORS

None

19

NAME: T.J. Dente

PHONE: (315) 343-2110