POWER & LIGHT / P.O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 29, 1984

W3K84-1504 Q-3-A35.07.60 Q-3-A35.07.78 Q-3-A35.07.105 Q-3-A35.07.108 Q-3-A35.07.109

JUL 10 1984

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiencies Nos. 60, 78,

105, 108, and 109 Extension Request

The Final Reports for the listed Significant Construction Deficiencies were due to the USNRC on June 29-30, 1984.

At the present time, a further review of the corrective action and supporting documentation is being undertaken and is scheduled to be completed in early July 1984.

The final reports will be submitted to the USNRC as indicated.

SCD-60, "Turnover Documentation and Inadequate Hanger Weld Problems T&B", July 20, 1984.

SCD-78, "American Bridge Structural Steel Deficiencies", July 20, 1984

SCD-105, "Electrical Separation Deficiencies (Reg Guide 1.75)", July 20, 1984

SCD-108, "Potential Failure to Comply with FSAR Safe Shutdown Commitment", July 20, 1984

SCD-109, "Inadequate Design of QSPDS/PPS Circuit Interface", July 20, 1984

Very truly yours,

Levreto

T. F. Gerrets

Corporate Quality Assurance Manager

TFG: CNH: VBR

IE-27

Mr. John T. Collins June 29, 1984 W3K84-1504 Page 2

cc: Director
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake Shaw, Pittman, Potts & Trowbridge 1800 M Street, N.W. Washington, D.C. 20036

Mr. W. M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

Mr. W. A. Cross 7910 Woodmont Avenue Suite 1200 Bethesda, Maryland 20814