



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION V
2111 BANCROFT WAY
BERKELEY, CALIFORNIA 94704

TELEPHONE: 841-5121
EXT. 651

September 26, 1972

J. G. Keppler, Chief
Reactor Testing and Operations Branch
Directorate of Regulatory Operations, HQ

RO INQUIRY REPORT NO. 050-0206/72-08
SOUTHERN CALIFORNIA EDISON COMPANY (SAN ONOFRE UNIT NO. 1)
FEEDWATER PUMP FAILURE

The subject inquiry report is forwarded for your information.

We consider the action planned by the licensee to be adequate. Our inspector will examine the details of the occurrence during the next scheduled inspection. You will note that the licensee plans to submit a written report of the occurrence to Licensing within 10 days as required by the technical specifications.

G. S. Spencer
Chief, Reactor Construction
and Operations Branch

Enclosure:

RO Inquiry Rpt No 050-0206/72-08
by A. D. Johnson

cc w/encl:

RS, AD for Safety and Security Stds. (3)
L AD for Boil. Water Reactors (2)
L AD for Press. Water Reactors (2)
L AD for Operating Reactors (3)
L AD for Site Safety (2)
RO Office of Operations Evaluation
RO AD for Procedures
RO AD for Inspection & Enforcement
RO Files
DR Central Files

U.S. ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

1972 SEP 28 AM 11 58

RECEIVED

8302230085 720929
PDR ADOCK 05000206
S PDR