

Entergy Operations, Inc.

J6471

Peri Damen, MS 39150

W. Y. Cottle

February 28, 1992

U.S. Nuclear Regulatory Commission Mail Station P1-137 Washington, D.C. 20555

Attention: Document Control Desk

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-29 1991 Annual Operating Report

GNRO-92/00014

#### Gentlemen:

Entergy Operations, Inc. is transmitting the Grand Gulf Nuclear Station (GGNS) Unit 1 Annual Operating Report for 1991. This report is in accordance with the reporting program described in Regulatory Guide 1.16, Revision 4, Part C.1.b as modified by the NRC letter to GGNS dated May 25, 1987 (MAEC-87/0131).

Provided as attachments are:

- A narrative summary of operating experience during the year 1991.
- 2. Main Steam Line Safety Relief Valve challenges,
- A tabulated annual report of personnel exposure greater than 100 mrem/yr, and

4. A summary of failed fuel indications/inspections.

Yours truly,

Can P CORE

WTC/TKM/cg attachments: cc: (Sec Next Page)

9203090080 911231 PDR ADDCK 05000416 R PDR

ANOPERRF/SCMPFLR + 1

February 28, 1992 GNRO-92/00014 Page 2 of 3

cc: Mr. D. C. Hintz (w/a) Mr. J. Mathis (w/a) Mr. R. B. McGehee (w/a) Mr. N. S. Reynolds (w/a) Mr. H. L. Thomas (w/o)

> Mr. Stewart D. Ebneter (w/a) Regional Administrator U.S. Nuclear Regulatory Commission Region 11 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30323

Mr. P. W. O'Connor, Project Manager (w/a) Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Mail Stop 13H3 Washington, D.C. 20555

#### Summary of Operating Experience 1991

The following is a summary of Grand Gulf Nuclear Station (GGNS) Unit 1 operating experience for the 1991 calendar year. During 1991, the reactor was critical for 8,230.3 hours with the generator on line for 8036.7 hours.

On February 13, 1991, a runback of Reactor Recirculation Flow Control Valve "A" occurred. This corresponded to a 14% reactor power reduction. The problem was traced to a circuit card which was replaced and retested. The plant returned to 100% power two hours after the event.

On March 8, 1991, reactor power was reduced to 70% at the request of the system dispatcher.

The plant had been on-line 96 consecutive days prior to a reactor scram which occurred on April 6, 1991 (LER 91-002-01), during the Automatic Turbine Testing (ATT) Turbine Overspeed Trip Test Surveillance. The scram was due to failure of the test circuitry power supply module, which caused a main turbine trip. The module was replaced and the generator was synchronized at 1603 hours on April 7, 1991.

Reactor power was decreased to 62% on April 30, 1991 to perform an investigation of an increase in Steam Tunnel temperature. It was determined that a reactor water cleanup instrument line and a flow element gasket were leaking and reactor power was reduced to 50% on May 1 for the repair activity. Reactor power was returned to 100% on May 3, 1991.

During a controlled shutdown on June 11, 1991 to replace the recirculation pump seals, the reactor scrammed at 1840 hours (LER 91-004). The scram was caused by a loss of condensate/feedwater flow resulting from condensate minimum flow control valve failure. New seals were installed on "A" and "B" reactor recirculation pumps and the generator was synchronized at 0856 hours on June 16, 1991.

On June 17, 1991 at 0935 hours, the unit tripped as a result of a "B" phase 500 kV switchyard circuit breaker ground fault and subsequent service transformer lockout (LER 91-005-01). Corrective actions were taken and the generator was synchronized June 19, 1991 at 0421 hours.

On June 25, 1991, a DIV II RWCU isolation occurred due to a voltage surge resulting from a lightning strike to an incoming 500 KV line (LER 91-006). The RWCU system was reset and RWCU pumps restarted.

On July 28, 1991, the reactor scrammed from a Turbine Control Valve (TCV) fast closure due to load shed of BOP buses (LER 91-007). A design fault was found in LSS panels. The Division I and II LSS panels were modified and the generator was synchronized August 6, 1991 at 2013 hours.

The reactor scrammed from 100% power August 10, 1991 at 1906 hours (LER 91-010). This scram was caused by a lightning induced spike on APRMs. The generator was synchronized August 12, 1991 at 0649 hours.

Attachment 1 to GNRO-92/00014 Page 2 of 2

#### Summary of Operating Experience 1991

The plant had been on line 99 days when an automatic reactor scram occurred November 19, 1991 (LER 91-012). The scram was a result of an APRM spike due to a lightning strike. A task force investigated Grand Gulf's susceptibility to lightning strikes. The generator was synchronized at approximately 2310 hours on November 23.

On December 6, 1991, the Division II LSS Panel power supply failed. The 15 and 24 volt power supplies were replaced. The panel was retested and restored to operable status.

Un December 29, 1991 power was reduced to cold shutdown for replacement of "B" kecirculation Pump Shaft. B21-F803 feedwater check valve failed its leak check surveillance. This valve was inspected and work completed. During system realignment, valve E12-F004A would not stroke due to thermal binding. Reactor coolant temperature was decreased and the valve was successfully opened. The plant returned to power January 10, 1992.

Attachment 11 to GNR0-92/00014 Page 1 of 3

## MAIN STEAM SAFETY RELIEF VALVE CHALLENGES 1991

This section contains a summary of main steam line rafety relief valve challenges which occurred during 1991 as reported the GGNS Monthly Operating Reports for that period.

The summaries were originally included in the following monthly reports:

June 10	1 Report	GNRO-91/00121		dated:	July 10, 1991
July 199	1 Report	 GNRO-91/00144	÷**32	dated:	August 14, 1991

Attachment II to GNR0-92/00014 Page 2 of 3

### MAIN STEAM SAFETY RELIEF VALVE CHALLENGES 1991

	DOCKET NO.		50-416
	COMPLETED TELEPHONE	BY	1 1. K. Murray (601) 437-2401
Date of Occurrence:June 17, 1991		2	
Plant Operating Condition:			
Rx Thermal Power 73,7% Rx Pressure (psig	) <u>999</u>	Rx	Mode
Rx Power (MWE) 862 Rx Temperatures	540 <sup>0</sup> F		
Number of mainsteam line SRVs: 20			
Number of SRVs affected by event:5			
Narrative:			
	time		the second se

On June 17, 1991, a ground fault on the B Phase of Circuit Breaker J1532 caused a lock out on Service Transformer 11.

There were no automatic SRV actuations. These SRVs were manually operated: SRV B21-F041K actuated 3 times. The following SRVs actuated once: B21-F051D, B21-F041E, B21-F047L and B21-F047D.

Attachment II to GNR0-92/00014 Page 3 of 3

#### MAIN STEAM SAFETY RELIEF VALVE CHALLENGES 1991

		DOCKET NO.	50-416
		COMPLETED BY TELEPHONE	T. K. Murray (601) 437-2401
Date of Occurrence:3	luly 28, 1991		en an
Plant Operating Condition:			
Rx Thermal Power 100%	Rx Pressure (psig	) <u>1046.7</u> Rx	Mode 1
Rx Power (MWE) 1220	Rx Temperatures	<u>540<sup>0</sup>F</u>	
Number of mainsteam line SR	Vs:20		
Number of SRVs affected by	event: 11		

Narrative:

On July 28, 1991, a reactor scram occurred from Turbine Control Valve fast closure due to loss of power to the turbine control fluid pumps (EHC). The loss of power resulted from an inadvertent Division II LSS load shed.

The following SRV's actuated automatically once:

B21-F047A, B21-F047C, B21-F047D, B21-F047G, B21-F047H, B21-F047L, B21-F051A, B21-F051B, B21-F051D, B21-F051F, and B21-F051K.

Attachment III to GNR0-92/00014 Page 1 of 4

#### GGNS UNIT 1 ANNUAL REPORT

#### MAN-REM EXPOSURE - 1991

This section contains a tabulation of the number of station, utility and other personnel receiving exposures greater than 100 mrem/yr and their associated Man-Rem exposure according to work and job function. Also included is a tabulation of the number of personnel by exposure range.

Attachment ITI to GNE0-92/00014 Page 2 of 4

ENTERGY OPERATIONS, INC.

PERSONNEL AND MAN-REM BY WORK AND DUTY FUNCTION FINAL END OF THE TEAR REPORT FOR 1991

NUMBER OF PERSONNEL OVER 100 MREM TOTAL MAN-REM

	STATION EMPLOYEES	UTILITY EMPLOYEES	CONTRACT WORKERS AND DTHERS	STATION EMPLOYEES	UTILITY EMPLOYEES	CONTRACT WORKERS AND DTHERS
REACTOR OFS/SURVEILLANCE						
MAINTENAKCE	5.0		4	0.632	0.000	0.000
OPERATIONS	52	0		12.039	0.000	0.189
HEALTH FRYSICS	36			8,507	0.000	1,386
SUPERVISORY				0,206	0,000	0.026
ENGINEERING	3	0		0,219	0.000	0.002
ROUTINE MAINTENANCE						
MAINTENANCE	128	0	59	38,647	0.000	20,982
OPERATIONS	18	0	성영은 전환 문제가	0,407	0,000	0.061
HEALTH PHYSICS	29	0		4,095	0.000	0.364
SUPERVISORY		8	가슴 이 많이 많다.	1,082	0.000	0.220
ERGINEERING	2	•		0.241	0.000	0.111
IN-SERVICE INSPECTION						
MAINTENANCE	0.00	6	같은 것 같은 것 같은 것 같은 것 같이 많이 많이 많이 많이 했다.	0.000	0.000	0.060
OPERATIONS		0	Ale and the second s	0.000	0.000	0.000
NEALTH PHYSICS		0	0	0.000	0,000	0.000
SUPERVISORY		0	0	0.000	0.000	0.000
ENGINEERING	0	0		0.000	0.000	0.000
SPECIAL MAINTENANCE						
MAINTENANCE	÷	0		0.000	0.000	0.000
OPERATIONS	0	0	0	0.000	0.000	0.000
HEALTH PHYSICS	0	0		0.000	0.000	6.000
SUPERVISORY	0	0		0,000	0.000	0.000
F#GINEERING	0	Q	0	0.000	0.000	0.000
WASTE PROCESSING						
MAINTENANCE	69	0		1.796	0.000	2.294
OPERATIONS		0	6	0.643	0.000	1.683
HEALTH PHYSICS	7	0		2,167	0.000	6.002
SUPERVISORY	0	0	0	0,000	0,000	0,000
ENGINEERING	0	0	Q	0.000	0.000	0.000
REFUELING						
MAINTENANCE	0		0	0.000	0.000	0.000
OPERATIONS	0	0		0.000	0.000	0.000
HEALTH PHYSICS	0	6	0	0,000	0.000	0.000
SUPERVISORY	0	1.4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1		0.000	0,000	0,000
ENCINEERING	0	Û	0	0.000	0.000	0.000
TOTALS						
MAINTENANCE	202	6	67	40.475	0.000	21.276
OPERATIONS	67	0	14	13,289	0,000	1,932
NEALTH PAYOTER	25	õ	1	14,770	0,000	1,252
CUDEDVIONDY	11	0		1.288	0.000	0.246
ENGINEERING	5	Ó	2	0.460	0.000	0.115
GRAND TOTAL	357	0	92 ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	1 19.282	1 0.000	25.321
and Bring the set havened	a file Z	10-92	over by . Col	1. Dute	Com. 2	-20-92
Resistan Protec	tion Namaber	Date	Cenera	Hanager 668	\$ D	ate

#### ENTERGY OPERATIONS, INC.

Attachment III to CMR0=92/00014 Page 3 of 4

#### SUMMARY OF PERSONNEL MONITORING REPORT FINAL END OF THE YEAR REPORT FOR 1991

Estin	nate	10	who	51	e	b	00	iy		e x	çp	01	5 U	r	0	r	a	n	34	,																						-	Ni ir ir	1 1 1 1 1	bie	ei vi ac	du h	f als range
No Me	east	ira	b14		Ē	(p	01	s u	r	e																										l							ļ		ļ		39	6
Less	tha	s ra	0.1	É,			c		,					ł	e,		à	i.	ŝ		í	4	i.,	k	.,		í.		d	1	i.	ż	į.,	k	i.	à		h	ŝ	ì			ŝ	i.	,		42	5
0.1	to	0.	25	×	÷.,	k										į,		į	į	i	ŝ	i.	i.	i,	í.	ŝ	à	ŝ	į.	í,	i,	÷	į,	à			į,		i.	•			i,		į		1.2	6
0.25	to	ΰ.	5						,			+					ļ	÷			Ļ	į,		į		ä		i,	í.	÷		ì	į,				į.		į	į	į,				ł		9	9
0.5	to	0.	75	×		4			,					,							ì	ł.	ci.	ł,		÷	ŝ	i.	ē.	į,		÷	į,	ļ			è		ļ								3	2
0.75	to	1.	0		,		* 1		ş		(a	*			;						4	ł	į,		į,	Ğ.	ł.	ł	i.	÷.		÷		į			i.		ŝ	ł	ŝ	÷	, ,				1	0
1.0	to	2,	0				*		ż								,	4				ŝ		x		l,		÷	l	į,		i,		à			÷	. ,	ż	ŝ		,						4
2.0	to	3.	0	-			ċ					÷	. ,		÷			•	į,		ł	•				÷				ŝ				ģ	4		į.		,			4			ł			3
3.0	to	4.	0			i.	e.		÷										ļ			4		×.	į,					÷				ļ	k		ŝ			÷								0
4.0	to	5.	ö				l	a				ş								. ,			a											ŝ,	i.				ļ					.,	×			0
5.0	to	6.	0		- 1 16 1				*						×			ł				ł		ļ		i.		×				i,				Å	ł			į		ų,		į,				0
6.0	to	7.	0		4			e 4	i. R			*							4			ŝ				i.			a 4								*				÷ 4							0
7.0	to	8.	0			Ğ.	1		į			ŝ								. ,								i.		×						. ,				÷		*						0
8.0	to	9.	0			à	÷	ć.e						i.								*			a a					i.				• •					.,			×	ş		ł			0
9.0	to	10	. 0	*	ie i	i.s	5.			ι.								,	+							i.		÷						e 19			,			,			ş		.,			0
10.0	to	11	, ù	÷	i.						i.		, , , ,		×																				*								,		ò			0
11.0	to	12	. 0		į,		1					,						8										*									i.				* 1		*	,				0
12.0	and	d o	ve	¢.	i.		ł		ŝ			*			4																		+							4		i K	×		i.			0
		-									i. 10	Apr											il es						-		-				- 14-1				6. 34	-	10.1						in 10 10	an. are the set of
(1) (1)	True	al e T rag	nu ot	mb al RE	e I M	r Do P	0 5	fer	P(P	e	r s R E r S	O M O	n	ne)	1	1	nc	n	1	te	o r	e	d															-							9	30	209 96 34	5 8 3
E ST	A. L	X	Pr		14		17	25		M	a 15			a 1				- 5	Za	co E e		12				(	1. 10	110	D	1	le.a	U	KM	Par	A 10	the	Aug	1.2	37	N	S						2	-20-9 Date

(1) Excluding 1821 persons with less than 0.1 REM. Total Dose on site for 1991 is 104,901 Rem for all persons monitored.

Attachment III to GNR0-92/00014 Page 4 of 4

# Special Maintenance Activities

There were no special maintenance activities in 1991.

÷

\*

Attachment IV to GNR0-92/00014 Page 1 of 1

## SUMMARY OF FAILED FUEL INDICATIONS/INSPECTIONS

No irradiated fuel assembly examinations were performed during the reporting period; however, one fuel rod failure is estimated from Cycle 5 fuel reliability data. No Technical Specification limits have been exceeded.