

From R. L. Langge

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

DATE: August 29, 1975

JECT: Abnormal Occurrence Report No. 50-220 75- 23  
(24 hour Notification)

The enclosed preliminary AOR is being submitted in accordance with Technical Specification Section 6.

Confirming R.A. Burns phone conversation  
with T. Shadlosky AEC RG:I office on  
August 27, 1975

TO: James P. O'Reilly  
Directorate of Regulatory Operations  
Region 1  
631 Park Avenue  
King of Prussia, Pa. 19406

OM: Niagara Mohawk Power Corporation  
Nine Mile Point - James A. FitzPatrick Site  
  
P.O. Box #32  
Lycoming, New York 13093  
  
Docket No. 50-220

ERENCE: License DPR- 63

port No.: 50- 220 /75- 23

port Date August 29, 1975

Occurrence Date August 26, 1975

ility: NY #1

Identification of Occurrence:

Iodine detection sensitivity in milk sample

8303110174 750829  
PDR ADDOCK 05000220  
PDR  
S

## NIAGARA MOHAWK POWER CORPORATION

NIAGARA      MOHAWK

Conditions Prior to  
Occurrence:

<input checked="" type="checkbox"/>	Steady State Power	Routine Shutdown
<input type="checkbox"/>	Hot Standby	
<input type="checkbox"/>	Cold Shutdown	
<input type="checkbox"/>	Refueling Shutdown	Load Changes
<input type="checkbox"/>	Routine Startup	Other

## Description of the Occurrence:

During an audit by NRP/JAF staff personnel of contractor's facility used in analyzing milk samples, it was discovered that required sensitivity per Appendix B 3.2.C was not met. Milk sample from location #1 collected 7/22/75 showed activity of I-131 =  $0.78 \pm 0.33$  pCi/l which has an associated error in the analysis of  $\pm 49\%$  rather than the required  $\pm 25\%$ .

## Apparent Cause of the Occurrence:

<input checked="" type="checkbox"/>	Design	<input checked="" type="checkbox"/>	Procedure
<input type="checkbox"/>	Manufacture	<input type="checkbox"/>	Unusual Service Condition
<input type="checkbox"/>	Installation/ Const.	<input type="checkbox"/>	
<input type="checkbox"/>	Operator	<input type="checkbox"/>	Component Failure
		<input type="checkbox"/>	Other (Specify)

## Analysis of Occurrence:

No effect on the environmental because of failure to meet this required sensitivity.

## Corrective Action:

Contractor has been informed that in order to meet the required sensitivity he must increase the milk sample counting time.

## Failure Date: