

LICENSEE EVENT REPORT

CONTROL BLOCK 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 N Y N M P 1										LICENSE NUMBER 11 - - - - -										LICENSE TYPE 4 1 1 1 1										EVENT TYPE 0 1													
CATEGORY 01 CONT M I										REPORT TYPE L		REPORT SOURCE L		DOCKET NUMBER 0 5 0 - 0 2 2 0										EVENT DATE 0 4 1 4 7 5										REPORT DATE 0 5 0 3 7 5									

EVENT DESCRIPTION

02 During normal power operation, the relay coil in RPS relay 12K30 (turbine trip
 03 1 out of 2 twice) shorted. EP# GEH-2024, part no. GEF-2757. Redundant relays were
 04 fully operable. Relay assumed tripped condition upon failure. Relay coil was
 05 replaced and unit tested.
 06 AOR 75-08

SYSTEM CODE 07 I A		CAUSE CODE E		COMPONENT CODE I N S T R U				PRIME COMPONENT SUPPLIER N		COMPONENT MANUFACTURER G I O 8 0				VIOLATION N	
-----------------------	--	-----------------	--	-------------------------------	--	--	--	-------------------------------	--	-------------------------------------	--	--	--	----------------	--

CAUSE DESCRIPTION

08 Appears to be normal failure, the result of the environment and high usage. Coil
 09 is always energized.
 10

FACILITY STATUS 11 C		% POWER 0 5 5		OTHER STATUS		METHOD OF DISCOVERY a		DISCOVERY DESCRIPTION	
FORM OF ACTIVITY RELEASED 12 Z		CONTENT OF RELEASE Z		AMOUNT OF ACTIVITY Z		LOCATION OF RELEASE			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0		TYPE 0		DESCRIPTION Z	
--------------------	--	-----------	--	------------------	--

PERSONNEL INJURIES

NUMBER 14 0 0 0		DESCRIPTION Z	
--------------------	--	------------------	--

CONSEQUENCES Probable

15 None as redundant component available and operable.

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z		DESCRIPTION Z	
--------------	--	------------------	--

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19

NAME: T.J. Dente

PHONE: (315) 343-2110