

## LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 6 0 15 0 0 0 3 1 5 7 0 6 1 2 8 3 8 0 6 2 4 8 3 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 THE PERFORMANCE OF TRAIN B OF THE BORON INJECTION TANK INLET PIPING HEAT TRACE  
03 CIRCUITRY WAS QUESTIONED ON 6/12/83 DURING THE SCHEDULED SURVEILLANCE TEST, BUT  
04 THE TRAIN WAS NOT DECLARED INOPERABLE UNTIL 6/16/83. THE ACTION STATEMENT OF  
05 T.S. 3.5.4.2 WAS NOT PERFORMED DURING THE PERIOD OF JUNE 12 TO JUNE 16. THE HEALTH  
06 AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.

07  
08

09  
SYSTEM CODE S F 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE H E A T E R 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17  
17 LER/RO REPORT NUMBER 8 3 21 EVENT YEAR 8 3 22 SEQUENTIAL REPORT NO. 0 5 3 24 OCCURRENCE CODE 0 1 28 REPORT TYPE T 30 REVISION NO. 0 32  
ACTION TAKEN B 18 G 19 33 FUTURE ACTION 34 EFFECT ON PLANT Z 20 35 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 22 37 ATTACHMENT SUBMITTED Y 23 40 NPRD-4 FORM SUB N 24 42 PRIME COMP. SUPPLIER L 25 43 COMPONENT MANUFACTURER C 3 3 2 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 MAINTENANCE REPAIRED A LOOSE SPLICE IN THE HEAT TRACE LINE ON 6/16/83. INVESTIGATION  
11 ON THE MISSED SURVEILLANCE REQUIREMENTS IS CONTINUING. PROCEDURE CHANGES HAVE BEEN  
12 MADE TO CORRECT A POSSIBLE CAUSE OF THIS EVENT. PERSONNEL CRUCIAL TO THE  
13 INVESTIGATION WILL NOT BE AVAILABLE UNTIL AFTER 14 DAY REPORTING REQUIREMENT  
14 L (EXPIRES 6/28/83). AN UPDATED LER WILL BE SUBMITTED.

15 FACILITY STATUS E 28 29 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
16 RELEASED OF RELEASE Z 33 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER D. F. KRAUSE

PHONE (616) 465-5901

8307050019 830624  
PDR ADOCK 05000315  
S PDR



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

June 24, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications  
the following report/s are submitted:

RO 83-053/01T-0

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/bab

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
B. Germano  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

JUN 27 1983

*Y 422*  
*11*