

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

May 14, 1984

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
LER/RO-369/83-20

Dear Mr. O'Reilly,

My letter of May 17, 1983 submitted reportable occurrence report RO-369/83-20 which dealt with discrepancies in the Unit 1 Initial Integrated Leak Rate Test. As part of the corrective actions given in the report it was stated that a procedural change will be incorporated in the 40±10 month Surveillance Test to cover Technical Specification 4.6.1.2f, detailing the Soap Bubble Test of hot penetration flued head to guard pipe welds while containment is pressurized. This change was originally to be incorporated in the Unit 1 procedure by 6/15/83; however, the change will now be incorporated prior to performance of the next surveillance testing.

Very truly yours,

H.B. Tucker / BT

Hal B. Tucker

PBN:glb

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8405290150 840514
PDR ADCK 05000369
S PDR

OFFICIAL COPY
IE 22
1/0