

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS MINNESOTA 55401

March 29, 1978

Mr J G Keppler, Director
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR 22

SBGTS "A" Train Low Flow

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b since it constitutes operation in a degraded mode for a period of time permitted by the Limiting Conditions for Operation.

Yours very truly,

L. O. Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

780950030

9105230307 780329
PDR ADOCK 05000263
S PDR

-over-

A002/s *
1/40

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M | N | M | N | P | 1 | 2 | 0 | 0 | - | 1 | 0 | 0 | 0 | 0 | 0 | - | 1 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 ST CAT SB

CON'T
 2 1 REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 3 | 7 | 0 | 2 | 2 | 8 | 7 | 8 | 9 | 0 | 3 | 2 | 9 | 7 | 8 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING SURVEILLANCE TEST, MINIMUM FLOW IN "A" TRAIN SBGTS COULD NOT BE ATTAINED AS
 0 3 REQUIRED BY T.S. 3.7.B.1. "B" TRAIN WAS SHOWN TO BE OPERATIONAL, ALSO ADEQUATE FLOW
 0 4 WOULD HAVE BEEN OBTAINED THROUGH BOTH SBGTS UNDER AUTOMATIC INITIATION CONDITIONS,
 0 5 NO EFFECT ON THE PUBLIC HEALTH AND SAFETY, PREVIOUS SIMILAR EVENT REPORTABLE OCCURR-
 0 6 ENCE M-RO-77-13 DATE 6-23-77,
 0 7
 0 8

0 9 SYSTEM CODE | S | C | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | V | A | L | L | V | O | P | 14 | COMP SUBCODE | D | 15 | VALVE SUBCODE | 2 | 16
9 10 11 12 13 14 15 16

17 LEAD REPORT NUMBER | 7 | 8 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 0 | 3 | 24 | 25 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN | A | 18 | FUTURE ACTION | E | 19 | EFFECT ON PLANT | E | 20 | SHUTDOWN METHOD | E | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | N | 23 | NRC-4 FORM SUB | Y | 24 | PRIME COMP SUPPLIER | X | 25 | COMPONENT MANUFACTURER | M | 4 | 3 | 0 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 DILUTION FLOW FROM COMPRESSED STORAGE NOT ISOLATED BY BV-4 WHEN SBGTS "A" TRAIN
 1 1 STARTED, FOREIGN MATERIAL IN BV-4 POSITIONER (MODEL 6608-004, 6" STROKE, DOUBLE
 1 2 ACTING), REPLACED POSITIONER AND INSTALLED FILTER IN CYLINDER SUPPLY/RETURN LINE,
 1 3
 1 4

1 5 FACILITY STATUS | E | 28 | % POWER | 1 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | MONTHLY SURVEILLANCE | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 ACTIVITY RELEASED | E | 33 | CONTENT OF RELEASE | E | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | E | 38 | DESCRIPTION | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE | E | 42 | DESCRIPTION | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUES DESCRIPTION | NA | 44
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER D. D. TILLY PHONE (612) 295-5151