APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION REGION IV

NRC Inspection Report: 50-285/91-12

Operating License: DPR-40

Docket: 50+285

Licensee: Dmaha Public Power District (OPPD)

444 South 16th Street Mall

Mail Stop 8E/EP4

Omaha, Nebraska 68102-2247

Facility Name: Fort Calhoun Station (FCS)

Inspection At: FCS, Blair, Nebraska

Inspection Conducted: April 22-26, 1991

Inspector:

Earnest Tysteal Security Specialist

Nuclear Materials and Safeguards Inspection

Section

Approved:

Charles L. Cain, Chief, Nutlear Materials and Safeguards Inspection Section

5/14/91

Inspection Summary

Inspection Conducted April 22-26, 1991 (Report 50-285/91-12)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program. The areas inspected within the physical security program. included the security organization, protected area (PA) barriers, PA detection aids, assessment aids, emergency power supply, alarm stations, communications, vital area (VA) barriers and detection aids, records and reports, audit program, and testing and maintenance.

Results: Within the program areas inspected, no violations or deviations were identified.

The inspector determined that significant progress in the security program was evident. Security management was proactive and appeared to be very effective in resolving any problems that arose. The security program appears to have

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION UPON SEPARATION THIS PAGE IS DECONTROLLED

improved in almost all areas. Licensee management appears to be very supportive of the security program.

The inspector expressed a concern about the excessive delays being encountered in correcting several detection and camera zones that have been under compensatory measures for periods of several months. According to Information Notice 86-88, dated October 15, 1986, prolonged use of compensatory measures represents periods of increased vulnerability. The licensee made a commitment to evaluate the concern in order to determine the cause of the delays. This issue is described in paragraph 6 of the report.

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION UPON SEPARATION THIS PAGE IS DECONTROLLED