

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
704) 373-4531

04 APR 9 9 March 30 1984


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: RII:WCL
50-413/83-22
50-414/83-19

Dear Mr. O'Reilly:

Please find attached a revised response to Violation No. 413/83-22-02 as requested by your letter of January 24, 1984 and pursuant to discussions with your staff on March 13, 1984.

Very truly yours,



Hal B. Tucker

LTP/php

Attachment

cc: NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

8405300382 840501
PDR ADOCK 05000413
Q PDR

Response to Violation 83-22-02

1. We admit the Violation in that calculations for problems CN1492-NB-152A and -267A did not clearly state all sources of information in accordance with Specification CNS-1206.02-04-0000, Rev. 5.
2. The cause of this violation was failure to completely follow Spec. CNS-1206-02-04-0000.
3. Calculations have been thoroughly reviewed. In all cases, the resultant designs represented good engineering practice, conservative applications of judgements, and full compliance with design licensing criteria.
4. Corrective action to prevent future occurrence is a change to Specification CNS 1206-02-04-0000 to better define the requirements and alternatives permitted by the Specification. This spec. was revised 3-30-84.
5. Full compliance was achieved 3-30-84.