

DEC - 5 1991

Docket No. 50-454
Docket No. 50-455

Licenses No. NPF-37; NPF-66

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Dear Mr. Reed:

SUBJECT: NOTICE OF VIOLATION (NRC INSPECTION REPORTS
NO. 50-454/91022; 50-455/91022)

This will acknowledge receipt of your letter dated November 21, 1991, in response to our letter dated October 22, 1991, transmitting a Notice of Violation associated with Inspection Reports No. 50-454/91022; 50-455/91022. The inspections and associated violation dealt with containment leak rate testing at your Byron Nuclear Power Station. We have reviewed your corrective actions and have no further questions at this time. These corrective actions will be examined during future inspections. Additionally, we would like to thank you for the correction to the above inspection report. We will amend the report to note that the airlock repaired during the Unit 1 1991 test was the personnel airlock rather than the emergency airlock. We regret this error.

Sincerely,

ORIGINAL SIGNED BY HUBERT J. MILLER

H. J. Miller, Director
Division of Reactor Safety

See Attached Distribution

RIII	RIII	RIII	RIII	RIII	RIII	RIII
-----SEE FOLLOWING PAGE-----						
Lougheed/cg	Salehi	Phillips	Farber	Wright	Martin	Miller
12/ /91	12/ /91	12/ /91	12/ /91	12/ /91	12/ /91	12/5 /91

71-110133 911205
PDR ADOCK 05000454
Q PDR

10
1201

DEC - 5 1991

Docket No. 50-454
Docket No. 50-455

Licenses No. NPF-37; NPF-66

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Dear Mr. Reed:

SUBJECT: NOTICE OF VIOLATION (NRC INSPECTION REPORTS
NO. 50-454/91022; 50-455/91022)

This will acknowledge receipt of your letter dated November 21, 1991, in response to our letter dated October 22, 1991, transmitting a Notice of Violation associated with Inspection Reports No. 50-454/91022; 50-455/91022. We have reviewed your corrective actions and have no further questions at this time. These corrective actions will be examined during future inspections. Additionally, we would like to thank you for the correction to the above inspection report. We will amend the report to note that the airlock repaired during the Unit 1 1991 test was the personnel airlock rather than the emergency airlock. We regret this error.

Sincerely,

ORIGINAL SIGNED BY HUBERT J. MILLER

H. J. Miller, Director
Division of Reactor Safety

See Attached Distribution

RIII <i>Jim Lee</i> Lougheed/rq 12/04/91	RIII <i>Jim Lee</i> Salehi 12/04/91	RIII <i>Jim Lee</i> Phillips 12/04/91	RIII <i>Jim Lee</i> Farber 12/04/91	RIII <i>Jim Lee</i> Wright 12/04/91	RIII <i>Jim Lee</i> Martin 12/04/91	RIII See Previous Page Miller 12/ /91
---------------------------------------------------	----------------------------------------------	------------------------------------------------	----------------------------------------------	----------------------------------------------	----------------------------------------------	------------------------------------------------

Distribution

cc: M. Wallace, Vice President,
PWR Operations
T. Kovach, Nuclear
Licensing Manager
T. Schuster, Nuclear Licensing
Administrator
R. Pleniewicz, Station Manager
D. Brindle, Regulatory Assurance
Supervisor
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspectors, Byron,
Braidwood, Zion
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
Diane Chavez, DAARE/SAFE
Licensing Project Manager, NRR
Robert Newmann, Office of Public
Counsel, State of Illinois Center
Robert M. Thompson, Administrator
Wisconsin Division of Emergency
Government