

GLENN L KOESTER VICE PRESIDENT NUCLEAR

May 23, 1984

Mr. E.H. Johnson, Acting Chief Reactor Project Branch 2 U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011


KMLNRC 84-078

Re: Docket No. STN 50-482

Subj: Interim 10CFR50.55(e) Report - Barton

752 Transmitters

Dear Mr. Johnson:



Three ITT-Barton 752 Transmitters were found to be short circuiting internally. Initial investigation showed that lock washers used on the mounting screws for the sensor assembly were apparently making electrical contact with the Transmitter Circuit Board Assembly. This connection was short circuiting the transmitters and rendering them inoperable. KG&E and Westinghouse are pursuing a solution to this matter with ITT - Barton. Westinghouse Field Deficiency Reports (FDRs) and a KG&E Startup Field Report (SFR) have been written to document and resolve the existing condition.

The status of this potential 10CFR50.55(e) will be carried on the monthly status update as file 53564-K135. The Final Report or any significant new information will be submitted by separate correspondence. In the interim, please direct any questions to me or to Mr. Otto Maynard of my staff.

> Yours very truly, Ilenn Lotaister

8406050263 84 PDR ADOCK 050

GLK:bb

xc: RCDeYoung HBundy PO'Connor

IE-27