

NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

January 6, 1992

Docket No.: 50-293

Mr. Roy A. Anderson Senior Vice President (Nuclear) Boston Edison Company Pilgrim Nuclear Power Station RFD No. 1 Rocky Hill Road Plymouth, Massachusetts 02360

Dear Mr. Anderson:

SUBJECT:

SYSTEMS BASED INSTRUMENTATION AND CONTROL INSPECTION AT THE PILGRIM NUCLEAR POWER STATION UNIT 1 (NRC INSPECTION REPORT

NO. 50-293/91-201)

Enclosed is the report of the systems-based instrumentation and control inspection that inspectors in the Nuclear Regulatory Commission (NRC) Office of Nuclear Reactor Regulation (NRR) conducted at the Pilgrim Nuclear Power Station, Unit 1, during November 4 through 8 and November 18 through 22, 1991. This inspection was conducted to verify the proper design and configuration of selected instrumentation and control equipment, and was focused on this equipment's interface with key safety-related systems. The specific areas the NRC inspectors examined are discussed in the inspection report. The results of this inspection were discussed with you and your staff during the exit meeting on November 22, 1991.

During the course of the inspection the team found seven deficiencies. The significant deficiencies included:

- an inadequate setpoint for the salt service water discharge pressure switch that could have resulted in the potential overloading of both emergency diesel generators;
- inadequate operating procedures for controlling the torus water level and temperature which failed to account for instrument uncertainties;
 and
- failures of the 10 CFR 50.59 evaluations for two modifications performed to the nuactor water level instrumentation to consider reference leg heatup due to a high energy line break.

Collectively, these findings indicate a potentially significant weakness with regard to the ability of certain instrumentation and control equipment to perform intended safety functions. Although you acted promptly and adequately to correct the specific deficiencies identified, we believe a timely, more comprehensive review of other important instrumentation should be considered.

090126

9201100284 920106 PDR ADGCK 05000293 9 PDR NUC FILE CENTER COPY

We found your staff technically competent and your more recent engineering work generally satisfactory. The plant calibration procedures were adequate. The team concluded that several deficiencies could be attributed to the lack of design basis information. We encourage the continued development of your design basis reconstitution program and believe that emphasis should be placed on the identification of the technical specification bases and the margins that exist between technical specification values and analytical limits.

Please inform us in writing, within 60 days, of your assessment of the safety significance of the deficiencies contained in Appendix A of the enclosed inspection. In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room. Region I will issue in separate correspondence any enforcement actions resulting from this inspection.

Should you have any questions concerning this inspection, please contact the NRR project manager, Ronald Eaton, or the inspection team leaver, Jeffrey Jacobson. Messrs. Eaton and Jacobson can be reached at (301) 504-3041 and (301) 504-2996, respectively.

Division of Reactor Projects, I/II
Office of Nuclear Reactor Regulation

Enclosure:

NRC Inspection Report 50-293/91-201

oc W/enclosure: See next page

Mr. W. C. Rothert, Acting Vice President of Operations and Station Pilgrim Muclear Power Station RFD #1 Rocky Hill Road Plymouth, Massachusetts 02360

Resident Inspector U. S. Nuclear Regulatory Commission Pilgrim Muclear Power Station Post Office Box 867 Plymouth, Massachusetts 02360

Chairman, Board of Selectmen 11 Lincoln Street Plymouth, Massachusetts 02360

Office of the Commissioner Massachusetts Department of Environmental Protection One Winter Street Boston, Massachusetts 02108

Office of the Attorney General One Ashburton Place 20th Floor Boston, Massachusetts 02108

Mr. Robert M. Hallisey, Director Radiation Control Program Massachusetts Department of Public Health 305 South Street Boston, Massachusetts 02130

Regional Administrator, Region I U. S. Nuclear Regulatory Commission 475 Allendale Roud King of Prussia, Pennsylvania 19406

Mr. John Dietrich Licerting Division Manager Boston Edison Company 25 Braintree Hill Park Braintree, Massachusetts 02184

Mr. H. Vernon Oheim Manager, Reg. Affairs Dept. Pilgrim Nuclear Power Station RFD #1 Rocky Hill Road Plymouth, Massachusetts 02360

Ms. Elanie D. Robinson Nuclear Information Manager Pilgrim Muclear Power Station RFD #1, Rocky Hill Road Plymouth, Massachusetts 02360

Mr. Dale C. Jenkins, Jr. Secretary of Public Safety Executive Office of Public Safety One Ashburton Place Boston, Massachusetts 02108

Mr. David Rodham, Director Massachusetts Civil Defense Agency 400 Worcester Road P.O. Box 1496 Framingham, MA 01701-0317 Attr: James Mickerheide

Chairmen, Citizens Urging Responsible Energy P. O. Box 2621 Duxbury, Massachusetts 02331

Citizens at Risk P. O. Box 3803 Plymouth, Massachusetts 02361

W. S. Stowe, Esquire Boston Edison Company 800 Boylston St., 36th Floor Boston, Massachusetts 02199

Distribution: Docket Files 50-293 RSIB R/F DRIS R/F Timurley, NRR FJMiraglia, NRR WIRussell, NRR JGPartlow, NRR BKGrimes, NRR EVImbro, NRR DPNorkin, NRR JEJacrhson, NRR RLSpessard, NRR SAVarga, NRR RHWessman, NRR M.Rushbrook, NRR RBEaton, NRR JEMacdonald, SRI Regional Administrators Regional Division Directors Inspection Team LFDR PDR ACPS (3) OGC (3) 19 Distribution