VIA	PRINGIPAL STAFF ONIGHT D/RAI DE D/RAI DRMSP A/RA DRMSP A/RA DRMA BC SCS PAO SCS SGA ML ENF FILE 107	3 P.O. BO	AND WEBSTER X 1963, MIDLA SIRS:	DATE 5 JONO PONO LTR NO	AN 48640 /12 /84 14509 SWM- /15
DISTRIBUTION		X co		REPRODUCIBLES	MICROFILM APERTURE CARD
_			DRAWINGS DOCUMENTS	SPECIFICATE	ONS
	STATUS	PLEAS	SE NOTE	SENT	FOR YOUR
FINAL PRELIMINARY NO COMMENT SUGGESTIONS AS NOTED YOUR ATTENTION IS	APPROVED APPROVED AS REVISED AS DEFINED IN SPECIFICATION UNACCEPTABLE CLOSED DIRECTED TO THE FOLLOWIN	REVISIONS ADDITIONS COMMENTS	OMISSIONS CORRECTIONS	USE SILES	COMMENT INFORMATION CONCURRENCE
PLEASE REVISE AND SUBMIT	PRINTS REPRODUCIBLES MICRO RINTS REPRODUCIBLES MICRO EACH OF THIS MATERIAL BEARING YOUR APPROV EIPT OF THIS MATERIAL BY SIGNING AND RETURN ES ARE IN ACCORDANCE WITH YOUR UNDERSTAN	MICROFILM DELLE APERTURE C. VAL OR COMMENTS NING THE ENCLOSE	ED COPY OF THIS FO		NGS SHOP DETA
TORIANI WEBSTER PURC	VISION TO DOCUMENTS OR DRAWINGS RETURNE! HASING DEPARTMENT WITHIN TEN 1101 DAYS EVEN L CONSIDER THE REVISIONS MADE WITHOUT COST	THOUGH A DEFINIT	VE A PRICE INCREASE E ESTIMATE CANNOT I	THE SUPPLIER	MUST NOTIFY STONE TIME OTHERWISE. TH
	ed CIO NIR(s) is (are) forwa	arded for y	our informat	ion:	
The following clos					
o26					

DISTRIBUTION:

Job File C.4.2 (orig + 1)

DiQuamme, CPCo NiReichel, CPCo

RAWells, CPCo JGKeppler, NRC

JJHarrison, NRC BLBurgess, NRC (site)

APAmoruso (2)

MRArndt/Chrono/Vault w/o attach(2)

Initiator

8406060185 840517 PDR ADDCK 05000329 S PDR

J. E. Karr

CIO Program Manager

JUN 4 1984

STONE & WEBSTER MICHIGAN, INC.

NONCONFORMANCE IDENTIFICATION REPORT

		PAGE 1 of 2
DATE OF NONCONFORMANCE: 3/31/84	NII	R NUMBER 026
IDENTIFICATION/LOCATION OF ITEMS:		
(Controlled) Document Station 309/MPQ	AD	
DESCRIPTION OF NONCONFORMANCE: During the CIO's ongoing evaluation of performed a sample inspection of docum. The population was determined to be 24 documents were randomly selected. The with two rejects and rejectable with to be discrepant as follows:)	ents contained at Wor 31, per 95/5 criteria sample was determine	k Print Station 309. , a sample of 125 d to be acceptable
 Drawing C-130, Rev. 13 - FCR-C7070 DCC's records indicate FCR is a "p 1984. 		
2. Drawing C-224, Rev. 7 - FCR-M6676 DCC's records indicate FCR is a "p	is listed and attache ullback". Station 30	d to Drawing C-224, 9 notified April, 1983.
THE TOTAL STATE OF THE PARTY OF	PROGRAM MGR	1. /
DATE - /2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 /	DATE	· 2 · 3 · 3
CORRECTIVE ACTION BY:		
IDENTIFY ORGANI	ZATION TAKING CORRECT	IVE ACTION
Based on CPCo Letter No. CSM-0772, date QAR No. RA-00176, Rev O, dated April 9 NIR 026 satisfactorily closed.		
VERIFICATION (SAT) UNSAT	NEW NIR#	CONCURRENCE
INITIATOR Rich Scallan And Scallan 4/1/91	N/A PRO	GRAM MGR JElan
DATE 5-17-84	DATE	5.17.84

REMARKS

DESCRIPTION OF NONCONFORMANCE (Con't)

- *3. Dowing C-97, Rev. 6 Drawing does not have "R" symbol. DDR shows awing C-97 as having an "R" status. (incorrectly)
- *4. Drawing C-852, Rev. 13 Drawing has "R symbol. DDR show no "R" symbol. (incorrectly)
- *Items 3 and 4 Sepias were verified to have an R" stamp which identifies discrepancies with register.



Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

May 8, 1984

Mr J E Karr Stone & Webster Michigan, Inc PO Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT - GWO 7020 STONE & WEBSTER CONSTRUCTION IMPLEMENTATION OVERVIEW NONCONFORMANCE IDENTIFICATION REPORT NO 026 DATED 3-23-84 FILE 24.2 SERIAL 27889 C5m-0772 LWW-16-84

In pursuance of Nonconformance Identification Report Number 026, an interim response is attached to address your concerns delineated in your Nonconformance Identification Report Form.

Should you or your staff have any questions on the content, contact Lonnie Worley at Extension 7707.

CC: DDJohnson, MEC BHPeck, MEC

NIReichel, MEC

JGKeppler, Regional Administrator, Region III JJHarrison, Chief, Midland Section, Region III

BBurgess, NRC Resident Inspector

RAWells, MPQAD

RECEIVED

MAY 0.9 1984 S & W / 4 CIO J.O. NO. 14509.00 Serial 27885 2

Interim Response to Nonconformance Identification Report Number 026 dated March 31, 1984.

Station 309 is located with MPQAD-QC Document Control. Distribution is done by Document Control and maintenance of the station is the responsibility of the workprint station receiving the document.

The following items address each of the concerns identified:

1. Findings 1, 2.

- a) A pull back transmittal for FCR-C 7070 to Drawing C-130 was issued March 7, 1984 by FDCC. The change paper was not removed from the drawing at this area per pull back instructions. This was a clerical error and corrective action has been taken.
- b) A pull back transmittal cannot be located removing FCR-M6676 from Drawing C-224. The "construction is complete" status stamp on the back of the FCR was no longer applicable to the drawing. A review of Drawing C-224, Revision 7 at other areas reflected no discrepancies. Therefore, it is assumed that a pull back transmittal had been issued but the change paper was not removed from the drawing at Work Print Station 309.

2. Findings 3, 4.

a) The register indicated that Drawing C-97, Revision 6 as having retired change paper against it. The drawing was distributed by FDCC without the appropriate stamping to reflect the correct status.

The drawings at recipient areas, as indicated on the FDDL, have been corrected.

A review will be made of the files in the reproduction center to ensure that all drawings reflect the appropriate retirement status as indicated on the DDR.

b) Drawing C-852, Revision 13, was correct in reflecting a retired change paper status. On March 16, 1984, the DDR correctly reflected FCR C-2317 as retired against Drawing C-852.

On March 18, 1984, an operator error was made in requesting the type of report status to be printed from the System 38. Therefore, this DDR did not reflect Drawing C-852 as having retired change paper against it. This error was discovered by Document Control and the next printout of the register indicated the correct status.

3. Quality Action Request Number RA-00176 dated April 9, 1984 was written in response to Nonconformance Identification Report Number 026.



FPD 1.000 Rev 19

QUALITY ACTION REQUEST

		KA	-00176
1000	Date 1:		8. Revision
9.	Page	1 of	3

PEQCE (ASME Only)

Date

-		GOALITY ACTION REGUEST	9. Page
. Assurame	nt '		10. ASM
	FPG 7.300 Rev	4	
	FPD 3.000 Rev	11	

Stone and Webster NIR-026 identifies the following deficiency during a C10 evaluation of controlled document Station 309:

- (1) "Pullback" FCRs still at document station
- (2) "Drawing Stamp" errors were identified

Unacceptable

3. QAR Originated by	14 Discipli	ine/Division/Section	I.S. Response Due Date	11. Potential 50.55(e) Yes X No 12. Date Reported to MPQA Mg
JELauen		ech Services	4/13/84	N/A
13 Action Item No. S06231	115. Item Priority 5	PGMOO	19. Action Organization Bechtel Field	20. QAR Reviewed BY
14. Dissibiline N/A	16. Trend Code ZD-5-0001	BPCO-STF-G	Document Control	21. Date 4/9/84
SEE AT	ACHED SHEET	PAGE 4	SEE ATTACHO PAGE +	
Assoonsible Organization Concurre	mont Control	JAN BROWN	April 27, 178	
GAR	Reviewer	Date	POAE (ASME Only)	Date
Lie attack	axen			
28. Method of Disposition	on Verification		29. QAR	Closed by
			MPQAD	Date

Superceaing QAR

NIR 026 Attachment 2 .

ONE & WEBSTER MICHIGAN, INC.

NONCONFORMANCE IDENTIFICATION REPORT

Page 2 of 4 Pare 2 of 84

2175 25 NOVEMBER 2011		NITO	MUMBED	026	THE STATE OF THE S
DATE OF NONCONFORMANCE: 3/31/84		NIK	NUMBER	020	
IDENTIFICATION/LOCATION OF ITEMS:					
(Controlled) Document Station 30	9/MPQAD				
DESCRIPTION OF NONCONFORMANCE: During the CIO's ongoing evaluati performed a sample inspection of The population was determined to documents were randomly selected. with two rejects and rejectable w to be discrepant as follows:)	documents contained be 2431, per 95/5 of The sample was de	d at Work criteria, etermined	a sample to be ac	tation e of 12 cceptal	309. 25 ole
1. Drawing C-130, Rev. 13 - FCR-DCC's records indicate FCR is 1984.	C7070 is listed and a "pullback". Sta	d attache ation 309	d to Draw notified	wing C	-130, uary,
 Drawing C-224, Rev. 7 - FCR-M DCC's records indicate FCR is 	6676 is listed and a "pullback". Sta	attached ation 309	to Draw notifie	ing C-2 d Apri	224,
DATE 3/31/84 CORRECTIVE ACTION BY:	DATE	AM MGR	3 - 5-1		
		***************************************	VE 407101		
IDENTIFY O	RGANIZATION TAKING	CORRECTI	VE ACTION	4	
VERIFICATION SAT UNSAT ,	NEW NIR#	T	C	ONCURR	ENCE
INITIATOR	_	PROG	RAM MGR_		
DATE	DATE	DATE			

REMARKS

DESCRIPTIC: OF NONCONFORMANCE (Con't)

PAGE 3 of 84

- *3. Drawing C-97, Rev. 6 Drawing does not have "R" symbol. DDR shows Drawing C-97 as having an "R" status. (incorrectly)
- *4. Drawing C-852, Rev. 13 Drawing has "R" symbol. DDR show no "R" symbol. (incorrectly)
- *Items 3 and 4 Sepias were verified to have an "R" stamp which identifies discrepancies with register.

NIR 026 Attachment 2 Page 4 of 4

Response to NIR 026, dated April 3, 1984; QAR RA-00176, dated April 9, 1984

Subject: Work Print Station 309

tro

Work Print Station 309 is located with MPQAD-QC-Document Control. Distribution is done by Document Control and maintenance of the station is the responsibility of the work print station receiving the document.

Note: For ease of reading, the findings have been grouped by subject. The letter identification noted on the NIR has been retained for cross referencing.

1. Change Paper Not Removed From Drawings (Findings 1 and 2)

- (1) A pull back transmittal for FCR-C7070 to Drawing C-130 was issued March 7, 1984, by FDCC. The change paper was not removed from the drawing at this area per pull back instructions. This was a clerical error and corrective action has been taken.
- (2) A pull back transmittal cannot be located removing FCR-M6676 from Drawing C-224. The "Construction is Complete" status stamp on the back of the FCR indicated the FCR was no longer applicable to the drawing. A review of Drawing C-224, Revision 7 at other areas reflected no discrepancies. Therefore, it is assumed that a pull back transmittal had been issued but the change paper was not removed from the drawing at Work Print Station 309. Corrective action will be taken by April 18, 1984.

2. Discrepancies Between Register and Sticks (Findings 3 and 4)

(3) The register indicated that Drawing C-97, Revision 6 as having retired change paper against it. The drawing was distributed by FDCC without the appropriate stamping to reflect the correct status.

The drawings at recipient areas, as indicated on the FDDL, have been corrected.

A review will be made of the files in the reproduction center to ensure that all drawings reflect the appropriate retirement status as indicated on the DDR. This review and any corrective action is scheduled to be complete by April 27, 1984.

(4) Drawing C-852, Revision 13, was correct in reflecting a retired change paper status. On March 16, 1984, the DDR correctly reflected FCR C-2317 as retired against Drawing C-852.

On March 18, 1984, an operator error was made in requesting the type of report status to be printed from the System 38. Therefore, this DDR did not reflect Drawing C-852 as having retired change paper against it. This error was discovered by document control and the next print out of the register indicated the correct status.

No further corrective action is required.

4-11-84

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION: REPORT

Tare as		Page 1 of 3
DATE OF NONCONFORMANCE: MARC	H 23, 1984	NIR NUMBER
IDENTIFICATION/LOCATION OF ITEMS:		
CENTROLLED DOCUMENT STATIO	N 501/ DOCUME	MT CONTROL CENTER
DESCRIPTION OF NONCONFORMANCE: Z DOCUMENT CONTROL, ARAM SELECTED FROM THE 5533 OF THESE 200 DRAWINGS, TH	DIRING CIO'S ON DOM SAMPLE OF DRAWINGS DISTR DE FOLL QUING DIST	GONG EVALUATION OF SITE F 200 DRAWINGS WAS PIBLITED TO STATION SCI. PREPANCIES WERE NOTED.
a) DWG # 17-871 SHEE	77. REVISION / W	UAS SHOULD IN THE
SYSTEM 38 REGISTER (S-38-R)) AS HAVING BEEN	ISSUED TO THE FIELD
ON ETT-04. STATION SOI HAD	D REV. O ON THE	IR STICK.
b) Dw6. #C-397 REV	1 IS NOT LEGIB	E
C) 206. #C-855. RE	V. El IS AT STATI	ON 501 WITH ONLY
DIN'S 20ERI ATTACHED. S.	38-R SHOWS REV	1.22 WAS ISSUED TO
THE FIELD WITH ONLY FOR-T	448 ATTACHED ON	2-23-84.
- , me . c. o.go., ne	NIVIS AT STATIO	U 501 WITH DON-18 AND
INITIATOR Passon	PROGRA	M MGR / Color
DATE MARCH 23, ASA	DATE	3-123-84
CORRECTIVE ACTION BY:		
IDENTIFY OF	RGANIZATION TAKING CO	DRRECTIVE ACTION
Based on CPCo Letter No. CSM-0770, QAR No. RA-00156, Rev O, dated Mar NIR 024 satisfactorily closed.	dated May 4, 1984 (ch 29, 1984 (Attachm	Attachment 1), and CPCo nent 2) CIO consideres this 3 25 state
ERIFICATION (SAT) UNSAT		
WITTIAGO IN IN CO.	NEW NIR#	CONCURRENCE
ATE CLIFTS4	공기 (1.1.) 연락 보통하는	PROGRAM MGR / Elan
111137	DATE	DATE 3-17-84

TTACHMENT 1 VIR NO. 024

MIR# PAGE 2 of 3

d-CONT) FCR-7365 ATTACHED. S-38-R SHOWS REV. 18 WAS ISSUED ON 3-6-84 WITH ONLY FCR-7365 ATTACHED.

- e) DUG #C-1322 REV. O ILLEBIBLE
- FROM THE S.38-R AND COULD NOT BE VERIFIED.
- 9) DUG. SERIES C-1000 HIEU C-1099 WERE MISSING FROM THE S-38-R AND COULD NOT BE VERIFIED.
- h) DUG # M-524-1 REV 24/FI. NOT STAMPED "CONTROLLED."
- i) DWG # M-524-1 REV 24/FI. S-38-R SHOWS THAT
 I KN-9765 AND FCR C-6364 SHOWD BE ATTACHED,
 HOWEVER THESE ARE NOT ATTACHED AT STATION 501.
- J) DUG. #M-658-13 REV. 8/FE. S-38-R SHOWS THAT ICS-7 SHOULD BE ATTACHED, HOWEVER THIS IS NOT ATTACHED AT STATION 501.
- L) DUG * M- LLO-7 REV 15/FI. S-38-R SHOWS THAT IDON'S 3872 AND 23852 SHOULD BE ATTACHED, HOWEVER THESE ARE NOT ATTACHED AT STATION 501.
- () DWGS. M-417-18, M-431-18, M439-28, M-440A, M443A, AND M445-1 WERE FOUND TO BE

· TTHEH NIENT 1

NIR#
PAGE 3 of 3

1-CONT.)

DISCREPANT AS DESCRIBED BELOW:

- 1) NOT SHOUDH IN S.38-R SEE ITEM F BBOVE.
- 2) "INFORMATION CALLY" DRAWINGS IN A CONTROLLED DOCUMENT STATION.
- 3) "INFORMATION ONLY" STAMPET WAS COPIED FROM THE ORIGINAL AND WAS THEREFORE BLUE IN COLOR, AND NOT AN ORIGINAL STAMP IN RED INK.
- M) LAYING IN ONE CORNER OF STATION 501 IS
 A COMPLETE SET OF UNCONTROLLED DRAWINGS.
 THESE DRAWINGS ARE ON STICKS AND ROLLED
 UP WITH RUBBER BANDS AROUND THEM



Midland Project: PO Box 1963, Midland, MI 48/940 + (517) 631-8650

May 4, 1984

Mr J E Karr Stone and Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT - GW07020

STONE AND WEBSTER CONSTRUCTION IMPLEMENTATION OVERVIEW
NONCONFORMANCE IDENTIFICATION REPORT NUMBER 024 DATED 03-23-84
FILE 24.2 SERIAL 37885 CSM-0770 LWW-13-84

In pursuance of Nonconformance Identification Report number 024, a response is attached to address your concerns delineated in your Nonconformance Identification Report Form.

ufan Jeginim

Should you or your staff have any questions on the content, contact Lonnie Worley at extension 7707.

D L Quamme Site Manager

CC DDJohnson, MEC
BHPeck, MEC
NIReichel, MEC
TASpellman, MEC
JBKeppler, Regional Administrator, Region III
JJ Harrison, Chief, Midland Section, Region III
BBurgess, NRC Resident Inspector
RAWells, MEC

RECEIVED

MAY 0.9 1984 S&W / 0.7 C10 J.O. NO. 14509.00 Serial 27885

Response to Nonconformance Identification Report number 024 dated March 23, 1984.

Station 501 is located in the radwaste building. Distribution as well as maintenance of this station is now the responsibility of FDCC. Centralization of distribution and maintenance activities on-site was part of the corrective action plan submitted in response to MCARR-DAT-1. This station has not been released by MPQAD to support Q-work.

The following items address each of the concerns identified:

1. Findings a, c, d. Drawing A-871, sheet 7 and C-855 did not have the current revisions on the sticks. Both of these drawings had already been ide. ified as missing prior to the audit by the Document Control personnel manning Station 501. Corrections have been made. All other locations on distribution for these drawings were checked and the correct revision was at all other locations. The Document Control personnel manning the station have been reminded of the importance of obtaining missing drawings.

Drawing C-898, revision 17 is on the stick. Revision 18 was processed in Document Control on March 6, 1984. It has not been distributed and should not be on any construction sticks. Daily monitoring of total processing time will continue until the performance goal of forty-eight hours is reached.

2. Findings b, e. Drawing C-397, Revision 1 is an old drawing (1974) that may be considered illegible. Document Control has replaced this drawing and checked its legibility at all other locations. The Document Control Internal Audit Group will check for legibility as part of their checklist. This group is being formed as part of the Document Control Corrective Action Plan.

Drawing C-1422 was illegible. Corrective action has been taken. All other distribution points receiving C-1422 have been checked and the drawing was legible.

3. Findings f, g, 1(1) Drawing series M-401 - M-445 and C-1000 - C-1099 are in the system 38 register (DDR). The Auditors were given sections of the registers as requested. The Auditors were informed that any additional drawings not on the sections given to them were available in Document Control on registers or through terminal call-up.

No request was made by the Auditors. No corrective action is deemed necessary by Document Control.

4. Findings i, j, k. The mechanical sticks have not been released for use as controlled drawings. Two signs, outside the door and near these sticks, indicate that employees must verify any mechanical drawings against the registers before use. If the current revision is not available, individuals must obtain the latest copy from Document Control. Station 501 is staffed full-time with Document Control personnel who provide assistance in reading registers.

No corrective action is planned outside of our current program of establishing and releasing distribution stations.

5. Findings 1, 2, 3. There is no procedural requirements limiting the placement of "information only" drawings in controlled stations. All drawings stamped "for information only" are P&ID's. FPD-1000, revision 20 was issued on March 23, 1984 and allows P&ID's to be distributed as controlled documents.

The "information only" stamp was required to be placed on the original P&ID according to FPD-1.000, revision 19. Therefore, when copies were run the stamp would become black (xerox) or blue (blue line).

Document Control will proceed to comply with new procedural requirements as the mechanical documents in Station 501 are prepared for release.

6. Findings h, m. The Auditors noted that drawing M-524-1, revision 25/F1 was not stamped "controlled". Document Control checked the drawing on March 23, 1984 and found it was stamped "controlled".

Bundles of uncontrolled drawings are located in a corner of Station 501 on the floor wrapped with rubber bands. These drawings are being stored in Station 501 for use in bringing up another distribution station. We do not feel it is remotely possible that someone would mistake these drawings as those that are to be used by personnel within the station. In addition, the stations are staffed full-time with Document Control personnel if someone questioned their purpose. No corrective action is deemed necessary.

7. Quality Action Request number RA-00156 dated 03-29-84 was written in response to Nonconformance Identification Report number 024 and closed on 05-02-84.

LWW 5/4/84



Requirement

Acceptable

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

QUALITY ACTION REQUEST

6. GAR Number	
RA-00156	
7. Date issued	8. Revision
3/29/84	0
9. Page 1 of 5	
10. ASME Related	

FPG 7.300 Rev 4 FPD 3.000 Rev 11 FPD 1.000 Rev 19

evaluation of comparison of the Attachments: 2) Illegible drag: 3) "Drawing star 4) Superceded drags:	ontrolled docume not referenced o awings mp" errors have rawing on stick	ent station 501: or attached been identified	following deficiencies	
3. QAR Originated by	4. Discip	line/Division/Section	5. Response Due Date	12. Date Reported to MPQA Mgr
- a Trelle	ruli PAP	- Tech Services	4/05/84	N/A
13. Action Item No.	15. Item Priority	17. S/U Code	19. Action Organization	20. QAR Reviewed by
\$0-5722	5	PGMOO	Bachtal Field	PDoe
14, Discipline	16. Trend Code	18. Resb Code	Bechtel Field Document Control	21. Date
N/A 22. Cause	ZD-5-0001	BCPCo - STF-G	Document Control	3-24-34
24. Responsible Organizat	D_CLMENT	CONTECL	25. Proposed Completion Date 4-3-54	
QARR	D De-	4/5/64 Date	NA SU 5/2	/54 Date
SECATTACE	HED SHEETS			
28 Method of Disposition	Verification		29 OAR CIO	sed by

SEE ATTACHED FOR CLOSURE JUSTIFICATION.

Superceding QAR

Unacceptable

NIR 024 Attachment 3 Sheet 2 of 14

QAR NO:

MIDLAND PROJECT		0C100-AA	
QUALITY ASSURANCE DEPARTMENT	QUALITY ACTION REQUEST	DATE:	REY:
CONTENT ADSUMANCE DEPARTMENT	CONTINUATION SHEET	3/29/84	0
	CONTINUATION SHEET	PAGE 2 OF 5	
		Trac _2 01 _5	
(Block #2 continued)			
ttachment status of di	rawings does not always reflect System	38 (DDR)	
7) Possible uncontrolled	drawings in a controlled drawing area		
			-4-11

NIR 024 Attachment 3 Sheet 3 of 14

Response to NIR 024, dated March 23, 1984, QAR RA-00156, dated March 28, 1984

Subject: Controlled Document Station 501/Document Control Center

Station 501 is located in the radwaste building. Distribution as well as maintenance of this station is now the responsibility of FDCC. Centralization of the distribution and maintenance activities on site was part of the corrective action plan submitted in response to MCARR-DAT-1. This station has not been released by MPQAD to support Q-work.

Note: For ease of reading, the findings have been grouped by subject. The letter identification noted on the NIR has been retained for cross-referencing.

1. Wrong Revisions on Sticks (Findings a, c, d)

Drawings A-871, sheet 7 and C-855 did not have the current revisions on the sticks. Both of these drawings had already been identified as missing prior to the audit by the document control personnel manning station 501. Corrections have been made. All other locations on distribution for these drawings were checked and the correct revision was at all other locations. The document control personnel manning the station have been reminded of the urgency in obtaining missing drawings.

Drawing C-898, Rev. 17 is on the stick. Rev. 18 was processed in document control on March 6, 1984. It has not been distributed (as of March 23, 1984) and should not be on any construction sticks. No corrective action will be taken. Daily monitoring of total processing time will continue until the performance goal of 48 hours is reached.

2. Drawing legibility (findings b, e)

Drawing C-397, Rev. 1 is an old drawing (1974) that may be considered illegible. Document Control will replace this drawing and check its legibility at all other locations. The Document Control Internal Audit Group will check for legibility as part of their checklist. This group is being formed as part of the document control corrective action plan.

Drawing C-1422 was illegible. Corrective action has been taken. All other distribution points receiving C-1422 have been checked and the drawing was legible.

3. Inability to Verify Drawings Because They Were Missing From System 38 Register (Findings f, g, 1 (1)

Drawing series M-401 - M-445 and C-1000 - C-1099 are in the system 38 register (DDR). The auditors were given sections of the registers as requested. The auditors were informed that any additional drawings not on the sections given to them were available in document control on registers or through terminal call-up.

No request was made by the auditors. No corrective action is deemed necessary by document control.

4. Audit of Mechanical Drawings (Findings i, j, k)

The mechanical sticks have not been released for use as controlled drawings. Two signs, outside the door and near these sticks, indicate that employees must verify any mechanical drawings before use against the registers. If the current revision is not available individuals must obtain the latest copy from document control. Station 501 is staffed full-time with document control personnel who provide assistance in reading the registers.

No corrective action is planned outside of our current program of establishing and releasing distribution stations.

5. "Information Only" Drawings in Controlled Document Location (Findings 1, (2), (3)

There is no procedural requirement limiting the placement of "information only" drawings in controlled stations. All drawings stamped "for information only" are P&ID's. FPD-1.000, Rev. 19 required that all P&ID's be stamped "for information only". FPD-1.000, Rev. 20 was issued on March 23, 1984 and allows P&ID's to be distributed as controlled documents. There was no procedural violation, and no corrective action is deemed necessary by document control.

The "information only" stamp was required to be placed on the original P&ID according to FPD-1.000, Rev. 19. Therefore, when copies were run the stamp would, of course, become black (xerox) or blue (blue line). There is no procedural violation and no corrective action is planned.

Document Control will proceed to comply with new procedural requirements as the mechanical documents in station 501 are prepared for release.

6. Other Miscellaneous Findings (h, m)

The auditors noted that drawing M-524-1, Rev. 24/Fl was not stamped "controlled". Document Control checked the drawing on March 23, 1984 and found it was stamped "controlled". No corrective action is deemed necessary.

Bundles of uncontrolled drawings are located in a corner of station 501 on the floor wrapped with rubber bands. These drawings are being stored in the radwaste station for use in bringing up another distribution station. We do not feel it is remotely possible that someone would mistake these drawings as those that are to be used by personnel within the station. In addition, the stations are staffed full time with document control personnel if someone questioned their purpose. No corrective action is deemed necessary.

Page 3

Summary

Based on the results of Bechtel internal auditing (QA) and a review of the responses to these findings station 501 appears to be meeting all document control requirements as well as the objectives of the document control action plan.

J. a. Srun

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION: REPORT

DATE OF NONCONFORMANCE: MARC	: 4 23, 1984	NIR NUMBER 024
IDENTIFICATION/LOCATION OF ITEM	<u>:</u>	
CONTROLLED DOCUMENT STATI	ON 501/DOCUM	PENT CONTROL CENTER
DESCRIPTION OF NONCONFORMANCE: DOCUMENT CONTROL, ARA SELECTED FROM THE SSE. OF THESE 200 DRAWINGS, TO A) DWG. # A-871 SHE. SYSTEM 38 REGISTER (S-38-) ON 2-17-84. STATION SOI HA b) DWG. # C-397 RE C) DWG. # C-855. TO DCN'S 205 21 ATTACHED. S THE FIELD WITH ONLY FCR-	DIRING CIO'S ON DOM SAMPLE OF THE FOLL CLOING DISTANCE OF THE FOLL CLOING DISTANCE OF THE FOLL CLOING BEEF OF THE STANCE OF THE ATTACHED OF THE PATTACHED OF TH	WAS SHOWN IN THE STICK. SERE STICK.
DATE MARCH 23, A84	/	3-23-84
CORRECTIVE ACTION BY:		
IDENTIFY	ORGANIZATION TAKING	CORRECTIVE ACTION
ERIFICATION SAT UNSAT	NEW NIR#	CONCURRENCE
NITIATOR		PROGRAM MGR
	DATE	DATE
EMARKS		

- d-court) FCR-7365 ATTACHED. S-38-R SHOWS REV. 18 WAS ISSUED ON 3-6-84 WITH ONLY FOR-7365 ATTACHED.
- e) Dus. # C-1322 REV. 0 ILLEBIBLE.
- FROM THE S-38-R AND COULD NOT BE VERIFIED.
- 9) DWG. SERIES C-1000 HEU C-1099 WERE MISSING FROM THE S-38-R AND COULD NOT BE VERIFIED.
- 1/1) DWG # M-524-1 REV 24/FI. NOT STAMPED "COUTROLLED"
 - VI) DUXS # M-524-1 REV 24/FI. S-38-R SHOWS THAT

 I DON-9765 AND FOR C-6364 SHOULD BE ATTACHED,

 HOWEVER THESE ARE NOT ATTACHED AT STATION 501.
 - ICS -7 SHOULD BE ATTACHED, HOWEVER THIS IS NOT ATTACHED AT STATION 501.
 - IN DWG. * M- 60-7 REV 15/FI. S-38-R SHOWS THAT IDON'S 3872 AND 23852 SHOWLD BE ATTACHED, HOWEVER THESE ARE NOT ATTACHED AT STATTON 501.
 - () DWGS. M-417-18, M-431-18, M439-28, M-440A, M443A, AND M445-1 WERE FOUND TO BE

1-CONT.).

DISCREPANT AS DESCRIBED BELOW:

- 1) NOT SHOWN IN S.38.R SEE ITEM & BBOVE.
- 2) "INFORMATION ONLY" DRAWTINGS IN A CONTROLLED DOCUMENT STATION.
- 3) "INFORMATION ONLY" STAMPET WAS COPIED FROM THE ORIGINAL AND WAS THEREFORE BLUE IN COLOR, AND NOT AN ORIGINAL STAMP IN RED INK.
- M) LAYING IN ONE CORNER OF STATION 501 IS

 A COMPLETE SET OF UNCONTROLLED DRAWINGS.

 THESE DRAWINGS ARE ON STICKS AND ROLLED IN

 UP WITH RUBBER BANDS AROUND THEM.

To LWWorley

FROM JMHarrison

DATE May 1, 1984

SUBJECT MIDLAND ENERGY CENTER PROJECT -QAR RA-00156

FILE 17.0 SERIAL 27878

Consumers Power Company

INTERNAL CORRESPONDENCE

LWW 8-84

CC

Response to NIR 024 dated March 23, 1984 controlled Document Station 501.

During overview conducted May 1, 1984 by Document Control Action Group items A through L were found to have been corrected.

- Item A Drawings A871 sheet 7 revision 1 on stick files at Station 501.
- Item B Drawings C-397 (new copy requested per reproduction request number 24530 (attached)).
- Item C Drawing C-855 R-22 with attachments DCN 22/FCR 7442 per DDR (DCN(s) 20 and 21 incorporated on revision 22)
- Item D Drawing C-898 R-18 on stick files FCR 7365 attached (DCN 18
 incorperated revision 18)
- Item E Drawing C-1322 R-O legible copy on stick files at Station 501.
- Item F Series M-401 through M-445 are on DDR.
- Item G Drawing series C-1000 through C-1099 are on DDR.
- Item H Drawing M-524-1 revision 24/Fl is stamped controlled.
- Item I Drawing M-524-1 revision 24/F1 -IDCN 9765 and FCR 6364 are attached to drawing at Station 501.
- Item J Drawing M-658-13 revision 8/F2 IDCN 7 is attached at Station 501.
- Item K Drawing M-660-7 revision 15/F1 IDCN 3872 was pulled back
 04-18-84 (attached) IDCN 23852 attached to revision 15/F1 at
 Station 501.
- Item L (See item F above)
- Item M (See item 6 QAR RA-00156) Drawings are stored in area and controlled by clerk in Station 501.

3 PULLBACK Pay 28 2 0 M.P. DEST. DAM. WITH HO BIT DOMESTA DIST. ALL BREEDERD DOCUMENTS SHOULD BE YONGED ON DESTROYED MECHTEL DIST. DISTRIBUTION LOG/TRANSMITTAL LOG BIL . 8 118 5 MAL PLALBACKS MUST BE DESTROYED, 6 INT. 29.3 PULLBACK SOIR FOWG MO 69 66 200 0 * 1 3 8 . - 88 -8 . • - 60 01-01-. þ 7 1 THE 2NCB-154.2-E 608 ELOJ E606 E609 E 408 4-18-84 2600-4-546 M-660. E 36 E31 はまと Day DON

RETIRENZAT STHROL AMBOTATED ON PARPET BOCHMENT:; fof FID 2.100

OAR RA-00156 Page 2 of 3

Sheet 10 of 14 Attachment 3 NIE OSt NIR 024

REPRODUCTION REQUEST

Page 3 of 3 QAR RA00156

Date Requested 3-28-84	Requested By D. Bea	love Approved By
Date Required ASAP	Area 501 Ext. 705	7 Return Original
TYPE OF REQUEST (Check One Request Type	ONLY)	
Full Size	Xerox	Manuals
Half Size	Specs.	Inter-Office
FSK	Corres	
DOCUMENT IDENTIFICATION NUMBER	NUMBER NUMBER OF PAGES OF COMES	(ITEM B)
2.		
3.		
4		OPERATOR
		2.08
5		DATE
G		
7.		
8		
9.		
10.		
INSTRUCTIONS FOR COPIES:		
PAPER SELECTION:	STAPLED:	7
Blueprint	Left	
Sepia	Right	
Vellan	Bottom	
My lar	Top/	
White		ments will be stamped UNCONTROLLED
Color Charge	unless otherwi	
3-Hole Drilled:	UNCONTROLLE	
Left	FOR INFORMAT	
Right	ISSUED FOR BID	A V The second s
Bottom	CONTROLLED P	
Тор	READY FOR DIS	
SIZE	NO STAMP REQU	
87, x 11	SPECIAL INSTRUCTIO	
8'9 x 14		
Hatt Size		
Other		
COMMENTS	11 i	apied)

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION: REPORT

NIR 024 Attachment 3 Sheet 12 of 14

DATE OF NONCONFORMANCE:		
MAR.	CH 23, 1984	NIR NUMBER 024
IDENTIFICATION/LOCATION OF ITEM		
CONTROLLED DOCUMENT STATI	TON 501/DOCUM	ENT CONTROL CENTER
DESCRIPTION OF NONCONFORMANCE: DOCUMENT CONTROL, ARE SELECTED FROM THE 553 OF THESE 200 DEALWINGS, TO DUG. # A-871 SHE DIVISITEM 38 REGISTER (S-38-, ON 2-17-84. STATION 501 H DIVIS. # C-397 RE DIVIS. # C-855. TO DIVIS 208 EL ATTACHED. STATION SOLY FOR	DIRING CIO'S OF PROGRAMME CANDON SAMPLE COMPANIES DISTINGS DISTING FOLLOWING DISTING REVISION / REVISION	WAS SHOWN IN THE STORE STORE STORE TO THE FIELD TO THE FIELD TO THE STORE STOR
TETUTTEN		
IDENTIFY	ORGANIZATION TAKING	CORRECTIVE ACTION
ERIFICATION SAT UNSAT	NEW NIR#	CONCURRENCE
HITIATOR	NEW NIR#	CONSURRENSE PROGRAM MGR
	NEW NIR#	Control of the Contro

d-court) FCR-7365 ATTACHED. S-38-R SHOWS REV. 18 WAS ISSUED ON 3-6-84 WITH ONLY FOR-7365 ATTACHED.

Dus. # C-1322 REV.O - ILLEBIEUE.

FROM THE S-38-R AND COULD NOT BE VERIFIED.

FROM THE S-38-R AND COULD NOT BE VERIFIED.

This DWG = M-524-1 REV 24/FI. NOT STAMPED "COUTROLLED"

DUS = M-524-1 REV 24/FI. S-38-R SHOWS THEAT

I DUN -9765 AND FOR C-6364 SHOWLD BE ATTACHED,

HOWEVER THESE ARE NOT ATTACHED AT STATION 501.

J) DUX. # M-658-13 REV. B/FE. S-38-R SHOWS THAT.
ICS -7 SHOULD BE ATTACHED, HOWEVER THIS IS NOT.
ATTACHED AT STATION 501.

LY DWS. # M. LGO-7 REV 15/FI. S-38-R SHOWS THAT ...
IDON'S 3872 AND 23852 SHOULD BE ATTACHED,
HOWEVER THESE ARE NOT ATTACHED AT STATION 501.

() DWGS. M-417-18, M-431-18, M439-28, M-440A, M443A, AND M445-1 WERE FOUND TO BE

1		1
1-	CONT.)
	man .	1 .

DISCREPANT AS DESCRIBED BELOW:

- DINOT SHOULD IN S.38. R SEE ITEM & BEOVE.
- DOCUMENT STATION. CNLY DEAUTINGS IN A CONTROLLED
- FROM THE ORIGINAL AND WAS THEREFORE BLUE IN COLOR,
- A COMPLETE SET OF UNCONTROLLED TRAWINGS.

 THESE DEAWINGS ARE ON STICKS AND ROLLED UP WITH RUBBER BANDS AROUND THEM