



Carolina Power & Light Company

P. O. Box 165, New Hill, North Carolina 27562
May 29, 1984

FILE: SH N-2/18
Item 172

MQAH 84-232

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400
FLAKING OF FLEXIBLE CONDUIT COATING

Dear Mr. O'Reilly:


This is to confirm the May 25, 1984 telephone conversation between Mr. K. V. Hate' (CP&L) and Mr. A. Hardin (NRC). Mr. Hardin was informed that the April 27, 1984 potentially reportable item, pertaining to the potential clogging of the containment sumps due to failure of the polyurethane coating on the flexible conduit for the Mercury Instrument Racks, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung
Mr. G. Maxwell
Mr. R. L. Prevatte


N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

1227

8406110317 840529
PDR ADOCK 05000400
S PDR