Janaury 25, 1984

MEMORANDUM FOR: Region III File

FROM: J. J. Harrison, Chief, Section 2, Midland

SUBJECT: STONE AND WEBSTER; EMPLOYEE INDEPENDENCE

REGARDING MIDLAND

On January 24, 1984, Mr. Paul Amaruso, Project Manager for Stone and Webster, independent third party overviewer for the Consumers Power Company (CPCo) Construction Completion Program (CCP), contacted the NRC to inquire if the established independence criteria had been violated.

Stone and Webster recently hired a field office clerk whose spouse is employed by CPCo as a QC Inspector. This young lady was instructed as to the sensitivity of her position and fully understands the rules of not disclosing CIO information.

In reviewing the independence criteria set forth in the Chairman Palladino letter to Congressmen Ottinger and Dingell with the Regional Counsel (S. Lewis) there is no distinction between technical and non-technical personnel.

However, in reviewing the Stone and Webster CIO program dated April 1, 1983, the rules on disclosure statements and in particular the rule on having members of the immediate family working for CPCo pertain to "...key technical personnel..." only. Further, this program was approved by the NRC on September 29, 1983.

Since this type of position is a local hire, non-technical in nature, and is within the confines of the approved CIO program, the NRC staff concluded that independence criteria was not violated. Stone and Webster (Mr. Amoruso) was so informed.

Original signed by 9.9. Harrison J. J. Harrison, Chief Section 2, Midland

8406120285 840517 PDR FDIA RICE84-96 PDR

Gardner/1s Harrison

of the x

JAN 2 5 1984

Mr. P. Amoruso, Project Manager Construction Implementation Overview Program Stone and Webster Michigan, Inc. P. O. Box 1963 Midland, MI 48640

Mr. S. Lucks, Project Manager Underpinning and Remedial Soils Overview Program Stone and Webster Michigan, Inc. P. O. Box 1963 Midland, MI 48640

Gentlemen:

The purpose of this letter is to request Stone and Webster to furnish one copy of the weekly reports to the local public document room located at the Grace Dow Memorial Library, 1710 W. St. Andrews Rd., Midland, Michigan 48640, at the same time copies are furnished to the NRC and Consumers Power Company.

The availability of these documents will allow members of the public proper time to prepare for the monthly meetings.

Your cooperation in this matter is appreciated.

Sincerely,

J. J. Harrison, Chief Section 2, Midland

cc: See attached distribution list


Harrison/ls 01/24/84 RIII RFW Warnick 1/24/84

8401270252



STONE & WEBSTER MICHIGAN, INC.

P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107



Mr. J. J. Harrison Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

January 24, 1984

Subject: DOCKET NO. 50-329/330

MIDLAND NUCLEAR COGENERATION PLANT

RESUMES AND AFFIDAVITS FOR CIO STAFF MEMBERS

SERIAL NO. SWMCP-016

Attached are the signed affidavits and resumes for Mr. K. J. Butler and Mr. G. A. Carter and the resume for Mr. W. G. Dick. As previously documented, these personnel have been assigned to the CIO staff at the Midland Nuclear Plant.

J. E. Karr

CIO Program Manager

Enclosures

JEK/nl

cc: CIO General Files

8402030191

Figure 3-1

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

In the Matter of CONSUMERS POWER COMPANY Docket No. 50-329 OM 50-330 OM (Midland Plant, Units 1 and 2) Docket No. 50-329 OL

AFFIDAVIT OF KENNETH J. BUTLER

50-330 OL

My name is Kenneth J. Butler		I am employed by Stone & Webster Quality Control Engineer .	
Michigan, Inc.	as	Quality Control Engineer .	

I am currently assigned to the team which is proposed to conduct a Third Party Construction Implementation Overview at the Midland Nuclear Plant site. Prior to being given this assignment, I have never worked on any job or task associated with the Midland Project, or any job or task for or on behalf of Consumers Power Company or Bechtel relating to issues that I will be reviewing. I have never been employed by Consumers Power Company or Bechtel. I do not own any shares of Consumers Power Company or Bechtel stock. Mutual funds or other funds in which I may have a beneficial interest, but over which I have no control, may own shares of Consumers Power Company or Bechtel stock, of which I am unaware. A list of such funds in which I have an interest are attached. I have no relatives which are or have been employed by Consumers Power Company or Bechtel.

Signed January Gentlee

Sworn and Subscribed Before Me This 9th Day of January, 1984

Patricia a Puffer

NOTARY PUBLICE

PATRICIA A. PUFFER Notary Public. Bay County, MI My Commission Expires Mar. 4, 1986

My Commission Expires 3-4-86

Figure 3-1

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

In the Matter of CONSUMERS POWER COMPANY

Docket No. 50-329 OM 50-330 OM

(Midland Plant, Units 1 and 2)

Docket No. 50-329 OL 50-330 OL

AFFIDAVIT OF GEORGE A. CARTER

My name is <u>George A. Carter</u> . Michigan, Inc. as	I am employed by Stone & Webster Inspection Supervisor
I am currently assigned to the team which Construction Implementation Overview Prior to being given this assignment, I associated with the Midland Project, or Consumers Power Company or Bechtel rel viewing. I have never been employed by I do not own any shares of Consumers Power funds or other funds in which I may have I have no control, may own shares of Consof which I am unaware. A list of such attached. I have no relatives which ar Power Company or Bechtel.	have never worked on any job or task any job or task for or on behalf of ating to issues that I will be re- Consumers Power Company or Bechtel. Wer Company or Bechtel stock. Mutual a beneficial interest, but over which sumers Power Company or Bechtel stock, funds in which I have an interest are

Signed Longe Q. Conton

Sworn and Subscribed Before Me This 2th Day of January, 1984

Patricia a fuller

NOTARY PUBLIC

PATRICIA A. PUFFER

Notary Public, Bay County, M.

My Commission Expires Mar. 4 1986

My Commission Expires 3-4-86

January, 1984

FIELD QUALITY CONTROL

BUTLER, KENNETH J.

November 21, 1936

Married

EDUCATION

Certificate (1 year 1966) - Mechanical Drafting and Machine Design Northeast Institute of Industrial Technology - Boston, Massachusetts
Certificate (1 year 1960) - Plane Geometry and Trigonometry Massachusetts Div. University
Extension Courses - Cambridge, Massachusetts
Apprentice Course (1 year 1959) - Mechanical Inspection
John E. Shaw Co. - Derry, N.H.
Graduate - Somerville, Mass. Public School System - 1958
Apprentice Course (1 year 1952) - Machinist - A.M.S. Industries
Cambridge, Mass.

EXPERIENCE SUMMARY

Mr. Butler joined Stone & Webster in August, 1976 as an Inspector Level I in the Field Quality Control Division, assigned to the Shoreham Nuclear Power Station. Mr. Butler was promoted to Inspector Level II, Senior Quality Control Inspector and in October, 1981 to Quality Control Engineer. During this time, his duties included a temporary assignment (18 months) with overall responsibility for inspection of Duquesne Light & Power Co.'s steam generator supports and reactor coolant pump supports which were built for Stone & Webster in Houston, Texas. Returning to the Shoreham Site, Mr. Butler was temporarily assigned to Long Island Lighting Co.'s Quality Assurance Department to coordinate the site's ASME Certification Program and also was involved in the client's Q.A. Program as an Auditor.

Mr. Butler was reassigned to Stone & Webster's As-Built Verification Program at Shoreham in a supervisory position. Upon completion of his Shoreham assignment, Mr. Butler was assigned as Senior Field Quality Control Representative to the Fort St. Vrain Nuclear Power Station Project for a period of four months.

Mr. Butler is currently assigned to the Construction Implementation Overview Program at Midland Nuclear Power Station in Michigan.

Prior to joining Stone & Webster, his experience included 8.5 years at the Massachusetts Institute of Technology's Nuclear Research Reactor and played an important part during a major modification to the reactor. Mr. Butler has over 27 years mechanical experience which includes 14.5 years in nuclear related activities.

PROFESSIONAL AFFILIATIONS

American Society of Quality Control - Member

DETAILED EXPERIENCE RECORD KENNETH J. BUTLER 11160

STONE & WEBSTER ENGINEERING CORPORATION, BOSTON, MA (August 1976 to Present)

Midland Nuclear Power Station (Jan 1984 to Present)

As QUALITY CONTROL ENGINEER, currently assigned to Stone & Webster Michigan, Inc. Construction Implementation Overview Group.

Temporary Assignment By Stone & Webster To Fort St. Vrain Nuclear Power Station, Colorado (Sept 1983 to Dec 1983)

Overall responsibility for Quality Control during construction of control room addition. Sole Field Quality Control Representative for three months of project.

Shoreham Nuclear Power Station (Dec 1981 to Aug 1983)

As QUALITY CONTROL ENGINEER, assigned to the As-Built Program. Responsible for verification of as-built safety related piping and hangers.

As SENIOR QUALITY CONTROL INSPECTOR (June 1980 to Dec 1981), temporary assignment to LILCO's QA Department. Responsibilities include surveillance of installer's pressure testing program, ASME Certification Program and Auditing.

Temporary Assignment By Stone & Webster To Hahn & Clay, Houston, Texas (March 1979 to June 1980)

INSPECTOR GROUP SUPERVISOR reporting directly to Stone & Webster Q.A. Manager at Plant #2.

Overall responsibility for in-process and final inspection activities pertaining to fabrication of steam generator and reactor coolant pump supports for Duquesne Light & Power Company:

- Supervision of twenty-one (21) Mag. Partical/Visual inspection personnel.
- Supervision of Delta Inspection Ultrasonic Testing Group - one (1) clerk and three (3) teams of inspectors. Total "8"
- 3) Supervision of Microfilming Section.

Stone & Webster Engineering, Shoreham, New York (Aug 1976 to March 1979)

FQC Inspector I - Mechanical - Piping & Welding

FQC Inspector II - 7/25/77 Mechanical - Piping & Welding

FQC Surveillance Inspector assigned to assure the ASME installer meets procedure requirements.

FQC Group assigned to equipment turn-over task force.

FQC Senior Inspector frequently worked in FQC's calibration laboratory. Currently holding certifications as follows:

Liquid Penetrant Testing - Level II
Magnetic Partical Testing - Level II
Ultrasonic Testing Level II (thickness)
Thirty-two (32) hour course on Stone & Webster Quality Assurance
Audit/Survey Orientation

JOHN E. SHAW COMPANY, DERRY, NH (Nov 1975 to Aug 1976)

MECHANICAL INSPECTOR while awaiting job opening with Stone & Webster. Duties were first piece and final inspection of machine components and assemblies.

MASSACHUSETTS INSTITUTE OF TECHNOLOGY (Apr 1967 to Nov 1975)

PROJECT MACHINIST assigned to the 5 Mw Nuclear Research Reactor located at Cambridge, Mass. Duties included the following:

- Responsible for the building of various components, from sketches, drawings, and specifications, used on research projects at M.I.T.'s Reactor.
- Sole responsibility for the fabrication assembly, inspection and control of nuclear fuel element at M.I.T.
- Responsible for work performed in the "HOT" shop (radioactive material).
- 4) Inspection of components and fuel plates at various vendor sites. Also, most of the inspection and acceptance of mechanical components built during a major modification of the M.I.T. Reactor.
- 5) Authorized to operate the following equipment: Welding Machines, 20 Ton Polor Crane, Rigging of Equipment, Fork Lift Trucks and Material Transporters, Hydrogen Leak Detectors, Mag. Particle and Liquid Penetrant Testing Equipment.
- Writing various procedures required during the major reactor modification.

BOND RESEARCH LABORATORY, INC., SOMERVILLE, MA (1961 to 1965)

All around MACHINIST responsible for fabrication and assembly of various machine tools and prototype, packaging machines. Work included:

- 1) Inspection and debugging during the final assembling process.
- 2) Duties also entailed various welding processes.

R.C.A. BURLINGTON, MA & LAWSON MACHINE CO., MALDEN, MA (1960 to 1961)

Worked as an all around machinist while looking for more secure employment.

JOHN E. SHAW COMPANY, DERRY, NH (1959 to 1960)

Machinist and Inspector responsible for building all mechanical jigs, fixtures and machine tools.

PARK GEAR AND MACHINE COMPANY (1954 to 1959)

Machinist and Gear Cutter responsible for four (4) men and eighteen (18) machines. Inspected all out-going mechanical power transmission products.

A.M.S. INDUSTRIES (1952 to 1954)

Part time Machinist

January 1984

INSPECTION SUPERVISOR FIELD QUALITY CONTROL

CARTER, GEORGE A.

EDUCATION

Orange County High School, Orange, Virginia - Diploma 1972 Various Stone & Webster Continuing Education Courses

LICENSES AND REGISTRATIONS

None

EXPERIENCE SUMMARY

Mr. Carter has 11 years experience in Nuclear Power Plant construction in the Field Quality Control (FQC) Division. He is currently assigned to the Construction Implementation Overview Program at the Midland Nuclear Plant, Midland, Michigan.

Previously, as Inspection Supervisor at the Clinch River Site, Mr. Carter was responsible for preparing inspection plans, receipt inspection of CRBRP components, reviewing shipping plans of equipment provided by others, verification of storage and preventive maintenance of equipment, maintaining measuring and test equipment, the FQC Site File, and reviewing specifications.

Since joining Stone & Webster in 1972, Mr. Carter has been assigned to the Clinch River Breeder Reactor Plant Project as Senior Inspector in FQC; North Anna Power Station as Senior Inspector, Inspector II, Inspector I, Technician, and Assistant Technician in the Electrical Department of FQC; Millstone Nuclear Power Station as Inspector I in the Civil and Electrical Departments of FQC; and Beaver Valley Power Station as Inspector I in the Electrical Department of FQC.

Temporary assignments have included inspection of T.M.I. modifications at Point Beach Nuclear Power Plant and independent raceway redundancy inspections at Shoreham Nuclear Power Plant.

PROFESSIONAL AFFILIATIONS

None

PUBLICATIONS

None

DETAILED EXPERIENCE RECORD CARTER, GEORGE A. 12569

STONE & WEBSTER ENGINEERING CORPORATION, BOSTON, MA (Aug 1972 to Present)

Appointments:

Field Quality Control Inspection Supervisor - May 1982 Senior Field Quality Control Inspector - Oct 1977 Field Quality Control Inspector II - Sept 1976 Field Quality Control Inspector I - March 1974 Field Quality Control Technician - Dec 1972 Field Quality Contro! Assistant Technician - Aug 1972

Midland Nuclear Cogeneration Plant, Consumers Power Company (Jan 1984 to Present)

As INSPECTION SUPERVISOR, his duties include, but are not limited to, assuring implementation of the construction completion program by systematic evaluation of procedures, instructions, directives, correspondence, specifications and drawings. He is also instrumental in the preparation of checklists, development of checklists applicable to specific project quality control instructions and performance of evaluation and verification of documented inspections and activities.

Clinch River Breeder Reactor Plant Project, U.S. Department of Energy (May 1982 to Jan 1984)

As INSPECTION SUPERVISOR, responsible for preparing inspection plans, receipt inspection of CRBRP components, reviewing shipping plans of equipment provided by others, verification of storage and preventive maintenance of equipment, maintaining measuring and test equipment, the Field Quality Control Site File, and reviewing specifications.

Shoreham Nuclear Power Station - Unit 1, Long Island Lighting Company (June 1983)

As INSPECTION SUPERVISOR, performed independent raceway redundancy separation inspections.

Point Beach Nuclear Power Plant, Wisconsin Electric Power Company (April 1982 to May 1982)

As SENIOR FIELD QUALITY CONTROL INSPECTOR and FIELD QUALITY CONTROL INSPECTION SUPERVISOR, performed inspections of electrical raceway installations, cable installations, cable meggering, cable terminations, and calibration of crimping tools.

Clinch River Breeder Reactor Plant Project, U.S. Department of Energy (Nov 1981 to April 1982)

As SENIOR FIELD QUALITY CONTROL INSPECTOR, duties included preparing inspection plans, receipt inspection of CRBRP components, reviewing shipping plans of equipment prepared by others, verification of storage and preventive maintenance of equipment, maintaining measuring and test equipment, the Field Quality Control Site File, and reviewing specifications.

Point Beach Nuclear Power Plant, Wisconsin Electric Power Company (Oct 1981 to Nov 1981)

As SENIOR FIELD QUALITY CONTROL INSPECTOR, performed inspections of electrical raceway installations, cable installations, and cable terminations.

Clinch River Breeder Reactor Plant Project, U.S. Department of Energy (Jan 1980 to Oct 1981)

As SENIOR FIELD QUALITY CONTROL INSPECTOR, duties were the same as listed for the period between November 1981 to April 1982.

North Anna Power Station - Units 1, 2, 3, 4, Virginia Electric and Power Company (Jan 1976 to Jan 1980)

As SENIOR FIELD QUALITY CONTROL INSPECTOR (Oct 1977 to Jan 1980), performed inspections of electrical raceway installations, cable installations, cable terminations, and system inspections for initial and conditional releases. Supervised personnel involved in the handling and processing of documentation, heat tracing inspections, equipment storage and equipment installation.

As FIELD QUALITY CONTROL INSPECTOR II (Sept 1976 to Oct 1977), performed inspections of electrical raceway installations, cable installations, cable termination inspections and system inspections for initial and conditional releases, and heat tracing M.I. cables.

As FIELD QUALITY CONTROL INSPECTOR I (Jan 1976 to Sept 1976), performed inspections of electrical raceway installations and cable installations.

Millstone Nuclear Power Station - Unit 3, Northeast Utilities (April 1975 to Dec 1975)

As FIELD QUALITY CONTROL INSPECTOR I, performed concrete and soils placement inspections and testing. Inspected electrical embedments before concrete placement.

Beaver Valley Power Station - Unit 1, Duquesne Light Power Company (Aug 1974 to April 1975)

As FIELD QUALITY CONTROL INSPECTOR I, performed inspections of electrical raceway installations, cable installations, cable term nation inspections, installation inspection of heat tracing M.I. cables, and the inspection of welding on electrical equipment.

North Anna Power Station - Units 1, 2, 3, 4, Virginia Electric and Power Company (Aug 1972 to July 1974)

As FIELD QUALITY CONTROL INSPECTOR I (March 1974 to July 1974), performed inspections of electrical raceway installations and cable installations.

As FIELD QUALITY CONTROL TECHNICIAN (Dec 1972 to March 1974), performed inspections of electrical raceway installations and cable installations.

As FIELD QUALITY CONTROL ASSISTANT TECHNICIAN (Aug 1972 to Dec 1972), participated and received training in an in-depth training program on the installation and inspection of electrical raceway and cables. Performed inspections of electrical raceway installations and cable installations.

NAME: W. GORDON DICK

December, 1983

DATE OF BIRTH: January 20, 1943

British Citizen

EDUCATION

Master of Science - Mechanical Engineering - 1966 (Thermodynamics)
University of Birmingham, England
Bachelor of Science - Mechanical Engineering - 1965 Royal College of
Science & Technology, Scotland
Higher National Certificate - Mechanical Engineering - 1963 Kilmarnock
Technical College, Scotland
Successful Completion of Pipefitter Apprenticeship - 1963 Glenfield &
Kennedy Ltd., Kilmarnock, Scotland
Ayr Academy - Ayr, Scotland - 1959 High School

LICENSES AND REGISTRATIONS

None

PROFESSIONAL AFFILIATIONS

None

PAPERS AND PUBLICATIONS

Design Criteria for Plasma Jet Total Head Enthalpy Calorimeter - 1966 (University of Birmingham)

Analog Transient Studies of a Point Reactor Core - 1965 (Royal College of Science & Technology)

EXPERIENCE SUMMARY

Stone & Webster Engineering Corporation, Boston, MA (May 1974 to Present)

Midland Nuclear Cogeneration Plant. Consumer Power Company (November 1983 to present)

As CONSULTANT assigned to the Third Party Construction Implementation Overview Task Force Team required to independently evaluate the implementation and effectiveness of the Consumers Power Company Construction Completion Program.

Shoreham Nuclear Power Station Long Island Lighting Company (November 1982 to November 1983)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION responsible to the Long Island Lighting Company Director of Nuclear to Manage and coordinate various Task Force Efforts concertrating on plant completion, licensing concerns, Open Nuclear Regulatory Commission Inspection items, and post fuel load outage and maintenance management methods. Tasks included resolution of Nuclear Regulatory Commission readiness assessment team evaluation concerns, development and implementation of a Quality Accountability Program, seismic equipment field evaluation, programmatic development of controls and validation

of the composite component list and review of procedures and methods relating to effective maintenance management methods after fuel load.

Shoreham Nuclear Power Station Long Island Lighting Company (November 1980 to November 1982)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION responsible for all electrical field construction work performed at Shoreham. Direct a construction management staff of approximately 35 field supervisor, engineers and administrative personnel and electrical contractor manual forces on a multiple shift basis, of approximately 400 craftsmen.

Shoreham Nuclear Power Station Long Island Lighting Company (May 1980 to November 1980)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION responsible for preparation and tracking all construction schedules. Also performed planning interface functions with management, construction disciplines, engineering, Quality Control, Start-up and Cost Engineering Departments. Developed comprehensive computerized problem tracking system to identify field problems promptly, for resolution. Directed a staff of eight to twelve Planning Engineers.

Shoreham Nuclear Power Station Long Island Lighting Company (September 1979 to May 1980)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION performed a special assignment relating to an external audit. Reported to Utility Vice President of Projects. Also, provided assistance with project rescheduling. Specific duties included preparation of chronological reports, monitoring preparation of electrical and multi-discipline area schedules and providing written proposals for implementing schedule control program.

River Bend Nuclear Power Station Gulf States Utilities Company (June 1979 to September 1979)

As ASSISTANT SUPERINTENDENT OF CONSTRUCITON reported to Superintendent of Construction and was responsible for piping and mechanical disciplines on a force account basis. Assisted with initial planning and mobilization phase of this project, directing three construction supervisors, one engineer and 20 to 30 craftsmen in the performance of their duties. Initial work included installation of circulating water piping, control building embedded drain piping. temporary service piping and receipt/repair of condenser tube modules and turbine generator components.

Forked River Nuclear Power Station GPIJ Service Corporation (June 1978 to June 1979)

As ASSISTANT SUPERINTENDENT Of CONSTRUCTION reported to Superintendent of Construction and was responsible for all work performed in the reactor building area. Directed supervisors, engineers and contractors in the performance of their duties. Directed major substructure contractor to successful and timely completion of the reactor building mat at least two weeks ahead of schedule milestone incentive objective.

Directed liner contractor in successful field fabrication and installation of reactor cavity liner and initial containment wall modules. Also participated in contract negotiations for reactor containment external wall rebar installation. Contracts were fixed price and unit price basis. employing unique contracts clauses which encouraged innovative modularized construction methods supported by American "Skyhorse" and Kroll tower cranes.

North Anna Nuclear Power Station Virginia Electric and Power Company (January 1976 to June 1978)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION reported to Superintendent of Construction and was responsible for all work performed in the turbine buildings, service buildings, control buildings, and selected yard structures. Directed the activities of 20 supervisors and engineers and work performed by approximately 300 craftsmen on a force account basis. Disciplines managed included Civil, Structural, Piping, Mechanical and essential support disciplines. Also coordinated work with electrical contractor, turbine generator contractor and various specialty contractors. Participated actively in employee training and development programs. Developed and implemented a highly successful work package program in conjunction with cost engineers, planning engineers and area supervisory and engineering personnel.

Millstone Nuclear Power Station Northeast Utilities Service Company (May 1975 to January 1976)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION responsible for administration of field contractors. Contracts in progress or under negotiation included containment liner, rock blasting and excavation, cofferdam construction, seawall contruction, structural steel, HVAC, waterproof membrane, substructures and temporary facilities.

Boston Headquarters Office (May 1974 to May 1975)

As ASSISTANT SUPERINTENDENT OF CONSTRUCTION reported to Project Manager. Responsible for construction reviews of drawings. specifications. procedures and bid proposals for HTGR (High Temperature Gas Reactor) projects and Sundesert project. Duties included preparation and review of construction procedures. review of project schedules and project estimates. Also participated in contract negotiations for major contractors, and review of Quality Assurance procedures.

COMBUSTION ENGINEERING. INC., WINDSOR, CT (July 1970 to May 1974)

Palisades Nuclear Power Station (October 1973 to May 1974)

As LEAD ERECTOR AND SR. CONSTRUCTION SITE REPRESENTATIVE responsible for directing supervisors, engineers, craftsmen and specialty contractors engaged in the repair of operational reactor vessel and steam generators. Specific work activities performed in radiation restrictive zones, involved repair of reactor vessel core barrel guide shims using hard had divers inside the reactor vessel, repair of core barrel and reactor vessel mating surfaces, using specialty grinding techniques and seal welding steam generators tube ends. Work performed on a multiple shift, around-the-clock basis, using strict construction procedures and Quality Assurance requirements.

Beaver Valley Nuclear Power Station (February 1973 to October 1973)

As ERECTOR AND SR. CONSTRUCTION SITE REPRESENTATIVE responsible for directing supervisors, engineers and craftsmen engaged in the repair of ASME III reactor pressure vessel. Repairs involved precision-grinding, welding and heat treatment to stringent code case requirements to avoid full temperature stress relieving. Welding rep rs were performed on vessel nozzles at bimatallic and trimetallic surfaces.

Keystone Conemaugh and Point Marion (October 1972 to February 1973)

As ERECTION SUPERINTENDENT responsible for directing craftsmen in the repair and maintenance of coal-fired power stations. Work performed included the repair and replacement of waterwall tubing, superheater and economizer modules, skin casing, coal transmission piping, coal buckets, ductwork and air preheaters.

Edwin I. Hatch Nuclear Power Station (April 1972 to October 1972)

As ERECTOR AND LEAD SHIFT SUPERVISOR responsible for directing craftsmen and coordinating specialty contractors in the repair of a boiling water reactor vessel to upgrade and achieve ASME XI requirements. Work supervised included extensive Air-Arc excavation and precision grinding, welding, preheating. and stress relieving the recirculation nozzles and mid-girth shell of the reactor vessel in place.

Arthur Kill Power Station (April 1973 to April 1972)

As ERECTOR responsible for supervising craftsmen and coordinating contractors in the coal-to-oil conversion of a coal-fired power station. Work included pile driving, structural concrete and steel, recirculation ductwork, recirculation fans, oil piping installation and boiler furnace modifications.

Keystone Power Station (December 1970 to April 1971)

As ERECTOR responsible for supervising craftmen engaged in the repair of 900 MWe supercritical boiler, badly damaged due to operational failure. Work included extensive repairs to boiler pressure parts, piping, skin casing, and structural steel.

Maine Yankee Nuclear Power Station (July 1970 to December 1970)

As NUCLEAR STEAM SUPPLY SYSTEM CONTRACTOR FIELD ENGINEER representing NSSS (Nuclear Steam Supply System) suppliers' interests during receipt, off-loading. transporting and installation/storage of the reactor vessel, head. accumulators and steam generators.

WESTINGHOUSE ELECTRIC CORPORATION, PITTSBURGH, PA (July 1968 to July 1970)

Indian Point Nuclear Power Station (July 1969 to July 1970)

As NUCLEAR STEAM SUPPLY SYSTEM START-UP ENGINEER responsible for start-up procedure preparation, flushing and hydrostatic testing of various NSSS (Nuclear Steam Supply System) systems.

Nuclear Operations Center (July 1968 to July 1969)

As DESIGN/DEVELOPMENT ENGINEER Advance Reactors Division responsible for development studies related to advanced containment concepts (ice condenser) and pressurizer optimization studies. Participated in exploratory usage of various time-sharing computer options, including Westinghouse in-house version and Com-Share Inc.

THE NUCLEAR POWER GROUP, LTD., KNUTSFORD, ENGLAND (July 1966 to July 1968)

Oldbury-On-Severn Station (November 1967 to July 1968)

As START-UP ENGINEER engaged in preoperational testing, fuel loading, chemical flushing of a gas-cooled Magnox twin nuclear station. Assigned Shift Supervisor during fuel loading operations.

Knutsford Cheshire. England (July 1966 to November 1967)

As DESIGN ENGINEER Engaged in reactor building design studies for the Hinckley 'B' Station advances gas-cooled reactor. Activities included core exit temperature transient analysis studies, insulation studies, fuel standpipe assembly design and operation and a conceptual steam generator removal plan.




STONE & WEBSTER MICHIGAN, INC.

P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Docket No. 50-329/330
Midland Plant - Units 1 and 2
Overview of the Construction
Completion Program
FCR/FCN Hold Point
Serial No. SWMCP-017



CIO has completed a sampling review of Phase I and II of the following documents:

- FCR's/FCN's affecting Instrumentation and Control Documents
- FCR's/FCN's affecting Civil Documents

Results of the sampling were satisfactory. Therefore, Hold Point 011 has been released for Civil and Instrumentation and Control documents.

J. E. Karr CIO Program Manager

SWB/nl


CC:
JGKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

840203029

STONE & WEBSTER MICHIGAN, INC.



P.O. BOX 2325. BOSTON, MASSACHUSETTS 02107



DOCKET NO. 50-329/330 MIDLAND NUCLEAR COGENERATION PLANT MONTHLY THIRD PARTY ASSESSMENT MEETING

The protocol governing communications for the Remedial Soils and Construction Completion Programs at the Midland Plant, specifies a monthly meeting to discuss third party assessment activities and assigns preparation of the minutes of those meetings to Stone & Webster.

Enclosed are minutes of the meeting held on January 12, 1984.

A. P. Amoruso Project Manager

CIO

WE Killer for 15 Suche A. S. Lucks

Project Manager

Underpinning and Remedial Soils

Enclosures

cc: JWCook, CPCo DLQuamme, CPCo RAWells, CPCo

notust

8402060365

MINUTES OF THE MEETING OF JANUARY, 1984

STATUS OF INDEPENDENT ASSESSMENT OF UNDERPINNING AND REMEDIAL SOILS WORK

PURPOSE

This was a Public Meeting to report the status of the Stone & Webster Assessment Team activities and observations regarding underpinning and remedial soils work.

SUMMARY

A. S. Lucks opened the meeting by identifying the major parts of the Assessment Team presentation. The first part is a summary of the Assessment Team activities by P. Majeski detailed in Weekly Reports 63 through 67. The second part is an update of the resolution activities for the Stop Work Order relative to the soils and underpinning work. This is followed by a status report on the action items assigned to the Assessment Team from the December meeting.

Mr. Lucks identified the following corrections to the December meeting notes. The corrections concerned changes to the five items listed at the top of page 6. The first item should read "Define Important Quality . . ." instead of "Define Poor Quality . . ." Also the third bullet in this list (the bullet only) should be deleted.

P. Majeski began a summary of Assessment Team activities by stating that no new construction work had been performed on the underpinning during

December due to the Stop Work Order. The present status of the underpinning was reviewed. On the east and west sides, 8 piers and one grillage have been completed. Activities that support crack mapping and routine maintenance continue as exceptions to the Stop Work Order.

Assessment Team evaluations were conducted on Crack Mapping, Work Activity Packages, and Open Items including a review of the progress made in actions being taken to improve operations at U.S. Testing.

Assessment Team procedural concerns related to crack mapping that were discussed in December's public meeting have been resolved. Additional concerns that originate from Assessment Team inspections of crack mapped areas resulted in the development of a criteria that defined which cracks must be mapped. As a result of the meeting held last week between the NRC and Consumers Power Company (CPCo), areas of the Auxiliary Building not being mapped are being surveyed. Any significant cracks will be added to the mapping program. The Assessment Team will review the results of this survey when it is issued.

Four Work Activity Packages (WAPs) were reviewed. They were:

- WAP 59 Cathodic Protection in Q Filled Areas
- WAP 69 SWPS Pier 1 and 1A Excavation and Scil Load Tests
- WAP 71 SWPS Anchor Bolt Holes
- WAP 73 Train B Service Water Pipe Replacement

The reviews for WAPs 59, 69, and 73 have been completed and closed. WAP 71 has one review action item concerning bolt corrosion that remains open.

With reference to the review of the progress being made in response to the evaluations of U.S. Testing Operations, Bechtel's Subcontracts Group originally identified 15 areas of concern with U.S. Testing. Of the original concerns, 5 open items remain.

- Item 1. Item 16 of the original QA audit concerned a field document control problem. This item is expected to be closed within a week of this meeting.
- Item 2. To improve efficiency, the majority of Laboratory Technicians are to be cross trained to 20 procedures within the next 6 months.
- Item 3. Two Laboratory Chiefs are to be cross-trained to all the procedures within 3 months.
- Item 4. Work instructions for testing activities are to be prepared and incorporated into U.S. Testing procedures within the next three months.
- Item 5. A site position for a Level III technician that had been vacated by a staff transfer is expected to be filled again by a Level III technician within a few weeks.

The Assessment Team will continue to follow the upgrading of of U.S. Testing. They must strive to meet the schedule for these actions.

The status of Nonconformance Identification Reports (NIRs) was reported next. NIRs 14, 16, 17, 18 and 19, discussed during the last meeting, were closed in December. NIR 20 remains open until specification changes are made concerning the calibration of admixture dispensers used for adding superplasticizer to concrete. One pier has been constructed using superplaticized concrete but in this case there was not a nonconforming condition.

There are currently nine Open Items that require action prior to closure.

The status of the resolution activities for the Stop Work Order were summarized by A. S. Lucks. The Stone & Webster Engineering Assurance Specialist returned to the site to assess the Stop Work Order resolution activities. The results of this assessment indicated that revisions to change document procedures have been completed and these revisions correct the problems that led to the Stop Work Order. Phase II resolution activities have been completed and were found to be satisfactory. Phase III resolution activities are in progress.

The status of the 3 action items assigned to Stone & Webster from the December meeting was addressed next.

Action Item 1. The NRC requested that in future Weekly Reports Stone & Webster provide Work Activity Package (WAP) titles along

with the WAP number. Stone & Webster complied beginning with Weekly Report 64. This item was closed by the NRC.

- Action Item 2. Stone & Webster was requested by the NRC to give an opinion on whether there should be a settlement criteria for acceptance of rejacking in response to strain readings on the E/W 8 support columns. The topic is now part of an ongoing review of existing criteria by CPCo and the NRC. The Assessment Team will evaluate the results of the review and provide an opinion on the need for a settlement criteria when the review is completed. This item remains open.
- Action Item 3. The NKC was concerned whether the Assessment Team review questions for WAP 59 had been resolved prior to submittal of the package to the NRC. The initial WAP review was completed and all questions were resolved in the first week of October, 1983. A subsequent review by another Assessment Team member identified a concern with an interference between an anode and a well. Based on the original review results CPCo submitted WAP 59 to the NRC on the 5th of October. The interference concern was resolved and then closed in the last week of November (Weekly Report 63). The NRC concern was whether CPCo had submitted the WAP for approval prior to resolving Assessment Team questions. At the time of sumbital, all Assessment Team questions had been resolved. This item was closed by the NRC.

This concluded the presentation by Stone & Webster. CPCo now addressed the 5 action items assigned to them during the December meeting.

- Action Item 1. The NRC requested information on the actions being taken to avoid delay in reporting alert level cracks. Six actions are being taken to avoid delays in reporting alert level cracks:
 - a) A Wiss Janney Lead Engineer has been assigned to overview all activities to provide greater accountability and continuity in crack monitoring.
 - as well as the data submittals. There will also be a final overall review by the Lead Engineer.
 - A Wiss Janney review for legibility is now required by procedure.
 - d) An alert level crack now requires verbal notification within two hours and a written report within 24 hours.
 - e) The specification now requires the RSE to review the alert mapping level values and the procedure requires
 Wiss Janney to forward a copy of the submittal to
 MPOAD for faster response and better visibility.

Action Item 1 was closed by the NRC.

Action Item 2. The NRC was concerned about the timing of the NCRs written against Carlson meter concrete blocks. They were poured on June 8, 1983, shipped for calibration on June 16, 1983 and returned to the site on June 18, 1983. The associated concrete piers were poured on June 25, 1983 and the NCRs were written on September 29, 1983 and November 3, 1983 during a document review. The nonconformance was that the IR, did not document that the forms had been stripped within the specified time period. The performance of the Carlson meters was not part of the nonconformance. The placement of the Carlson meters in the piers, did not interface with the IR to accept curing of the concrete pour. The two IRs are now tied together. The NRC closed this action item.

Action Item 3. The NRC was concerned about concrete mixer drum rotation. A specification change now requires in general that the truck continuously rotate the mixer drum while waiting to discharge. If a mixer drum has been idle for 15 minutes or more the concrete shall be agitated a minimum of ten revolutions. The NRC closed Action Item 3.

Action Item 4. The NRC asked for a report on the transfer of the lessons learned in the auxiliary building underpinning to the Service Water Pump Structure. A total of 36 items were identified with 6 not applicable to the Service Water Pump Structure. 19 items have been incorporated while 11 are still being evaluated. The NRC indicated Action Item 4 is still open pending their review.

Action Item 5. This item concerned crack mapping problems identified during November. The appropriate specifications and procedures have been revised and the NCRs and QARs have been closed. The NRC closed Action Item 5.

This concluded the report on CPCo action items.

Questions and Answers

Mr. J. Harrison and Mr. R. Landsman asked several questions concerning items included in Weekly Reports 63 through 67.

- What is the relationship between items 63-10 and 63-12? They dealt
 with information related to the NIR concerning the admixture dispenser
 calibration.
- 2. Does item 63-17 address the same welding report discussed a couple of months ago? Can CPCo identify what changes were made as a result of the recommendations in this report? It was not the same report. Examples of changes would include items that clarify the applicable code requirements. Also design changes that were more practical for welding were implemented. The NRC asked that a copy of the welding report be supplied to them. (Mr. Harrison indicated that this should not be considered as an action item).

- 3. With reference to items 64-6, 64-8 and 64-9, has interim approval for FCNs and FCRs been eliminated? Interim approval no longer exists for FCNs except to provide as-built information. Interim approval of FCRs is still allowed during a transition period after which they will no longer be allowed.
- 4. With reference to Item 64-14, was an evaluation done to consider the impact of the problems with U.S. Testing on past test results? A 100% audit by MPQAD evaluated the impact on past test results and any problems were addressed in an NCR.
- 5. With reference to Item 64-13, is the 20 day limitation on FCR final approval an interim measure? Yes, until the new process is in effect.
- 6. With reference to Item 64-2Q, can CPCo provide the status of the MPQAD review and verification of past IRs for soils? All activities now are preliminary and the review procedure is being developed. The review will commence after the Stop Work Order is lifted.
- 7. Is the 30 mil alert level indicated in Item 64-4Q a change to the criteria on crack mapping? The 30 mil alert level is for existing cracks, the 10 mil alert level is the criteria for new cracks. These have not changed.
- 8. With reference to Item 65-4, what is the base line for settlement data on the service water pump structure? July 28, 1983.

- 9. Item 65-11 states that Stone & Webster did a spot check on crack mapping and identified cracks that were not being mapped. What was the engineering resolution? Should an NIR have been issued? The Assessment Team did a random check of the crack monitoring data sheets. Two of the Auxiliary Building floor areas were found to have cracks not recorded on the data sheets. An Open Item (66-7) resulted in the 2 ft., 5 mil criteria being established for the crack survey now being conducted by CPCo. Since this criteria was not in the original crack mapping procedures, a nonconformance did not occur. No NIR was required. A survey of the building is being conducted. The NRC stated that it was their understanding that <u>all</u> cracks would be mapped and that they would confer with NRR and the issue will be addressed fin next month's meeting.
- 10. What caused the 20 mil change in settlement readings referred to in Item 65-17? Exact causes are not known, but other backup measurements and surveillance since the change indicates a problem with the gauge rather than an actual 20 mil movement during one day.
- 11. Could CPCo explain why the upper 10 ft. of the fill on the Service Water Pump Structure is to be stabilized by grouting described in Item 67-9? The area is temporarily backfilled with sand. The grout stabilization will prevent the sand from flowing into the excavation. This grouting will become part of the Work Activity Package controlling the work. A test program to establish the grouting procedures may be conducted.

12. Item 67-16 indicates that CTL stated that certain cracks recently identified by Wiss Janney had originally been identified by CTL back in 1981 or 82. There appears to be a disconnect between the two crack mapping companies. CTL doesn't do crack mapping, they are called in to evaluate the cracks identified by Wiss Janney. The NRC stated that they believed that there are also more new cracks identified. At the next meeting CPCo was requested to give a report concerning the results of the crack mapping survey row being conducted.

Required Action

The following action is required by the Assessment Team:

1. The Assessment Team will evaluate the results of the CPCo/NRC review of existing criteria for allowable building movements and jacking. The Team will then give an opinion on whether there should be a settlement criteria for rejacking of the E/W8 grillages triggered by greater than 20% change in strain readings on the support columns.

The following item remains open for CRO.

1. The issue of crack mapping will be addressed in the February meeting.
CPCo will update the status of the crack survey and the NRC will discuss the results of the conference with NRR.

MINUTES OF THE MEETING ON JANUARY 12, 1984 STATUS OF CONSTRUCTION IMPLEMENTATION OVERVIEW (CIO) PROGRAM

Purpose

To discuss Third Party Overview activities of Stone & Webster (S&W) and problems encountered regarding the Construction Completion Program (CCP) during December 1983.

Summary

Mr. A. P. Amoruso, Project Manager for the CIO Program, presented a summary of Program activities for December 1983. The following topics were covered:

Assessment Activities

Opportunities to assess the Construction Completion Program (CCP) continued to be limited during December due to the stop-work orders that were issued because of concerns about the control of FCR/FCN field change documents. Those orders prevented starting statusing and verification of work in the plant, the principal components of Phase I of the CCP. Activities that were assessed included the FCR/FCN Resolution Program, preparations for Phase I statusing and verification, training presentations, training records, and management meetings. The three phases of the FCR/FCN Resolution Program were checked, and document Control problems were identified. These problems included inconsistencies between the document distribution list and holdings at field stations, differences between registers and changes attached to base documents, and practices that were not proceduralized. Consumers Power Company is developing a corrective action plan to resolve these problems. Preparations for statusing and verification that were monitored. included updating construction punchlists, material lists, and labor data and training CCP team members. These activities were conducted in

accordance with CCP supporting procedures. Seven training presentations were evaluated. These presentations followed prescribed lesson plans and conveyed key information effectively. Some 100 training records were checked to assess the adequacy of corrective actions for administrative discrepancies that had been identified previously. No discrepancies resulted. Thirty-seven management meetings were monitored. The consistency of action being taken showed effective management involvement. In the three areas outside the CCP but within the scope of the CIO; namely, the Nuclear Steam Supply System (NSSS), the Spatial System Interaction Program (SSIP), and the Heating, Ventilation, and Air Conditioning System (HVAC), assessment opportunities were also limited during December due to the stop-work orders. Activities that were assessed included the qualification records of three welders in the HVAC program and the establishment of parameters for weld procedure qualification. Results of both of these checks were satisfactory.

° CIO Items, Nonconformances, and Hold Points

Three CIO items were identified during December. The items follow:

- A checklist developed to monitor status assessment did not contain all attributes of the governing procedure.
- A controlled architectural drawing was found missing from a stick file during a sample inspection of holdings at a field station.
- Resolution sheets for one FCR out of a sample of civil documents did not clearly indicate whether one or two drawings were affected by the change.

Two of the three items noted above were also verified corrected and closed during December. The two items are the missing architectural drawing and the unclear resolution sheets for the FCR.

Three nonconformances identified by the CIO Program remained open. These non-conformances address administrative deficiencies in training records and are the same items that were listed as open at the last meeting.

The following six Hold Points established by the CIO Program remained open. The Hold Points are the same as those listed as open at the last meeting.

- Development of a vendor equipment verification program before the start of Phase II of the CCP.
- Evaluation of the management review of the results of Phase I activities before the start of Phase II of the CCP.
- Correction of training records for construction support groups before people involved are used in the statusing part of the CCP.
- Upgrading the level of training in five elements of the Construction System Team Training Matrix before people involved are used in the statusing part of the CCP.
- Verification of Phase I and II evaluations of the FCR/FCN review before stop-work orders are lifted.

· Highlights of December

- FCR/FCN Resolution Program

The FCR/FCN Resolution Program consists of three phases. Phase I involves identifying FCR/FCNs that do not clearly indicate which documents are affected by the changes. Phase II involves resolving uncertainties identified in Phase I. Phase III involves making changes to FCR/FCN registers that were caused by corrective action in Phase II. The status of the CIO assessment follows:

- Architectural and civil documents have been checked satisfactorily through Phase II.
- Architectural documents at three field stations have been checked satisfactorily through Phase III. Checks are ongoing at other stations,

Minutes of Meeting PAGE 4

> and one CIO nonconformance has been identified to date. That nonconformance was issued to address several document control problems that were identified during these checks.

- Instrumentation and control, electrical, and mechanical documents will be checked through Phase II and Phase III when document control problems are resolved.

- Document Control Problems

The document control system at the site is complex. Verification of holdings at a particular field station could require use of some fifteen registers.

Administration of the system has been complicated further by a large number of documents distributed on the site, a large number of changes to those documents, and practices that have not been proceduralized. Consumers Power Company recognizes the difficulties in administering the system and has been shifting to a simpler, state of the art system.

The weaknesses of the document control system were accentuated by the FCR/FCN stop-work orders which froze the processing of most documents. This was the situation when both the Midland Project Quality Assurance Department (MPQAD) and CIO checked document distribution during Phase III of the FCR/FCN Resolution Program. The findings of both groups were similar and included:

- Differences between the distribution list and actual holdings at field stations.
- Inconsistencies in the system for retiring documents.
- A practice for decontrolling drawings that was not proceduralized.

 Consumers Power Company is developing a corrective action plan which will be evaluated by the CIO before releasing hold points on the FCR/FCN Resolution Program.

Minutes of Meeting PAGE 5

Miscellaneous Items

- CIO Staff

The CIO staff remained at 29 in anticipation of the start of CCP statusing and verification. As discussed at the last meeting, the number of people and mix of disciplines will be adjusted as the actual verification load dictates.

- Safety Related Work Instructions

As discussed at the last meeting, a CIO item will be opened requesting

Consumers Power Company to ascertain that memorandums have not been used

to promulgate work instructions for safety related systems.

Action items from Last Meeting

- The CIO had one action item from the last meeting. That item involved the routing of nonconformance reports. Checks revealed no instances of lost or misplaced reports. The report that generated concerns about routing was not lost but had been sent back to the originator for additional information so that a disposition could be made. After the disposition was made, the report was routed correctly.
- consumers Power Company (CPCo) had one action item. That item involved training level codes used in training matrices. Mr. D. L. Quamme, CPCo, stated that the management review of training prior to Phase I of the CCP looked primarily at the procedures that were in place to develop training matrices. Since that review, procedures, job descriptions, and work assignments have been more clearly defined. The discrepancies identified by the CIO consisted primarily of inconsistencies between matrices based on current information. To resolve these problems, the matrices are being bounced against each other to ensure consistency and are being checked to ensure that people are being trained at the proper level now that job

assignments are better defined. Until this formal review is completed, people being put in the field are governed by a special training bulletin which clarifies specific areas that have been identified. After the review, all people assigned to the field will be checked against the new training requirements to ensure that their level of training is proper.

Questions and Answers

- Mr. R. N. Gardner, NRC, asked if CPCo and the CIO differed on their evaluation of the condition of the cable jacket that was in contact with nails in a board that was lying in a cable tray.
 - Mr. J. E. Karr, CIO, said that there was a difference of opinion, and CPCo was reevaluating the disposition of a nonconformance which was based on the assumption that the cable jacket had not been damaged.
- o Mr. Gardner asked if the CIO evaluation of nonconformances for closure would also look at generic aspects.
 - Mr. R. G. Burns, CIO, said that the CIO would routinely go back to closed nonconformances and compare those trends with existing conditions. The whole population and not just immediate items would be included in reviews to identify generic problems.
- Mr. B. L. Burgess, NRC, asked how CPCo is informed when disciplines have been cleared by the CIO through Phase II of the FCR/FCN Resolution Program. Mr. Amoruso stated that disciplines are being released by letters which modify the Hold Point that has been established at Phase II.
- o Mr. Gardner asked what type of problem would be addressed by a memorandum and result in a Design or Specification Change Notice as mentioned in a CIO Weekly Report.

Mr. Karr stated that a phone call might be made to Ann Arbor by resident engineering to ask a question about a design document or a specification. To preclude misinterpretations about what is being asked, a memorandum would be prepared to back up the phone call. Review of the question by project engineering might conclude that a change to a document is really needed. A Design or Specification Change Notice might then result.

Mr. Gardner and Mr. J. J. Harrison, NRC, stated that their concerns were that memorandums might become substitutes for required formal documentation.

Mr. R. A. Wells, CPCo, stated that the memorandums will not be substitutes for other documentation but will be used as a means of communicating when items need clarification.

- Mr. Harrison asked for a summary of findings of the Stone and Webster corporate audit of the CIO as mentioned in a CIO Weekly Report.
 Mr. Burns stated that the overall conclusion of the audit was that the CIO has met commitments specified in planning procedures. The most significant finding involved the need for team members to improve consistency in documenting sample sizes.
- Mr. Harrison asked for information about a special checklist that was mentioned in a CIO Weekly Report as being prepared by Bechtel for use in conducting status assessment. The checklist did not have all the attributes of the governing procedure.

Mr. Karr stated that the checklist was to be used as an aid in performing the assessment. Therefore, the list contains only key points that are desired to be emphasized and not all attributes from the procedure. Because of the potential problems with such a list, a CIO item was opened. Mr. Quamme stated that the response from Bechtel indicated that the checklist was to be used as a guide and not as a detailed working document. Mr. Gardner stated that such lists

Minutes of Meeting PAGE 8

have created problems in the past. Mr. Quamme stated that the matter would be reviewed.

- o Mr. Harrison asked if the Public had any questions. The following items were discussed:
 - Instrument aberrations
 - FCR/FCN Resolution Program
 - Crack mapping
 - Objective of the monthly meeting

Action Item

° CPCo discuss at the February meeting the condition of the cable that was in contact with nails in a board lying in a cable tray.



STONE & WEBSTER MICHIGAN, INC.

P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Docket No. 50-329/330 Midland Plant - Units 1 and 2 Site Program Manager Serial No. SWMCP-019 January 23, 1984

PRINCIPL STAFF

DOS

Oug + 3

Mr. Joel E. Karr has been assigned as the Site Program Manager for the Stone and Webster Construction Implementation Overview (CIO) Program at the Midland Nuclear Power Plant. This assignment was effective on January 12, 1984.

A. P. Amorusa

CIO Project Manager

APA/ka

cc: JJHarrison, US NRC Glen Ellyn RJCook, US NRC Midland (site) RAWells, CPCo Midland (site)

5 400000000 JAN 27 1984




STONE & WEBSTER MICHIGAN, INC.

P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107

Mr. J. J. Harrison Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

DOCKET NO. 50-329/330
MIDLAND NUCLEAR COGENERATION PLANT
RESUME AND AFFIDAVIT FOR MR. J. E. KARR



Attached is the resume and affidavit for Mr. Joe! E. Karr.

Mr. Karr is being assigned as the Site Program Manager for the Construction Implementation Overview (CIO) Program at the Midland Nuclear Plant.

A. P. Amoruso CIO Project Manager

APA/ka

ATTACHMENTS

Figure 3-1

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

In the Matter of CONSUMERS POWER COMPANY

Docket No. 50-329 OM

50-330 OM

(Midland Plant, Units 1 and 2)

Docket No. 50-329 OL 50-330 OL

AFFIDAVIT	OF_	JOEL	E.	KARR	
-----------	-----	------	----	------	--

My name isJoel E. Karr		I am employed by Stone & Webster
Michigan. Inc.	as	Senior Engineer (Titled) .

I am currently assigned to the team which is proposed to conduct a Third Party Construction Implementation Overview at the Midland Nuclear Plant site. Prior to being given this assignment, I have never worked on any job or task associated with the Midland Project, or any job or task for or on behalf of Consumers Power Company or Bechtel relating to issues that I will be reviewing. I have never been employed by Consumers Power Company or Bechtel. I do not own any shares of Consumers Power Company or Bechtel stock. Mutual funds or other funds in which I may have a beneficial interest, but over which I have no control, may own shares of Consumers Power Company or Bechtel stock, of which I am unaware. A list of such funds in which I have an interest are attached. I have no relatives which are or have been employed by Consumers Power Company or Bechtel.

Sworn and Subscribed Before Me This 5th Day of January, 1984

Patricia a Luffer

NOTARY PUBLICITY

PATRICIA A. PUFFER Notary Public, Bay County, MI My Commission Expires Mar. 4, 1986

My Commission Expires 3-4-86

LIST OF FUNDS

I am not participating in any funds which may own shares of Consumers Power Company or Bechtel stocks.

January 1984

KARR, JOEL E.

PROJECT QA MANAGER QUALITY ASSURANCE DEPARTMENT

EDUCATION

United States Coast Guard Academy - Bachelor of Science in Engineering, 1968

LICENSES AND REGISTRATIONS

None

EXPERIENCE SUMMARY

Mr. Karr joined Stone & Webster in July 1973 as a Quality Control Engineer in the Quality Systems Division, and since April 1983, is assigned as the Project Quality Assurance Manager for the Clinch River Breeder Reactor Plant Project.

Since joining Stone & Webster, he has been assigned to several major nuclear projects where he performed tasks related to program development and evaluation for construction, operation, and nuclear fuels management licensing, procedure development and evaluation, Quality Assurance program administration and overall Quality Assurance program management.

Prior to joining Stone & Webster, he was a commissioned officer in the United States Coast Guard with assignments in management and administrative areas as well as dealing with several aspects of engineering.

PROFESSIONAL AFFILIATIONS

American Society for Quality Control - Member

PUBLICATIONS

None

. ,

DETAILED EXPERIENCE RECORD KARR, JOEL E.

STONE & WEBSTER ENGINEERING CORPORATION, BOSTON, MA (July 1973 to Present)

Appointments:

Quality Control Engineer - July 1973 Quality Assurance Engineer - Jan 1975 Senior Quality Assurance Engineer - Dec 1979 Project QA Manager - Apr 1983

Clinch River Breeder Reactor Plant Project, U. S. Department of Energy (Apr 1983 to Present)

As PROJECT QUALITY ASSURANCE MANAGER for the CRBRP Project in Oak Ridge, Tennessee, responsible for the management and administration of the overall Stone & Webster Quality Assurance program as applicable to the Stone & Webster scope of work on the Project including the administration of Quality Assurance and Quality Control personnel assigned to the Project.

Clinch River Breeder Reactor Plant Project, U. S. Department of Energy (Jan 1980 to Apr 1983)

As ACTING PROJECT QUALITY ASSURANCE MANAGER for the CRBRP Project in Oak Ridge, Tennessee, responsible for the management and administration of the overall Stone & Webster Quality Assurance program as applicable to the Stone & Webster scope of work on the Project including the administration of Quality Assurance and Quality Control personnel assigned to the Project.

Nine Mile Point Nuclear Power Station, Unit 2, Niagara Mohawk Power Company (May 1978 - Dec 1979)

As PROJECT QUALITY ASSURANCE MANAGER for the Nine Mile Point, Unit 2 Project in Scriba, New York, had overall authority and responsibility for administration of Project Quality Assurance functions, including Field Quality Control, Procurement Quality Assurance, and Project auditing. Also responsible for direction and control of Project-related Quality Assurance administrative activities and operations at the Project Office and at the construction site.

Clinch River Breeder Reactor Plant Project, U. S. Department of Energy (Apr 1976 - May 1978)

As ACTING PROJECT QUALITY ASSURANCE MANAGER for the CRBRP Project in Oak Ridge, Tennessee, responsible for the management and administration of the overall Stone & Webster Quality Assurance program for the Clinch River Breeder Reactor Plant Project including the administration of Quality Assurance and Quality Control personnel assigned to the Project.

As QUALITY ASSURANCE SECTION SUPERVISOR for the CRBRP Project, responsible to the Project QA Manager for the operation of the Quality Assurance Project Office in Oak Ridge for the CRBRP Project.

As QUALITY ASSURANCE ENGINEER assigned to Clinch River Breeder Reactor Plant Project in Boston Headquarters Office, developed initial plans and procedures for quality activities on this Project and quality assurance portion of safety analysis report.

JEK

SWEC Boston Headquarters Office (July 1973 - Mar 1976)

As QUALITY ASSURANCE ENGINEER in Boston Headquarters Office, performed quality assurance services related to nuclear project licensing, development of S&W QA Topical Report for submission to NRC, Quality Control Procedure development at a construction site and quality assurance systems. Assisted several utilities in developing their own quality assurance programs and procedures for construction, operation, and nuclear fuels for their nuclear plants. Also involved in evaluation of existing utility quality assurance programs and development of utility portions of safety analysis reports.

As QUALITY CONTROL ENGINEER in Boston Headquarters Office, developed systems and procedures for control of quality related activities for construction of nuclear power plants. Served on corporate committee tasked with development of company records management system.

UNITED STATES COAST GUARD (June 1968 - Feb 1971)

First Coast Guard District Staff, Boston, MA (Feb 1971 - July 1973)

As Officer In Charge of the District Communications Center, handled work in all areas of design, construction, and installation of new communications center and associated Rescue Coordination Center during relocation of this facility.

U. S. Coast Guard Cutter Sherman (June 1968 - Feb 1971)

Deck Department Head



Deen L Quemme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

January 19, 1984

Mr S W Baranow Stone & Webster Michigan, Inc. P O Box 1963 Midland, MI 48640

PRIN	CIPAL STAF	F
RAT	DPRP	_
D/RA	DE	_
A/RA	DRMSP	
PC	DRMA	
PAO	SCS	Toring + 3
SGA	ML	7 8
ENF	File	7 "

MIDLAND ENERGY CENTER GWO 7020

STONE & WEBSTER LETTER SWMCP-008, DATED 1-10-84

FILE: B1.1.7 UFI: 53*50*04 SERIAL: CSC-7189

0655 99*08

Consumers Power Company will be in the position to respond to your letter four to eight weeks after the mechanical stop work is lifted. This unfortunate delay in our response is due to our concern that we properly assess anything that may come out from the stop work review process. If this is not adequate to meet your immediate needs, our QC records are always open to your staff. Should you or any of your staff have any questions on this topic, please contact Norm Reichel at ext. 6402.

CV DLQ/TAS/pal

CC: JGKeppler, NRC Region III
JJHarrison, NRC Region III
RJCook, NRC Site
RAWells, MPQAD
BHPeck, MEC
NIReichel, MEC
GAHierzer, Bechtel



STONE & WEBSTER MICHIGAN, INC.

P.O. Box 2325, Boston, Massachusetts 02107

January 18, 1984

Mr. D. L. Ouamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

SCSV ML

PRINCIPAL STAFF

DPRP

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-013

Re:

Midland Energy Center

Training of Construction Personnel

Reference CPCo correspondence CSC-7156 1/11/84.

CSC-7162 1/12/84, CSC-7166 1/13/84, and CSC-7171 1/16/84

Please be advised that CIO has performed sampling inspections of the Construction Training Records of those personnel noted in the attachments of the above referenced correspondence. The results of the sampling inspection were satisfactory. Personnel listed on the attachments are cleared to perform status assessment. As a result of the satisfactory review of the Training Records, CIO has closed out NIR 006.

Very truly yours.

JEK/nl

- JGKeppler, US NRC Glen Ellyn, IL JJHarrison, US NRC Glen Ellyn, IL RJCook, US NRC Midland (site) RAWells, MPOAD NReichel, CPCo APAmoruso, S&W



Deen L Quamme Site Manager Midland Project

PRINCIPAL STAFF

DAG

DRMA

SCS / ML File

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

January 12, 1984

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWC 7020
TRAINING OF CONSTRUCTION PERSONNEL
File: 0400.2, 0655 UFI: 53*50*04, 06*02 Serial: CSC-7162
B1.1.7 99*08

Attached is a list of Bechtel construction personnel who have completed their training requirements to commence status assessment. Please contact E H Pillsbury, Bechtel Ext. 7167 to initiate your audit requirements on these individuals.

WDLQ/DDJ/klp

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD v/a
BHPeck, MEC w/a
NIReichel, MEC w/a
GAHierzer, Bechtel w/a

Date	Team	Records Ready For Audit	Records Audited by Stone/Webster
1-11-84	PRAZYRWYEEE	Anderson LARRY 429221	
1-11-84	· ARAZSLSE	ASARD SARD 886849	
1-11-84	HER31WEE	Beauer Carl 325218	
1-11-84	HGR3/CASTAST	Benin Sandi 372970	
1-11-84	APAZHRWYSES	Bunners David 07.396/C	
1-11-84	NGR30CANTANT	CASHED MARY 372 748	
1-11-84	ACCSTEL YEFE	CHMELAR Peter 204112	
1-11-84	SOSEFE	Crowell Wayne 804105	
1-11-84	HERBIWEE	Fracio Bruce 360016	
1-11-84	PKB27 CSE	Fisher Den Ster	
1-11-84	Sys 14mFE	Fulmer Gary 61879)	
1-11-84	5,517 MFE	funk Steve 223529	
1-11-8-1	ARRATECIU	Gezesial Tom 373845	The Principles
1-11-84	ARAZICHE	Hall Don 3430	
1-11-84	HERBILSE	HASSOUN, CSAMA 925566	
1-11-84	NER32CA	Liberia, Kathy 372199	
1-11-84	ARAZEME.	London, Dynic 853468	
1-11-84	HER31 MFE	Mamula, David 35-9944	
1-11-89	ARAZUPLAR	MANLY LAURA ECTELL	
1-11-84	ARASYRWYEFE	mclus, Betty 439899	
1-11-84	ARA 23 RWYESE	Mehta SK. 372417	
1-11-84	AR & STRWIEFE	memenus Brian 709782	
1-11-84	PRAZYOR	M. Iler Jim 600261 .	
1-11-84	7,272312WYEFE	PARTYOTIDES Michael 519976	
1-11-84	· HERZEMFE	Ochocks. Jenny 372045	
1-11-84	SYSILLSE	SANBLER BERT 925396	
1-11-84	ACH SY PLN 12	Snn 05 - ED 923476	
1-11-84	HGR30 MEE	Schaffleth Laura 361072	

CONSUMERS POWER COMPANY MIDLAND ENERGY CENTER

Transmittal No: CSC- 7163

Date: January 13, 1984

To: Stone & Webster
P O Box 1963
Midland, MI 48640

Attached Is: Partial Response To

X Complete Response To

For Your Information

Other

Description:

Tracked Information Items 038, 042, and 044.

·Signature: HOLL

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
DDJchnson, MEC w/a

- STONE	TION	O38		T NUMBER		
CONSTRUCTION IMPLEMENTATION OVERVIEW MIDLAND NUCLEAR PLANT J.O. NO. 14509			TRACKED ACTION ITEM			
			X TRACKED INF			
			TRACKED RECOMMENDATION ITEM			
REFERENCE(S) CIO Wee	kly Report Number 2	6	UNTRACKED I	TEM		
			HOLD POINT	NOTIFICATI	ON	
in conducting System Status clude all of t If special che addressed by a lists are to b CPCo is reques	checklist develope Status Assessments and Completion), th he attributes requi cklists are to be u n administrative pr e prepared, used an ted to provide CIO ant control measure	to Procedure Fine CIO noted the red by the processed in statusing occdure that produced the controlled.	pm-7.000 Rev. 1 at the checklis cedure. ng, these lists rovides details ded use of thes	should be	in-	
			Type	(PAGE	XNO	
		The second second second		NO 37	CONTRACTOR OF STREET	
			ATTAC	HMENTS		
DATE RESPONSE REQ'D.	INITIATORIDATE			HMENTS		
1/16/84 RESPONSE	JElan	1-6-84/	INITIATION A	HMENTS	DATE 6.84	
1/16/84 RESPONSE Our respons	Se to Tracked Information No CSC-7134 dated J	nation Item #03	NITIATION A	PAGE	. 84 -	
1/16/84 RESPONSE Our respons	JEllan se to Tracked Inform	nation Item #03	8 was sent by	PAGE NO.'S)		
1/16/84 RESPONSE Our respons	se to Tracked Inform No CSC-7134 dated J	nation Item #03, January 5, 1984	8 was sent by	PAGE	□ NO	

Sheet 1 of 1

STONE	& WEBSTER	042
CONSTRUCTION	N IMPLEMENTATION	TRACKED ACTION ITEM
OVI	ERVIEW	I TRACKED INFORMATION ITEM
MIDIAND NUCLEA	R PLANT J.O. NO. 14509	TRACKED RECOMMENDATION ITEM
Intereffice	Momorand m. SuBaranow to DLOuamme,	T UNTRACKED ITEM
PCo Training of 10/21/83. C	PCo Letter, DLOUanne to SwBaranow,	HOLD POINT NOTIFICATION
training of CPCo pers Construction Completi		ization of procedures for the rming tasks relative to the to CIO for review and evaluation. YES (PAGE NO.'S) NO
		ATTACHMENTS
		INITIATION APPROVED/DATE
DATE RESPONSE REQ'D. 1/20/84	INITIATOR/DATE	1-6
A copy of the in the CCP wa	e training procedure for CPCo sas given to your John F Seely	SMO personnel involved on January 6, 1984.
		Tyes No.53
		YES NO.'S) ONC
	ON I RESPONDENT	YES NO.'S)
EST. CORRECTIVE ACTIO	ON RESPONDENT	ATTACHMENTS TITLE Construction 1/13/84
EST. CORRECTIVE ACTION COMPLETION DATE Action Complete	ON RESPONDENT	ATTACHMENTS TITLE DATE

		DED POINT NUMBER
STONE & WEBSTER	044	
CONSTRUCTION IMPLEMENTATION	TRACKED ACTIO	ON ITEM
OVERVIEW	X TRACKED INFO	HMATION ITEM
MIDLAND HUCLEAR PLANT J.O. NO. 14509		OMMENDATION ITEM
Meeting January 6, 1984 - S&W CIO and	UNTRACKED IT	
CPCo - General Discussions of open items	HOLD POINT N	OTIFICATION
Pursuant to the referenced meeting it is requested the reports issued by TERA Corporation for their activity Midland Nuclear Plant.	☐ YES	CPAGE WIND
		PPROVED/DATE
DATE RESPONSE REQ'D. INITIATOR/DATE 1/30/84 RESPONSE Donald B Tulodieski, TEPA Corporation Projection requested by CPCo SMO on January 10, 1984 Stone & Webster, on Distribution for TERA Midland Nuclear Plant.	ject Manager, was to include S W Bar reports related to	ranow, o the
	TITLE	DATE
EST. CORRECTIVE ACTION RESPONDENT COMPLETION DATE Action, Complete BHPeck	Construction Superintendent	1/13/84
RESPONSE ACCEPTED DATE RESPONSE VERIFIED	CLOSED	DATE
	- No control of the second	

CONSUMERS POWER COMPANY MIDLAND ENERGY CENTER

Transmittal No: CSC-7166

Date: January 13, 1984

To: Stone & Webster
P O Box 1963
Midland, MI 48640

Attached To	Partial Response To
*	Complete Response To
	For Your Information
	X Other

Description:

List dated 1-12-84 of Bechtel Construction Personnel trained to commence Status Assessment.

Replacement list dated 1-9-84 of Bechtel Construction Personnel trained to commence Status Assessment. This list apparently was detached from our January 12, 1984 transmitaal.

Signature:

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
DDJohnson, MEC w/a

Date	- Team	Records Ready For Audit	Records Aud Stone/Web	ited by
10-12-83	SYSO8MFE	Hines, Jeffrey 669322		1.77.79
	SYS18LSE	Milke, Fred : 681861		
	H6R3IQR	Hummer, Dirk PDS-460		
	ARA 26SPV4 SPT	Davey, Lance 982939		
	SYSI4EFE	Hatter, Gary 238768		
	ARAQ3RWYEFE	Revich, Mira 272790		
	ARA23RWYEFE	Vine, Edward 671688		
	HGR30MFE	Winter, Robert T+B		
10.2.2.2.3	SYS19 PLNR	Wyse, Stephen 926335		
	ARAQUENYEFE	Trimble, Robert 372425		
	ARA 24RWY EFE	Smith, Jerry 887091		
	ARAQ5SPT	Streib, Willie 582990		
	SYS 18 IFE	Rohloff, Brod. 927534		
	ARA 25GR	Pavledes, Chris 541488		
	ARA23RWYEFE	Patel, Ike 863236		
	ARA 24 RNY EFE			
	ARAQ4 RWYEFE	Kish, Charlie 371732		
	SYS14MFE	Southers, James 360587		
	H6R30MFE	Siebert, Stephen 359936		
	SYS18 EFE	Rabe, Karl 305907		
	ARADSQR	McCluan, Jack 647977		
	SYS14MFE	Hildreth, Tom 267741		
	SYSI4MFE	Easterby, Robert 203729	•	
	ARA 25 PLNR	Demos, Deb :664576		
4,	SYS18MFE	Al-Kadhim, A. 361353		
				•

F : . .

Pate	Team	For Audit	Records Audited by Stone/Webster
1an. 9. 84	Sysolite	Andrey, Steve 783958	
,	1 '	BIS, R.F 757953	
7	545/7PLDR	Beacken Braugh, Thomy 372623	
	1 /	Brown David 327660	
Jan. 9, 84	3,509 848	Chiles, Cheis 967143	
Jan, 9, 84	Sy519888	Callins, Thomas 4/1036	
Jan. 9, 84	Sysogmes	CLAM, AL EGEG	
Inn 9,84	3,508 MFE	CRUZ Jesse 637205	
Jan. 9, 84	Sys/8 5 PV	Cully, George 429254	
JAN. 9, 84	SUSIZMEE	CZAPICKI, RANDI 327686	
Jan. 9, 84	373 80 458	DEEM, Charles 874455	
Jan. 4, 84	Sysobere	FEYED, GORDON 905-923	
Jan. 9, 84	SISIB PLDE	GATES, KER MIT 98 4867	· ·
Jan 9, 84	Sys 16 EFE	G. Juk, Edwar 0.36720049)	
7	1 /	GRIEBEL, ELVIN 544884	
7		GRATHE, TOOD 372003	
Jan. 9, 84	Sysobar	HOSLER, C. 796840	
Jan 9,84	Sys 18 PLAR	King Manci 372631	
JAn. 9, 84	Sys DG EFE		
Jan. 9, 84	Sys 08 Wife	MANNO, JOSEPH 346131	
Jan. 9, 84	3,318 EFE	OGRAM JAMES 381229598	
/	1545/6LSE	PAPENHU 42ED, CON 532918	
)	SysolmfE	PRESENT JAMES 361337	
	SIS 17 PLAR	QUALIZZA, John 908389	
/	SySOB PLAR	Quinn, Howard, 842125	
	SysITLSE	RASHID, MARK 222 191	
	System FE	P. TIER, G. 550221	
Jan. 9, 81	Sys17 mfe	Turley Dollar 327545	
Jan. 9, 84	15,516 mFE.	128BB, David, 757.353 1	

ALCOHOLD BY

bate	Team	Records Ready For Audit	Records Audited by Stone/Webster
an 9,84	Sys16ZFE	Williams, Dan 905834	
an. a 84	AEADTLEE	1.1.1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	
	SUSDATES	WISHESKI, DAVID 927859	
	Sys17 mfE.	P.10' XOWSKI PAUL 348213	
	1		

			•
	1.7		
	<u> </u>		
	1		
	,		



Dean L Quamme Site Manager Midland Project

PRINCIPAL STAFF

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

January 11, 1984

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWC 7020
TRAINING OF CONSTRUCTION PERSONNEL
File: 0400.2, Bl.1.7, 0655 UFI: 99*08, 53*50*04, 06*02
Serial: CSC-7156

Attached is a list of Bechtel construction personnel who have completed their training requirements to commence status assessment. Please contact E H Pillsbury, Bechtel Ext. 7167 to initiate your audit requirements on these individuals.

year Danme

DLQ/DDJ/klp


cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
GAHierzer, Bechtel w/a

Date	Team	Records Ready For Audit	Records Audited by Stone/Webster
Jan 5,84	SYS OL IFE	Andrews, Denive 977390	Secretary Treatment
Jan 5, 84	SYSOL MIFE	Eisenhardt, Elaine 707007	
Jan 5, 84	SYS CL MFE	LOVIE J.F. 347614	
Jan 5, 84	SYS CL MFE	Macatangay, M. 372087	
Jan 5, 84	SYSOL MIFE	Moore, Richard 238700	
gan 5, 84	SYS ON EFE	Hoppe Linara 863625	
Jan 5, 84	SYS 14 EFE	Rambo, Reil 679334	
Jan 5, 84	SYS 14 MFE	Joone, Roy C. 909317	
Jan 5, 84		Sikorski, C. TEB 20842	
Jan 5,84	SK IT EFE	Leigeb, Karay 238544	
Can 5,84	SYS IT IMFE	Storev, Wayne 363577	
Jan 5, 34	S45 17 SPV	Francis, J. W. 283226	
Jan 5, 84	SYS 17 MFE	Nant, 2/214 371435	
Jan 5,84		Adrina, Kivin 905818	
Jan 5,84	SYS 17 MFE	Osmanski, a. 430533	
Jan 5,84	ARH 27 GR	Akery Ren CL-111	
Jain 5,84	ARA 27 CFE	Di Ponio, Stave 327537	
		EDMLGER, E. 327917	
Jan 5,84	ARA 27 CFE	Musial, M. 328428	
		Savory C. 328147	
		Ochmanik, T THE 22455	
Jan 5,84	ARA 29 CFE	Raymond, T. 327678	
Jan 5, 84	ARA 29 CFE	Small, Lug 777363.	THE KLEW PLANT
Jan 5,84	ARA 29 LFE	Well, Can 238479	TARREST CONTRACTOR
,			

*


Date	Team	Records Ready For Audit	Records Audited by Stone/Webster
JAn. 9, 84	SySOLTEE	Andrey Steve 783958	
JAN. 9, 84	Sys 08 mfE	BIS, R. F 757953	
JAD. 9. 84	Sys 17 PLAR	Beacken Braysh, They Jakes	
		Brown, David 327660	
Jan. 9, 84	3+3908,2	Chiles, Ches 967143	
Jan. 9, 84	Sys19EFE	Callins Thomas 4/10.36	
Jan. 9, 84	Sysoames	CLAM, AL EGEG	
Inn 9, 84	SUSDEME	CRUZ Jesse 637205	
		Cully, George 429254	
JAD. 9, 84	Systamfe	CZAPICKI, RANDI 327686	
Jar . 9, 84	5,009 EFE	DEEM, Charles 874-155	
Jan. 4, 84	34306888	FEYEN, GORDON 905-923	
Ian 9, 84	Sys18 PLAR	Gates, Kerm+ 98 4867	
Jan 9, 84	Sys 16 EFE	Gilux, Edwar D36720048)	
Jan, 9,84	Sys14PLDR	GRIEBEL, ELVIN 544884	
Jan. 9, 84	Sysobute	GRATHE, TOOD 372003	
Jan. 9, 84	Sysobar	HOSLER, C 796840	
Jan 9,84	Sys/8 PLAN	King Manci 372631	
JAn. 9,84	Sys Ob EFE	LAPIDUS E. 863471	
Jan. 9, 84	54308 WE	MANNO, Joseph 346131	
Jan. 9, 84	343 BIEVE	OGRAM JAMES 38422 9598	
Jan 9, 84	543/6LSE	PAPENHUYZED, CON 532918	
fan 9, 84	Sisolme	PRESENT JAMES 361337	
Jan. 9, 84	Sys 179cme	QUALIZZA, John 908289	
Jan 9,84	SySOB PLAR	Quinn, Howard, 842125	
Jan. 9, 84	Sys17LSE	RASHID, MARK 222 191	
Jan. 9, 84	Sys06 mfE	P. TER, G. 550221	
		TURLEY, DALLOW 327545	
JAn. 9, 89	5,45,1670FE	WEBB, DAVID, 757.3.53	

Date	Team	Records Ready For Audit	Records Audited by Stone/Webster	
Jan 9.84	SUSTATE	Williams, Dan 905834		
an. 9, 84	AEBATLEE	W.LL. ams, David 921159		
m. 9.84	Sysogife	Wisneski David 92259		
	Sys17 mfE	ZIOLXOUNSKI, PAUL 348213		
			•	
Tribut G. I.				
	les fortes	1 de la companya della companya della companya de la companya della companya dell		





P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107 PRINCIPAL



January 10, 1984

Mr. D. L. Quamme
Consumers Power Company
Midland Nuclear Plant
3500 E. Miller Road
Midland, Michigan 48640

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-008

Re:

Hanger Re-inspecion Program (HRP) CPCo letter Serial CSC 7115

The reference letter identifies hangers that will be subject to varying degrees of inspection by MPQAD.

Please provide the following information for use by CIO in scheduling verification activities and developing sampling plans:

- Identification (Mark #) of all affected hangers
- 2. Tabulation of hangers which fall into each inspection category
- 3. Schedules pertinent to each activity
- 4. Notification of any meetings discussing HRP.
- 5. Copies of relevant correspondence.

S. W. Baranow Program Manager

SWB/fs

cc:
JGKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

8401190368.



STONE & WEBSTER MICHIGAN, INC.

P.O. Box 2325, Boston, Massachusetts 02107

January 10, 1984

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-009

Re:

Hold Point By-Pass CIO Weekly Report #25

CPCo Letter Serial CSC 7110

Page 2 meeting note B of CIO Weekly Report #25 identified a CIO concern regarding by-passing of QC Hold Points as reported in NCR-C00628, C00640 and C00650.

CIO has reviewed the NCRs, additional correspondence and relevant PQCIs and concurs that the hold points were established in Revision 13 of PQCI E-5.0 and that any inspection performed prior to Revision 13 would not invoke a QC hold.

S. W. Baranow Program Manager

SWB/fs

cc:
JJKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

DATE /-//-84 1 0. NO. 14509 1 0. NO. N/A LITE NO. SWOC - 84-007 REF. N/A
N/A
DEAR SIRS: THE FOLLOWING ARE TATTACHED: SENT SEPARATELY:
COPIES PRINTS REPRODUCIBLES APERTURE CAR EACH OF DRAWINGS SPECIFICATIONS
DOCUMENTS NOTES OF CONFERENCE
PLEASE NOTE SENT FOR YOUR
REVISIONS OMISSIONS OMISSI
MICROFILM APERTURE CARDS. APERTURE CARDS OF DOCUMENTS DRAWINGS SHOP DET COMMENTS. HE ENCLOSED COPY OF THIS FORM. IF NOT. PLEASE ADVISE US.
EWITH INVOLVE A PRICE INCREASE. THE SUPPLIER MUST NOTIFY STON IN A DEPINITE ESTIMATE CANNOT BE GIVEN AT THE TIME. OTHERWISE,
) is (are) attached for
4 0

S. W. Baranow Program Manager

STUNE AND WESSTER MICHIGAN, INC.

cc: JGKeppler, US NRC
JJHarrison, US NRC
RJCook, US NRC
RAWells, CPCo
CIO Site File


17th . G EST,

Sheet 1 of 1

STONE & WEBSTER CONSTRUCTION IMPLEMENTATION OVERVIEW MIDLAND NUCLEAR PLANT J.O. NO. 14509			TRACKED ACTION ITEM TRACKED INFORMATION ITEM						
							TRACKED RE	COMMENDAT	TION ITEM
							REFERENCE(S) Meeting, January 6, 1984 - S&W CIO and		UNTRACKED ITEM
			CPCo - General Discussions of open items			HOLD POINT	NOTIFICATION	ON	
CONDITION DETAILS									
Pursuant to the refere	enced meeting it is re	quested th	at CIO be prov	ided copies	of the				
	Pursuant to the referenced meeting it is requested that CIO be provided copies of the reports issued by TERA Corporation for their activities related to design of the								
Midland Nuclear Plant				*					
			Π.,	S (PAGE	X NO				
				CHMENTS	20110				
	INITIATOR/DATE			APPROVED/D	DATE				
DATE RESPONSE REQ'D. 1/30/84	1.11	1-9.84	Melan		-84				
RESPONSE	1/Ellan	1 67	1 cent						
RESPONSE									
				S NO.'S)	□ NO				
			ATTACHMENTS						
EST. CORRECTIVE ACTIO	N RESPONDENT	17	TITLE	DAT	Ε				
COMPLETION DATE	HEO! ONDER!								
RESPONSE ACCEPTED	DATE RESPONSE	VERIFIED/C	LOSED	DATE					



STONE & WEBSTER MICHIGAN, INC.



P.O. Box 2325, Boston, Massachusetts 02107

January 17, 1984

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 FCR/FCN Stop Work Orders Serial No. SWMCP-012

Re:

CPCo letter, DLQuamme to SWBaranow, subject as above, file CSM-0719 of January 16, 1984

CIO has received and reviewed the referenced letter. Based upon this review, the CPCo response is acceptable with one exception. In using designated Status Assessment Prints (SAPs), please clarify how the possibility of receiving a revised document during the 30 day life of a SAP and subsequently using an outdated document will be precluded.

Please include this information in your response to CIO Item Report Number 043 when the report form is returned to CIO. For the remainder of the information required by Item 043, identifying the above referenced letter will be sufficient.

E. Karr

CIO Program Manager

JEK/fs

WGKeppler, US NRC Glen Ellyn, IL JJHarrison, US NRC Glen Ellyn, IL RJCook, US NRC Midland (site) RAWells, CPCo Midland (site) RBKelly, SWEC APAmoruso, SWEC



Deen L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

January 16, 1984

Mr S W Barenow Stone & Webster P O Box 1963 Midland, MI 48640

MIDLAND RNERCY CENTER
FCR/FCN STOP WORK ORDERS
File: B1.1 7, 0460.3 UFI: 99*08, 73* Serial: CSM-0719

As presented during our discussion on January 16, 1984, this letter transmits the actions which have or will be taken to address the concerns identified in MPQAD Management Corrective Action Request/Report (MCARR) DAT-1 and Stone & Webster Construction Implementation Overview Item Number 043.

The specific outline of short-term and long-term corrective actions is given in Attachment 1. Included in this attachment is the discussion on document control actions to be taken in relation to lifting the FCR/FCN Stop Work Orders.

The resolution and document control process for soils are being provided in Attachments 2 and 3. Specifically, as we discussed on January 16, 1984, Soils will work to documents processed through Document Control Stations 8, 10, 13, 24 and 64. The approach toward document distribution for Status Assessment and Quality Verification Program activities, however, has been re-evaluated to provide direct control of distribution from the Field Document Control Center (Station 59). As outlined in Attachment 4, Work Prints and Installation Status Assessment Prints will be processed and controlled. Bechtel Field Procedure FPD-1.000, FPD-3.000 and FPG-7.500 have been revised to address this process. These procedures have been approved on January 16, 1984.

Installation Status Assessment will only utilize "Status Assessment Prints (SAPs)", and Quality Verification will only utilize "Work Prints". Other packaged construction activities where specific documents are utilized and controlled, such as Construction Work Plans (CWFs), will also only utilize work prints. All Status Assessment Prints and Work Prints will be identified as such on the document.

As we discussed, we will continue to release on a discipline-by-discipline basis. We will continue to coordinate this effort with you through Norm Reichel.

If you have any further questions regarding this subject, please do not hesitate to contact me directly.

DLO/DAT/DD

NAN 20 BE

Page 2 CSM-0719 January 16, 1984

CC: JJHarrison, NRC Region III
RJCook, NRC Site
JGKeppler, NRC Region III
RAWells, MEC
NIReichel, MEC
BHPeck, MEC
DDJohnson, MEC
JKMeisenheimer, MEC
DATaggart, MEC

FE-AI-J-586

QA-AI-S-04146

CPCo-MCAR/R-DAT-1

Detailed below is Construction's complete response to the subject MCAR/R.

ROOT CAUSE

Lack of full implementation to established procedures at certain station locations. The magnitude of the revised documents being distributed to the stations has impacted document control compliance following the issue of the Stop Work Order. In order to support actions necessary to correct deficiencies associated with SWO FSW 33-41, several interim registers are being utilized for document control. We regard this as inadequate for long term document control.

CORRECTIVE ACTION TAKEN

SHORT TERM

Improvements In Administrative Coordination During The SWO

Registers and distribution deficiencies noted by MPQAD and/or Stone and Webster have been corrected. We will continue to release documentation for audit by discipline groups. As noted in the MCARR, the magnitude of document distribution associated with the stop work along with our accelerated movement to automated registers has impacted compliance with established procedures. To reduce non-compliances the following actions have been taken or are planned:

- 1. Increasing oral and written communications between document control and recipient organizations. Daily sessions began December 5, 1983 and have included status updates, explanation of documents, procedures and process changes associated with the stop work. Status handou - and other written materials are distributed in the meetings.
- 2. Training sessions for field employees including Bechtel, SMO, MPQAD, and subcontractors who are updating/auditing sticks were held on January 6, 1983. These sessions provided a review of drawing, specification, FSK, one time deviation, vendor, and change paper registers being used on the jobsite, and in addition, the FDDL (Field Document Distribution List).

T/N 54944 Page 1 of 3

- Adding additional supervisory personnel to the document control center to improve the interface with recipient organizations and improve monitoring of the work.
- 4. Increasing levels of register verification due to the accelerated schedule of converting from primarily manual to automated document control register systems. This effort began in early December, 1983.
- Drawing and revision registers will continue to be distributed to document distribution locations for use as a master reference.
- 6. Bechtel management and MPQAD have reviewed and reduced the number of distribution points on site, and the amount of distribution to each location. Both types of reductions will significantly reduce the volume to be reproduced and distributed by FDCC, (Field Document Control Center).

Document Control Actions Associated With Lifting SWD 33-41


Field procedures FPD 1.000 and FPD 3.000 are being revised to incorporate changes in the status assessment print and workprint process. The procedures address the comparison of the registers with any workprint or status assessment print to be used in the field. All workprints and status assessment prints will be distributed from the FDCC (Station 59) and be verified against the Composite Register. Following release of FSO by MPQAD, distribution to existing stick locations will proceed in accordance with procedures. All distribution will originate from the FDCC, utilizing latest Composite Register as reference. Actions taken or planned include:


- 1. Completing the composite registers for drawings, specifications, vendor prints, FSK's and associated change paper incorporating the results indicated on the resolution sheets.
- Revise PD 1.000 and PD 3.000 and instruct document control and field engineering in the new procedures.

LONG TERM

A detailed plan, including forecast completion dates will be submitted by February 10, 1983. A majority of the long term corrective actions were either in the planning or implementation phase prior to issuing of SWO FSW 33-41. These corrective actions were based on internal Bechtel decisions or decisions associated with the implementation of the Master Document Control Center on site. (This is a joint Consumers Power/Bechtel activity initiated in mid 1983). Specific corrective action items that will be undertaken by Bechtel and Consumers Power include:

- Evaluating further the number of distribution points actually required on the jobsite, eliminating distribution points where possible.
- Assigning functional responsibility for the updating of all document distribution locations, regardless of recipient organization, to document control. This will include procedures, training, distribution, updates and routine auditing.
- 3. Completing implementation of a single data base creating a shared, interactive document control register for the project on System 38. This register will serve as a single source of information on document status throughout the project. In addition, the current combination of automated and manual systems, utilizing differing formats and terminology will be reduced to one data base with consistent updating and processing requirements, formats and terminology.
- 4. Improving the accuracy and usefulness of the FDDL (Field Document Distribution List) through regular review by recipient organizations of distribution requirements, followed by regular distribution of the FDDL. The FDDL will also be converted to System 38 from the current automated and manual format.
- Reviewing document control procedures for interface problems, omissions and/or inconsistencies.






bresse . Scalfeche barr BPC. conscoses OK Notes: I. MPGAD seview/contra with 100% of

- Reservement ree Q-lieres FCE/PCNJS. Controls 2. MPGAD squieus/concues wire 100% of with new- & status or semnialist.
 - I MIGAD Soils with cueck Documents Sections Ashingt Accients

		-4		
		-1		
		- 1		
		-3		
		- 1		
		п		
		74	к.	
			¥ .	





RELEASE AND CONTROL OF SOILS WORK

skm 1/1/09

WORK PRINTS

To Readeston FOCE laser FOCE STAMPS TO LOCUTION AS WORK PRINT FOCC Cuecus Paints TO LATEST REGISTER Nove !

> INSTALLATION STATUS ASSESSMENT PRINTS (SAPS)

Moosee / Anen Rocense STATUS ASSESSMENT FDCC Issues REGUALUATE STATUS Por Cunucas | Revisions Assessment READLET Document Chances Review Registers FDEC CHECKS PRINTS DOCC STAMPS CLEIGHTION DATE Revisions/ Cunuces To Documents And Recisters Nove !

Nove: 1 No. West and Status
Assessment Rouns Isses
Desputes France
Desputes Course Course
Égention S') ones

STONE & WEBSTER ENGINEERING CORPORATION



245 SUMMER STREET, BOSTON, MASSACHUSETTS

ADDRESS ALL CORRESPONDENCE TO P.O. BOX 2325, BOSTON, MASS. 02107

BOSTON
NEW YORK
CHERRY HILL, MJ.
DENVER
CHICAGO
HOUSTON
PORTLAND, OREGON
WASHINGTON, D.C.

PRINCIPAL STAFF

PRINCIPAL STAFF

RA* 1/02/DPRP | CONSTRUCTION REPORTS
EXAMINATIONS
CONSULTING
ENGINEERING

PAO | 503 0 cc/43

SGA | L

ENF | File | January 16, 1984

Mr. J. J. Harrison U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

J.O.No. 14358 MPS-45

DOCKET NO. 50-329/330
MIDLAND PLANT - UNITS 1 AND 2
INDEPENDENT ASSESSMENT OF UNDERPINNING
AFFIDAVITS AND RESUMES FOR ADDITIONAL TEAM MEMBERS

Stone & Webster's subcontractor, Parsons Brinckerhoff Michigan, Inc., has found it necessary to supplement their staff assigned to the Independent Assessment Team. In this regard, affidavits and resumes are enclosed for Mr. John P. Oliveira and Mr. Bernard A. Metros. Mr. Oliveira and Mr. Metros meet the independence requirements for this work. The original Parsons Brinckerhoff team members may still participate in the continuing assessment work.

If you have any questions, please contact me at (617) 589-2067.

A. S. Lucks Project Manager

Enclosures

ASL:nsd

MAN 20 1984

£ .

8401240610 SIP

UNITED STATES OF AMERICA MUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

In the Hatter of CONSUMERS POWER COMPANY (Midland Plant, Units 1 and 2) Docket No 50-329 OH 50-330 OH Docket No 50-329 OL 50-330 OL

December 28, 1983

Hy name is Bernard A. Metrosi as employed by Parsons Brinckerhoff/Tudor
Engineer Engineering Company

I am currently assigned to the team which is conducting an independent assessment of soils work at the Midland Muclear Plant site. Prior to being given this assignment, I have never worked on any job or task associated with the Midland Project, or any job or task for or on behalf of Consumers Power Company, Bechtel, or the Mergentime Company relating to soils or underpinning. I have never been employed by Consumers Power Company, Bechtel, or Mergentime Company. *I do not own any shares of Consumers Power Company, Bechtel, or Mergentime stock. Mutual funds or other funds in which I may have a beneficial interest, but over which I have no control, may own shares of Consumers Power Company, Bechtel, or Mergentime stock, of which I am unaware. A list of such funds in which I have an interest are attached. I have no relatives which are or have been employed by Consumers Power Company, Bechtel, or Mergentime Company.

* I was employed by Bechtel as Resident Engineer prior to 1977.

Sworn and Subscribed Before He This 30 Day of 12, 1983.

Notary Public

Jackson County, Michigan

Hy Commission Expires

Donna Tatel - Notary Public Fulton County, Georgia

Notary Public, Georgia, State at Large My Commission Expires Jan. 29, 1985

というには、100mmのでは

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

In the Matter of CONSUMERS POWER COMPANY (Midland Plant, Units 1 and 2)

であるというとうというとはないないないない。 日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ののでは、日本ので

Docket No 50-329 OH 50-330 OH Docket No 50-329 OL 50-330 OL

December 28, 1983

AFFIDAVIT OF	
--------------	--

Hy name is John P. Oliveira I as employed by Parsons Brinckerhoff Tudor
Engineering Company

I am currently assigned to the team which is conducting an independent assessment of soils work at the Midland Muclear Plant site. Prior to being given this assignment, I have never worked on any job or task associated with the Midland Project, or any job or task for or on behalf of Consumers Power Company, Bechtel, or the Mergentime Company relating to soils or underpinning. I have never been employed by Consumers Power Company, Bechtel, or Mergentime Company.* I do not own any shares of Consumers Power Company, Bechtel, or Mergentime stock. Mutual funds or other funds in which I may have a beneficial interest, but over which I have no control, may own shares of Consumers Power Company, Bechtel, or Mergentime stock, of which I am unaware. A list of such funds in which I have an interest are attached. I have no relatives which are or have been employed by Consumers Power Company, Bechtel, or Mergentime Company.

* I was employed as Construction Superintendent for a joint venture of P and Z/Mergentine prior to 1972.

Sworn and Subscribed Before He This 30 Day of 12, 1983.

Notary Public Jackson County, Michigan

Oliveira

Notary Public Fulton County, Georgia

Hy Commission Expires

My commission Expires

Notary Public, Georgia, State of Large
My Commission Expires Jan. 29, 1985

BERNARD A. METROS Resident Engineer

Education Chicago Tech, BSCE, 1954

Experience

Mr. Metros has over 35 years in the heavy construction industry, rising through the ranks from tradesman and foreman to superintendent and Engineer. His experience includes tunnelling, underpinning, highway, highway and railroad bridges, steel mill, water plant, and rapid transit. Mr. Metros' experience also includes the development and implementation of a viable construction program, utilizing native labor and supervisors, in an underdeveloped Asian nation.

Mr. Metros is currently the resident engineer for the Metropolitan Atlanta Rapid Transit Authority (MARTA) performing construction management of three major transit projects: the \$50 million Five Points Station; a \$13 million open cut subway and at-grade line segment; and a \$10 million at-grade and aerial structure line segment. His major responsibilities include contract administration and quality assurance. Construction involved on these projects include soldier file and slurry wall excavation supports systems, tie-back and external bracing of support systems; underpinning; cast-in-place and precast concretes; post tensioned segmental precast concrete members; structural erection; marble, granite and tile architectural finishes and associated electrical and mechanical features.

Previous Experience

As resident engineer for the Washington Metropolitan Area Transit Authority he was responsible for construction management of the \$40 million L'Enfant Plaza Station.

Chief of Construction section, Third Combat Tactical Zone in Vietnam. Mr. Metros was responsible for development and implementation of a \$120 million construction program utilizing indigenous labor and contracting forces. This program was non-existent prior to this effort and involved supervision of design, specifications, awarding of contrac, and construction management.

Resident engineer for the City of Chicago, Department of Public Works, Division of Bridges and Viaducts. Mr. Metros was in complete control of the following projects which involved dredging, cofferdam construction, sewer and road construction, and movable and fixed bridges with related electrical and mechanical work...

- o Railroad Underpass at 40th and Ashland.
- o Fixed Bridges at Archor and Ashland.,
- o The East 95th Street Movable Bridge.
- o The Halsted Street River bridge over the North Branch of the Chicago River.
- o The Damen Avenue Sky-Way which extends for one and one quarter miles over railroad facilities.

JOHN PATRICK OLIVE!RA
Technical Specialist for Tunneling and Underpinning

Education

Johns Hopkins University, B.S. Chemical Engineering, 1963

Mr. Oliveira is a technical specialist for tunneling and under pinning and has served in the technical services division of the firm's joint venture for construction of the Metropolitan Atlanta Rapid Transit Authority (MARTA) system. In nearly 20 years of construction experience, he has worked on several stations and line sections of both the MARTA system and, with other firms, the Washington Metropolitan Area Transit Authority (WMATA) subway system in Washington, D.C.

He is coauthor of a monograph on tunnel photography for the Urban Mass Transportation Administration. His work with the firm includes several roles at the MARTA rapid transit project in Atlanta:

- MARTA technical specialist responsible for pile load tests; concrete and painting tests; instrumentation for stress analysis; and inspection of plant-fabricated structures.
- MARTA field inspector for drilling and blasting, steel-setting, and shotcreting phases of tunneling. In this capacity, he worked on several types of tunneling: compressed air, soft-ground, and hard-rock.
- MARTA building underpinning inspector. Mr.
 Oliveira worked on the underpinning of the Continental Insurance Building and the Merchandise Mart. The work involved installation of rock dowels and bolts, installation of tie backs, cut-and-cover, and shotcrete.

Previous Experience

Pile driver foreman for a foundation company,
 Bethesda, Maryland. Mr. Oliveira was foreman for pile

driving and for sheeting, shoring, and foundation work, including setting up and laying out.

Mr. Oliveira participated in various phases of construction of the WMATA system as an employee of three firms:

- Underpinning superintendent for a New York City firm working on the WMATA system. He supervised the underpinning of buildings for the Clarington Station.
- Employee for another New York City underpinnin and foundation company working on the WMATA system. He worked on underpinning of buildings for the 7th Street subway station, including work with welding machines, hydraulic pumps, and jacks.
- Foreman for shaft and tunneling operations for three stations of the METRO system and foreman for underpinning and sheeting and shoring of a fourth station, all while employed as miner and miner foreman for a Washington, D.C., firm. The stations for which he was foreman for shaft and tunneling operations were Union Station, 9th Street Station, and G Street Station; he was foreman for underpinning and sheeting and shoring for the National Gallery Station.

Publications

 Monograph on Tunnel Photography (coauthor), UMTA-GA-06-0007-81-1, March 1981.



1 Warrick

Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

January 12, 1984

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640 MIDLAND ENERGY CENTER GWO 7020

PQCI'S FOR MODULE 340 AND AUDIT REPORT MSA-83-39

File: 0655, B1.1.7 UFI: 53*50*04, 99*08 Serial: CSC-7160

18.4, 0460.3 73*03*03

Attached per your request is the subject information. Please note that the item regarding PQCI's to be used in the Quality Verification and Status Assessment in Module 340 was provided to you on January 11, 1984.

DLQ/DDJ/klp

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD w/o
BHPeck, MEC w/o
NIReichel, MEC w/o

To Stone & Webster

Store of webster

your

On January 11, 1984, in a discussion between our Mr. D. F. Ronk and Stone & Hebster, your Mr. Walter Sienkiewicv, requested a list of PQCIs expected to be used in the Quality Verification & Status Assessment of Module 340. The requested list is as follows:

We expect to utilize the following PQCIs to verify closed inspection records (IR) associated with Module 340.

C -	1.10	C	-5.10	E -2.0
C -	1.31	C	-7.00	E -2.1
c -	1.40	C	-8.51	E -1.2
C -	4.00	. W	-1.00	C -1.52
C -1	6.00	CI	W-1.00	P -1.90
C -	8.50	R	-1.00	P -2.30
C -	1.50	E	-1.0	PI-1.90
C -:	2.10			

We expect to use the following PQCIs, in addition to some of those listed above, in the Status Assessment program of Module 340.

			AIN
E	-1.10	P -2.10	PI -1.40
E	-6.0	P -2.20	PW -1.00
P	-1.00	T -1.00	PIW-1.00
P	-1.10	MP -1.00	WR -5
-	-1.20	PE -1.10	C -1.20
P	-1.30		

At this time, the association of IRs with Module 340 is not complete. We will provide any additional PQCIs that are expected to be used in Module 340 as they are determined.

Please contact D F Ronk at extension 7155 if you have any question; regarding this matter.

cc RAWells DFRonk BMPalmer



AUDIT REPORT

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

DATE OF ISSUANCE

1/10/84

PAGE 1 OF 5

DISTRIBUTION: SBaranow	HPLeonard	ALAB-2	AUDIT 30:
JABauer	BWMarguglio/DJones	THGamon	MSA-83-39
AEBice	JKMeisenheimer	WAHedzik	FILE NUMBER:
WRBird/JPKnight	JAMooney	MDewitt	18.4
JEBrunner	DHQuamme	DHorn	DATE OF AUDIT:
RBCameron JWCook	JARutgers RCSember	HPerrine JLWood SZeller	12/12/83 - 12/22/83
RJErhardt GFEwert WJFriedrich	DATaggart RAWells JLWood		MPQAD - Soils/BOP/HVAC
SIG. OF AUDIT TEAM LEADER	Timen 1-10 87 PROVED BY/DAY	Z:	PLANT & PROJECT:
W. a. Hes Hi	TITIY RC Pen	1-1/10/84	Midland 1 & 2

I. OBJECTIVES & SCOPE

The objective of this audit was to evaluate the adequacy and implementation of the following quality system requirements: NCR/QAR processing and resolution systems.

The scope of the audit included preparation, processing, resolution, voiding and close out of nonconformance problems documented by NCRs and QARs. Included in the scope are MPQAD Soils, HVAC and BOP activities as well as the Nutech NCR reconciliation program.

II. AUDIT TEAM

4

The Consumers Power Company audit team consisted of the following personnel:

T H Gamon - Audit Team Leader

W A Hedzik - Acting Audit Team Leader

G V Wenninger - Auditor

R B Cameron - Auditor-in-Training

J Nicholas - Auditor-in-Training

R Carvel - Auditor-in-Training

W Gratza - Auditor-in-Training

III. PERSONNEL CONTACTED DURING AUDIT

The following personnel were contacted during the course of the audit:

NAME	COMPANY	TITLE	ENTRANCE	AUDIT	EXIT
F H Schulmeister	CP Co	MPQAD-PAE	х		
J P Knight	CP Co	DQAE - Jackson	X		X
S D DePillo	CP Co	MPQAD - Soils	X	х	7.
J Abeles	Nutech	QA Manager	X	X	
G B Sanders	Nutech	Eng. Manager	х.	X	
S Cox	CP Co	HVACA - Adm. Supv.	X	X	
G Parker	CP Co	PAE	X		
C Miller	BPCo	Res. QE, Group Lead	X		X
J L Wood	CP Co	HVAC - Asst. Supt.	X	X	
				F-14-6A (REV. 0)



ALJIT REPORT

MIDIAND PROJECT QUALITY ASSURANCE DEPARTMENT

CONTINUATION SHEET

AUDIT NO. MSA-83-39 TAGE 4 OF 5

V. C. OBSERVATION #2

Several NCRs reviewed during the audit have careless errors, indicative of insufficient attention to detail, such as:

- A. NCR #C-00344 prepared on 9/7/83, reviewed on 9/19/83 and a change indicated on 7/8/83.
- B. NCR #C-00537 Block #8 not checked.
- C. General Blank continuation sheets included with NCRs.
- D. General Questionable trend codes.

(Attention W Friedrich, items A & B) No response required, A thru D.

OBSERVATION #3

A review of MB-FP-8, Open Nonconformance Reports, revealed that some of the reports were not completed in a clear and structured manner. It was stated by HVAC that all the open NCRs will be transferred to the applicable form in the upcoming revision of F-2M. This is being accomplished to provide consistancy and at the same time will provide for clearly defining the extent of the NCR, i.e. references, requirements, violations and resolutions. (Attention J L Wood/H Perrine) No response is required.

D. Exit Meeting

An exit meeting with those personnel identified in Section III of this report was conducted on December 22, 1983. During this meeting, the results of the audit were presented.

VI. PROGRAM EVALUATION OF EFFECTIVENESS

The system for processing and resolution of NCRs and QARs was found to be an effective means of identifying potential problems.

The AFRs and URIs issued as a result of this audit are of an administrative nature. They represent what appears to be a lack of attention to conformance of procedure detail, i.e. data not recorded or improperly recorded, inconsistent status of NCRs/QARs, insufficient data, missing tags. Some examples are AFRs OIF, O2F, O4F, O5F, 13F and 14F.

It is recommended that personnel involved in the processing and resolution of NCRs/QARs and their maintenance, i.e. logs, files, working systems, be instructed in the importance of maintaining these important documents to program requirements as described in the procedures. Periodic training classes or retraining classes should be established and conducted to continuously familiarize personnel to both

(continued)

F-1M-6B (R2. 0)



AUL T REPORT

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

CONTINUATION SHEET

AUDIT NO. MSA-83-39 PAGE 5 OF 5

VI. PROGRAM EVALUATION OF EFFECTIVENESS (continued)

present and revised procedure administrative requirements. The responsible supervision of the personnel involved in these activities should assure continued adherence to procedure requirements by periodic assessment of personnel performance.

Please note that although these conditions exist, there is no evidence at this time that installed plant hardware has been compromised.

VII. CLOSING ITEMS

All responses and corrrespondence related to this audit shall be forwarded to R C Sember, Branch Head, Audit Branch, who will be responsible for the review and verification of the corrective action.

Written responses are to be received no later than the dates noted on the individual AFRs and URIs.

VII. ATTACHMENTS

Audit Finding Reports MSA-83-39-01F to MSA-83-39-14F Unresolved Items MSA-83-39-01U to MSA-83-39-05U Audit Plan (File 18.4 Only) Audit Checklists (File 18.4 Only) Audit Notification Letter



N/A

R A Carvel

AFR ORIGINATOR'S SIGNATURE/DATE:

C/A VERIFICATION SIGNATURE:

AUD. FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

Soils S/U: XXXOR DISCP: TREND: R-5 AREA: QA AFR SER NO: "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS NEEDED" COMDITION WITH REFERENCES: MSA-83-39-01F MPQAD Procedure M-4, Rev 4, 8/29/83, states in part: PROJ/DEPT AUDITED: MPOAD -(Para. 2.0 note) that QARs generated prior to 8/29/83 shall Soils/BOP/HVAC be completed in accordance with MPQAD Procedure M-4, Rev 3, 1/10/84 Para 5.1 which states QAR originator "shall log each QAR FILE NUMBER: 16.0 issued in QAR Log, Att. B." ACTION ITEM SO: S04264 Contrary to the above, in the Soils area, QARs issued prior DISTRIBUTION: to 8/29/83 are not being recorded for status on the QAR Log SBaranow **JARutgers** form. The form being used did not reflect all required JABauer RCSember information from Att. "B" form, and as an example did not AEBice DATaggart WRBird/JPKnight RAWells reflect the correct status of QAR F-363. The QAR is recorded JEBrunner JLWood as open but is actually closed. RBCameron ALAB-2 OHorn JWCook RJErhardt **RACarvel** B. MPQAD Procedure M-4, Rev 4, 8/29/83, Para B 11, Att. 7.2 GFEwert requires QAR reviewer to complete blocks 11 & 12 on QAR Form WJFriedrich indicating potential reportability and date reported to the **HPLeonard** BWMarguglio/DJones MPQAD Manager. JKMeisenheimer (continued) JAMooney **DHQuamme** RECOMMENDED CORRECTIVE ACTION: A. (1) Record all QAR Log entries on proper log form (2) Review status of all QARs indicated as open in the Log and provide additional information for log entries as necessary to indicate closed QARs. (3) Instruct personnel in requirements for maintenance of QAR Log. (continued) CORRECTIVE ACTION CUMMITMENT: Response due by 1/31/84. DATE OF C/A COMPLETION: PERSON MAKING C/A COMMITMENT: ORG. RESP FOR C/A: DATE OF C/A EFFECTIVENESS: MPQAD - Soils D Horn METHOD OF VERIFICATION: IF "YES", DATE OF REPORT TO MRC: IS AF REPORTABLE PER 50.55(e): YES NO X N/A IF "YES", NAME OF MRC OFFICIAL TO WHOM REPORTED: IF "YES", TIME OF REPORT TO MRC: N/A IF "YES", WHO MADE REPORT:

48/11/1 M 11/1

1100

ATL SIGNATURE/DATE:

waite- (1 +42 3 2 1/10/84

N/A



AUDIT-FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE

CONTRACTOR SELECT

MSA-83-39-01F

Page 2 of 2

IS CONDITION TRACE "AS REQUEED" CONDITION WITH REFERENCES (CONTINUED):

B. Continued

Contrary to the above, in the Soils area, two QARs (S-00033, 10/3/83 and S-00058, 11/7/83) did not exhibit entries in blocks 11 and 12.

COMMENDED CORRECTIVE ACTION: (continued)

- B. (1) Review all QARs issued by Remedial Soils Group since 8/29/83 for completion of blocks 11 & 12. As an example, in the Soils area, two QARs (S-00033, 10/3/83 and S-00058, 11/7/83) did not exhibit entries in blocks 11 and 12.
 - (2) Evaluate each deficient QAR, including S-00033 and S-00058 for reportability.
 - (3) Revise affected QARs as necessary.



Soils

AUD T FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE

AREA: QC

DISCP: F

TREND: R-5

PRIORITY:

AFR SER NO:

DEPARTMENT XXXOR

"AS IS" CONDITION VERSUS "AS REQUIRED"/"AS NEEDED" CONDITION WITH REFERENCES:

MPQAD Procedure F-2M, Rev 6, Att. A, Para 7.5.2.1 entitled "NCR Voiding Instructions" states that when voiding an NCR, "the NCR originator shall indicate concurrence with the decision to void the NCR by signing in the Disposition Block."

Contrary to the above:

- Voided BOP NCR Number A-00019 has not been signed in block A. #35 by the originator.
- NCR S-00579, Soils, written on 11/15/83 and voided on 11/23/83 was not signed in block #35 by the originator.

MSA-83-39-02F PROJ/DEPT AUDITED: MPQAD -Soils/BOP/HVAC

DATE OF ISSUANCE:

1/10/84

FILE NUMBER:

16.0

ACTION ITEM SO:

504265

DISTRIBUTION:

JARutgers SBaranow RCSember JABauer DATaggart AEBice WRBird/JPKnight RAWells JLWood JEBrunner ALAB-2 RBCameron DHorn JWCook RACarvel RJErhardt WGratza GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones

JKMeisenheimer JAMooney DHQuamme

RECOMMENDED CORRECTIVE ACTION:

CORRECTIVE ACTION CONCEMENT:

(1) Have originator sign and date block #35 of BOP NCR A-00019.

Response due by 1/31/84.

- Revise and reissue BOP NCR A-00019. (2)
- Review existing voided NCRs for Att. 7.5 requirements and make corrections as required (BOP-HPerrine)

(continued)

PERSON MAKING C/A COMMITMENT: DATE OF C/A COMPLETION: ORG. RESP FOR C/A: MPQAD - Soils D Horn DATE OF C/A EFFECTIVENESS: MPOAD - BOP H Perrine METHOD OF VERIFICATION:

IS AF REPORTABLE PER 50.55(e): IES	IF "YES", DATE OF REPORT TO NRC: N/A
IF "YES", TIME OF REPORT TO MRC: N/A	IF "YES", NAME OF MRC OFFICIAL TO WHOM REPORTED:
IF "YES", WHO MADE REPORT:	N/A
R A Carvel/W Gratza	water Cr. Hoth 1/10/84
C/A VERIFICATION SIGNATURE:	TERIFICATION DATE: () F-1M-4A (REV.



AUD FINDING REPORT CONTINUATION SHEET

MSA-83-39-02F

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT Page 2 of 2

"AS IS CONDITION VERSUS "AS REQUIRED" COMDITION WITH REFERENCES (CONTINUED):

RECOMMENDED CORRECTIVE ACTION (CONTINUED):

- B. (1) Have originator sign and date block #35 of Soils NCR S-00579.
 - (2) Revise and reissue Soils NCR S-00579.
 - (3) Review existing voided NCRs for Att. 7.5 requirement and make corrections as required. (Soils - DHorn)
 - (4) Retrain Soils and BOP personnel responsible for originating and reviewing MCRs in the procedural requirements for voiding NCRs.

CORRECTIVE ACTION (CONTINUED):



R A Carvel

C/A VERIFICATION SIGNATURE:

111 34

Soils AUTT FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE

DEPARTMENT

AREA: QA TREND: R-5 S/U: DISCP: F XXXOR AFR SER NO: "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS MEEDED" CONDITION WITH REFERENCES: MSA-83-39-03F MPQAD Procedure F-2M, Rev 6, effective 8/29/83, Control of PROJ/DEPT AUDITED: MPOAD Nonconforming Items , Para 2.0, Note, states that existing CP Co Soils/BOP/HVAC NCRs as of 8/29/83 shall be closed using MPQAD Procedure F-2M, DATE OF ISSUANCE: Rev 5. 1/10/84 FILE NUMBER: 16.0 MPQAD Procedure F-2M, Rev 5, Para 5.6, states that "the Group ACTION ITEM SO: Supervisor, Administration, shall be responsible for maintaining 504266 a file copy of each NCR ... " DISTRIBUTION: SBaranow JARutgers Contrary to the above, while reviewing three open CP Co NCRs, it RCSember JABauer was noted that a copy of NCR #MO1-9-3-051 was not present in DCC. DATaggart AEBice This NCR was signed out by an inspector on 11/3/83 and neither it WRBird/JPKnight RAWell's JLWood JEBrunner nor a copy was on file in DCC from that time until 12/15/83 when ALAB-2 RBCameron the audit was performed. JWCook DHorn RACarvel RJErhardt **GFEwert** WJFriedrich **HPLeonard** BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: (1) Review Soils DCC NCR files to verify that a copy of each open NCR is present. (2) Recall all original copies of dispositioned NCRs checked out of the files and obtain copies for the file. Reinstruct Soils DCC personnel on the requirement for maintaining copies of open NCRs in the DCC files. Response due by 1/31/84. CORRECTIVE ACTION CONGINERY: DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A COMMITMENT: DATE OF C/A EFFECTIVENESS: MPOAD - Soils D Horn METHOD OF VERIFICATION: IF "YES", DATE OF REPORT TO MRC: IS AF REPORTABLE PER 50.55(e): TO X YES N/A IF "YES", NAME OF MRC OFFICIAL TO WHOM REPORTED: IF "YES", TIME OF REPORT TO MRC: N/A IF "YES", WHO MADE REPORT: N/A AFR ORIGINATOR'S SIGNATURE/DATE: WOW 1/10/84 ATL SIGNATURE/DATE:

F-1M-4A (REV.

1/0/87



C/A VERIFICATION SIGNATURE:

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

F-1M-4A (REV. 0)

Consumers AUD! FINDING REPORT

	AREA: QC	DISCP: F	TREND:	R-5	PRIORITY:	2 5/	U: XXX	OR
AS TS" CO	DEDITION VERSUS "AS		DED" CONDITION	WITE REF	REGS:		ER NO:	
	Procedure F-2M					MSA-	83-39-04F	COLUMN TWO IS NOT THE OWNER, THE PARTY OF TH
MPQAD	Para 5.1.2.b	states in par	t the "MPO	AD orig	inator shall	PROJ	DEPT AUDITED	
annly	Hold Tags" to	the nonconfor	ming items			DATE	OF ISSUANCE:	THE RESIDENCE AND ADDRESS OF THE PARTY OF TH
appry	nord rago co					1/1	0/84	
Para	. 5.2.3 states	in part:					NUMBER:	
						16.0		
"T	he PFQCE shall	ensure the c	conditional	ly rele	ased item is	504	267	
"i	dentified"."						RIBUTION:	
							ranow	JARutgers
Para	. 5.2.4 states	in part:					auer	RCSember PATaggart
					to the		ice ird/JPKnight	4.4
"T	he PFQCE shall	l ensure, when	work auth	orized	by the	100	runner	JLWood
co	nditional rele	ease is comple	eted and ju	ist pric	removed "	RBC	ameron	ALAB-2 MDewitt
th	e conditional	release that	the Hold I	ags are	removed.		rhardt	HPerrine
							wert	RACarvel WGratza
Contra	ry to the above	/e:					riedrich eonard	Maracza
	ld tags were	(1	n nonconfo	rming	tems in		arguglio/DJ	ones
A. Ho	cations recor	ded on two NC	Rs issued i	for Soil	ls-related wo	rk. JAM	eisenheimer oonev	
Th	ney are as fol	lows:	(contin		A Charles of the	DHQ	uamme	
_	ED CORRECTIVE ACTIO			/				
	The second second residence				11 W	·n -		
Soils	- (1) Verify	missing tags	s are in p	lace To	fall open NC	15500 av	d PSO-417	
	(2) Replace	te a system t	including	alla wa	rife her same	line or	other me	and that
	Hold Ta	gs are presen	t for open	NCRs.	(MDewitt)		ounce me	,
	HOLG 14	83 are bresen	c tot open	mono.	(IDCTIC)			
						(co	ntinued)	
CORRECTIV	E ACTION COMMITMENT	: Response	due by 1/31	/84				
		Response	ade 0, 1, 5.	,				
DATE OF	C/A COMPLETION:			ORG.	RESP FOR C/A:		PERSON MAKEN	G C/A COMMITMETT:
-	C/A EFFECTIVENESS:			Soi	1s		M Dewitt	
DALE OF	V/A METAVALYMIANA:			100,000	AD - BOP		H Perrin	P
METHOD O	F VERIFICATION:							
				177 "	YES", DATE OF REPO	RT TO NRC		
IS AF REI	PORTABLE PER 50.55(•):	NO X					
			LA			N//		
ma flymat	. TIME OF REPORT TO	Mac.		T "	ES", NAME OF NRC			TED:
		are:						
-	/A			_				
IF "YES"	, WEO MADE REPORT:							
	/ A					N/.	A	
		DATE:	110	d ATT	SIGNATURE/DATE:	N/	A	
AFR ORIG	INATOR'S SIGNATURE	DATE:	1/10/8		SIGNATURE/DATE:	N/.		,
Fertice		PATE: Work 19/8	1/10/8		SIONATURE/DATE:	elzie	1/10/8	4

VERIFICATION DATE:



AUTIT FINDING REPORT

MIDIAND PROJECT QUALITY ASSURANCE DEPARTMENT Page 2 of 2

CONTINUATION SEEM MSA-8

MSA-83-39-04F

"AS IS CONDITION VERSUS "AS REQUIRED" CONDITION WITH REFERENCES (CONTENUED):

- 1. Joils Area NCR #FSO-417 No Hold Tag present on or near dewatering well #502 as stated.
- NCR # S-00500 No Hold Tag present in feed water isolation valve pit #1 and conditional release No. S-00500-01 were not attached to equipment (hydraulic rams) in the same location.
- B. BOP Area
 - 1. NCR A-00108, Rev 0 No Hold Tag located on or near nonconforming "bolt".

RECOMMENDED CORRECTIVE ACTION (CONTINUED):

BOP - (1) Apply Hold Tags to nonconforming "bolt" as identified by NCR-00108.

(2) Initiate a system for verifying Hold Tags are present for open NCRs. (HPerrine)

CORRECTIVE ACTION (CONTINUED):

6	Consumers
T	comhana

AUE T FINDING REPOF

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

F-1M-4A (REV. 0

DEPARTMENT S/U: AREA: HVAC DISCP: M TREND: N-5 PRIORITY: 3 PGMOO "AS IS" CONDITION VERSUS "AS REQUIRED"/"AS MEEDED" CONDITION VITA REFERENCES: AFR SER NO: MSA-83-39-05F Zack Procedure MB-FP-8, Att. 2, Page 3, Para VI.A.3 states: PROJ/DEPT AUDITED: MPQAD Soils/BOP/HVAC DATE OF ISSUARCE: 1/10/84 "The appropriate block of Coluwn #8 is marked in the DR Log." and Para VI.A.6 states: FILE NUMBER: 16.0 "The NCR number is entered in column #9 of the DR Log, if ACTION ITEM SO: 504268 blank #12 of the DR was marked "reject"." DISTRIBUTION: JARutgers SBaranow Contrary to the above, the unsatisfactory half of column #8 of RCSember JABauer the log was checked and a totally unassociated NCR (#A1749) was DATaggart AEBice entered in column #9 while block #12 of DR #106 was marked WRBird/JPKnight RAWell's JLWood JEBrunner "accept". ALAB-2 RBCameron JLWood JWCook RBCameron RJErhardt GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones JKMe i senheimer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: 1. Clerk corrected log entry (line out, initial, date) in view of auditor. 2. Review remainder of DR Log for comparable deficiencies. CORRECTIVE ACTION COMMINENT: Response due by 1/31/84. DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A COMMITMENT: DATE OF C/A EFFECTIVENESS: JLWood MPOAD-HVAC METHOD OF VERIFICATION: IF "YES". DATE OF REPORT TO NRC: IS AF REFORTABLE PER 50.55(e): NO X TES N/A IF "YES", MAME OF MRC OFFICIAL TO WHOM REPORTED: IF "YES", TIME OF REPORT TO MRC: N/A IF "YES", WHO MADE REPORT: N/A N/A 1,0101/1 ansu ATL SIGNATURE/DATE: AFR ORIGINATOR'S SIGNATURE/DATE!

VERIFICATION DATE:

Kull year

R B Cameron S

C/A VERIFICATION SIGNATURE:

9	Consumers Power Company
	AREA:

7.8.1(c) states:

AUC T FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

JARutgers

DATaggart

RCSember

RAWells JLWood

ALAB-2

HPerrine

GVWenninger

BOP-QC

"AS IS" CONDITION VERSUS "AS REQUIRED"/"AS NEEDED" CONDITION WITH REFERENCES:

MPOAD Procedure F-2M, Rev 6, G-3.2, Rev 8, Attachment 7.8, Para

"Changed NCRs shall be reviewed, initialled and dated by the

NCR reviewer and all disposition concurring individuals."

Contrary to this requirement, revisions were made to NCRs A0018

and A0015 without being initialled and dated by all disposition

DISCP: M TREND: I-5 PRIORITY: 2

S/U: PGMOO

AFR SER NO: MSA-83-39-06F

PROJ/DEPT AUDITED: MPOAD Soils/BOP/HVAC

DATE OF ISSUANCE:

1/10/84

FILE SUMBER:

16.0

ACTION ITEM SO:

504269

DISTRIBUTION: SBaranow JABauer AEBice WRBird/JPKnight JEBrunner RBCame ron-JWCook RJErhardt

GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones

JKMeisenheimer JAMooney **DHQuamme**

RECOMMENDED CORRECTIVE ACTION:

concurring individuals.

- 1. Revisions to subject NCRs shall be reviewed by appropriate individuals for concurrence. These individuals shall initial and date referenced revisions. "Late Entry" shall be noted adjacent to all late entries.
- 2. Instruct cognizant individuals in procedural requirements.

CORRECTIVE ACTION COMMITMENT:	Response due by 1/3	1/84.	
DATE OF C/A COMPLETION: DATE OF C/A EFFECTIVENESS:		ORG. RESP FOR C/A:	PERSON MAKING C/A COMMINGET: H Perrine
METHOD OF VERIFICATION:		THE GROWN SOL	n retrine
IS AF REPORTABLE PER 50.55(e):		IF "YES", DATE OF REPORT	TO MRC:

	N/A	
IF "YES", TIME OF REPORT TO MRC:	IF "YES", NAME OF MRC OFFICIAL TO WEOM REPORTED:	
JF "YES", WEO MADE REPORT: N/A	N/A	
AFR ORIGINATOR'S SIGNATURE/DATE:	ATL SIGNATURE/DATE:	
G V Wenninger 4 1! 16 2 2 2 2 1/10/84	Walter a. Herz 1/10/84	
C/A VERIFICATION SIGNATURE:	VERIFICATION DATE:	
	F-1M-4A (REV. 0)	

9	Consumers Company Company	H- AUT	
	AREA:	BOP-QCDISCP:	M

AUT T FINDING REPOFT

TREND: I-5 PRIORITY:

MIDLAND PROJECT QUALITY ASSURANCE PEPARTMENT

"AS IS" COMMITTUE VERSUE "AS REQUIRED"/"AS MEEDEM" COMMITTES WITH REFERENCES:

MPQAD Procedure F-2M, Rev 6, G-3.2, Rev 8, Para 4.5.4 "Note" states in part:

"For "use as is" and "repair" dispositions the NCR reviewer shall ensure that the lead design organization identifies on the NCR the specific design calculations including revisions ... "

Contrary to the above, the "use as is" disposition on NCRs A0015 and A0018 does not reference the specific design calculations used as a basis for the disposition.

AFR SER SO:

MSA-83-39-07F PROJ/DEPT AUDITED:

Soils/BOP/HVAC

DATE OF ISSUANCE:

1/10/84

FILE NUMBER: 16.0

ACTION ITEM SO: 504270

DISTRIBUTION:

SBaranow JABauer AEBice WRBird/JPKnight JEBrunner RBCameron JWCook RJErhardt

JARutgers RCSember DATaggart RAWells JLWood ALAB-2 HPerrine GVWenninger

F-1M-4A (REV. 0)

MPQAD

GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme

RECOMMENDED CORRECTIVE ACTIOS:

1. Project Engineering shall revise NCR disposition to include reference to specific design calculation in addition to the applicable revision.

2. Cognizant engineering personnel shall be retrained in procedural requirements.

Response due by 1/31/84. CURRECTIVE ACTION COMMITMENT: DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A CONCUENTED DATE OF C/A EFFECTIVENESS: MPQAD - BOP H Perrine METHOD OF VERIFICATION:

IS AF REPORTABLE PER 50.55(*): TES NO X	IF "YES", DATE OF REPORT TO MRC:
IF "YES", TIME OF REPORT TO MRC:	IF "YES", NAME OF MRC OFFICIAL TO WHOM REPORTED:
IF "YES", WEO MADE REPORT:	N/A
G V Wenninger 4 / Klinninge 1/10/84	Walter a. Hedzik 1/10/84
C/A VERIFICATION SIGNATURE:	VERIFICATION DATE:



IF "YES", TIME OF REPORT TO MRC:

N/A

AU IT FINDING REPO T

MIDLAND PROJECT QUALITY ASSURANCE

DEPARTMENT PGMOO AREA: BOP-QC DISCP: M TREND: I-5 "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS MEDIED" CONDITION WITH REFERENCES: AFR SER TO: MSA-83-39-08F PROJ/DEPT AUDITED: MPOAD MPQAD Procedure F-2M, Rev 6, Att 7.2, Sect 22 states: Soils/BOP/HVAC DATE OF ISSUANCE: "The person responsible for review of the NCR shall evaluate 1/10/84 the nonconformance for potential 50.55(e) reportability and FILE NUMBER: 16.0 indicate whether or not the nonconformance potentially must be reported to the NRC." ACTION ITEM SO: S04271 Sect. 29 states: DISTRIBUTION: SBaranow JARutgers JABauer RCSember "indicate the cause of the nonconformance." AEBice DATaggart WRBird/JPKnight RAWells JEBrunner JLWoos Block 22 information of NCR A00108 has also been omitted and RBCameron ALAB-2 block 29 on BOP NCR A-00015 has not been completed as required. JWCook HPerrine RJErhardt GVWenninger **GFEwert** WJFriedrich **HPLeonard** BWMarguglio/DJones JKMe i senhe imer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: (1) Review all BOP NCRs for proper entries in block 22 and make corrections as necessary. Change procedure to clarify the requirements for entries made in block 22. (2) Instruct BOP personnel in the requirements for completing and reviewing NCRs. (1) Determine the cause for the nonconforming condition cited in NCR A-00015. Revise NCR A-00015 to include the cause of the nonconformance in block 29 and reissue the NCR. (continued) CORRECTIVE ACTION COMMUNEST: Response due by 1/31/84. DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A CONCINETE: HPerrine DATE OF C/A EFFECTIVENESS: METHOD OF VERIFICATION: IF "YES", DATE OF REPORT TO MRC : IS AF REPORTABLE PER 50.55(e): TES N X N/A

IF "YES", WEO MADE REPORT: N/A N/A AFR ORIGINATOR'S SIGNATURE/DATE: ATL SIGNATURE/DATE: C/A VERIFICATION SIGNATURE:

IF "YES", NAME OF NRC OFFICIAL TO WHOM REPORTED:

F-1M-4A (REV.



AUD'T FINDING REPORT

CONTINUATION SHEET

MSA-83-39-08F

MIDLAND PROJECT
QUALITY ASSURANCE
DEPARTMENT
Page 2 of 2

"AS IS CONDITION VERSUS "AS REQUIRED" CONDITION WITE REFERENCES (CONTINUED):

RECOMMENDED CORRECTIVE ACTION (CONTINUED):

- B. (continued)
 - (3) Retrain the cognizant individual in procedural requirements for completing block 29.

CORRECTIVE ACTION (CONTINUED):



AUD! FINDING REPORT

MIDIAND PROJECT QUALITY ASSURANCE DEPARTMENT

TREND: I-5 HVAC DISCP: COMDITION VERSUS "AS REQUIRED"/"AS NEEDED" COMDITION WITH REFERENCES:

MPQAD Procedure F-2M, Rev 8, Para 5.1.7a states in part:

"Propose or obtain a disposition for the NCR...."

Contrary to the above, it was observed that on NCR H-00023-ZZ the action organization dispositioned the NCR as both rework and scrap/reject.

AFR SER SO: MSA-83-39-09F PROJ/DEPT AUDITED: MPQAD

PGMOO

Soils/BOP/HVAC

1/10/84 FILE NUMBER:

16.0

S/U:

ACTION ITEM NO: S04272

DISTRIBUTION:

JKMeisenheimer JAMooney

SBaranow JARutgers JABauer RCSember DATaggart AEBice RAWells WRBird/JPKnight JLWood JEBrunner RBCameron ALAB-2 JWCook JLWood JNicholas MADietrich RJErhardt GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones

RECOMMENDED CORRECTIVE ACTION:

- Initiate a review of all F-2M, Rev 8 NCRs and verify that each nonconformance has only one disposition.
- Document and report results of review to MPQAD Audit Branch. (2)
- (3) H-00023-ZZ and any other NCR with more than one disposition should be evaluated and properly dispositioned.

CORRECTIVE ACTION COMMITMENT: Response due by 1/31	1/84.	
DATE OF C/A COMPLETION:	ORG. RESP FOR C/A:	PERSON MAKING C/A COMMITMENT:
DATE OF C/A EFFECTIVENESS:	MPQAD-HVAC	JLWood
METHOD OF VERIFICATION:		
IS AF REPORTABLE FER 50.55(e):	IF "YES", DATE OF REPORT T	O NRC:
[]		N/A
IF "YES", TIME OF REPORT TO MRC:	IF "YES", NAME OF NRC OFFIC	CIAL TO WHOM REPORTED:
IF "YES", WEO MADE REPORT: N/A		N/A
J Nicholas Mile & Victoria 1/10/54		Helzit Molor
C/A VERIFICATION SIGNATURE:	VERIFICATION DATE:	3
		F-1M-4A (REV. 0



AUD! FINDING REPORT

MIDLAND PROJECT
QUALITY ASSURANCE
DEPARTMENT

"AS IS" COMDITION VERSUS "AS REQUIRED"/"AS NEEDED" CONDITION WITH REFERENCES:
MPQAD Procedure F-2M, Att. 7.7, Para 5.2.3 states in part:

HVAC DISCP:

"The PAE Supervisor/PFQCE shall complete the form in accordance with the completion instructions, ensure the conditionally released item is identified and distribute copies of the approved CR...."

Contrary to the above, on NCR #H00023-ZZ and CR #H-00023-ZZ-01,

- 1. NCR block 32 was marked that there was no CR issued,
- 2. CR block 13 (distribution) was not completed,
- 3. CR Log did not show that the CR was closed out.

This is the only conditional release issued under Procedure F-2M.

3 S/U: PGMOD

AFR SER NO:

MSA-83-39-10F

PROJ/DEPT AUDITED: MPQAD Soils/BOP/HVAC

DATE OF ISSUARCE:

1/10/84

FILE SUMBER: 16.0

ACTION ITEM SO: S04273

DISTRIBUTION:

SBaranow JARutgers JABauer RCSember AEBice DATaggart WRBird/JPKnight RAWells JEBrunner JLWood RBCameron ALAB-2 JWCook JLWood RJErhardt **HPerrine** GFEwert JNicholas

RJErhardt GFEwert WJFriedrich HPLeonard BWMarguglio

DHQuamme

BWMarguglio/DJones JKMeisenheimer JAMooney

RECOMMENDED CORRECTIVE ACTION:

- 1. Where this is an isolated case, correct the recorded errors,
- 2. Have the responsible personnel attend training to improve their knowledge of this area.

CORRECTIVE ACTION COMMITMENT: Response due by 1/31/84.

DATE OF C/A COMPLETION:

DATE OF C/A EFFECTIVENESS:

CRG. RESP FOR C/A:

PERSON MAKING C/A COMMITMENT:

MPQAD - HVAC

J L Wood

METHOD OF VERIFICATION:

IS AF REPORTABLE PER 50.55(e):	IF "YES", DATE OF REPORT TO NRC:
IF "YES", TIME OF REPORT TO MRC:	IF "YES", NAME OF MRC OFFICIAL TO WEOM REPORTED:
IF "YES", WEO MADE REPORT: N/A	N/A
J dicholas (June A Midle 1/1:154	WATE SIGNATURE/DATE:
C/A VERIFICATION SIGNATURE:	VERIFICATION DATE: 0




AUD FINDING REPOR

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

F-1M-4A (REV. 0)

AREA: BOP-OC-E DISCP: E TREND: I-5 PGMOO AFR SER NO: "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS NEEDED" CONDITION WITH REFERENCES: MSA-83-39-11F QAPP Vol II, Procedure No. 14-1, Page 5, Para 4.3.1 requires that PROJ/DEPT AUDITED: MPOAD the NCR be tracked from the time of its identification through Soils/BOP/HVAC its closure. NCRs, per F-12M, App A are a permanent QA Record DATE OF ISSUANCE: which are required to be controlled, completed and the originals 1/10/84 or legible copies turned over to DCC. FILE NUMBER: 16.0 Contrary to the above, the F-2M, Rev 6 requirements for handling ACTION ITEM SO: 504274 the original NCR are inadequate. The procedure does not state how the NCR original is to be handled between Paras 5.1.6e and DISTRIBUTION: **JARutgers** SBaranow 5.1.10e and between Paras 5.1.10e and 5.1.13,c,4. (i.e. Para RCSember JABauer 5.1.2d = NCR to NCR reviewer, Para 5.1.6e = from NCR reviewer to DATaggart AEBice RAWells action organization, Para 5.1.10c = from NCR reviewer to action WRBird/JPKnight JLWood JEBrunner organization, Para 5.1.13,c,4 = from assigned Inspector to DCC.) ALAB-2 RBCameron **HParrine** JWCook Furthermore, Para 6.0 appears to conflict with the requirements WGratza RJErhardt of Para 5.1.3.c.4. In 6.0, either the NCR reviewer or the PAE GFEwert WJFriedrich Supervisor or the PFQCE shall submit the NCR to DCC. 5.1.3.c.4 **HPLeonard** requires the assigned Inspector to submit it to DCC. BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: (1) It is recommended that the procedure be revised to better define the handling of the original NCR and that the conflicts identified be resolved. One method of accomplishing improved and clearer control of the original NCR would be to have the DCC maintain control of the original NCR at all times and obtain necessary information, signature, etc. under the control of a DCC messenger. (Hand carry NCR to signees.) CORRECTIVE ACTION CONCLIMENT: Response due by 1/31/84. DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A COMMITMENT: DATE OF C/A EFFECTIVENESS: MPQAD - BOP H Perrine METHOD OF VERIFICATION: IF "YES", DATE OF REPORT TO NRC: IS AF REPORTABLE PER 50.55(e): TES X OF N/A IF "YES", NAME OF MRC OFFICIAL TO WHOM REPORTED: IF "YES", TIME OF REPORT TO MRC: N/A IF "YES", WEO MADE REPORT: N/A N/A AFR ORIGINATOR'S SIGNATURE/DATE: wax 1/10/24 ATL SIGNATURE/DATE: w Wratha 1/10/84 W Gratza C/A VERIFICATION SIGNATURE:



AUD FINDING REPORT

MIDLAND PROJECT QUALITY ASSURANCE

TREND: I-5 PRIORITY: CONDITION VERSUS "AS REQUIRED"/"AS NEEDED" CONDITION WITH REFERENCES:

Procedure F-2M, Rev 6 (NCR) and Procedure M-4, Rev 4 (QAR) both reference procedure "M-2, Trend Analysis" which requires in part "that MPQAD personnel who initiate a trended document shall annotate the document with a trend code within 4 hours of the time the document was originated." (Para. 5.1. Also, when hardware is involved, a number (Para. 5.4.4) shall be included. Para. 5.4.4 and Para. 3.1 (per DR #168) require when hardware is involved, that the number of nonconforming conditions applicable to the nonconforming category be added in parenthesis next to the trend code.

Contrary to the above, NCRs reviewed during the audit generally lacked the additional entry of the number of nonconforming conditions applicable to the NCR. Also, it was noted that there were long time delays between the date of NCR initiation and trend code placement on the NCR by the reviewer. In one case, the delay was 4 days.

(continued)

DEPARTMENT

PGMOO

AFR SZR NO:

MSA-83-39-12F

MPQAD PROJ/DEPT AUDITED: Soils/BOP/HVAC

DATE OF ISSUANCE:

1/10/84

FILE NUMBER:

16.0

ACTION ITEM SO:

S04275 PISTRIBUTION:

SBaranow JABauer AEBice

JARutgers RCSmber DATaggart RAWells JLWood

WRBird/JPKnight JEBrunner RBCameron JWCook

ALAB-2 **HPerrine** WGratza

F-1M-4A (REV. 0)

RJErhardt GFEwert WJFriedrich **HPLeonard**

BWMarguglio/DJones JKMeisenheimer

JAMooney **DHOuamme**

RECOMMENDED CORRECTIVE ACTION:

- (1) It is recommended that the key elements of M-2 be included in F-2M and M-4 and conflicts between the procedures be resolved. This includes the M-2 requirement of the 4 hour time limit.
- (2) NCRs written under F-2M, Rev 6 be reviewed for the incorporation and/or condition of

M-2, Para 5.4.4 reduirements.		
CORRECTIVE ACTION COMMITTEE: Response due by 1/	31/84.	
DATE OF C/A COMPLETION: DATE OF C/A EFFECTIVENESS:	MPQAD - BOP H Perrine	
METHOD OF VERIFICATION:		
IS AF REPORTABLE PER 50.55(+): TES NO X	IF "YES", DATE OF REPORT TO MRC:	
IF "YES", TIME OF REPORT TO MRC: N/A	IF "YES", MAME OF MRC OFFICIAL TO WEOM REPORTED:	
IF "YES", WHO MADE REPORT:	N/A	1
W Gratza W Drefige 1/10/10 Was	1010 Watter Gettelet	
C/A VERIFICATION SIGNATURE:	VERIFICATION DATE:	



AUD T FINDING REPOR CONTENUATION SHEET

MSA-83-39-12F

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT Page 2 of 2

"AS IN COMDITION VERSUS "AS REQUIRED" COMDITION WITH REFERENCES (CONTINUED):

QAR #RA-00022 had a 15 day time delay from date of initiation to placement of the trend code by the reviewer.

There also appears to be a lack of clarity in the two procedures (F-2M & M-4) and M-2 concerning who is responsible for fulfilling the initiation requirement.

Who is responsible for fulfilling the initiation requirement? Procedure M-2 refers to "Personnel who initiate" the trended document; M-4 requires the QAR reviewer and F-2M requires the NCR reviewer.

RECOMMENDED CORRECTIVE ACTION (CONTINUED):

CORRECTIVE ACTION (CONTINUED):

6	Consumers Power
	company

AUD FINDING REPOR

MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

F-1M-4A (REV. 0)

DEPARTMENT AREA: BOP QC E DISCP: E TREND: I-5 P "M00 "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS NEEDED" COMDITION WITH REFERENCES: AFR SER NO: MSA-83-39-13F MPOAD Procedure F-2M, Para 5.1.8,b requires that the concurrence PROJ/DEPT AUDITED: MPOAD of the Field Engineering be obtained for all NCRs dispositioned Soils/EOP/HVAC as rework or scrape/replace for Bechtel items. DATE OF ISSUANCE: 1/10/84 Contrary to the above requirement, NCR #A-50004 is missing the FILE MIMBER: 16.0 Field Engineering concurrence. ACTION ITEM 50: S04276 DISTRIBUTION: SBaranow **JARutgers** JABauer RCSember AEB1ce DATaggart WRBird/JPKnight RAWells JEBrunner JLWood RECameron ALAB-2 JWCook **HPerrine** WGratza RJErhardt **GFEwert** WJFriedrich HPLeonard BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: Recommend correcting the case discovered and reviewing all NCRs under F-2M, Rev 6 for similar concurrance and correcting as required. Response due by 1/31/84. CORRECTIVE ACTION CONCINCAT: DATE OF C/A COMPLETION: PERSON MAKING C/A COMMITMENT: ORG. RESP FOR C/A: H Perrine DATE OF C/A EFFECTSVENESS: MPQAD-BOP METHOD OF VERIFICATION: IF "YES", DATT: OF REPORT TO NRC: IS AF REPORTABLE PER 50.55(e): NO X TES | IF "YES", NAME OF MRC OFFICIAL TO WEOM REPORTED: IF "YES", TIME OF REPORT TO MRC: N/A IF "YES", WEO MADE REPORT: N/A N/A AFR ORIGINATOR'S SIGNATURE/DATE: ATL SIGNATURE/DATE: War · lioliu W Gratza C/A VERIFICATION SIGNATURE:

0	Consumers
9	Company

MIDLAND PROJECT

AUL T FINDING REPORT QUALITY ASSURANCE DEPARTMENT BOP QC E DISCP: S/U: PGMOO "AS IS" COMDITION VERSUS "AS REQUIRED"/"AS MEEDED" COMDITION WITH REFERENCES: AFR SER NO: MSA-83-39-14F QAR Procedure M-4, Rev 4, Att. 7.4 requires, for voided QARs, PROJ/DEPT AUDITED: MPQAD Soils/BOP/HYAC that the void indication, the justification for voiding, and MATE OF ISSUANCE: concurrence by the originator be indicated in the disposition 1/10/84 block #27. . NUMBER: 16.0 Contrary to the above requirement, QAR #RA-00036 is missing the ACTION ITEM SO: void indication, the justification, and the concurrence in block S04277 #27. DISTRIBUTION: **JARutgers** Saranow RCSember JABauer DATaggart RAWells AEBice WRBird/JPKnight JI.Wood JEBrunner ALAB-2 RBCameron **HPerrine** JWCook WGratza RJErhardt GFEwert WJFriedrich **HPLeonard** BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme RECOMMENDED CORRECTIVE ACTION: Recommend correcting existing discrepancy and reviewing existing voided QARs for Att. 7.4 requirements and correcting as required. CORRECTIVE ACTION COMMITMENT: Response due by 1/31/84. DATE OF C/A COMPLETION: ORG. RESP FOR C/A: PERSON MAKING C/A COMMITMENT: DATE OF C/A EFFECTIVENESS: MPQAD-BOP H Perrine METHOD OF VERIFICATION: IF "YES". DATE OF REPORT TO NRC: IS AF REPORTABLE PER 50.55(e): TES NO X N/A IF "YES", MAME OF MRC OFFICIAL TO WHOM REPORTED: IF "YES", TIME OF REPORT TO MRC: IF "YES", WHO MADE REPORT: N/A 1/1017 AFR ORIGINATOR'S SIGNATURE/DATE: ATL SIGNATURE/DATE:

Willy

15 x 1 1 10 14

W Gracza

C/A VERIFICATION SIGNATURE:

F-1M-4A (REV. 0

Company AREA: BOP QA DISCP:	UNRESOLVED ITEM PRIORITY:	MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT S/U:PGMOO Al: S04278
6. LESCRIPTION OF UNRESOLVED ITEM:		1. URI 30:
Procedure F-2M. Rev 6/G-3.2,	Rev 8, Para 5.1.6(e) states:	MSA-83-39-01U 2. PROJ/DEPT AUDITED: MPQ
		Soils/BOP/HVAC 3. DATE OF ORIGINATION:
"The NCR Reviewer shall forganization."	forward the NCR to the action	1/10/84
		16.0
	ocumented objective evidence to sub-	5. DISTRIBUTION:
was not available for audit	forwarded to the action organization	SBaranow RAWells JABauer JLWood
		AEBice ALAB-2 WR3ird HPerrina
		JEBrunner GVWenninger
		RBCameron JWCook
		RJErhardt
		GFEwert WJFriedrich
		HPLeonard BWMarguglio/DJones
		JKMeisenheimer
		JAMooney DHQuamme
		JARutgers RCSember
It is recommended that for r documented objective evidence satisfied.	referenced NCRs the cognizant review ce to substantiate that procedural r	DATaggart er shall provide equirements have been
It is recommended that for r documented objective evidence	referenced NCRs the cognizant review se to substantiate that procedural r	er shall provide
It is recommended that for r documented objective evidence	referenced NCRs the cognizant review se to substantiate that procedural r	er shall provide
It is recommended that for recommended objective evidence satisfied. HPerrine HPerrine HPOAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommented objective evidence satisfied. HPerrine	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISED FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISED FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISID FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISID FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISED FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine HPerrine ACTION REQUISED FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine HPerrine ACTION REQUISED FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISID FROM: MPQAD - BOP	ce to substantiate that procedural r	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine HPerrine ACTION REQUISED FROM: MPQAD - BOP	9. ACTION REQUIRED BY-DATE: 1	er shall provide equirements have been
It is recommended that for recommended objective evidence satisfied. HPerrine ACTION REQUISED FROM: MPOAD - BOP O. RESPONSE TO URL:	9. ACTION REQUIRED BY-DATE: 1	er shall provide equirements have been

14. AFR 30_

ISSUANCE OF

RECEIPT OF ACCEPTABLE RESPONSE

Consumers	MIDLAND PROJECT
POWER MPOAD UNRESCLVED ITEM PRIORITY: 3 SA	U: PGMOD AI: S04279
6. DESCRIPTION OF UNRESOLVED ITEM:	1. URI 10:
MPQAD Procedure M-4, Rev 4, Para 5.1.4 states in part:	MSA-83-39-02U
	2. PROJECT AUDIT: MPQAD Soils/BOP/HVAC
"The QAR Reviewer shall review the need to issue Stop Work	3. DATE OF CRICINATION:
Order."	1/10/84 • FILE 50:
Contrary to the above, the reviewer of QAR-0004-ZZ, stated that he	16.0
did consider the need for a Stop Work Order, however, he had no	SRaranow RAWells
objective evidence that this had been done. The procedure fails to outline how the reviewer ill document this review.	JABauer JLMOOG
	AEBice ALAB-2 WRBird SZeller
	JEBrunner JNicholas RBCameron
	JWCook
	RJErhardt GFEwert
[10] 그런 그는 사람이 아니는 이 가게 있는 것 같아. 그는 동안 된 사람이 되었다.	WJFriedrich HPLeonard
	BWMarguglio/DJones
	JKMeisenheimer JAMooney
이 아니아 그 게 그는 것은 그리고 있는 그리는 그리는 그리는 아니다.	DHQuamme JARutgers
[18] H. L. L. 1986 - T. H.	RCSember
T. AEQUIRED ACTION:	DATaggart
S Zeller	
8. ACTION REQUIRED FROM: MPQAD - A&T 9. ACTION REQUIRED ET-DATE: 1/3	31/84
10. RESPONSE TO URI:	
1995년 1996년 1997년 1일 전 1998년 1일	
성격을 하다 하지만 맛있는데 그렇게 하면 보다 하고 있었다면 하지만 하다.	
J Nicholas James : Wicholas 1/4/34 11918 W. G. Helz &	1/5/54
	LOSED BY-SIGNATURE/DATE:
16. A72 30	
ACCEPTABLE ISSUANCE OF AFR	
	F-1M-5 (PFU A)

		APPENDING TO A STATE OF THE STA
Comsumers Power Company AREA: BOP QA DISCP	UNRESOLVED ITEM PRIORITY:	MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT 3 S/U: PGMOO A1: S04280
6. DESCRIPTION OF UNRESOLVED ITEM:		1. URI SO:
shall review the QAR for potention of Att. 7.5. Att. 7.5	.1.5 requires that the QAR reviewer ential reportability using the inst is the "Reportability Checklist". f by the reviewer indicating the cklist.	Block 3. DATE OF ORIGINATION: 1/10/84 TILE 50:
compliance with 5.1.5 is the	that can be reviewed to verify check-off in block #11. M-4, Rev disposition of Att. 7.5 checklist.	JABauer JLWood AEBice ALAB-2 WRBird SZeller JEBrunner WAGratza RBCameron JWCook RJErhardt GFEwert WJFriedrich HPLeonard BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme JARutgers RCSember
. REQUIRED ACTION:		. DATaggart
If this checklist can be consincluded with completed QARs. Att. 7.5 after it is complete. SZeller 8. ACTION REQUIRED FROM: MPQAD - ACTION REQUIRED FROM: M		he methods of halding
10. RESPONSE TO URI:	y. ACTION REQUIRED BI-DATE	1/31/04
11. URI ORIGINATOR'S SIGNATURE/DATE:	ward 12. ATL'S SIGNATURE/DA	imp.
W A Gratza	1/4/174 W. C. Hel	

14. AFR 30_

13. URI CLOSURE MASED CH:

RECTIPT OF ACCEPTABLE RESPONSE

IF TUANCE OF

15. CLOSED BY-SIGNATURE /DATE:

	TREND: W-5	PRIORITY: 3	S/U: PGMOO AI: S04281
DESCRIPTION OF UNRESOLVED ITEM:			1. URI NO: MSA-83-39-04U
	0.0 0	Leady by Lac	2. PROJ/DEPT AUDITED: MPC
rocedure M-4, Rev 4 requires the eed for a Stop Work Order. Neith orm provides for objective eviden	er the procedure r	or the QAR	Soils/BOP/HVAC 3. DATE OF GRIGHATION: 1/10/84 4. FILE SO: 16.0 5. DISTRIBUTION:
			SBaranow RAWells JABauer JLWood AEBice ALAB-2 WRBird SZeller JEBrunner WAGratza RBCameron JWCook RJErhardt GFEwert WJFriedrich HPLeonard
BEQUIRED ACTION:			BWMarguglfo/DJones JKMeisenheimer JAMooney DHQuamme JARutgers RCSember DATaggart
is recommended that a check-off op Work Order has been considere	on the QAR form i	ndicating that	the need for a
SZeller			
ACTICS REQUIRED FROM: MPQAD - A&T RESPONSE TO URI:	9. ACTION REG	UIRED BY-DATE: 1/31	/84

14. AFR 30_

13. URI CLOSURE BASED ON:

RECEIPT OF ACCEPTABLE RESPONSE

ISSUANCE OF

15. CLOSED BY-SIGNATURE/DATE:

, AREA: BO	P QA DISCP: E		TEM PRIORITY:	504202
No copies availab written prior to the old procedure: QARs and NCRs to	le in DCC of voice 8/29/83. Retents s. However, F-12	ion was not a 2M, App A does	requirement und require voided	er Soils/BOP/HVAC
				5. DISTRIBUTION: SBaranow RAWells JABauer JLWood AEBice ALAB-2 WRBird HPerrine JEBrunner WAGratza RBCameron JWCook RJErhardt
				GFEwert WJFriedrich HPLeonard BWMarguglio/DJones JKMeisenheimer JAMooney DHQuamme JARutgers RCSember DATaggart
It is recommended requirement so th				the new program.
. ACTION REQUIRED FROM:	HPerrine MPQAD - BOP	9. ACTIO	REQUIRED BY-DATE:	1/31/84
DALGINATOR'S SION		Ward 12.	ATL'S STOTATURE/DAY	Dich 1/9/84
RECEIPT OF ACCIPTABLE RESPONSE	ISSUANCE OF	130 A73		15.0 CLOSED BY-SIGNATURE/DATE:

PRINK	LL ST	AFF	
D/RA	DE DOMES		
A/RA RG	A A		vigt:
340			-71.
EIFT	10	1) 1

P.O. BO) 363, MIDLAND, MICHIGAN 48640

DATE	1/10/84
1 0 NO	14509
P. O. NO.	N/A
LTR NO	SWOC - 84-005
REF.	N/A

TO D. L. QUAMME, COCo Midland (site)

VIA

THE FOLLOWIN	G ARE AT	TACH	ED. SENT SEP	ARATELY:
COPIES _	PRINTS	-		MICROFILM APERTURE CARDS
	DRAWINGS		SPECIFICATIONS	
	DOCUMENTS		NOTES OF CONF	ERENCE

STATUS	PLEASE NOTE	SENT FOR YOUR
☐ FINAL ☐ APPROVED ☐ PRELIMINARY ☐ APPROVED AS REVISED IN SPECIFICATION ☐ NO COMMENT ☐ UNACCEPTABLE ☐ SUGGESTIONS AS NOTED ☒ CLOSED	REVISIONS OMISSIONS ADDITIONS CORRECTIONS COMMENTS	APPROVAL COMMENT USE INFORMATION FILES CONCURRENCE
YOUR ATTENTION IS DIRECTED TO THE FOLLOWIN RELEASED FOR: PABRICATION PURCHASE OF NECESSARY MAT PLEASE REVISE AND SUBMIT PRINTS REPRODUCIBLES MICRO PLEASE RETURN ONE COPY EACH OF THIS MATERIAL BEARING YOUR APPROV PLEASE ACKNOWLEDGE RECEIPT OF THIS MATERIAL BY SIGNING AND RETURN	MICROFILM APERTURE CARDS. OFILM APERTURE CARDS OF DOCUME VAL OR COMMENTS.	

IMPORTANT SHOULD ANY REVISION TO DOCUMENTS OF DRAWINGS RETURNED HEREWITH INVOLVE & PRICE INCREASE. THE SUPPLIER MUST NUTIFY STONE & WESTER PURCHASING DEPARTMENT WITHIN TEN IIIDI DAYS EVEN THOUGH & DEPINITE ESTIMATE CANNOT BE GIVEN AT THE TIME. OTHERWISE, THE PURCHASER WILL CONSIDER THE REVISIONS MADE WITHOUT COST.

The following Closed CIO Item/Hold Point Notification(s) is (are) attached for your action/information:

Item 040	

S. W. Baranow Program Manager

cc: JCKeppler, US NRC
JJHarrison, US NRC
RJCook, US NRC
RAWells, CPCo
CIO Site File

-8401190348 3pp

. TJAN 1 3 19EA

	G WEBSTER	11	EM NUMBER HO	OLD POINT NUMBER	1
CONSTRUCTIO	N IMPLEMENTATION	ল	TRACKED ACTIO	ON ITEM	ヿ
OV	ERVIEW		TRACKED INFO		7
MIDLAND NUCLEA	R PLANT J.O. NO. 14509	一一		MMENDATION ITE	и
		-	UNTRACKED ITE		7
NIR-009	kly Report No. 27	- Innered	HOLD POINT NO		
FCR/FCN Resolution Pr at four stations were ments that had been p not been processed, A file. NIR 009 was is NOTE: This Report is issued the referenced docume is required.	of the register reconciling of the register reconciling of control of reviewed. Although no district of the Resolution No. 55, as used to document the deficit of the Record and Continuity and the item has previous in the	screpanci ution Pro was foun iency.	es were found gram, a drawin d missing from only. As indosed. No furt	with docu- ng that had n a stick dicated in ther action	
DATE RESPONSE REQ'D. N/A	INITIATOR/DATE N/A		INITIATION AP	1-6-84	
RESPONSE		111	/		
re	QAD added drawing A-213 to -sampling was conducted. tisfactory and the item and	hat check	was closed.	(PAGE X NO	
			-	HMENTS)
EST. CORRECTIVE ACTIO	N RESPONDENT	TITE	Ε	DATE	
N/A	N/A		N/A	N/A	
177					
RESPONSE ACCEPTED N/A	DATE RESPONSE VERI		SED	1-6.84	

Sheet 1 of 1 ITEM NUMBER HOLD POINT NUMBER STONE & WEBSTER 040 CONSTRUCTION IMPLEMENTATION TRACKED ACTION ITEM OVERVIEW TRACKED INFORMATION ITEM MIDLAND NUCLEAR PLANT J.O. NO. 14509 TRACKED RECOMMENDATION ITEM REFERENCE(S) C10 Weekly Report No. 27 UNTRACKED ITEM NIR - 010 CIO Weekly Report No. 28 HOLD POINT NOTIFICATION CONDITION DETAILS To check the adequacy of the resolution phase, Phase II, of the FCR/FCN Resolution Program, a sample of civil drawings was reviewed. Resolution sheets for one FCR, FCR C-1526, were found to be ambiguous. The sheets were unclear as to whether the FCR affected both of the drawings listed, C-358 and C-479. NOTE: This report is issued for Record and Continuity Purposes only. As indicated in the referenced documents the item has previously been closed. No further action is required. YES NO.'S) X NO ATTACHMENTS INITIATION APPROVED/DATE DATE RESPONSE REQ'D. INITIATOR/DATE 1.6.84 N/A N/A RESPONSE Field project engineering has issued another resolution sheet, which was reviewed and found acceptable. PAGE X NO YES NO.'S) ATTACHMENTS DATE EST. CURRECTIVE ACTION TITLE RESPONDENT N/A N/A N/A N/A DATE RESPONSE VERIFIED/CLOSED DATE RESPONSE ACCEPTED 1-6.84 N/A N/A



Dean L Quamme Site Manager Midland Project

Midland Project: PO 8ox.1963, Midland, MI 48640 • (517) 631-8650

December 29, 1983

PRINGIPAL STAFF

A LOPPRE

D/RA DE

C/RA DRMSF

RC DRMA

PAO SCS VOUG 13

SGA ML

ENF FILE MAS

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER

FCN/FCR SOILS STOP WORK ORDERS

File: Bl.1.7, 0460.3 UFI: 99*08, 73* Serial: CSM-0714

This is to advise you that the MPQAD Audit of Civil Stations 8, 10, 13, 24 and 64 has been completed and are now ready for the Stone and Webster final audit.

These stations represent the first of the two Civil packages that were described to you in my letter to Stone and Webster of last week. With the successful completion of your audit of these stations, it is our intent to lift the stop work on the soils activities and allow physical work in that area to resume.

Your cooperation in completing your audit functions will be appreciated. If you need any support for the Consumers or Bechtel organizations during your audit activities, please do not hesitate to make your needs known.

DLQ/JKM/kp

cc: JJHarrison, NRC Region III
JGKeppler, NRC Region III
RJCook, NRC - Site
NIReichel, MEC
BHI ck, MEC
DDJohnson, MEC
JKMeisenheimer, QA

-84011000-86



Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

LAB 156-83

December 28, 1983

Mr Stan Baranow Stone & Webster Engineering Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640 PRINCIPAL STAFF

RA CLOPRP

D/RA DE

A/RA DRMSP

C DRMA

PAO SCS VOUG+3

SGA ML

ENF FILE Cas

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF (3) COMPUTER PRINTS

You have been placed on a weekly distribution for the following MPOAD Personnel printouts.

Summary of Inspector Training - PMerritt Personnel Forms - Perschk Item Complete - PBack

These prints will be forwarded to you each Monday until further notice.

GFEwert/LABotimer

Prints for the week of December 26, 1983

DLQuamme, Site Mgr RAWells, MPQAD

8401100384

	D/RA A/RA PC TAO	DE DRMSF DRMA SCS VOUG-13	}		DATE 1/3/	/63 509
VIA	ISGA NE	File				-0003
Г	-		DEAR S	IRS:	N/A	
D. L. OU.	AMME, CPCo Midland	(site)		VING ARE ATT	ACHED: SENT	SEPARATELY:
<u></u>		١	cores	DRAWINGS DOCUMENTS	EACH OF SPECIFICATION NOTES OF C	
	STATUS		PLEASE	NOTE	SENT	FOR YOUR
PRELIMINARY NO COMMENT	UNACCEPTAS	S REVISED AS DEFINED		OMISSIONS CORRECTIONS	USE FILES	COMMENT INFORMATION CONCURRENT
YOUR ATTEN	TION IS DIRECTED	TO THE FOLLOWING				
- PLEASE REVISE	AND SUBMIT PRINTS	PRODUCIBLES MICROFIL TERIAL BEARING YOUR APPROVAL TERIAL BY SIGNING AND RETURNIN	MICROFILM API	05 OF DOCUM		NGS SHOP DE

CIO NIR 012 is forwarded for appropriate action

cc: JGKeppler, NRC JJHarrison, NRC RJCook, NRC RAWells, CPCo

> S. W. Baranow Program Manager

ATTACHMENTS

8401166465

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION: REPORT

Page 1 of 2 QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANC	E: January 2	, 1984	NIR NUMBER 012
IDENTIFICATION/LOCATI	ON OF ITEMS:		
Civil Review Phase II	I FCR/FCN Midla	nd CIO Office Dr	awings Stations 8-10-13
DESCRIPTION OF NONCON	FORMANCE:		
Station 8: FSK Drawi Register, the revision is a generic problem	n column and the	e sheet column a	ith Bechtels Master Composite ppears to be a problem. This
quantity distribution count in the field st. Drawings # C-1492, C-drawings have one copy verified per procedure Drawings missing from C-97. Two sepia were	The Bechtel ation. Specifi 1493-1, C-97, C y in their stat e. 3) Spencer- station 10, one issued for each	FDDL quantity docation # C-195, (-8 and C-2031. (ion that is voide White and Prentice copy (sepia) on drawing per Bec	ecifications have inconsistent es not agree with the actual C-197, C-198, C-200. Design 2) All vendor controlled ed. This practice can not be be had the following Design f C-8 and one copy (sepia) of chtels FDDL. 4) Design ttached to the drawing.
		(continued on	Page 2)
R. Scallan INITIATOR DATE January 3,		PROGR	AM MGR 13 for Sw Bavanow 1/3/84
CORRECTIVE ACTION BY:	MPQAD		
	IDENTIFY ORGA	NIZATION TAKING	CORRECTIVE ACTION
VERIFICATION SAT	UNSAT	NEW NIR#	CONCURRENCE
INITIATOR			PROGRAM MGR
DATE		DATE	DATE
EMIDIT			

(5) -- pulled-back, the Composite Register did not. 6) Mergentime FSK CA 1062 Revision 6 - FCR C-6053 was on the blue-line (attached) but was not on the Sepia. 7) FSK 1060 shows in the Register as "FSK 1060 sheet 7", however it should indicate "FSK 1060 Revision 7 with only one sheet." 8) FSK 1062 shows in the Register as "FSK 1062 sheet 6 revision 4," however it should indicate "FSK 1062 revision 6 with only one sheet." 9) Specification C-305 located in station 10 Mergentime was missing the symbol ® to indicate that there is a retired document against this specification.

Station 13: Specification C-306 had referenced FCR C-4854 but it was not attached to the Specification. 2) Control Drawing CO482 sheet 1 outstanding attachment stamp could not be read. Also a ® symbol was located on the drawing while the Composit Register had it voided.

STONE AND WEBSTER MICHIGAN, INC. P.O. BOX 1963, MIDLAND, MICHIGAN 48640

	VIA T		٦		SIRS:	DATE 1/3/ 1 0 NO. 145 P 0 NO. N/A LTR. NO. 83-0 REF. N/A	509 A 0004
0	D. L. QUAMME,	CPCo Midland (site		_ co	DRAWINGS OCCUMENTS	REPRODUCIBLES EACH OF SPECIFICATIO	MICROFILM APERTURE GARDS
0000	FINAL PRELIMINARY NO COMMENT SUGGESTIONS AS NOTED		AS DEFINED IN SPECIFICATION	PLEAS REVISIONS ADDITIONS COMMENTS	OMISSIONS CORRECTIONS	SENT	CONCURRENCE
	RELEASED FOR:	S DIRECTED TO TH	REPRODUCIBLES	ERIALS MICROFILM PILM APERTURE C VAL OR COMMENTS NING THE ENCLOS	ARDS OF DOCUM		NGS SHOP DETAIL
C	IO NIR O11 is for	warded for appropr	iate action		PRINT D/RA A/RA RC PAO ISGA	DE DRUSP ORMA SOS	6 cig, +3
c	c: JWCook, CPCo RAWells, CPCo				1		

ATTACHMENTS

B & SW Baranow.

S. W Baranow

Program Manager

5.40H60002

JJHarrison, NRC JGKeppler, NRC

JAN 8 1984

S. .E AND WEBSTER ENGINEERING CORP. ATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANCE: DECE	MBER 30,1983	NIR NUMBER 011
IDENTIFICATION/LOCATION OF ITEM		
ARCH. REVIEW PHASE III FCR/FCN		DWG STATIONS 51 AND 59
DESCRIPTION OF NONCONFORMANCE: While performing a sampling the following was noted concern retired FCR/FCNs. FID 2.100 Rev.5 states: 1. Paragraph 6.3 (Recipients wi	inspection of conting the Implementation of	trolled architectural DWGS, tion of the Symbol R for the title block of the e retirement of an FCR/FCN.) f the original "parent" while Drawing A-71 did not.
Rich Scallan Rol Scot INITIATOR DATE 12/30/83		GRAM MGR 13 for SWBavano w
ORRECTIVE ACTION BY:	POAD	
IDENTIFT	URGANIZATION TAKIN	G CORRECTIVE ACTION
RIFICATION SAT UNSAT	NEW NIR#	CONCURRENCE
ITIATOR	NEW NIR#	CONCURRENCE PROGRAM MGR
	NEW NIR#	CONCURRENCE PROGRAM MGR

BELINER 10: WEDDN B CONUNT BITS

CONLENIS MORI NOT BE REMOVED

: 1140

SRETECL'S TRUCKE NO. SETSIES LOCKERIES CETELITYALOFS

IL A SUCLEM INTERACTION IN



Deen L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

December 22, 1983

PRINCIPAL STAFF

RA
DPRP
D/RA
DE
A/RA
DRMSP
RC
DRMA
PAO SCS
SGA
ML
TNF
File /kr

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWO 7020
BY PASSING OF QC HOLD POINTS
File: B1.1.7, 0655 UFI: 9908, 53*50*04 Serial: CSC-7110

Attached is Bechtel's Letter No BCCC-8837 dated December 19, 1983 in complete response to the issue regarding the bypassing of QC Hold Points. Please advise if this response is acceptable to close out this issue.

DLQ/DDJ/klp

cc: JGKeppler, NRC w/a
JJHarrison, NRC w/a
RJCook, NRC w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a

8401050371

DÉC 30 35

Post Office Box 2167 Midland, Michigan 48640



December 19, 1983

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme

Job 7220 Midland Project REVIEW OF STONE & WEBSTER'S CCP OVERVIEW REPORT NO. 25 BCCC-8837

Dear Mr. Quamme:

- References: (1) NCRs C-00628; C-00640, & C-00650, By Passing of QC Hold Points
 - (2) Meeting between Mizan Majumder (BPCo), Ed Jones (MPQAD) Dick Schaut (MPQAD) and Mark Johnson (MPQAD)

Construction's review of Stone & Webster's Overview Report No. 25 identified one (1) open (Construction) action item, specifically, the meeting note "B" on Page 2, concerning by passing of QC hold points.

Detailed below is our complete response on the issue:

We have conducted an investigation on the subject which revealed that the QC inspectors concerned misinterpreted the provision of hold points as stated in PQCI E-5.0, Rev. 13, as it related to the actual field situation at the time.

After careful examination of the facts, the QC inspectors and their respective supervisors agreed that the hold points were not by passed (Ref. 2 above). Since the NCRs contained other nonconforming conditions apart from this issue, revisions to the NCRs were initiated by MPQAD on 12/16/83 to delete the hold point violation portions.

Based on the results of this investigation it is concluded that there is no generic problem associated with Construction by passing QC hold points.

If you have any questions concerning the above, please contact B.T. Foote at Ext. 7507.

Very truly yours,

Im a Liegu

Site Manager

Attachments: Copies of revised NCRs C-00628, C-00640 & C-00650

CC: N. Reichel

RELORD COPY

16 MCR NO	
C-00	
1. LATE ISSUED	18 REY A
SEPTEMBER 30	
19	3 710-06-X3
PAGE 1	OF 2
	F 12-16-83

DEPARTMENT	NONCO	NEORMA	NCE RE	PORT	SEPTEMB	ER 30 ,	1983	107
· DEFAREMAN					19		3	710-06-XI
					P	AGE 1	OF 2	- 7
							7	710-00 83 12-16-83
1 ITEM LOCATION						1.		
AUXILLARY BLDG ELEV. 6	59' - EQUIT	20166-	UNITI					
2 ITEM DRAWING/PART NO.		3 ITEM PA	T HAVE RE	FER TO CHIK-	2-RLC-E-19:	28	TYEN SER	IAL MG.
FSK-EGI- SH.II, REV/18 mg	10.14.83	COSIE OF	T041.D-1				NA	
5 ITEM DESCRIPTION MA	10-00-0-	CASE OF	THEFALLE	ON DEEL	TH WITTE			
MAR MAR	KEL TUBIN	G IRAI 13	INJINELE	ם טא שאת	IN WILL.			
						_		*
					0-		0 16AE 1 1	N.I. REQUIRED
6 ITEM STARTUP SYSTEM NO.	1	7 REFEREN	E O DEV I	FSK-E	SI REV. 7 10	-2-83	TES	
9 INSPECTION RECORD NO.	LOS NO.	REY NO.	1 10 RESP	ONSTBLE ORE	ANIZATION	-		
	213131	0		RUCTION		0-0-2	3	
ORIO46D-10		DEST		RECEIVING	- CONS			FOR INSPECT
			T TURNOVER	- 00		FINAL TURNOYER		CYERINSPECT
D POST INSPECT	TURNOYER	Z POS	TURNOVEX	12				
12 REQUIREMENT 1. POCI-E	5.0, R.13]	DESIGNAT	ES A-HOL	D-POENI-	EOR ACTIVI	14-2	+ D 0	
2. FSK-EGI-SK.II R.7 :	INSULAT	E DRAIN	WIRE WI	TH MARKE	EL INSULA	TINE S	TLEEVE T	APED AT
	BOTH EN	VDS TO PA	EVENT F	PAYING.				
13 NONCONFORMANCE TTEM 1:	QC WAS N	OT PRESEN	TO INS	PECT THE	ATTRIBUT	ES-LI	STED IN	V
ACTIVITY 27 PRIOR	TO WORK	PROCEEDIA	K- A-	12-16-23				
ITEM 2: THE MARKEL	THISULATIN	G SLEEVE	THAT IS	INSTALL	D ON THE	E DRAZ	N WIRE	DOES
NOT HAVE TA	DE DEPLITE	N TO FTI	WER END	BOTH EN	SENDS ARE	FRAY	D.	
NOT HAVE IN	AL AFFELL	0 10 221		1800	14 MCR ORIG	INATED	BY (PERSON))
				04.	m. 1.	In	~	09-30
					-0			DATE
					15 NCR ORIG	SINATED	BY (DISCIPI	LINE)
					ELECT	RICAL		
								ne chara
20 MUNGER OF HOLD TASS (IF	APPLIED)		21 LOCATI	Ary B	TAGS EC	EV.	659'	
2 HOLD TAGS ATTACHE	47		INE @ 2	CILL	DNE @		575A	
22 POTENTIAL 50.55(e)	24 ACTI	ON ITEM NO.		26 ITEM P	RIORITY CODE	NO.	The Su	12.16.83
TES NO	so	3363			5		Jen	とものか
23 REPORTED TO MPOA MANAGE	R 25 DISC	IPLINE:		27 TREND	CODE		DATE:	
		_		. R.	-3		10-3	5-83
DATE N/A		=		2				

			-		
F.1	TAT	TTT	400	TRANCE	
ų٠	ner.	***	200	URANCE	•
	- 40	Pr. 45	שושרדים	WT	
Carrie		ELA	-	410	

DA	TE	IS	SU	ED	
_	SE	PT.	3	0,	93

REV 3

HONCO. ORMANCE REPORT

CONTINUATION SHEET

PAGE 3 OF 3

CONTENDETON	
BLDCK 18: A	
BLOCK 12 AND 13 EXPLANATION OF DELETING OF ITEM # 1 IN BLOCKS	
12 + 13. 12-16-85	•
12 7 3	
TAPING OF MARKEL INSULATING SLEEVE WAS NOT D	DNE B7
CONSTRUCTION ENABITHE QC INSPECTION OF THIS H	OLD TOINT
ACTIVITY, ITEM I WAS WEITTED IN EADE.	
The second secon	
	* * *

- THIAND PROJECT	ETCOUR COLL	שוב ושובו
ZOKASUZZA IIIIADO		10-4-83
DEPARTMENT NO	NC NFORMANCE REPORT	1411
		PAEZ 1 OF 3 12/16/33
		Lynn Tor ZDHH.
TIEN LOCATION		
LE. 659; AUXILLARY BLDG,	AREA 3, UNIT Z, EQUIP & ZC166	
TIEN DRAWING/PART NO.	3 TIEN PART KINE	. A TEN SERIAL M.
OC I E-5.0. REV. 13	REFER TO CWR Z-RLC-E-192	N/A
SK-EG1, Shill, REV 8	CABLE CALOASA-1a	
TIEN DESCRIPTION .	TIRTUR OU DRAIN LIBE	
INSTALLATION OF MARKEL T	OSING ON DRAIN WIRE	
ITEM STARTUP STSTEM NO.	17 REFERENCE DOCUMENT	. S ASSE A.A.I. RETUI
OGLH	POCI ESO, REV. 13 FSK-E	the same of the sa
DEPETION RECORD NO. E-50 LOS	MI. REY NO. 10 RESPONSIBLE CAS	SATISTICA .
DAID45.A-1a 213	130 O CONSTRUCTIO	
1 KONCORFORMANCE DISCOVERED DUR	ING: DESIGN DRESTYDE	र्भित्रका स्वाधिक प्रकार
POST INSPECT TUR	E 0 M	ETO D THE TOP TO OVER THE
1001 0101	MOYER PRIT TURNOVER - TI	
Z EMIREST	TO THE PROPERTY OF THE PARTY OF	-W-Z = BOWN TATION A
1. POCI E-S.C. KEVIS. DE	SIGNATES A HOLD POINT FOR AC	TITTI Z. I PRIOR ID WORK 24
PROCELDING PAST THE PE	THOI. 12/14/83 2/6.70.	TAREN OF TAREN OF
	INSULATE DRAIN WIRE WITH MARKE	I INSCLATING SLEEVE TAPED AT
ENBS-TO PREVENT FRAYIN	16.	
		• • • • •
13 - NONCONFORMACE		
TITM 1: OF WAS NOT PI	PESTAT TA THEFE ATRIBUTE	SLISTED IN ACTIVITY 2.7 TRIOR
	ST THIS POINT. 12/16/83 S.H.H.	
		TALLED ON THE DRAIN WIRE DOES
NOT HAVE TAPE APPLIE	D TO EITHER END. BOTH ENDS	14 NO CLEDATE ST (FESCH)
OF THE SLEEVE ARE FI	KATED.	J. Son H. Holley 4
		15 KO CRIEDATED SY (DISCIPLINE)
		ELECTRICAL
D MUNSER OF HOLD TASS (IF APPL	IED) ZI LOCATION OF HOLD	THES AUXILIARY BLOS BUALL, 8'E.
	EL:654, 9-6'E 5.6,0"3/	Coiled IN 1AJ1556, SON BUALC, 8'E
2 HOLD TAGS ATTACHED		ONE AT OFT65 75A
22 POTENTIAL 50.55(e) 2	4 ACTION ITEM NO. 26 .TEM P	PRICE TO MO. 12 MO REVISED ST
DIE SINO	S03346	5 25 to 10
		. 18:46.00
ZI REPORTED TO MPOA MANAGER 2	S DISCIPLINE: 7 TOD	CODE . LATE:
DATE NIA	F. B.	-3 10-5-8
	L . D.	
-	CONTINUED ON REVERSE	

HIDLAND PROJECT		NCR NO. C-00628
QUALLIT ASSURANCE		12.16.83 PET
	EGNICONFORMANCE REPORT CONTINUATION SEELT	PAGE_3_ OF _3_
BLock 18: A		
BILLION BENEFIT OF THE		
		D / 1: : 0 T/
Block 12 and	#1's in blocks 12 a	Deleting of Item Nd 13 Bizli4831
	7 0 0 1 1 7	1 1. 61
	Taping of Markel I	NSULATING SLECKE
	was not done by co	his Hold Point Activity
	Item#1 written in	
	TICH TORNING	
	the second of th	
The second secon		
The same with		
4 4 4 4		

HIDLE'S PROJECT	_		15	DZI STAD TI	18 2
DEPARTMENT	NONCL . VE	ORMAN	CE REPORT	10-5	5-83
				19	.4745
				PAS	E _/ OF \$3,3
					A) 58.83
ITEM LOCATION .					
ELEV. 65	9-AUX B		10'E/8.6		201660
ITEN DRAWINE/PART NO. FSK -E61 REV. 8	. 3	ITEM PART	ZRLC-E-	1928	4. ITEM SERIAL MO.
	EV.3		ZAIOOZA		N/A
TIEM DESCRIPTION .					
CABLE	: ZCONI	DUCTOR .	SHIELDED	7- TAZ	
		,,,,			
	- 1-				14 105 11 2 20017
TIEN STARTUP STSTEM NO. Z	EGA'	E 900 RE		FSK-EGI SH.III	REVE D YES NO
DISPECTION RECORD NO.	LOS NO. R	THE RESERVE OF THE PARTY OF THE	O RESPONSIBLE		
-5.0-2AI002-1a	213129	0			626 828.143/83
NONCONFORMANCE DISCOVERED	NAME AND ADDRESS OF TAXABLE PARTY.	□ DEZIEN	C RECEIVE	NE CORST	A RELUX FOR DEPE
D POST DISPECT D	TURNOVER	POST TI		PRE-OP FIN	HOVER OF OVERTHERE
2 REDUIRDENT	EQQQ PEV.	u 773.1.5	STATES T	HAT ALL WIRE	E TERHINATIONS
					VINSTALLED, THE
//	DENTATIO	N SHALL	FACE OUT.	,000	יוויון איייייייייייייייייייייייייייייייי
ITEHZ: F	SK-EGI SH	11 STATE	S THAT ONE	MUST INSULAT	E DRAIN WIRE WITH
					REVENT FRAYING .
					E SHALL WITNESS W
					APE - 678 14/11/83
3 HONCONFORMACE					
					HE CRMPED LUG 15.
			E(+) CONDUC		
ITEM 2: C	ONTRARY TO	THE ABI	OVE REQUIRE	MENT MARKEL	SLEEVE IS FRAYED A
	PED.			14 XCR CRISINA	
			I'F REQUIRE		
P.Z.	ERARATIVA 6			my to R.	Brode 10
	THESSEY B	a.c.	RB 12/16/83	15 HCR CRISINA	TED BY (DISCIPLINE)
			/ 8		
	-			- APE	AD- QC ELECT.
D NUMBER OF HOLD TASS (IF A	PPLIED)	1 2	LOCATION OF HOL	D THES ELGSAUX	BLD6. EL. 49540"
2			BOTH ENDS O	10 E/8.E	
2 POTENTIAL 50.55(e)	24 ACTION			PRICETTY CODE NO.	ZE NO REVIDED BY:
□ 155 ⊠ K0	50337			5.	1900
D 12 M 10				9	ではいっている
REPORTED TO MOU MANAGER	25 -DISCIPL	IME:	ום זגם	SD CDDE	CATE:
DATE N/A			D	-3	10-5-83
-	1 -		1 5	, - 3	1 10

COALITY ASSURANCE	C-00650
DEPARTMENT	DATE ISSUED
NONCONFORMANCE REPORT	10-5-83
CONTINUATION SHEET	PAGE 3 OF 3
Block 31A: Additional Infor	mation
Item 1 · Rework	
Determ Cable	2AI OOZA At both er
and turn luns	so that the indental
15 facing out	. Reterm Cable:
	The Carrie
Item 2 \$ 3:	
This is not a n	on-conforming condition
OF TIME WORK I	was accomplished the
Was Do require	ment for toing our
INSULATING SIE	eve on the doding in
WARK WAS CARA	leten bu Canalanali
Mallember at 198	2. C'ER 2811-E-1
was signed off	· THUMAN 22 1002
Construction (p)	molete Ley 7 of
FSK-EG1 (0) U	which requires the top
to he used state	25:
"NO R	ETRAFIT REQUIRED"
	J. Wayne Slocumb-11.
	Keymond mies
BLOCK IZ AND B : FXPIANATION OF BELETING SE TE	0 0 1
BLOCK IZ AND B: EXPLANATION OF DELETING OF ITE	4 3 IN BLOCK IZ AND 13:
TAPING OF MARKEL INSULATINE	SLEEVE WAS NOT DONE BY C
STRUCTION ENABLING QC. INSPE ITEM 3 WRITTEN IN ERROR.	CHON OF THIS HOLD PANT ACTIVIT,
- THE THE CANAL	6. K. B. 12-/6-83



Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

December 22, 1983

Mr. S W Baranow Stone & Wester P O Box 1963 Midland, MI 48640

PRINC	CIPAL STAFF	
RA	DPRP	
D/RA	DE	
A/RA	DRMSP	
RC	DRMA	
PAO	SCS	Toria?
SGA	ML	1 0
ENF	File	7

MIDLAND ENERGY CENTER FCR/FCN STOP WORK ORDERS File: Bl.1.1.7, 0460.3 UFI: 99*08, 73* Serial: CSM-0710

Per discussion on December 21, 1983, we will provide a schedule of activities that can be audited by Stone & Webster with respect to lifting the recent FCR/FCN Stop Work Orders. This letter presents a schedule of activities for the Civil discipline and is provided for your initial planning information. It is our intent to examine other disciplines and provide you with a clear definition of packages and schedule for audit by December 30, 1983.

There will be no change to the present Phase I and Phase II review and audit process. Audits for Phase III will be performed to packages designed for release of work activities. A package will consist of specified document control stations and specified drawings and specifications within a single technical discipline. Fackages will not be turned over to Stone & Webster until a package has completed audits by MPQAD. Stone & Webster will be notified in writing when each package is ready for audit.

Norm Reichel will be the single point contact for coordination of the schedule for Stone & Webster work.

At the present time, Phase I and Phase II for Electrical, Instrumentation and Mechanical have been reviewed by MPQAD and are available for Stone & Webster to audit or review. In the combined areas, there is an identified small population of resolution sheets in the process of finalization review.

As noted earlier, schedule information for the Civil Phase III is included for your planning. The Phase III review for the Civil discipline includes all drawings and specifications including FSK and vendor documents. The audit and release of stations for civil documents has been divided into two packages as follows:

- a) Package necessary to release Soils Underpinning Work:
 - Stations: 8, 10, 13, 24 and 64 to include U S Testing, including all Civil drawings and specifications, FSK and vendor documents DEC 30 1983 on those stations.

2. Mechanical and Electrical Drawings used for reference in drill and excavation permits will be audited only to verify there are no outstanding or unresolved resolution sheets against the document. (Reference list attached) No Mechanical or Electrical work will be performed to these documents until cleared through respective discipline document control audits.

The package described above will be available for Stone & Webster audit on December 27, 1983.

b) All other stations with Civil documents will be audited as a separate package. These stations will be available for Stone & Webster audit on December 28, 1983.

If you have any questions regarding the contents of the above, please do not hesitate to contact me directly.

J J Harrison, NRC Region III

R J Cook, NRC Site

J G Keppler, NRC Region III

N I Reichel, MEC

B H Peck, MEC

D D Johnson, MEC

Electrical

```
- E-500, Sheet 2A
E-500, Sheet 28
E-500, Sheet 20
-E-500, Sheet
____E-500, Sheet
___E-500, Sheet
-E-500, Sheet
-E-500, Sheet 4A
->-E-500, Sheet 48
---E-500, Sheet 4C
--- E-500, Sheet 40
--- E-500, Sheet 50
E-500, Sheet 5D
E-500, Sheet 5E
E-500, Sheet 12
E-501, Sheet 1
 →E-501, Sheet 2
→E-502, Sheet 1
 E-504, Sheet 1 /
     E-506, Sheet 1 -
     E-508 -
     E-509, Sheet 1-
   E-510, Sheet 1/
 -- E-511
 ___E-512, Sheet 1
 -E-513, Sheet 1
 ---E-520
 ____E-521, Sheet 1
     E-522, Sheet 1A
     E-522, Sheet 18
E-522, Sheet 10
     E-522, Sheet 1D
     E-522, Sheet 2A
     E-522, Sheet 2B
     E-522, Sheet 2C
     E-522, Sheet 3
C-1430-3
```

1

Electrical

```
E-523, Sheet 1
  =E-523, Sheet 3
    E-526, Sheet 1 '
E-526, Sheet 2 '
  · E-526, Sheet 3
    E-525, Sheet 4.
    E-57 , Sheet 5 /
E-526, Sheet 6 /
    E-526, Sheet 7"
    E-527, Sheet 1
    E-527, Sheet 2
    E-528, Sheet 3 E-529, Sheet 1
    E-529, Sheet 2'
    E-530, Sheet 1'
    E-530, Sheet 2-
    E-531, Sheet 1A -
    E-531, Sheet 18 E-531, Sheet 10
    E-531, Sheet 10
    E-531, Sheet 2 -
    E-532, Sheet 1.
    E-543, Sheet 1
 E-547, Sheet 1
 _== E-594, Sheet 1
 --- E-595, Sheet 1
.-- E-596, Sheet 1
 .__E-600, Sheet 1
 __E-601, Sheet 1;
    E-698, Sheet 1 ...
    E-698, Sheet 3.
    E-698, Sheet 4
- E-699, Sheet 1
____E-699, Sheet 2
--- FSK-EY-3
---- FSK-EY-9
--> FSK-EY-17
--- FSK-EY-36, Sheet 1
----FSK-EY-38, Sheet 1.
-->=SX-EY-45
```

Electrical

```
FSK-EY-64
   FSK-EY-66
  FSX-EY-69, Sheet 1
   FSK-EY-69, Sheet 2
   FSK-EY-74
   FSX-EY-79
   FSK-EY-93
   FSK-EY-94
   FSX-EY-104
   FSK-EY-106
   FSK-EY-108
   FSK-EY-111
   FSK-EY-150, Sheet 1
FSK-EY-150, Sheet 2
   FSK-EY-151, Sheet 1
   FSK-EY-151, Sheet 2
FSK-EY-151, Sheet 3
   FSX-EY-151, Sheet 4
   FSX-EY-152
   FSK-EY-153
   FSK-EY-154
   FSK-EY-155
   FSK-EY-156
   FSK-EY-157
    FSK-EY-158
    FSK-EY-159
    FSK-EY-160
    FSX-EY-161
    FSK-EY-162
    FSK-EY-163
    FSK-EY-164
    FSK-EY-165
    FSK-EY-166
    FSK-EY-167
    FSK-EY-168
    FSK-EY-169
    FSK-EY-170
    FSK-EY-171
    FSK-EY-172
FSK-ET-2-4
```

Mechanical

```
→ M-58, Sheet 1

   M-58, Sheet 2
   M-152
  M-165
   M-166 -
   M-167
₩-168
   M-169 ~
- M-170, Sheet 1
→ M-170, Sheet 2
- M-607, Sheet 16
   M-612, Sheet 7
   M-612, Sheet 8 -
   M-613, Sheet 7
   M-613, Sheet 8 -
   M-649, Sheet 1 -
   M-649, Sheet 2
   M-649, Sheet 3 .
> M-665, Sheet 1
   FSK-MPY-16, Sheet 1
   FSK-MPY-16, Sheet 2
   FSK-MPY-18
   FSK-MPY-24
   FSK-MPY-29
   FSK-MPY-32
   FSK-MPY-33
   FSK-MPY-44
   FSK-MPY-45
   FSK-MPY-46
   FSK-MPY-72
   FSK-MPY-98
   FSK -MPY -108
   FSK-MPY-165
   FSK-MPY-166
   FSK-MPY-167
   FSK-MPY-168
   FSK-MPY-170
   FSK -MPT-1-1
   FSK-MPT-1-2, Sheet 1
FSK-MPT-1-2, Sheet 2
   FSK-MPT-1-2, Sheet 3
   FSK-MPT-1-2, Sheet 4
   = SK -MPY -: 79
```

14

Mechanical

FSK-MPT-1-35 FSK-MPT-2-1 FSK-MPT-2-2 FSK-MPT-2-4 FSK-MPT-2-44, Sheet 1 FSK-MPT-2-44, Sheet 2 FSK-SP-561, Sheet 3 FSK-M-OCCC-1-1 FSK-M-0JBD-217-1 FSX-M-1CCB-45-4 FSK-M-1HBC-3-2 FSK-M-1HBC-3-3 FSK-M-1HBC-3-4 FSK-M-1HBC-4-1 FSK-M-1HBC-4-2 FSK-M-1HBC-4-3 FSK-M-1HBC-4-4 FSK-M-1HBC-4-5 FSK-M-1HBC-497-1 FSK-M-1HBC-497-2 FSK-M-1HBC-497-3 FSK-M-1HBC-498-1 FSX -M-1HBC-498-2 FSK-M-1HBC-498-3 FSK -M-1HBC-498-6 FSK-M-2HBC-3-1 FSK-M-2HBC-3-2 FSK-M-2HBC-3-3 FSK-M-2HBC-3-4 FSK-M-2HBC-4-1 FSK-M-2HBC-4-2 FSK-M-2HBC-4-3 FSK-M-2HBC-4-4 FSK-M-2HBC-497-1 FSK -M-2HBC-497-3 FSK-M-2HBC-498-1 FSK -M-2HBC-498-2 FSK-M-2HBC-498-3 FSK -M-2CCB-45-4 FSK-M-0GRD-554-2



Deen L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

December 30, 1983

PRINCIPAL STAFF

PA JA-DFRP

D/RA DE

A/RA DRMSP

RC JA-DRMA

PAO SCS:/ origit 3

SGA ML

FILE Jan

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER
FCR/FCN SOILS STOP WORK ORDERS
File: B1.1.7, 0460.3 UFI: 99*08, 73* Serial: CSM-0717

With respect to Part 2 of the Soils Underpinning Work Package in our letter of December 22, 1983, Serial CSM-0710, the mechanical and electrical drawings used as location references for drill and excavation permits will be reviewed differently than described in the letter. Since the mechanical drawing register is not complete, the drawing review proposed cannot be performed at this time.

Until all the drawings referenced in the letter are cleared by the register, each drawing used for a specific drill or excavation permit will be reviewed by field engineering as to suitability for use as a reference for location of buried and embedded utilities. The adequacy of this drawing review process will be overviewed and approved by MPQAD Soils. The Stone & Webster independent assessment team for Soils has reviewed the proposed review process and has agreed to provide an assessment to determine the adequacy of the drawing review process as it relates to the use of these drawings for use as location references for excavation and drill permits.

Dyloteal for DL Quarame

DLQ/JKM/kp

cc: JJHarrison, NRC Region III
JGKeppler, NRC Region III
RJCook, NRC Site
BHPeck, MEC
RAWells, MPQAD
NIReichel, MEC
DDJohnson, MEC
JKMeisenheimer, QA

8401100357

			STER MICHIGAN, INC.
D. L. QUA	MME, CPCo Midland (site)	DEAR SIRS:	EACH OF
		PLEASE NOTE	I SENT FOR YOUR
FINAL PRELIMINARY NO COMMENT SUGGESTIONS AS N	APPROVED APPROVED AS REVISED AS DEPINED IN SPECIFICA UNACCEPTABLE OTED OPEN	REVISIONS OMISCIE	ONS APPROVAL COMMENT
MEASE REVISE AND MEASE SUBMIT MEASE RETURN ON MEASE ACKNOWLES		MICROFILM APERTURE CARDS OF APPROVAL OR COMMENTS. RETURNING THE ENCLOSED COPY OF T	DOCUMENTS DRAWINGS SHOP DETA
MEGETANT WERETE	O ANY REVISION TO DOCUMENTS OR DRAWINGS RE ER PURCHASING DEPARTMENT WITHIN TEN (10) DAYS USER WILL CONSIDER THE REVISIONS MADE WITHOUT	EVEN THOUGH A DEFINITE ESTIMATE G	CREASE THE SUPPLIER MUST NOTIFY STON
The following Op	en CIO Item/Hold Point Notific	cation(s) is (are) atta	ched for
your action/info	ormation:		
Hold Point Of	12		
Hold Point O	13		
Hold Point O	14		

S. W. Baranow Program Manager

cc: JGKeppler, US NRC
JJHarrison, US NRC
RJCook, US NRC
RAWells, CPCo
CIO Site File

JAN 1 3 19

STONE & WEBSTER CONSTRUCTION IMPLEMENTATION OVERVIEW MIDLAND NUCLEAR PLANT J. O. NO. 14509	TRACKED ACTION IT	012 EM TION ITEM
REFERENCE(S) CPCo Letter, File B1.1.1.7, Serial CSM-0710, FCR/FCN Stop Work Orders, 12/22/83	UNTRACKED ITEM HOLD POINT NOTIF	CATION
CONDITION DETAILS This Report provides notification Hold Point at the conclusion of CPCo activities for Pl Hold Point: Prior to issue of documentation lifting to civil discipline - Soils (Stations 8, Using the response section below, CPCo should notify necessary to lift the Stop Work has been prepared, but then perform its evaluation and notify CPCo when this in the "Response Verified/Closed" block below and retice.	the CPCo Stop Work Ord 10, 13, 24 and 64). the CIO when the docum t prior to its issue. Hold Point is lifted	er related entation CIO will by signing
DATE RESPONSE REQ'D. INITIATOR/DATE Prior to lifting Stop Work 1-10-8.	ATTACHMENT INITIATION APPROV	rs
RESPONSE	YES NO.'S	TS LINO
EST. CORRECTIVE ACTION RESPONDENT	TITLE	DATE
RESPONSE ACCEPTED DATE RESPONSE VERIFIED/	CLOSED DATE	

and the state of t

CONSTRUCTIO	C WEBSTER N IMPLEMENTATI ERVIEW R PLANT J.O. NO. 1	ON D	TRACKED ACT	013 TION ITEM ORMATION	ITEM
REFERENCE(S) CPCo Lett CSM-0710, FCR/FCN Stop	er, File B1.1.1.7, Se Work Orders, 12-22-	erial 3	TRACKED RE UNTRACKED HOLD POINT	ITEM NOTIFICAT	ION
	issue of documentation discipline (other the	on lifting the an Stations 8,	CPCo Stop Wo	ork Order r	related
Using the response seconecessary to lift the issue. CIO will then lifted by signing in the completed form to CPC.	Stop Work identified perform its evaluation the "Response Verified	above has bee	n prepared, to CPCo when think below and r	s Hold Poi	nt is
			ATTAC	CHMENTS	
DATE RESPONSE REQ'D. Prior to lifting Stop Work	NITIATOR/DATE	1-10-84	ME Can	1-10-8	
RESPONSE			-	(PAGE S NO.'S) CHMENTS	□мо
SET CORRECTIVE ACTIO	N RESPONDENT	TIT		DA	TE
EST. CORRECTIVE ACTIO	T RESPONDENT				
RESPONSE ACCEPTED	DATE RESPONSE	VERIFIED/CLO	SED	DATE	

CTONE C	WEBSTER	ITEM NUMBER	HOLD POINT NUMBER
	IMPLEMENTATION	TRACKED AG	
OVE	RVIEW	-	FORMATION ITEM
MIDIAND NUCLEAR	PLANT J.O. NO. 1450	9 TRACKED B	ECOMMENDATION ITEM
REFERENCE(S) CPCo Lette CSM-0713, FCR/FCN Stop W	ork Orders, 12/22/83	M HOLD POINT	NOTIFICATION
			THE RESIDENCE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.
CONDITION DETAILS This Hold Point at the conclu	sion of CPCO activities	101 Filase III Kesore	
Hold Point: Prior to is to architec	sue of documentation li tural discipline (other	than Stations 14, 55	6, 48A, 48B and 48D).
Using the response section necessary to lift the Stathen perform its evaluation the "Response Verific CPCo."	op work has been prepar	n this Hold Point is	lifted by signing
		П	ES NO'S) X NO
		-	ACHMENTS
			APPROVED/DATE
DATE HEST SHOE HEST	NITIATOR/DATE	16/	1-10-84
Prior to lifting Stop Work	18/am 1-1	0.84 11 Elan	140 07
RESPONSE			
			ES NO.'S) NO
		ATT	ACHMENTS
EST. CORRECTIVE ACTION COMPLETION DATE	RESPONDENT	TITLE	DATE
		RIFIED/CLOSED	TDATE
RESPONSE ACCEPTED	DATE RESPONSE VE	WIELED/CLUSED	LUAIE

	PRINCIP/ STAFF		ONE O WEBSTE	THE WILLIAM INC.
U	T. ICPRP	P.O	. BO 1963, MIDL	AND, MICHIGAN 48640
	DE			DATE 4/40/04
	VAN RIME			1/10/84 1 0 NO 14509
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			P. O. NO. N/A
	40 1 y priggs			LTR NO. SWOC - 84-00
VIA	EGA L			IRER. N/A
	ENF	DE	EAR SIRS:	N/A
D. I. OLIAMN	ME, COCo Midland (site)	THE	FOLLOWING ARE LAT	TACHED. SENT SEPARATELY:
b. C. QUANN		F	COPIES PRINTS	REPRODUCIBLES MICROFILM APERTURE CA
-	_		DOCUMENTS	NOTES OF CONFERENCE
	STATUS	PI	EASE NOTE	SENT FOR YOUR
FINAL	APPROVED	. REVISIO		APPROVAL COMMENT
PRELIMINARY	APPROVED AS REVISED AS DEPINED	I		USE INFORMATION
NO COMMENT	UNACCEPTABLE	COMME!	=	TILES CONCURRENCE
SUGGESTIONS AS NO				D CONCORRENCE
Particular and Property and Personal Propert	N IS DIRECTED TO THE FOLL	OWING:		14
RELEASED FOR: PLEASE REVISE AND S PLEASE SUBMIT PLEASE RETURN ONE PLEASE ACKNOWLEDG	PARRICATION PURCHASE OF NECESSAR SUBMIT PRINTS REPRODUCIBLES PRINTS REPRODUCIBLES COPY EACH OF THIS MATERIAL BEARING YOUR A E RECEIPT OF THIS MATERIAL BY SIGNING AND E NOTES ARE IN ACCORDANCE WITH YOUR UNDI	MICROFILM APERTUI APPROVAL OR COMME RETURNING THE ENC	RE CARDS OF DOCUMENTS.	

S. W. Baranow Program Manager

cc: JGKeppler, US NRC
JJHarrison, US NRC
RJCook, US NRC
RAWells, CPCo
CIO Site File

A 029 5G

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION: REPORT

QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANCE: December	14, 1983	NIR NUMBER 010
IDENTIFICATION/LOCATION OF ITEMS:		
Civil Rev	iew Phase II FCR	R/FCN/Midland-CIO or Fice
DESCRIPTION OF NONCONFORMANCE: The FCR/FCN C-1526 did not indi C-479 or both, were affected by did not clarify this situation. potential exists for FCR C-1526	this change. So	ubsequent resolution sheets acts CIO concludes that a
DATE 12-14-83 CORRECTIVE ACTION BY:	PROG	GRAM MGR S. Barana-Mi Jale
	ield Engineer	
	THE RESERVE OF THE PARTY OF THE	CORRECTIVE ACTION
The Project Engineer has issued a by MPQAD dated December 15, 1983. This NIR is closed (see attachmen	, to clarify the	R Resolution Sheet, approved above nonconformance.

FCR RESOLUTION SHEET

)	1/3
ARVA BY	of C-1526.
	- CLAPICI C/A BLYCK FOR SHEET 3
TO FUELFICE	CLAMINI CIA DILCE FOR SHEET 5
POTENTIAL IMPACT STATEMENT ((Q	133/301 NO IMPACT, SEE SHEET 3
CORRECTIVE ACTION:	FUR C-1526 WAS PROPERLY APPLIED
NONE	TO DWG. C-479(C SINCE THIS CHANGE
CORRECT DISTRIBUTION	
INITIATE CORRECT FCR	AFFECTS THIS DWG FUR SHOULD
	PENNAN ATTACHED TO DWG C-47912
PLACE FCR ON HOLD	WHIL INCORPORATION OF THIS CHANGE
WRITE NCR	15 PERFORMED.
INVESTIGATE FURTHER	
E CONTACT (IF QUESTIONABLE)	
REPARD BY Michael M. Ruban	/ 1/2/14 PATE CORRECTIVE ACTION COMPLETE
0	DATE / /
TEND BY: K. KAURGI	OIN/4/SLEAD DATE
MPQAD Accept of Frozoied C/A By	DAIR DONG (2-15-03) VERIFT ST
CE Mad don't	ch 12/15/6:
CA AZSOLUTION/WORKS	

FCR RESOLUTION SHEET

2/3

AREA BOP	FCR C-1526
PROBLEM: Project Engineering's r	emarks do not address any (DWG)SPEC. C-358(Q).
	(NO) None. This change was a one time deviation to the
	ed to these DWG/SPEC. C-358(0).
CORRECTIVE ACTION:	The FCR is incorporated
X_NONE	into the referenced drawing.
CORRECT DISTRIBUTION	as noted on back side of
INITIATE CORRECT FCR PLACE FCR ON BOLD	FCK. PER Dug investigation
WRITE NCB	KEN S, 11/3/48 MAS 12/5/83
INVESTIGATE FURTHER	CHECK INCOORDANGED OF CHANCE, WHEH
	1 Wbs? Me 11/5/035 OPR 11/5/63.
RE CONTACT (IF QUESTIONABLE)	of Proposed C/A By
PREPARED BT: Dieg Anuder	11/3/83 FE CORRECTIVE ACTION COMPLETE
REVIEWED BY: P. Launtofo	INIA 183 LEAD TK DATE
DATE OF THE PARTY	VERIFIED BY
FCR RESOLUTION/WORES !	of Froposed C/A By (printing Late illules)

FCR RESOLUTION SHEET

3/3

	1271 BOP 702 (-1526
	PROBLEM: (MIS) OTHER DWG) I SPEC. AFFECTED C-479(0)
	WAS NOT ADDRESCED IN PROJECT ENGINEERING'S REMARK
	WAS NOT ADDR-COED IN PROJECT ENGINEERING'S REMARK
	mas religies.
	POINTIL MALE STATION (6 TES) NO) (DWG) / SPEC. (-479(0) -NOT
	· · · · · · · · · · · · · · · · · · ·
	AFECTED BY CHANGE . CHANGE WAS NOT GENERIC
	AND WAS WELLETOR A UNIQUE INSTALLATION, AND
	NO NOT REQUIRE A CHANGE TO ALL THE AFFECTED
	SPEC: ROWES IN ORDER TO PERFORM WORK IN
	ACCORDANCE WITH THE CHANGE.
	Prince son sele
	COZZECTIZ ACTION:
	LEFERNIED DRAWING.
	1 PER DUE CELLEN, FOR CHOUN HAVE BEEN ADDITED
MFGAD of Frope	- INITIATE CORRECT TO SEE SHE AND THEREFORE WAS NOT MISAPPUED TO DUG.
AD	FLACE FOR ON BOLD 1/3 C-479 Q. NO FURTHER ACTION COD. OFR 11/5/973
GAD Accept Proposed C	The state of the s
Uā	The many was rester
-	THE STREET THE PROPERTY OF CHANGE WHICH
-	12/14/67 DUGG ? ARD 45/63 TEL 1/5/20
1	100077 : 1110 17107 1812/11/07
6	EZ CONTACT (IZ QUESTIONARIZ) MPGAD Accept
150	of Preposed C/A By (20) Date [2/6/83
Russia	TIPLED IT: Dea / Wider 111/3/83 TZ Composite Register update
11.	722 37: Lea / Wider 111/3/83 72 CORRECTION CONTINUE ACTION CONTINUE
?	1 10 114 . TK. DATE
118 :	25.20 37: Tavaloto 111/3/83:200
15	VELT:D 37
10	1) Vo.h. a. 11/h/22
-	1. Method 17/93 10000 com
	THATE!

	FIELD CYAN	ON SHEET	REV QI		F DWG CR DVC 19	-/526
	C-358 · O	NA	SYNE YES	Conc.	at El. 659-0	morceo.
HOPOSED CR X FCN	PREPARED BY AM	4-/1-78	YES NO	a. The	A ZO-	76 FCR R
in the n	To forth and south				tion opening the steam gene	is requir
Dwgs. C- the cent	NOITION 357 & C-358 shoer of the north	ow the #11 h	norizontals refueling c	REG	MAY 1 8 1978	
below:	OF CHANGE	ield reques	ts approval		splice lengths	
(7-6		9-0		
1	R H	9-7	—	-		
Refu	ELING	REFUEL \$ SECON	FOR ALL I WHERE TH NG CANAL A DARY STIELD	E WALLS		SHIE
CANAL REC'O	pproval by the		opp. Hand		74	REM -28-78
THER C	VIL AREA H	TRICAL	ASTRUMENTATIO	MECHANICAL	PIPING .	WELDING
HEEKED BY	DR-st	J/A	N/A	N/A	N/A	NI
ECXED STA	4 Juvean	4		+ /	1	1
CR 🗵	APPROVE	D YE	S MO	PROJECT	ENGINEER SIGNATU	V-15-7
BMAXS 7	le requests	1. Than	qu is	appine	1 -0 PENISE	
				to the file on the file	11 190121	A) 3

. .

.

	PRINCIPAL FF		AND MERSIE	
VIA F	A' DPRH /RA DE /RA DRASP DRASP DRASP AO SIS 4 Orig + 3	DEAR	SIRS:	DATE 1/10/84 1 0. NO. 14509 P. O. NO. N/A LITE NO. SWOC 84-00 REP. N/A
D. L. QUAN	MME, COCo Midland (site)			REPRODUCIBLES MICROFILM REPRODUCIBLES APENTURE CA EACH OF SPECIFICATIONS NOTES OF CONFERENCE
PINAL PRELIMINARY NO COMMENT SUGGESTIONS AS N	STATUS APPROVED APPROVED AS REVISED AS DEFINED UNACCEPTABLE OTED TO CLOSED	PLEAS REVISIONS ADDITIONS COMMENTS	OMISSIONS CORRECTIONS	SENT FOR YOUR APPROVAL COMMENT USE INFORMATION FILES CONCURPENCE
PORTANT SHOULD WEESTE PURCHA	DOE RECEIPT OF THIS MATERIAL BY SIGNING AND RETURNESS NOTES ARE IN ACCORDANCE WITH YOUR UNDERSTAND ANY REVISION TO DOCUMENTS OF DRAWINGS RETURNED FOR PURCHASING DEPARTMENT WITHIN TEN 1101 DAYS EVEN SER WILL CONSIDER THE REVISIONS MADE WITHOUT COST	ED HEREWITH INVOLVE THOUGH A DEFINITE	E A PRICE INCREASE ESTIMATE CANNOT I	THE SUPPLIER MUST NOTIFY STOP BE GIVEN AT THE TIME OTHERWISE.
nie rorrowing	*	arded for yo	our internat	1011.

cc: JGKeppler, US NRC JJHarrison, US NRC RJCook, US NRC RAWells, CPCo CIO Site File

JAN 1 3 1984

A029.30

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

DESCRIPTION OF NON	CONFORMANCE:		
drawings was select	ted. Accept/Rejection 5	of control drawing	techural drawings at Q.C. Using a lot size of 224 Eccept O Reject 1. Drawing Sticks. As a result, the
This NIR describes of the Control Card applicable.	a deficiency agai for drawing A-2	nst the Document C 13 does not show an	ontrol Center. A check y FCR/FCNs as being
Robard	Zeallan	PROGRA	M MGR She Burner
DATE 12/12/2			M MGR Subures Hes 12, 1983
DATE - 4742	•	DATE_	12014,1705
ORRECTIVE ACTION B			
	IDENTIFY ORG	ANIZATION TAKING CO	ORRECTIVE ACTION
of the drawings at	this station. The	review was considers of FID-2 400 Po	verified that the missing erformed a sample inspection ered to be satisfactory and v. 3, Review and Resolution 983.
ERIFICATION SATE	UNSAT COLLON 35-10-5	NEW NIR#	PROGRAM MGRANGE



STONE & WEBSTER MICHIGAN, INC.

P.O. Box 2325, Boston, Massachusetts 02107

January 6, 1984

DE DRMSP
DRMSP
DRMA
SCS of suig+3
ML
File for

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-007

This letter forwards, by enclosure, CIO Item number 038 for your attention.

You will note that we have revised our method of notifying you of CIO Items and Hold Points. In the future, each item or Hold Point will be identified on an individual document, similar to that attached, which provides space for CIO to inform you of a condition and for CPCo to document your response. This format should improve both of our abilities to track and control CIO requests and CPCo action relative to these requests as well as saving administrative time.

This particular Item is being forwarded by letter since it is the first time this format has been used. In the future we will revert to the process currently used for NIRs and use standard document transmittals to forward Items and Hold Point Notifications.

Enclosure JEK/fs

E. Karr

cc:
JGKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

-8401160036

			LIEM NUMBER		NT NUMBER
	G WEBSTER	TION	038	1	
	MPLEMENTA	HON	TRACKED A		
	RVIEW	*****	X TRACKED IN	FORMATIO	NITEM
MIDLAND NUCLEA	R PLANT J.O. NO.	14309	TRACKED R	ECOMMEND	ATION ITEM
REFERENCE(S) CIO Week	ly Report Number 2	6	UNTRACKED		
			HOLD POIN	NOTIFICA	TION
in conducting S System Status a clude all of th If special chec addressed by an lists are to be CPCo is request	checklist develope tatus Assessments nd Completion), th e attributes requi klists are to be u administrative pr prepared, used an ed to provide CIO nt control measure	to Procedure e CIO noted t red by the pr sed in status ocedure that d controlled. with the inte	FPM-7.000 Rev. hat the checkl ocedure. ing, these lis provides detai nded use of the ded.	1 (Mechan ist does no ts should I ls on how	ical ot in- be the
			Market comments	ACHMENTS	
DATE RESPONSE REQ'D.	INITIATOR/DATE			APPROVED	DATE
DATE RESPUNSE NEW D.			11 -1		
1/16/84 RESPONSE	J'Ellan	1-6-84	4/7/la	1	6.07
1/16/84	1/7/lan	1-6-84		(PAGE	□ NO
1/16/84	1/7Kan	1-6-84			□no
1/16/84				ES NO.'S)	□no
1/16/84 RESPONSE EST. CORRECTIVE ACTIO			□ _Y	ES NO.'S)	□no

DEAR SIRS: DEAR SIRS:				P.O. 50	1963, MIDL	IND, TO	-34V	45540
DEAR SIRS: THE FOLLOWING ARE ATTACHED SENT SENARATELY: DEAR SIRS: THE FOLLOWING ARE ATTACHED SENT SENARATELY: COMES PRINTS ARE DATACHED SENT SENARATELY: COMES PRINTS ARE DATACHED SENT SENARATELY: CACH OF DATACHED SENT SENARATELY: DATACHED SENT SENARATELY: COMES PRINTS ARE DATACHED SENT SENARATELY: CACH OF DATACHED SENT SENARATELY: DATACHED SENT SENARATELY: PLEASE NOTION SENT SENT SENARATELY: DATACHED SENARATELY: DATACHED SENARATELY: DATACHED SENT SENARATELY: DATACHED SENARATELY: DATAC						2012		
DEAR SIRS: DEAR SIRS:						1 0 40	14500	
DEAR SIRS: DEAR SIRS:						P 0 NO.	N/A	
DEAR SIRS: THE FOLLOWING ARE THE ATTACHED SENT SEPARATELE: DEAR SIRS: THE FOLLOWING ARE THE ATTACHED SENT SEPARATELE: COPIES PRINTS ATTACHED SENT SENT SEPARATELE: COMMENT DOLOMENT DOLOMENT SEPARATELE: PLEASE NOTE SENT FOR YOUR DEMONSTRATE COMMENT SEPARATELE: PAGE ASSESSMENT PRINTS ATTACHED SENT SEPARATELES MICROFILM APERTURE CARDS OF COMMENTS DRAWINGS SHOP DE PLASE SUBMIT PRINTS ATTACHED SENTING TOUR APPROVAD OR COMMENTS DRAWINGS SHOP DE PLASE SUBMIT PRINTS ATTACHED SENTING APPROVAD OR COMMENTS DE PLASE SUBMIT SENT SENT SENTING AND RETURNING THE ENCLOSED COPY OF THIS FORM WE TRUST THAT THESE NOTES ARE IN ACCORDANCE WITH YOUR UNDERSTANDING IN NOT. PLASE ADVISE US IMPORTANT SENTING AT REVISION TO DOCUMENTS OR DRAWINGS RETURNED HERMITH INVOLVE A PRICE INCREASE THE SURFILER MUST NOTIFY STORM WE TRUST THAT THESE NOTES ARE IN ACCORDANCE WITH YOUR UNDERSTANDING IN NOT. PLASE ADVISE US IMPORTANT SENTING AT REVISION TO DOCUMENTS OR DRAWINGS RETURNED HERMITH INVOLVE A PRICE INCREASE THE SURFILER MUST NOTIFY STORM WE TRUST THAT THESE NOTES ARE IN ACCORDANCE WITH YOUR UNDERSTANDING IN NOT. PLASE ADVISE US IMPORTANT SENTING AT REVISION OR DRAWINGS RETURNED HERMITH INVOLVE A PRICE INCREASE THE SURFILER MUST NOTIFY STORM WE TRUST THAT THESE NOTES AND SECURITIES OF MICROFICES THAT THOUGH A DEFINITE ESTIMATE CANNOT SET GIVEN MIT THE THE OTHERWISE MICROFICES THAT THOUGH ADDRAWING SET OF THE THE OTHERWISE MICROFICES THE THEORY CANNOT SET GIVEN MIT THE THE OTHERWISE MICROFICES THE THEORY CANNOT SET GIVEN ATTER THE OTHERWISE MICROFICES THE THEORY CANNOT SET GIVEN AT THE THE OTHERWISE MICROFICES. THE POLICY OF THE TRUST OF THE MICROFICES THE THEORY CANNOT SET GIVEN AT THE THE OTHERWISE THAT THE THE OTHERWISE MICROFICES THE SUBMED THE THEORY CANNOT SET GIVEN AT THE THEORY CANNOT SET GIVEN AT THE THEORY CANNOT SET GIVE						LTR. NO.	SWOC	34-002
D. L. QUANNE, CPCO Midland (site) CDPIES	VIA		_			*5*	N/A	
D. L. QUAMMS, CPCO Midland (site) COPIES			1	DEAR	SIRS:			
DRAWINGS SPACIFICATIONS DOCUMENTS NOTES OF CONFERENCE				THE FOL	LOWING ARE X ATT	ACHED -	SENT SEN	ARATELT:
DRAWINGS SACRIFICATIONS DOCUMENTS NOTES OF CONFERENCE	TO D) GHAMME	CPCo Midland (site)						
STATUS PLEASE NOTE SENT FOR YOUR		, 0.00		co	PIES PRINTS			APERTURE CAN
STATUS PLEASE NOTE SENT FOR YOUR					DRAWINGS	-	CATIONS	
FINAL APPROVED AS DEFINED ADDITIONS CORRECTIONS COMMENT DECEMBER ADDITIONS CORRECTIONS USE INFORMATION DIRECTED TO THE FOLLOWING: FILES CONCURRENT DIRECTED TO THE FOLLOWING: PILES CONCURRENT PILES			_		DOCUMENTS	- NOTES	OF CONFE	RENCE
# APPROVED APPROVED AS REVISED AS DEFINED ADDITIONS OMISSIONS APPROVAL COMMENT APPROVAL APPROVAL ADDITIONS COMMENTS OF PILES CONCURRENT ADDITIONS OF PILES OF P				-				
PRELIMINARY		STATUS		-		-	-	
NO COMMENT	PINAL			_	=	-	-	
SUGGESTIONS AS NOTED TO OPEN YOUR ATTENTION IS DIRECTED TO THE FOLLOWING: RELEASED FOR:		_	ECIFICATION !		U CORRECTIONS		_	
YOUR ATTENTION IS DIRECTED TO THE FOLLOWING: RELEASED FOR: FABRICATION PURCHASE OF NECESSARY MATERIALS MICROFILM APERTURE CARDS PLEASE REVISE AND SUBMIT	D NO COMMENT			COMMENTS	_	-	_	CONCURRENCE
RELEASED FOR: PASSIGNATION PURCHASE OF NECESSARY MATERIALS PLASE REVISE AND SUBMIT			OLL CIMING			111.401	LUN	
The fell and Open 110 Item/Hold Point Notification(s) is (are) attached for your attion of the Open Item Item Open Item Item Item Item Item Item Item Item						**		
Ttv. 042	IMPORTANT WEEDTER FOR	119 Item/Hold Point No	OI DAYS EVEN TH WITHOUT COST.	DUGH A DEFINIT	E ESTIMATE CANNOT	BE GIVEN AT	LIER WUST THE TIME	NOTIFY STON
Ttv. 042	your action unforms	1.001						
	Item	041						
216m 475	Item Item	042						
	Item	041						

STONE AND MESSTUR

S. W. Baranow Program Manager

cc: JGKeppler, US NRC
JJHarrison, US NRC
PRJCook, US NRC
RAWells, CPCo
CIO Site File

8401160096

Sheet 1 of 2

- STONE & WEBSTER	ITEM NUMBER HOLD POINT NUMBER 041
CONSTRUCTION IMPLEMENTATION	TRACKED ACTION ITEM
OVERVIEW	TRACKED INFORMATION ITEM
MIDLAND NUCLEAR PLANT J.O. NO. 14509	TRACKED RECOMMENDATION ITEM
REFERENCE(S) Brio Letter of December 28, 1983, Serial #3000-	T UNTRACKED ITEM
8852, Emergency Diesel Generator, Transamerica Delaval, Inc., Request for Pesumotion of Installation	HOLD POINT NOTIFICATION
CONDITION DETAILS The referenced letter indicates that BPCo is preparing work on the emergency diesel generators. BPCo Material Requisition 7220-M-18 (Q) requires that be furnished in accordance with several listed BPCo sp. Additionally, this work may be affected by current act of Phase III activities on FCRs/FCNs, vendor drawings. Therefore, please provide CIO with CPCo plans and schereleasing the diesel generator installation work, the are also requested to address your plans for covering this work such as training/qualification of personnel.	the emergency diesel generators pecifications and drawings. tivities relative to the evaluation and FSKs. edules for assuring that prior to above issues are resolved. You other activities relevant to
control, etc.	YES PAGE X NO
(Please see Sheet 2)	ATTACHMENTS
	INITIATION APPROVED/DATE
DATE RESPONSE REQ'D. INITIATOR/DATE	
	YES NO.'S) NO
	ATTACHMENTS
EST. CORRECTIVE ACTION RESPONDENT COMPLETION DATE	TITLE DATE
	01.0050
RESPONSE ACCEPTED DATE RESPONSE VERIFIED!	CLOSED DATE

CONDITION DETAILS (continued)

After review of the requested information, CIO will determine whether in-process evaluation of CPCo actions will be conducted or a Hold Point will be established at the completion of CPCo action for CIO to assess the readiness to proceed.

Sheet 1 of 1

- STONE & WEBSTER	ITEM NUMBER HOLD POINT NUMBER 042
CONSTRUCTION IMPLEMENTATION	TRACKED ACTION ITEM
OVERVIEW	TRACKED INFORMATION ITEM
MIDLAND NUCLEAR PLANT J.O. NO. 14509	TRACKED RECOMMENDATION ITEM
REFERENCE(S) Interoffice Memorandum, Sysaranow to DiQuanne,	UNTRACKED ITEM
CPCo Training of 10/21/83. CPCo Letter, DLOJamme to SwBaranow,	HOLD POINT NOTIFICATION
CONDITION DETAILS The above referenced documents refer to the formalize training of CPCo personnel (SMO) who will be perform Construction Completion Program. It is requested that these procedures be provided to	ning tasks relative to the
	YES CAGE NO
	ATTACHMENTS
DATE RESPONSE REO'D. INITIATOR PATE	INITIATION APPROVED/DATE
) - "1,5 1/14" () - "1 () - "() () () () () () () () () (1 / 1 / 2 Com 1 / 1 / 2 Es
	YES NO S)
	ATTACHMENTS
EST. CORRECTIVE ACTION RECEDITION COMPLETION 1778	TITLE DATE
RESPONDE ACCRETED DATE RESPONSE VERIFIED!	CLOSED DATE

Sheet 1 of 1

STONE	& WEBSTER	1	TEM NUMBER H	IOLD POINT	NUMBER
CONSTRUCTIO	N IMPLEMENTAT	ION E	TRACKED ACT	ION ITEM	
OV	ERVIEW		TRACKED INFO		TEM
MIDLAND NUCLEA	R PLANT J.O. NO. 1	4509	TRACKED REC	OMMENDAT	TON ITEM
REFERENCE(S)			UNTRACKED I	TEM	
N/A			HOLD POINT N	NOTIFICATION	ON
measures resulted in Audit has resulted in Ported in MQAR-DAT-1 Please provide CIO with plementing and verify Your response should ment 2 to this report Upon receipt of the any necessary CIO as	the findings listed is similar conditions dated 1-4-84. Ith CPCo's plan for a ying corrective action cover, but not necessary.	in Attachment being identifi addressing the or, on both MQAF ssarily be limit	problems noted R-DAT-1 and thi ited to the ite	d and for its report. ems in Atta	re- im- ach-
			X YES	PAGE 3	DNO
			13.5	HMENTS	
LATE RESPONSE REC'S.	PATIATOR/DATE		I HITIATION A		
13/83	F. C. 1	1-6-12	1. Miles	1-5-1	£
			☐ YES	(PAGE NO:5)	
			ATTAC	HMENTS	
SOMPLETION DATE	DN MESPONDENT	717	LE	DAT	E
		E VERIFIED/CLC		DATE	

PHASE III EVALUATION RESULTS DOCUMENT CONTROL

- 1. Drawing Registers Distribution Control
 - a) It is necessary to consult several registers to determine the correct distribution of controlled documents e.g. FDDL, Vendor Prints, FSK, Composite Register, Specifications, Revision Register etc.
 - b) Computer input errors in one or more registers compound 1a.
 - c) The System of retiring documents (The R Symbol) has inconsistencies between the flat files (drawer files) and the field blue lines.
 - d) The exemption list compounds problem 1a.
- 2. Document Control Field Stations
 - a) Existing controls (cards, registers, transmittals) do not readily identify controlled documents. Therefore, Field Stations cannot easily locally about documents they should have.
 - b) Some Stan in follow the practice of de-controlling drawings. This practice to assertly not proceduralized.
 - If Distriction of the model in this is contained on some is the constituted to some is the
- 5. The FDDL is not representative of field drawing distribution (upples). Station 10: The tollowing Design Drawings and Specifications have inconsistent quantity distribution. The Bechtel FDDL does not agree with the actual field count - Specification #C-195, C-197, C-198, C-200. Design Drawings #C-1692, C-1493-1, C-97, C-8 and C-2031.
- 4. Sheet numbers from Registers are inconsistent. For example Station 10: F5K 1060 shows in the Register as F5K 1060 sheet 7, however it should be Revision 7 with only one sheet. F5K 1062 shows in the Register as sheet 6 Revision 4, however it should be Revision 6 with only one sheet.
- 5. The exception list is constantly changing causing potential control problems. This situation indicates that a higher level Document Control Canter may be required.
- There is no way to valid the final disposition of controlled documents some transfers to valid prints are not receipt acknowledged.

Item Number 043 Attachment 1 Page 2 of 2

- 7. At the time NIR 011 was written, Document Control Center could not supply any one source of information that could identify which documents were affected by the Retired Document Procedure (FID 2.100).
- 8. Change Documents are improperly posted on drawings. For example at Station 10, the Design Drawing C-2031-19 Revision 1 did not have FCR 6974 attached to the drawing. Other drawings had incorrect "R" designations. Some drawings have inapplicable Change Documents attached.
- Given the total number of documents, the wide distribution and the number of changes. The sheer bulk of documentation is a problem and effort should be made to reduce the bulk.

CPCo CORRECTIVE ACTION PLAN INFORMATION REQUEST

- CPCo plan for implementing and verifying corrective action on a generic basis with time phasing (schedule).
- Plan for packaging corrective action measures by discipline, work station, etc., and method for presenting discrete work groups to CIO for evaluation.
- Plans, if any, to pull back documents from field stations to affect corrective action.
- 4. Method for assuring the identification of all changes which affect all documents and for verification that Document Control and Field Stations are consistant in their records.
- Method for identification of all data necessary for the control of distributed documents, discipline, stations, sheets, revisions, hanging paper, "R" status.
- Any plans for reduction in the numbers of documents issued to/used by free's static as or in the number of field stations themselves.
- 7. Share italia I detained are distributed to off-site vendors and these distributed to review?

The last relation of overall corrective reclaims to the fee to be reclaimed to the feet to be reclaimed to be reclaimed to the feet to be reclaimed to be

Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

PRINCIPAL STAFF

A Ma PAP

D/RA DE DOMA

RC DOMA

PAO DOMA

SSA DOMA

ENF FILO WAS

ENF FILO WAS

TO DE DOMA

BY & WAS

BY WAS

BY

contractions of the contraction of the contraction

January 4, 1984

Mr Stan Baranow Stone and Webster Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF REFERENCE COPIES FILE 24.2 SERIAL 27263

This will confirm the transmittal of all reference copies of the following document to Stone and Webster, as listed below:

Stop Work Orders

FSW 33 FSW 38 FSW 34 FSW 39 FSW 35 FSW 40 FSW 36 FSW 41 FSW 37

and log pages.

1 a Free in

G F Ewert, Division Head Quality Services Midland Project Quality Ssurance

GFE/JAP/kmc

CC JRKeppler, NRC Region III Administrator 7
DLQuamme, SMO
RAWells, MPQAD

OC0983-0001A-QL05

8401120206



Midland Project: PO Sox 1963, Midland, MI 48640 • (517) 631-8650

January 4, 1984

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWO 7020 NIR'S 001, 006, 007, 008 & 009 File: B1.1.7, 0655 UFI: 99*08, 53*50*04 Serial: CSC-7133

Attached are MPQAD QAR's for the corresponding S&W NIR's as indicated:

QAR No	NIR No
RT-00016	001
RT-00017	009
RT-00019	006
RT-00020	007
RT-00021	008

These QAR's were written to enter the S&W identified nonconforming conditions into MPQAD's QUAIL System and to review the corrective actions to determine if process corrective action is required.

DLQ/DDJ/klp

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
RAWells, MPQAD w/a

THE S ESS

Dean L Quamme Site Manager Midland Project

310

840420274

ATOLAND PRO	WECT	0.011=1			6. QAR NO	RT-00016
QUALITY ASSURANCE	DEPARTMENT	QC LITY ACT	TION RE	QUES	7. DATE I	- 1
L. REQUIREMENT:					9- PAGE	1_ OF _3
	ning Matrix re m Support Engi	quires Code 3 tra	ining for	G C-9.0	0 10. ASME R	
						YES X NO
2. DEFICIENCY:						
Training rec	ords show Code	2 training for R	oger Guard	as repo	rted on S&W	
						11. POTENTIAL 50.55(
3. QAR ORIGINATED DMTurn		4. DISCIPLINE/DIVIS	SION/SECTION	5. RESP	N/A	12. REPORTED TO MPO
3. ACTION ITEM NO:	15. ITEM PRIOR	TY: 17. S/U CODE:	19. A	CTION ORE	ANIZATION 20.	QAR REVIEWED BY:
S04120	4	PGM00	A CONTRACTOR OF THE PARTY OF TH		truction 9	Hall
4. DISCIPLINE:	16. TREND CODE:	18. RESB CODE:	Trai	ning Coo		DATE:
N/A	DNT	N/A			CTIVE ACTION:	7/29/83
Z4. RESPONSIBLE OR	GANIZATION/PERSON			INFO	RMATIO	H ONLY
Bechtel Cons	truction/Train	ing Coordinator			on was 8/15/	83.
e. DISPOSITION CO	NCURRENCE:	12/29/63				
211	QAR REVIEWER	DATE	-	POAE (N/A ASME ONLY)	DATE
No further a	on training re	cord for Mr Guard . The checked bo red by FPG 2.000	x on the co	nstruct	August 15, 1 ion training	983 (copy attached) record is consiste
See NIR #001	OSITION VERIFICAT	ION			29. QAR CLOSE HEREN MPQAD	D BY 2 /2/29/83 DATE N/A
ACCEPTABLE X UN	ACCEPTABLE	SUPERCEDING QAR			PFQCE (AS	

STONE AND WEBSTER ENGINEERING CORPORATION NONLUNFORMANCE IDENTIFICATION REPORT

Page 2 of 3 QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANCE:	August 9, 1983	NIR NUMBER 001
IDENTIFICATION/LOCATION OF IT	EMS:	
CONSTRUCTION TRAINING RECORDS	FOR AG-C.900	
DESCRIPTION OF NONCONFORMANCE Computer records show LSE Rog require's training to Code 3.	er Guard as trained t	o Code 3. Training Matrix ords show Code 2.
A Blenham INITIATOR DATE 8/17/83		E August 17, 423
CORRECTIVE ACTION BY: BEC IDENTIF	FY ORGANIZATION TAKIN	G CORRECTIVE ACTION
A construction training record copy attached. No further a The cnecked box on the construction training required by FPG 2.0	ection required.	
VERIFICATION (SAT) UNSAT INITIATOR/15 to Late DATE 81 17 183	NEW NIR#	DATE August 17, 923
KEMARKS		

	TRAINING RECORD .
ME COGER L GUA	
EPARTMENT BULE HANGE	Team # 30
SSIGNMENT LOND TEAM SUPPOR	F ENGINEER
HECK THE APPROPRIATE BOX (ONE BOX	ONLY) SIGNATURES REQUIRED
CONFLETED READING	EMPLOYEE & SUPERVISOR
COLPLETED READING AND REVIEW .	EMPLOYEE & SUPERVISOR
COMPLETED TRAINING	EMPLOYEE, SUPERVISOR, & TRAINER
EXEMPT FROM TRAINING DUE TO PRIOR WORK EXPERIENCE (NOTE ≠1)	EMPLOYEE, SUPERVISOR
DOCUMENT TITLE	DOCUMENT TITLE
700 C-9.00	
12=VISION 2 5-9-83	
SIGNATURES	DATE
ENTER DOSER, & Dans	Clig 15, 1983
SUPERVISOR OF Quen C. Little	U <u>B/15/83</u>
TRAIRER	
. CPCC-SMO	

TE . S EXEMPTION REQUESTS MUST BE SUPPORTED BY DOCUMENTATION OF WORK RELATED EXPERIENCE ON THE REVERSE SIDE OF THIS FORM. REVIEW OF REQUESTS FOR EXEMPTION, WITH SUPPORTING DOCUMENTATION, WILL BE . THE RESPONSIBILITY OF THE TRAINING COORDINATOR. HE WILL SECURE THE

				16	040 80		
MIDLAND PRO					QAR NO	RT-00017	*
QUALITY ASSURANCE	DEPARTMENT .	OC LLITY AC	HON RE	QUES. 7.	DATE I		8 REY
AND MARKET STATES					12/29	/83	0
REQUIREMENT:				9-	PAGE _	1 OF 2	
		equires that the lled sticks at lo		1 111	ASME RE	ELATED	
by the PFE-		_				YES D	X XO
				17.14			_ NO
2. DEFICIENCY:							
	ster NIR #009	identified the	fact that or	ne drawing in a	samp	le of 50 w	as ·
missing.							
						11. POTEN	TIAL 50.55(
						T	ES NO
3. QAR ORIGINATED	BY:	4. DISCIPLINE/DIVI	SION/SECTION	5. RESPONSE DUE	DATE		TED TO MPQA
DMTurni	oull	QSD		N/A		DATE	ER: N/A
3. ACTION ITEM NO:	15. ITEM PRIORI	TY: 17. S/U CODE:	19. A	CTION ORGANIZATIO	N 20.	QAR REVIEWS	D BY:
504121	4	PGM00		Document Contr	10	1/1/20	25
4. DISCIPLINE:	16. TREND CODE:	18. RESB CODE:	Center		21.	DATE:	
N/A	DNT	N/A				2/29/	63
22 CAUSE:			23 . PROP	SED CORRECTIVE AC	TION:	411	65
24. RESPONSIBLE OR		ervisor/Judy Davi	25. PROP	OSED COMPLETION DO	TE		
6. DISPOSITION CON	CURRENCE:	7					
- 11	Miles	12/29/1	23 _		N/A		
	AK KETIENEK	DATE		POAE (ASME DIN	.Y)		DATE
added to the this station.	tion had been controlled st The review of FID-2.400	accomplished. (ick drawings and was considered to Rev 3, Review and	performed a	a sample inspectance acceptance	tion	of the dra	wings at
METHOD OF DISPO	SITION VERIFICAT	ION		29. QAR	CLOSE	D BY	
See NIR #009.				2	MODAL	Talt	77/39/E DATE
						N/A	
				- Pc	QCE (AS	SME ONLY)	DATE
ACCEPTABLE X UNA	CCEPTABLE	SUPERCEDING CAR					

.

..

STONE , WEBSTER ENGINEERING CORPOR ON NONCONFORMANCE IDENTIFICATION REPORT

QAR No. RT-00017 Page 2 of 2 QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANCE:	December 11, 1983	NIR NUMB	ER 009
IDENTIFICATION/LOCATION	OF ITEMS: Support Se	ervices Building ion #55	
DESCRIPTION OF NONCONFO	RMANCE:		
A sample inspection was Station No. 55. A samp drawings was selected. No. A-213 was missing frentire lot of the 224 drawings was missing frentire lot of the 224 drawings.	le size of 50 drawings Accept/Reject criteria rom Station 55 control rawings has been reject	representing a lot si a is; Accept O Reject drawing sticks. As a ted.	ze of 224 . 1. Drawing result, the
This NIR describes a de- of the Control Card for applicable.	drawing A-213 does not	t show any FCR/FCNs as	A check being
epolicable			
20,08	~ 00 mi	PROGRAM MGR & Jane	
DATE 12/12/23		DATE #20/2,1	983
CORRECTIVE ACTION BY:			
	MPOAD		
	IDENTIFY ORGANIZATION	TAXING CORRECTIVE AC	TION
Corrective action had it dwgs had been added to or the drawings at this acceptable in meeting t Program. Corrective Act	the controlled stick of station. The review with requirements of FII	was considered to be s 0-2.400 Rev. 3, Review	sample inspect

REMARKS

						6. QA	R NO:		-	
MIDLAND PROJ QUALITY ASSURANCE D		U	TITY ACTION	N REC	UEST	7. DA	TE ISS	RT-000		8 REY:
deverti hasaramen a							2/29/	83		0
. REQUIREMENT:						9- p	AGE _	1 OF 3	3	
FPG-2.000 Rev	5 identifies	regi	irements for mai	ntainin	8	10. AS	ME REL	ATED		
	training recor							YES	X N	,
. DEFICIENCY:						45.7	4.5	1		
Stone and Web	ster NIR #006	iden	ntified numerous	deficie	ncies i	n constr	uctio	n train	ing r	ecords.
								73 007	ENTIAL	50.55(e
								11. POT	YES	NO.
			DISCIPLINE/DIVISION/	CEPTION	5. RESP	OKSE DUE I	ATT	12. RES		TO MPQA
. QAR ORIGINATED 5		4.	QSD	SECTION	J. KEST	1/6/84	MIE	MANAGER:		
ACTION ITEM NO:	15. ITEM PRIORI	TY:	17. S/U CODE:	19. A	CTION ORG	MOTTATION	20.	ÇAR REVI	-	
SO4122	3		PGM00	Becht	el Cons	truction	14.	1	1 A	_
. DISCIPLINE:	16. TREND CODE:	_	18. RESB CODE:	The second second second		rdinator		DATE:		
N/A	DNT		BC PCO FEST				13	2/29	183	
2 CAUSE:			2	3 . PROP	SED CORR	ECTIVE ACT	ION:			
				FOR	INF	orma	110	N UI	111	
74. RESPONSIBLE OR	GANIZATION/PERSON	٧:		25. PROP	OSED COMP	LETION DAT	TE.			
6. DISPOSITION CO	NCURRENCE:	_								
	QAR REVIEWER		DATE		POAE	(ASME ONL	7)		DATI	
27. DISPOSTION ACT	TION TAKEN:									
						Tan				
E METHOD OF DIS	POSITION VERIFICA	HOIT				29. QAR	CLUSE	D B1		
							MPQAD			DATE
							NYUNU			DATE
										1
						PF	QCE (A	SHE ONLY)	DATE
ACCEPTABLE U	MACCEPTABLE .	SU	PERCEDING QAR							
							H-	4/3A (Re	w 11	

Page 2 of 3

STONE AND WEBSTER ENGINEERING CORPORATION NONC .. FORMANCE IDENTIFICATION REPOR.

QCI 15.01 Attachment 4.1 Revision 2

PAGE 1 OF 2

the second control of the latest and	CTOBER 27, 1983	NIR NUMBER 006
IDENTIFICATION/LOCATION OF ITE	MS:	
BECHTEL DOCUMENT CONTROL CENT	ER	
DESCRIPTION OF NONCONFORMANCE:	-	
During the review of 2054 non-	-manual Construction	Training Records, three areas
of discrepancies were observer	d which were not in co	ompliance with the requirements
		sonnel." (The following Teams
wore evaluated #5, 6, 8, 9, 12		
	2, 13, 16, 17, 19, 20	, 25, 26, (2//28), 29, 30,31,
32/33), BHO Team Staff.		
(See attached for descriptions	s of Discrepancies)	
DATE otober 28, 198	0	Catobol 26, 1923
CORRECTIVE ACTION BY:		
IDENTIF	FY ORGANIZATION TAKING	COODECTIVE ACTION
3051111	TONDAMIZATION TAXING	CORRECTIVE ACTION
PRIFICATION SAT UNSAT	Lucy used	
VERIFICATION SAT UNSAT	NEW NIR#	CONCURRENCE
VERIFICATION SAT UNSAT	NEW NIR#	PROGRAM MGR

1) Course Rosters Attachment D to FPG-2.000 exhibited one or more of the following discrepancies.

BLOCK NO.	ENTRY REQUIRED	ENTRY RECORDED
1 2	(a) Name of lesson (b) Procedures (c) Revision	DWG. No. FIG. No. Either a.b. or c missing
6	Location of Session (a) Signature	Bechtel
	(b) Print Last Name	Either a or b missing
	Instructor Name	Instructor Department
	In addition many entries were left blank	. /

2) Reading Records Attachment C to FPG-2.000 exhibited one or more of the following discrepancies:

Reading Record

- 1) The department and or assignment lines are illegible or incomplete.
- Assigned reading performed on October 11, 1983 and September 29, 1983 were not documented on Reading Form Attachment C, Rev. 5.
- 3) Team Records and TSR (Training Status Report) show training completed Document Control Files showed no record of training. For example:

NAME	TEAM #	TRAINING REQUIREMENT		DISCREPANCY		
Kranzfelder	Management	FPD-2.000 (Code 2	No Record in File		
J. Hull	32/33	M-204	Code 5			

In addition to these violations, inconsistency was noted in 4 areas:

(1) Modification to records, some lined through, signed and dated and others simply lined through. (2) Some entries on course register are completed using pencil while most are in ink. (3) Difficulty is experienced in determining the accuracy of records where attendance at a course carries credit for several others. (4) Some entries carried the revision number to procedures and some omitted the revision. (5) Proper "Course Roster Form as listed in Procedure FPG-2.000 were not utilized. (6) Some courses on Rosters contain information not identical to matrix listing.

It is recommended that the disposition to this NIR include a committment to verify training records of each individual prior to status assessment assignment.

" MIDLAND PRO	JECT	~			6. QAR NO	RT-00020	
QUALITY ASSURANCE	DEPARTMENT (LITY .	ACTION R	EQUES.	7. DATE I 12/29	इक्राह्यः	8 REV
1. REQUIREMENT:					9- PAGE	1 OF 3	
	5 identifies ecords of the				d 10. ASME R	ELATED	X NO
2. DEFICIENCY: Stone and Web construction	ster NIR #007 personnel.	identified n	umerous disc	repancies	in the recor		TIAL 50.55(
3. QAR ORIGINATED I	BY:	4. DISCIPLINE	/DIVISION/SECTION	ON S. RESP	ONSE DUE DATE		TED TO MPOA
DMTurn	bull		QSD		1/6/84	DATE	
3. ACTION ITEM NO:	15. ITEM PRIORI	TY: 17. S/U C	ODE: 19.	ACTION ORG	ANIZATION 20.	GAR REVIEWS	ED BY:
504123	3	PG		htel Cons		14/10	1
4. DISCIPLINE:	16. TREND CODE:	18. RESB	CODE: Tra	ining Coo	21.	DATE:	
N/A	DNT	BC PC	O FEST		/	2/29/8.	3
Z4. RESPONSIBLE OR	GANIZATION/PERSON	li .	25. P	ROPOSED COMP	LETION DATE		
26. DISPOSITION CO	NCURRENCE:						
	QAR REVIEWER		DATE	POAE	(ASME ONLY)		DATE
27. DISPOSTION ACT	ION TAKEN:						
25. METHOD OF DISP	OSITION VERIFICA	TION			29. QAR CLOSE	ED BY	
					мродар		DATE
ACCEPTABLE UN	ACCEPTABLE	SUPERCEDING QA	IR		PFQCE (A	LSME ONLY)	DATE

W-2/18 /Day 11

STONE ANT 'EBSTER ENGINEERING CORPORATI NONCONFORMANCE IDENTIFICATION REPORT

Page 2 of 3
QCI 15.01
Actachment 4.1
Revision 2
Page 1 of 2

DATE OF NONCONFORMANCE: November	er 7, 1983	NIR NUMBER 007
IDENTIFICATION/LOCATION OF ITEMS:		
DESCRIPTION OF NONCONFORMANCE: During the review of 834 non-manuof discrepancies were observed who of FPG-2.000 Rev. 5, "Training of were evaluated #24, Field Procure and CGSO. (See attached for descriptions for	Construction Personment, Sub Contracto	pliance with the requirements
DATE NOVEMBER 7, 1983	PROG	Paramer 7,1905
CORRECTIVE ACTION BY:		
IDENTIFY	ORGANIZATION TAKING	CORRECTIVE ACTION
VERIFICATION SAT UNSAT INITIATOR DATE	NEW NIR#	PROGRAM MGR_
REMARKS		

NIR 007

(1) Course Rosters Attachment D to FPG-2000 exhibited one or more of the following discrepancies.

BLOCK NO.	ENTRY REQUIRED	ENTRY RECORDED
1	CCP	DWG. No. Fig. No. Course No.
2	(a) Name of lesson (b) Procedures (c) Revision	Either a. b. or c missing
6	Location of Session	Bechtel
	In addition some entries were left blank	

- 2) In addition to these violations, inconsistencies were noted in 6 areas:
 - (1) Modification to records, some lined through, signed and dated and others simply lined through. (2) Some entries on course register are completed using pencil while most are in ink. (3) Difficulty is experienced in determining the accuracy of records where attendance at a course carries credit for several others. (4) Some entries carried the revision number to procedures and some omitted the revision. (5) Proper "Course Roster Form" as listed in Procedure FPG-2.000 were not utilized. (6) Some courses on Rosters contain information not identical to matrix listing.

It is recommended that the disposition to this NIR include a committment to verify training records of each individual prior to status assessment assignment.

QUALITY AS:	AND PRO	JECT DEPARTMENT	ه)	ALITY ACTIO	ON REC	QUES	7. DATE IS	RT-0002	1 8 RE
1. REQUIREM	EVT	,					12/29		0
seal houseword	10						9- PAGE	1 OF 3	
approv	ed for m	training matr	ices	rements for, an . Various peop ne common facto 1 of them.	le genera	ate and	10. ASME RE		X NO
2. DEFICIEN	and the last of th								
Stone in a si	and Web	ster NIR #008 f 50 which re	ide	ntified five in ented 318 job a	adequacie ssignment	es in the	system team	11. POTU	XTIAL 50.55
3. QAR ORIG	INATED 8	Y:	4.	DISCIPLINE/DIVISION	N/SECTION	5. RESPON	SE DUE DATE	-	RTED TO MPO
	DMTurnt	bull		QSD			6/84	DATE	
3. ACTION IT	EM NO:	15. ITEM PRIOR	TY:	17. S/U CODE:	19. A	CTION ORGAN		QAR REVIEW	
804124		3		PGMOO	CP Co	Site Man		150	1
4. DISCIPLIN	E:	16. TREND CODE		18. RESB CODE:		ization	- Marine	DATE:	1
N/A	-	DNT		CPCO SM				2/29/	
		ANIZATION/PERSON				SED COMPLET	INATIC	i. Uni	¥
	Q.	AR REVIEWER		DATE		POAE (AS	ME DMLY)		DATE
ZZ. METHOD		SITION VERIFICAT	TON			29	MPQAD	ВУ	DATE
ACCEPTABLE	UMA	CCEPTABLE -	SUPE	RCEDING QAR		4	PFQCE (AS	ME ONLY)	DATE

W-4/14 /Day 11

QAR No. RT-00021 Page 2 of 3

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

		PAGE 1 OF 2
DATE OF NONCONFORMANCE: NOVEMBE	R 8, 1983	NIR NUMBER 008
IDENTIFICATION/LOCATION OF ITEMS:	Link State and Con-	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SYSTEM TEAM TRAINING MATRIX, REV.	1. DATED JULY 20.	1983
DESCRIPTION OF NONCONFORMANCE: During the review of the adequacy size of 50 training level assigns five unsatisfactory conditions we The System Team Training Matrix of to perform the review. See the attached for unsatisfactor conditions reported represents a TNITIATOR DATE 1/14/83	of the construction nents, representing are observed in the soft the Construction ory conditions observed condition for the construction the con	n training matrices, a sample a lot size of 318 assignment training level assignments. Training Program was utilized a lot size of 318 assignments.
CORRECTIVE ACTION BY:		
IDENTIFY	ORGANIZATION TAKING	CORRECTIVE ACTION
VERIFICATION SAT UNSAT	NEW NIR#	CONCURRENCE
VERIFICATION SAT UNSAT INITIATOR	NEW NIR#	CONCURRENCE PROGRAM MGR

REMARKS .

1. *FPG 9.700, "System Team Charter"

FPG 9.700 appears on the "System Team Training Matrix" as a Level "O" (no training required) for the system team field engineer, mechanical. Paragraph 5.2.7 of this procedure identifies the job responsibilities and reporting relationships for the system team field engineers. As such, a level of training of "O" (no training) is not satisfactory.

2. FPO 1.201, "Bechtel Assigned Post Turnover (PTO) Work".

FPO 1.201 appears on the "System Team Training Matrix" as a Level "O" (no training required) for the system team field engineer, mechanical. In discussion with the Team #5 supervisor, it was noted that the Team members do get involved in Post Turnover Work. Because of this involvement by the Team members, a level of training of "O" (no training) is not satisfactory.

3. FIG 1.400 "Preparation, Review and Routing of Field Engineer's Reports."

FIG 1.400 includes responsibilities for several disciplines, ie; mechanical. civil, welding, and instrumentation as well as including responsibilities for the electrical discipline. The following conditions were noted as being unsatisfactory;

- (a) The "System Team Training Matrix" under the column entitled "Responsible Discipline" shows this procedure to be an electrical discipline procedure.
- (b) The "System Team Training Matrix" requires the field engineers of the mechanical and the instrumentation disciplines to receive a level "2" training whereas the field engineers of the electrical and welding disciplines receive a level "3" training. There is an inconsistancy of training levels being assigned.
- 4. Specification M-214, "Piping System Erection Fit-up Control Requirements."

M-214 appears on the "System Team Training Matrix" as a level "O". (no training required) for the system team field engineer, welding. Specification pages 3, 5; 78 and 8 address welding. Also, weld fit-ups are addressed throughout this specification. As such, a level of training of "O" (no training) is not satisfactory.

5. Drawing E-039 - "Seismic Wireway Supports."

E-039 appears on the "System Team Training Matrix," as a level "0" (no training required) for the system team field engineer, welding. This drawing contains weld sizes and weld symbols for typical wireway supports. As such, a level of training of "0" (no training) is not satisfactory.

It is recommended that the disposition to this NIR include a committment to verify the adequacy of all training matrices.

Midland Project: PO Box 1963, Midland, MI 43640 + (517) 631-8650

PRINC	IPAL STAI	F
RA KUB	2	-
A/RA	DAMSH	COLUMN TO SERVICE STATE OF THE
RC.	DRIGA	- 3.au
PAO	BUS	

LAB 01-84

January 4, 1984

Mr Stan Baranow Stone & Webster Engineering Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF (3) COMPUTER PRINTS

You have been placed on a weekly distribution for the following MPQAD Personnel printouts.

Summary of Inspector Training - PMerritt Personnel Forms - Perschk Item Complete - PBack

These prints will be forwarded to you each Monday until further notice.

GFEwert/LABotimer

Prints for the week of January 2, 1984

cc: JHarrison, NRC DLQuamme, Site Mgr RAWells, MPQAD

2401120426



Deen L Quemme Site Manager Midland Project

Midland Project: PO Box 1963; Midland, MI 48640 * (517) 631-8650

January 3, 1984

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640 PRINCIPAL STAFF
PA MAPPED

D/RA

DE

A/RA

DRASH

RC

PAO

SOS

SOA

ENF

FITO

ANA

3 16 49.

MIDLAND ENERCY CENTER GWO 7020
UNSATISFACTORY CONDITIONS ON TRAINING MATRIX, NIR-008
File: 0400.2, Bl.1.7, 0655 UFI: 06*02, 99*08, 53*50*04 Serial: CSC~7127

Attached is a letter from Bechtel dated December 29, 1983 regarding the five unsatisfactory training level assignments identified in NIR-008. The scheduled date for completing a review of the entire matrix and issuing a new revision is mid January 1984.

DLQ/DDJ/klp

CC: JJHarrison, NRC Region III w/a
JGKeppler, NRC Region III w/a
RJCook, NRC-Site w/a
BHPeck, MEC w/a
RAWells, MPQAD w/a
NIReichel, MEC w/a

SY04120367

6.05

LL.LRIT

1 10 > 1001

Sila Mg:.

Midland Project

Becl 3 Power Corporation

Post Office Box 2167 Midland, Michigan 48640

December 29, 1983

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D. L. Quamme

Site Manager

Job 7220 Midland Project NIR-308, OBSERVATION #34 UNSATISFACTORY CONDITIONS ON TRAINING MATRIX BCCC-8838 JFF

JMB

VMB

TAB

RFK

ADK

SLAN

SKP

NJS

VCC-NJR

FLENO.

Dear Mr. Quamme:

The review of a sampling of the training matrix by Stone & Webster uncovered five possible unsatisfactory conditions. The conditions are inconsistencies between the levels and areas of Orientation and Indoctrination (O&I) Training that the systems teams receive.

The assignment of the level and area of O&I training is based on judgement as to what the requirements are for bringing a qualified employee up to speed to accomplish the CCP. This judgement was made by various groups who established the levels for their respective areas, using some general guidelines. With this approach, there is a chance for inconsistencies due to difference of opinion and judgement.

One item sited by Stone & webster was the lack of O&I training for a welding engineer on the electrical support drawings (E-039). Even though these drawings have welding symbols and sizes on them, the group establishing the levels of training made the determination that these drawings, as well as many other drawings, do not have to be included in the O&I training for welding engineers.

Another item involved an inconsistency between some members of a team receiving a level 2 (read only) and other; having level 3 (read and review with supervisor) on the same procedure (Preparation, review and routing of Field Engineer's Report). This is an inconsistency though not serious, and the matrix is presently being reviewed to eliminate this type.

The other three unsatisfactory conditions involved leaving off some members of a team from an O&I training requirement of level 2 (read only) on two general procedures and failing to require O&I training for the welding engineer on piping specification M-214 (Piping system erection fit-up control requirements).

D. L. Quamme BCCC-8838 Page Two

In regard to the piping specification, it has almost no involvement with welding or welding fit-up and is a pure judgement call as to whether welding engineers should be required to have O&I training on the specification. Of the other two procedures, one obviously should have been included as a systems team requirement (FPG-9.700, System Team Charter) and the other is a matter of judgement as to who requires O&I training on the "Bechtel Assigned (PTO) Work" procedure.

In summary of the five items noted by Stone & Webster, two are clear inconsistencies and the other three fall into an area of subjective opinion.

To eliminate our inconsistencies in levels and areas of O&I training, we have a committee reviewing the entire matrix with the goal of issuing the next revision by mid January 1984.

Very truly yours,

G. A. Hierzer Site Manager

GAH/EK/jkc

Written Response Requested: No



Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

December 22, 1983

PRING	CIPAL ST	AFF	
VA JE	OPRP		1
J/RA	DE		1
A/RA	DRMSP		1
VRC Ila	DRMA		1
PAO	SCS		veri + 3
SGA	ML		0
ENF	File	Kin	1

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWO 7020
HANGER REINSPECTION
File: Bl.1.7, 0655 UFI: 99*08, 53*50*04 Serial: CSC-7115

Attached are copies of memos written by J Christy, MPQAD on November 21, 1983 and December 6, 1983. These should clarify the meeting note in Report No 23 regarding reinspection of 500 large bore hangers. Please advise us if more information is needed to resolve this issue.

DLQ/DDJ/klp

cc: JGKeppler, NRC w/a
JJHarrison, NRC w/a
RJCook, NRC w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a

5401050350

UEC-30 1988

JTChristy & Christy FROM

DATE

MIDLAND ENERGY CENTER PROJECT SUBJECT PROJECT CONCERNS RELATIVE TO DESIGN CONTROL -REDLINE REINSPECTION IMPACT ON THE HANGER

REINSPECTION PROGRAM

Consumers power company

CORRESPONDENCE OC-JTC-83-62

TC MEPlumb

HPLeonard WJFriedrich ...

The following data is submitted to support the required decision on the action plan for the subject Project Concern:

1) 1768 hangers have been reinspected using the P-2.30 PQCI.

2) Based on a survey of the closed P-2.30s, between 69 and 73 percent were inspected using redlines (LH, SH or FRL drawings). This is a population of approximately 1250 reinspections.

3) Of the 1250 reinspections in 2), approximately 450 will have to be reinspected due to problems with disapproved, illegible or "approved with comment" redlines.

4) Approximately 50% of all reinspections will require another inspection due to the decision to remove paint and rust from welds.

5) All large bore hangers will require reinspection for the location criterion.

The data in 1-5 above can lead to the following conclusion concerning reinspection after redline incorporation:

P-2.30s using unacceptable P-2.30s which used Completed P-2.30s using redlines - redlines which must be redlines which probably minus- reperformed (3) require weld reinspection (2) minus (50% of (2)) 1250 625

Number of hangers which will have to be P-2.30s which used redlines which are reinspected as a result of the subject minus part of population (3) proposed action plan. (50% of (3)) 400

This does not account for possible decisions related to NDE issues or IE Bulletin 79-14 issues.

If you have any questions concerning this data please see me.

JTC:mlt

225

To

JChristy

FROM

MEPIUM

DATE

December 6, 1983

SUBJECT .

MIDLAND ENERGY CENTER PROJECT -HANGER REINSPECTION PROGRAM

CONSOLIDATED APPROACH TO RESTART

MEP-83-52

cc CPaulsen

LMouring CAnderson MMcClain BWilliams WJFriedrich

FSchulmeister

Consumers Power Company

SORPESPONDENCE

The following recommended actions deal with the restart of the Hanger Reinspection Program. These actions were discussed and agreed upon by the MPQAD personnel listed below.

M Plumb

F Schulmeister

C Paulsen

M McClain (NDE only)

L Mouring

B Maycheck (NDE only)

C Anderson

Redlines A: For all inspections completed after the lifting of stop work order #FSW-34, only drawing/ISO's for which all redlines have been incorporated will be used.

B: All P-2.30's which were completed using redline drawings will be reinspected for orientation and configuration using a drawing/ISO with incorporations completed.

Paint/Rust: Welds are being inspected with all paint and heavy rust removed.

Any welds inspected previously through paint or rust will be inspected again after cleaning.

Location: Due to stress calculation requirements for large bore hangers, locations for all large bore hangers will be inspected to the H-ISO location.

Drawing
Conflicts A: There has been a conflict between H-ISO and M-ISO for pipe
configuration. The known cases have been corrected. Any future
cases will be documented on an NCR for indeterminate location
and class break.

B: The ATMS will be completely updated by 12/9/83 per Document Control. When FSW-34 is lifted the ATMS will be the controlling document to determine drawing revision status.

C-1.52's:

All hangers with open C-1.52's will have to be closed. QA will rewrite the PQCI and training will be provided to certify inspectors.

-TE Bulletin 79-14:

A copy of the hanger sketch will be marked up as an as-built drawing during the P-2.30 re-inspection. This drawing will be retained by MPQAD-QC. This will continue until a commitment to 79-14 is made by MPQAD.

QARS/NCRS Against M-326 & C-304:

Because of the undispositioned QAR's and NCR's against these specifications, PQCI P-2.30 will be revised to meet the minimum requirements of the FSAR and codes referenced in the FSAR. Note: A) Undercut requirements under the new revision to P-2.30 are going to be revised. B) Skewed fillet weld criteria is going to be revised.

Recommendations: Request a freeze of P-2.30 inspection criteria until the HRP program has reached a stabilized level. At that time changes would be discussed and added with concurrance of the assistant

superintendent.

Summary:

During the restart and for the completion of the HRP, and to facilitate the above actions, all hangers within the program will have a Rev. 5 IR for P-2.30 opened. This could be only for a statement that none of the criteria changes affects this hanger to a detailed inspection. The scope of the IR would be the governing factor for the amount of reinspection to the later rev. Items needing reinspection will be determined by the AQAES for inspection atributes and the Assistant PFQCE for the individual hangers.

10 12.6.83



Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-9650

December 20, 1983

L PR	INCIP	PAL ST	AFF	1
RA	for	DPRP		7
D/RA		DE		7
9/RA		DRMSF		1
PC	he	DRMA		7
PAO		SCS -		Jorin +
CGA		ML		1 5
E.NF		File	Ka	1

Mr Stan Baranow Stone and Webster Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -STONE & WEBSTER NIRs 002 THROUGH 004 FILE 24.2 SERIAL 27245

Our QAR No. RT-00010, which was sent to you on October 13, 1983, was issued to track the extended review of qualification and certification records.

This QAR indicated that the proposed completion date was December 16, 1983. The purpose of this letter is to advise you that completion is now scheduled for December 30, 1983.

Gary F Ewert, Division Head

Quality Services

Midland Project QA Department

GFE/kw

CC LABotimer
JRKeppler, NRC Region III Administrator
DLQuamme, SMO
DMTurnbull
I \Wells



Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

December 16, 1983

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

PRINC	CIPAL STAFF	
RA	- DPRP	
D/RA	DE	
A/RA	DRMSP	
RC	DRMA	
DAO	SCS	Jorig +
SGA	ML	X
ENF	File	

MIDLAND ENERGY CENTER GWO 7020 OBSERVATION 37, REPORT 24

File: Bl.1.7, 0655 UFI: 99*08, 53*50*04 Serial: CSC-7102

Attached is close out documentation for NCR-C00925 which resulted from your Observation 37, Report No. 24. Please advise if this action is acceptable for close out of Observation 37.

DLQ/DDJ/klp

cc: RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
RJCook, NRC w/a
JGKeppler, NRC w/a
JJHarrison, NRC w/a

Bechtel Power Corporation

Post Office Box 2167 Midland, Michigan 48640



December 15, 1983

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme

Job 7220 Midland Project CONSTRUCTION REVIEW OF STONE AND WEBSTER'S CCP OVERVIEW OBSERVATION NO. 37, REPORT NO. 24 BCCC-8822

Dear Mr. Quamme:

Reference: Ltr. G.A. Hierzer to D.L. Quamme dated December 9, 1983 BCCC-8802

Per the above reference, Construction's complete response to the subject observation is detailed below.

The disposition of NCR C00925 was implemented on December 9, 1983, and the NCR was subsequently closed on December 14, 1983. A copy of the closed NCR is attached for your use.

If you have any questions concerning the above, please contact B.T. Foote at Ext. 7507.

Very truly yours,

G.A. Hierzer Site Manager

GAH/BTF/MRM/1cc

Attachment: NCR C00925

Written Response Requested: No

5	DEPARTMENT NON	ONFORMANCE	REPORT	1	11-22-83	
		RECORD		PAGE _	1 of 1	
1	AUX. BLDG. (6'-6"E	15.0; 2'-6"5/4	ELEV.	634'+15'		
	ITEN DRAWING/PART NO	3 ITEN PART NAME	NAME AND ADDRESS OF THE OWNER, WHEN PERSON NAMED IN COLUMN 2 ASSESSMENT ASSES		4. ITEN SERIAL M	٥.
	. NIA	IAKA19			NIA	
	THE DESCRIPTION CABLE TRAY IAKA					
6	THE STARTUP STSTEM NO. N/A	7 REFERENCE DOCL	E-42	Α	B ASTE A.M.I. R	ECU XO
9	DESPECTION RECORD NO. LOS NO. N/A		CONSTRL	JCTION		
1	NONCONFORMANCE DISCOVERED CURING:	D POST TURKON	CR D PRE	, , ,	ER CYELL	
2	REQUIREMENT E - 42A (SHT	· P STATES	"CONDUCTO	ES IN TRAY	SHALLBE	
	PROTECTED DURING T	HE CONSTRUCT	TION PERI	OD AGAINST	DAMAGE	
	FROM ANY SOURCE.	PARTICULAR	ATTENTIO	N SHALL B	E GIVEN TO	>
	PROTECTION FROM	WELDING .AND	BBENIO	7		
3	CABLE TRAY LAKA	IN CONTAIN	LUMBE	A WITH NA	LS PROTRI	Ou
	CABLE TRAY TARA	- 4 0:56	5 05 500	D. 15 14 711	E SAME TO	0.1
	FROM IT. ALSO THE	RE IS A PIEC	E OF COR	DAMAGE	TO ALL OF	-
	THIS SITUATION IS					
	CABLES IN THIS. TO			A NER ORIGINATED	BY (PERSON)	
	VIOLATION OF E-4	2A, SHT. 7(f)	•	(olaines	Sigue.	11-
			,	S MER CRIGINATED	BY (DISCIPLINE)	
				MPQAD -	OCD- ELECT	210
	THE ATTEMPT OF A PERSON AND A P	1 21 1004	TION OF HOLD TA	£5		
	MUMBER OF HOLD TAKES (IF APPLIED)		1AKA19			• • •
2	POT LAL 50.55(e) 24 AC	רדומא ודבא אס.	26 TIEN PRI	DRITY CODE NO.	Z8 NCR REVIEWED	BY:
	□ 155 ⊠ NO S	03991		5	Melo relate	1-
3	REPORTED TO HADA MANAGER 25 DE	SCIPLINE:	2 TO:0 CC	DE . 1	DATE: .	
	CIT	E	B- 3	5	11-22-83	
		י בבהתוואכם	ON REVERSE		F-25/14 (Ed	• 7

i smiffolds in disposal.	
D PROCESS CORRECTIVE ACTION OFF NO DAR NO.	
31 RECONTROL DISPOSITION 32	COMDITICIAL RELEASE
☐ SEPARE ☐ SEPARE ☐ USE AS IS	TES NO
Construction to remove Leftover materials, Lumbe the tray IAKAI9, Following Housekeeping procedure	Allow Aiz-1-83
Construction:	
JAMEN 12-1-83 DE NPQAD CONCURRENCE DATE	PRIE (1.9E)
	PORE (ASPE)
LEAD DESIGN ORS DATE CP Co SMO (for turned over systems)	A.H.I. (ASKE)
Lumber and conduit have been removed from Tray IAKA blanket protective covering was pulled back. Cables which near Lumber and conduit were examined for damage Fire blanket protective Covering was replaced. Note No 1: This NCR is in response to; Stone & Well.	oster Pipt 24/08
36 KETHOO OF DISPOSITION ACTION YERIFICATION	37 NOR CLOSED BY
RESULT OF DISPOSITION ACTION VERIFICATION IF UNACCEPTABLE, REFERENCE SUPERCEDING NOR NUMBER	Colona Salar



STONE & WEBSTER MICHIGAN, INC.

P.O. Box 2325, Boston, Massachusetts 02107

Mr. J. J. Harrison Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137 December 15, 1983 J. O. No. 14509

Re: DOCKET NO. 50-329/330

MIDLAND NUCLEAR COGENERATION PLANT MONTHLY THIRD PARTY ASSESSMENT MEETING

The protocol governing communications for the Remedial Soils and Construction Completion Programs at the Midland Plant, specifies a monthly meeting to discuss third party assessment activities and assigns preparation of the minutes of those meetings to Stone & Webster.

Enclosed are minutes of the meeting held on December 8, 1983.

A. P. Amoruso Project Manager

CIO

Of momenta for A. S. Lucks

Project Manager Underpinning and Remedial Soiis

Enclosures

cc: JWCook, CPCo DLQuamme. CPCo RAWells, CPCo

3401100224

DEC 27 1983

MINUTES OF THE MEETING OF DECEMBER 8, 1983

STATUS OF INDEPENDENT ASSESSMENT OF UNDERPINNING AND REMEDIAL SOIL WORK

Purpose

This was a Public meeting to discuss the Third Party Overview activities of Stone & Webster (S&W) and observations encountered regarding underpinning and remedial soils work.

Summary

A.S. Lucks opened the Assessment Team's presentation by stating it would consist of three parts: first, A.S. Lucks would address two of three action items assigned at the previous Public meeting; second, W.E. Kilker would cover the Assessment Team's activities for the month; and third W.C. Craig would address the third action item with a presentation on his report concerning the change and nonconformance documents.

A.S. Lucks began the first part of the presentation addressing the first of two action items. This First item concerned a question by the NRC as to whether two NCRs written against a concrete pour were related to problems with U.S. Testing. A.S. Lucks stated that the governing specification for the concrete cylinders in question required that the forms be removed between 12 and 24 hours after placement or after 7 days. QC had not verified compliance with the requirement so MPQAD issued two NCRs against QC. This problem was not related to U.S. Testing.

The second action item concerned the status of the Stop Work Order review of change documents pertaining to soils. A.S. Lucks presented the status as of December 6, 1983. The breakdown is as follow:

- Total civil FCRs/FCNs related to soils 856
- Phase I review of FCRs/FCNs indicating potential problems 410
- Phase 2 review of the 410 Phase I documents that contain problems
 208
- A.S. Lucks indicated that the most significant result as of December 6th. was that no NCRs have been issued for the soils area from either Phase 1 or Phase 2 reviews. The Assessment Team along with the CIO Team are reviewing the Phase 1 product. This review has not been completed and there are no Assessment Team conclusions to date. Mr. Wells confirmed the soils figures and added that 8 NCRs had been written so far for the total effort. These relate to questions of generic implementation.
- W.E. Kilker opened his presentation by indicating that, due to the Stop Work Order no construction progress had been accomplished on the underpinning. A summary of the Assessment Team activities during the period November 5 through December 6, 1983, follows:
 - A review of crack monitoring procedures and activities of the subcontractor Wiss, Janney & Elstner (WJE) was the major Assessment Team effort during this time. The review results indicated:
 - Minor data recording problems.
 - 2) A procedural violation where the subcont.act used a procedure with a hold indicated on it. The related specification did not have a corresponding hold on it. NIR 16 was issued.
 - (3) Incomplete entry of crack monitoring data for a particular wall. NIR 18 was issued.

- 4. Prior to the Assessment Team review NCRs and QARs had been issued against WJE for procedural violations. An Assessment Team observation stated that not enough attention was given by Consumers Power Company (CPCo) in performing the crack mapping.
- More attention should be paid to coordinating procedure changes with specification changes and vice versa.
- 6.) The MPQAD group follow-up for closing out inspection reports should be more prompt. No PIPRs had been issued for the crack monitoring. NIR 19 was issued.

In summary, three NIRs (16, 18, 19) and numerous NCRs and QARs have been written concerning data on this subject. They require resolution prior to continuing construction upon release of the Stop Work Order. The data itself is basically sound and should not be voided. Problems were mainly procedural, for example, attention to minor details and timeliness for closeout. Mr. Harrison stated that the NRC has issued a document to Mr. Quamme dated December 6, 1983, placing a hold on soils work until this issue is resolved.

An overview of FSO prepared Work Activity Packages (WAPs) by
the Assessment Team continued. Two overviews were conducted,
one on Piers E/W5 and grillages and the other on anchor bolt
installation in the Service Wate Pump Structure. Mr. Landsman
asked that in the future weekly reports, the subject of the WAP
be identified along with the WAP number. W.E. Kilker agreed.

- The Assessment Team commitment to review past weekly reports for open items with closures that may not have been fully documented, has been completed. All open items identified as requiring verification of closure have now been closed.
- The last activity was summarized by A.S. Lucks concerning the S&W review of FCR/FCN resolution.

The stat s of NIRs is as follows:

- NIR 14 is in the process of being closed on the basis of a response that has been prepared by MPQAD. This NIR indicated that the receipt inspection did not properly identify a certain grade of nut to be used with particular bolts on the grillages at Pier 8.

 A programmatic investigation produced a revision to the receipt inspection procedure that now requires a 100 percent inspection where before it was done on a sampling basis. PQCI will verify that the nuts actually installed are those specified on the drawing. On this basis the NIR will be closed.
- NIRs 16, 18, and 19 have been previously addressed in the discussion of crack monitoring.
- NIR 17 addressed the Phase 1 review of the change document that is being conducted as a result of the Stop Work Order. Later dialogue indicated that the MPQAD review was preliminary and did not match the Assessment Team interpretation of the applicable procedure. The procedure was changed to clarify this point. The affected FCRs were disposed of in accordance with the Assessment Team interpretation and the NIR was closed.

W.C. Craig opened the summary of the Assessment Team report "Evaluation of Change/Nonconformance Documents" by explaining that the report was initiated due to Assessment Team's concerns expressed in Weekly Reports 40, 43, and 46, about the time it was taking to construct piers.

A familiarization process was conducted where Mr. Craig took the following actions:

- A review of design drawings
- Visits to the site and work areas
- Attendance at appropriate meetings
- An evaluation of change and nonconformance documents to establish trends
- Review of governing procedures
- An evaluation of the organizational structure for processing the change and nonconformance documents.

The results indicated that the effect of FCRs and FCNs on construction warranted further investigation.

An analysis of change/nonconformance response times was performed using a large sample of the documents. They were classified to show impact by subject matter. The results indicated that although response times in general, looked good on a day to day basis, the unique importance of sequencing to underpinning efforts magnified the effect on the construction schedule.

The recommendations that resulted from this study were then presented.

Recommendation No. 1

A program implemented to review both existing and new construction procedures,

project quality control instructions, and project specifications should receive a high priority. This effort should:

- define poor quality attributes,
- ensure that activities are more consistent with the
- intent of the specifications,
- clarify quality requirements
- define better utilization of technical resources in achieving quality goals.

Response to Recommendation No. 1

The Bechtel Field Soils Organization (FSO) presented a proposal for the QAP review program to CPCo. management. The generic concept of the QAP review program was accepted by CPCo management. CPCo's management assigned the lead responsibility of this activity to MPQAD and established a Task Force approach involving a full committee and subcommitte.

The Task Force committee established guidelines as follows:

- a. Select subject for a pilot review program
- b. Develop guidelines for the subcommittee
- c. Identify subcommittee representatives
- d. Schedule activities
- e. Review subcommittee recommendations
- f. Make recommendations to management.

The subcommittee reviewed installation of Hilti Expansion Anchors and covered the PQCI, Construction Procedure, and the specification and made recommendations to the Task Force committee regarding proposed revisions to these documents.

A second procedure covering structural steel was selected for review.

After the review of the second procedure is completed, the subcommittee will make further recommendations to full committee.

The final extent of this effort and the decision to review other procedures is contingent upon the recommendations that will be made to CPCo's management by the Task Force committee after the completion of the review of the second procedure.

Recommendation No. 2

Expedite the underpinning design work so that the associated design calculations and drawings may be transmitted to the job site along with necessary technical support. This will expand the ability of the Resident Engineer to approve the change or non-conformance documents in the shortest time possible. Maximum engineering support at the jobsite would assist with problems encountered with this type of work.

Response to Recommendation No. 2

The design calculations for the Borated Water Storage Tank were delivered to the site as of November 2, 1983.

The design calculations for the Service Water Pump Structure will be delivered to the site in two phases. An initial review of the proposed delivery dates coincides appropriately with the construction activities.

The design calculations for the Auxiliary Building, with the exception of computer calculations or extremely complex calculations, will be delivered to the site in three phases. An initial review of the delivery schedules indicates that they coincide appropriately with the construction activities. These calculations will also be supported with additional design personnel

'assigned to the jobsite.

The Resident Engineering Soils Organization has been reorganized and an additional Group Lead dedicated to the handling of FCRs, FCNs and design-related NCRs and vendor drawings has been assigned. Seven additional designers have been assigned to this organization.

Bechtel has issued a memorandum covering the reorganization of the Resident Structural Engineering Soils Group, assignments of increased responsibility at the jobsite, and the goal of having the capability for 80 percent final approval of change documents at the jobsite.

Technical support is currently onsite for the engineering consultants of Hanson Engineering Inc. and Mueser, Rutledge, Johnston and DeSimone.

Recommendation No. 3

FCRs should receive final approval by the Project Engineer shortly after interim approval has been granted.

Response to Recommendation No. 3

Bechtel procedure entitled "Field Change Request/Field Change Notices, PEP No. 4.62.1, Rev. 1, dated December 2, 1983 has established time intervals from interim to final approval of FCRs and FCNs. An expected approval time, a maximum approval time, and an overall approval time for initiation to final approval have been stipulated.

This procedure also establishes guidelines for the updating of drawings and covers this in terms of all change documents and specifies a maximum time for updating drawings from the issuance of the first document and a maximum time after the issuance of a fifth document.

The response time will be improved with the delivery of the calculations to the jobsite, increase in the staff of the Resident Structural Engineering Soils Group and its reorganization as described in the Responses to Recommendations No. 2.

Bechtel has also instituted a review for drafting completeness on the change documents in order to expedite the turnaround time on drawing update.

CPCo. proposes to phase out the use of interim approval on the FCRs and FCNs and expects to implement this in the first quarter of 1984.

Recommendation_No. 4

NCRs should have trend analysis performed which relate the number of NCRs to the level of construction effort. Also, the NCRs should be classified by subject, and this should be issued and reviewed to assist in providing an indicator to problem areas.

Response to Recommendation No. 4

Bechtel performed a one-time study of NCRs that relates the NCR to the construction effort in terms of man-hours. This study indicated a direct correlation between the number of NCRs issued and the level of effort in terms of man-hours that was being expended. However, no trending of quality can be made from this study.

Bechtel has entered all of the NCRs in a computerized logging system that permits the NCRs to be sorted by date, subject matter, response time, and other attributes.

The FSO has developed and is using an NCR evaluation form which will review each NCR issued and determine if there is a need to take corrective action

on the methods used to accomplish the work. The FSO is also performing a detailed evaluation of all NCRs related to welding.

MPQAD is developing a trend analysis system to be applied plantwide that will evaluate the total number of attributes against a number of unsatisfactory attributes versus time for each activity and attribute. It is expected that this new trend analysis will be implemented in the first quarter of 1984.

Recommendation No. 5.

It is important that Bechtel continues to strive to reduce the response time on critical NCRs that could delay the work.

Response to Recommendation No. 5

The FSO will continue to identify and status critical NCRs at the weekly Engineering/Construction meetings which are attended by AAPD Project Engineering, Resident Engineering, Field Engineering, MPQAD, SMO, and the Independent Assessment Team.

The Resident Engineering Soils Organization has been expanded with additional personnel onsite who have specific responsibility and authority to disposition design-related NCRs. This should reduce the current response time and minimize the response time on priority NCRs which could impact the progress of the work.

Bechtel will continue to give priority to the NCRs being reviewed by MPQAD.

- Mr. J. Mooney and Mr. R. Wells then provided the following responses to the five items requiring CPCo action from the November public meeting.
 - Compare the findings of the MPQAD audit of U.S. Testing with results of Field Engineering's evaluation.

The primary purpose of the Field Engineering evaluation of U.S.

Testing was conducted with the goal of assessing management, staffing, and ability to meet project demands. It was not an audit directed at identifying non-conforming programmatic QA requirements. However,

CPCo compared the results of the Field Engineering evaluation with the MPQAD and confirmed that the Field Engineering evaluation observations had not identified non-conforming items that had been missed by the MFQAD audit. U.S. Testing has continued to make progress in improving their operation and a new manager, Mr. Lawrence Smetana is on site.

- 2. Evaluation of the concrete work truck mixer drum rotation problem.
 Several discussions have been held between the NRC Region III Staff
 since the November public meeting. CPCo now understands what is required to resolve the problem. CPCo will provide a response on this item to
 Region III within the next several days.
- 3. Transfer of the lessons learned from the Auxiliary Building underpinning to the Service Water Pump Structure.underpinning

A task force has been formed to review the auxiliary building underpinning activities. The task force is compiling a matrix of lessons learned which will be used to review the underpinning for the Service Water Pump Structure. The matrix is scheduled for completion by December 16, 1983 and the review has a targeted completion day of January 30, 1984.

Based upon review of the QC inspections of non-structural welds, it was determined that when the QC inspectors were verifying the

4. QC inspection of non-structural welding on Q materials

welding engineer's sign-off on non-structural welds, they have been reinspecting the welds for possible damage to base Q materials even though this was not required by the PQCI. This was verified by 100 percent interview of the QC inspectors. However, there was one exception, the tack welding of jackstand guides to pier baseplates was not inspected by MPQAD. In this case, reinspection has found that the welds are satisfactory. The PQCI will be modified to require that this aspect be documented in future.

5. Crack mapping problems

An extensive review of the crack mapping program has been undertaken. Problems were identified with respect to procedural attributes, specifications, and timeliness of reporting and review. Several NCRs and QARs were issued. On November 30, 1983 a status report was provided to Region III and the specific corrective actions were documented in a letter to Mr. Harrison dated December 2, 1983. All corrective action will be accomplished before work resumes.

Mr. Landsman asked whether the revised procedures would be under level 3 approval. CPCo replied that they would be Level 1. Mr. Landsman and Mr. Harrison also expressed concern that the QA overview had not been performed for an activity that had been ongoing for some 2 years. CPCo pointed out that the overview requirements had only been in existence for some 10 months, but they realized that this function had been missed. The corrective action will be taken to prevent recurrence.

This concluded the presentations at which point Mr. Harrison stated that the status of the required actions from the November meeting are:

S&W actions—all items closed

CPCo actions -- Items 1 and 4 closed, with the other items
 remaining open

Questions and Answers

- Mr. J. Harrison and Dr. R. Landsman asked several questions concerning items included in Assessment Team Weekly Reports Nos. 59 through 62:
 - 1. Could Stone & Webster elaborate on Item 59-18 that refers to a hold on a crack monitoring procedure? The part of the Wiss, Janney and Elstner crack mapping procedure dealing with crack monitoring after the loading of the E/W8 grillages was designated as being on hold. The crack monitoring was performed using this procedure. The specification did not indicate that there should have been a hold. The crack monitoring was completed at the appropriate time but the hold was still indicated in the procedure. NIR No. 16 was issued because of this.
 - 2. On page 2 of Weekly Report No. 59 it is mentioned that the review of Weekly Reports No. 30 through 59 identified 8 items that required verification of closure. Were these included in the open item list? Yes. The correct number was 5 items.
 - 3. Item 59-5 indicates that the 4 hour time requirement for reporting two new 10 mil cracks at the SWPS was exceeded by a large amount (18 days). The NRC stated that action must be taken to avoid such delays in the future. The initial report was made some 2 days after the cracks were noted but the data sheets were illegible and this resulted in the long delay in noting the alert level.

- 4. Item 59-13 reports that the Assessment Team received strength test results for the plasticized concrete mix design. Did the Assessment Team state whether they were satisfactory? No. the results were requested for information only.
- 5. Item 59-16 indicates that the SWC was revised to allow the processing of interim approved FCRs and the completion of the SWPS/CWPS seals. Why was this action taken? The interim approved FCRs had to be processed so that they could be included in the SWO corrective action. The work on the SWPS/CWPS seals was a maintenance type item.
- 6. Item 59-17 mentions two NCRs on Carlson meter concrete curing at Pier W8. Was Pier W8 loaded with open NCRs? The NCRs were written based upon a QA Overview of Inspection Reports. Pier 8 was completed during the summer and the QA overview of old Inspection Reports was conducted during November. Therefore, these NCRs were not issued when the pier was loaded. CPCo will respond to this item at the January public meeting.
- 7. Item 59-6Q identifies a welding consultants report that was given to the Assessment Team. What were the contents of the report? The welding consultant was retained by MPQAD to review the welding inspection because there had been a number of NCRs issued in this area. The consultant, Mr. Svekric of Welding Consultants, reviewed the welding procedures and the inspections. The consultant concluded that the number of NCRs were related to the type of welds being performed and that the level of inspection was appropriate.

- 8. Item 60-3 indicates that crack mapping was included in the SWO. Was that the case? Yes, initially the crack mapping was stopped. Two days later it was exempted from the SWO.
- 9. Item 60-3Q identifies a mechanism for identifying Quality concerns. Could CPCo elaborate on this item? MPQAD has A new procedure to obtain information or clarifications is now used to replace the old QAR procedure. The new procedure is entitled "Request for Information/Action."
- 10. What does the last sentence of Item 60-4Q mean? The inspection of structural welds is not accomplished by the same procedure as nonstructural welds. In the case of structural welds. QC does all of the inspection.
- 11. On page 1 of Weekly Report No. 61, the Assessment Team reviewed a sample of the classification of change documents: being reviewed as part of Phase 1 of the SWO corrective action and found one-third did not meet the procedural requirements. Could this be elaborated upon? The batch of change documents supplied to the Assessment Team had not been subjected to the complete review process thus resulting in the high percentage of problems.
- 12. Is the Assessment Team finding that the Work Activity Packages
 (WAPs) submitted for review are in better shape than they were,
 say, a year ago? What is the turn around time? Yes, there
 has been improvement. The turn around time is about a week, but

there are reviews that take longer.

- 13. Weekly Report No. 61 indicates that Assessment Team questions on WAP-59 are still open. This WAP has been authorized by the NRC. Why are Assessment Team questions still open? Originally, the Assessment Team did not have any comments on it. After the work was authorized, the Assessment Team did submit questions. Additional information on this item should be presented at the January public meeting.
- 14. Item 61-3 deals with the wedging of the E/W8 bulkhead lagging.

 Could this be explained? The Assessment Team had previously discussed the need for full bearing of the lagging on the soldier pile flanges. FSO had agreed to make an addition to the drawings to address this concern. However, this was one of the items identified from the review of previous, open items, as still requiring action. The Assessment Team had originally inspected the lagging and had found it to be properly wedged.
- 15. Item 61-9 states that there is not a settlement criterion for the rejacking and lock-off for the E/W8 grillages. Should there be an acceptance criteria for settlement? There is an acceptance criteria for settlement when rejacking is required due to relative movement between a pier and the building. The rejacking discussed in 61-9 was required by an alert level in the steel column that transfers the load from one end of the grillage beams down into the containment building mat. Under this condition there is not a criteria for settlement. The Assessment Team has not evaluated this requirement but will do so and will be prepared

to discuss it at the January public meeting.

- 16. Item 61-11 mentions that Bechtel issued a memorandum giving instructions relative to the rotation of concrete truck drums. The NRC restated their concern with respect to the past use of memoranda to correct problems. It was pointed out that in this case there had not been any procedural violations that required correction.
- 17. Item 61-15 deals with the control of the consistency of bentonite slurry. Does the Assessment Team believe that requirements with respect to slurry consistency should be included in the procedure? Work covered by this procedure has been completed (removal of 36 inch diameter casings). In the case of the use of slurry for soldier pile installation, the procedural requirements are adequate. The NRC stated that if in the future additional slurry operations are required, consistency requirements should be included in the necessary procedures.
 - 18. Is Item 62-2 dealing with the response time with respect to the review of crack mapping data still open? Is Bechtel's issuance of a memorandum the only action being taken? Yes, it is still open. Procedural changes are also being required to address this problem. The NRC again expressed concern with respect to the possible over-reliance on memoranda.
 - 19. With reference to the Management Review Team's trip report that.

 is attached to Weekly Report No.62, is CPCo planning to address
 their comment.

In particular what efforts are being undertaken to reduce the time for which areas of the building remain unsupported during underpinning construction? The following steps have been taken: more road map meetings are being held prior to major activities so that everyone understands what is necessary; the availability of required materials is being reviewed prior to the start of construction operations. It is CPCo's goal to make progress in this area.

Required Action

The following actions are required by the Assessment Team:

- In future Weekly Reports, Work Activity Package titles will be included along with the Work Activity Package number.
- 2. The Assessment Team will evaluate the need for a settlement criterion when rejacking of the E/W8 grillages is required by alert strain levels on the steel columns that bear on the containment mats.
- 3. At the January public meeting, explain why there are still Assessment Team questions open on Work Activity Package No. 59 (Refer to Item 13).

The following actions are required by CPCo:

- Action must be taken to avoid delays in reporting alert level cracks (Refer to Item 3).
- At the January public meeting, provide information on timing of two NCRs on Carlson meter concrete form removal (Refer to Item 13).

The following items remain open from the November meeting. CPCo required action.

- 3. Evaluation of Concrete Mixer Drum Rotation
- Transfer of Lessons Learned in Auxiliary Building underpinning to SWPS underpinning.
- 5. Crack Mapping Problems.

MINUTES OF THE MEETING ON DECEMBER 8, 1983

STATUS OF CONSTRUCTION IMPLEMENTATION OVERVIEW (CIO) PROGRAM

Purpose

To discuss Third Party Overview activities of Stone & Webster (S&W) and problems encountered regarding the Construction Completion Program (CCP) during November 1983.

Summary

- Mr. R. G. Burns, Assistant S&W Corporate Quality Assurance Manager, outlined the classification and tracking system for items identified by the CIO and Remedial Soils Programs. Key points follow:
 - The system has two major categories Tracked Items and Untracked Items.
 Tracked Items are further divided into three subcategories Action,
 Information, and Recommendation.
 - Tracked Items require the completion of appropriate steps before the items are closed. Tracked Action Items will be closed when completed corrective measures are verified. Tracked Information and Recommendation Items will be closed when replies are received. Based on the importance of the items and confidence established by the replies, items could be closed at that time, kept open until corrective measures are verified, or kept open until amplifying information is provided. Information and Recommendation Items that are closed before all steps are accomplished, will be reviewed periodically to ensure that commitments are met before the items are retired.
 - Outracked Items are general in nature and not conductive to tracking. These items will be documented in CIO weekly reports and reviewed periodically to monitor changes in status. Changes will also be included in weekly reports.

- o Items identified to date will be reclassified in accordance with this new system.
- Mr. A. P. Amoruso, Project Manager for the CIO Program, presented a summary of Program activities for November 1983. Three main topics were covered:

Assessment Activities

The stop-work orders involving concerns about the control of design changes remained in effect during November. Since these orders prevented starting the statusing and verification parts of the CCP, assessment efforts continued to be focused on monitoring management meetings, checking the progress of teams to be used in carrying out the statusing phase of the CCP, and evaluating training programs. Fifty-three management meetings were monitored. Management direction at these meetings appeared appropriate. Some 480 hours were expended monitoring the development of commodity lists for use in statusing and verifying conditions in the plant and monitoring training being given members of CCP teams to standardize assessment terminology. Procedures used in developing the commodity lists proved adequate and the training designed to standardize terminology met objectives. Four training presentations followed prescribed lesson plans and effectively conveyed key information.

In two of the three areas outside the CCP but within the scope of the CIO; namely, the Nuclear Steam Supply System and Heating, Ventilation, and Air Conditioning (HVAC) programs, assessment opportunities continued to be limited during November due to the lack of significant activity in those programs. For the Spatial System Interaction Program (SSIP), the third area, the analyses of twelve interactions were witnessed and found to be in accordance with Program requirements.

CIO Items, Nonconformances, and Hold Points

Five CIO items were identified during November. Two of the items were discussed during the last meeting. Topics covered by the items follow:

- Administrative discrepancies in the training records of construction support groups.
- Discrepancies in training levels of the Construction System Team
 Training Matrix.
- Missing isolation spacers for galvanic protection of copper pipes in galvanized steel supports in the non-safety related Instrument Air System.
- Request for confirmation that field change notices will no longer be issued for safety items.
- Oamage to cable jacket from protruding nails in boards lying in a cable tray.

Checks for the document that specified isolation spacers for the Instrument Air System produced only an interoffice memorandum. Because memorandums may have also been used to promulate work instructions for safety related systems. a new item is being opened requesting that Consumers Power Company (CPCo) ascertain that this is not the case. This item will be discussed at the next meeting.

One item was verified corrected and closed during November. That item addressed discrepancies in the training records of quality assurance and quality control personnel.

Three nonconformances identified by the CIO Program remained open. The three address administrative deficiencies in training records.

Six hold points established by the CIO Program remained open. These included the following:

- Development of a Vendor Equipment Verification Program before the start of Phase II of the CCP.
- Evaluation of the Management Review of the results of Phase I activities before the start of Phase II of the CCP.
- ° Correction of Training Records for Construction CCP Teams before people involved are used in the statusing part of the CCP.
- ° Correction of Training Records for Construction Support Groups before people involved are used in the statusing part of the CCP.
- Opprading the level of training in five elements of the Construction System Team Training Matrix before people involved are used in the statusing part of the CCP.
- Overification of Phase I and II evaluations of the FCR/FCN Review before Stop-Work Orders are lifted.

Highlights of November

° Classification of CIO Items

The 37 items identified by the CIO Program through November have been reclassified in accordance with the new system described at the beginning of meeting by Mr. Burns. In the new system, seventeen items are in the Tracking Action category, sixteen are in the Tracking Information category, and four are in the Tracking Recommendation category.

Seven of the 37 items are open. Six of these are in the Tracking Action category and one is in the Tracking Information category.

Quality Assurance Department Training Records

Four CIO nonconformances addressed administrative deficiencies in the training records of Quality Assurance Department personnel.

Corrective action was taken by the Department. The effectiveness of this action was verified by the CIO, and the nonconformances were closed.

° CIO Staff

The CIO staff has increased to 29 in anticipation of the start of CCP statusing and verification. Additional people will be brought in and the mix of disciplines varied as the actual verification load dictates.

Action Items from Last Meeting

- o Mr. Burns, S&W, presented the new system for classifying and tracking items at the beginning of the meeting. The summary of the reclassification of CIO items in the new system was presented under Highlights of November.
- Mr. R. A. Wells. CPCo, discussed when inaccessible items would be evaluated. The items will be evaluated during Phase I of the CCP. Concern about when such items would be evaluated came from a statement made at a Verification and Status Assessment meeting that was included in a CIO weekly report. That discussion addressed procedures that might be used if Phase II was started before Phase I finished.
 Mr. Wells stated that CPCo understands their obligation to obtain NRC approval if clarification or a change to the CCP is needed.
 Mr. J. J. Harrison, NRC, stated that the CPCo staff had recently given a comprehensive presentation on their program for inaccessible items which he thought was a good system.

Questions and Answers

- o Mr. R. N. Gardner, NRC, asked if actions being taken to correct the specific training deficiencies identified by the CIO will be applied to all people who will be used in Phase I of the CCP.
 Mr. D. L. Guarra, CDCs, stated that training required for each
 - Mr. D. L. Quamme, CPCo, stated that training required for each person will be assured before that person starts work.
- o Mr. J. J. Harrison, NRC, asked what category in the new system would the issue concerning welding criteria in PQCI's fall into. The issue was discussed at the last meeting. Mr. Amoruso, S&W, stated that the item was a Tracking Recommendation.
- o Mr. R. Cook, NRC, asked if discrepancies in the training program were all programmatic. Mr. Amoruso replied that the discrepancies were administrative.
- Mr. Harrison asked if the CIO had an opinion as to whether the action taken by the Quality Assurance Department concerning disposition of the nonconformance report on an arc strike on a fabrication produced at the Standish Fabrication Plant was proper. The item was contained in a CIO weekly report. Mr. J. C. Thompson, S&W. stated that the action was proper. The arc strike had occurred at the fabrication plant and was detected and reported by quality control personnel. Since the defect had been detected by quality control personnel, preventive action was a construction responsibility.
- Mr. Harrison asked if the discrepancies found in codes on the construction training matrix were similar to those that were discussed at a management review meeting in July. Mr. Wells stated that action believed appropriate in July was taken but now a different opinion is being given on the correctness of those decisions.

- Mr. Harrison asked CPCo to check into the issue to see if the problem is recurring.
- o Mr. Harrison asked if the six interactions reviewed by the CIO and included in a CIO weekly report were satisfactory. Mr. Amoruso stated that the interactions were satisfactory.
- o Mr. Harrison asked about turnover packages between field engineers and test engineers. Mr. Quamme stated that the packages contain documentation and turnover exceptions that construction considers complete for test operations. Test engineers walk down the systems to verify that the documentation agrees with existing conditions. Errors have appeared in some of these packages, and steps have been taken to correct the problem. One of the steps is to submit preliminary packages for review.
- o Mr. Hai ison asked if the relocation of 500 pipe hangers that will require reinspection was due to rework. Mr. Wells stated that the relocations are due to rework.
- Of Mr. Harrison asked when the revision of the training matrix would be completed since an item in a CIO weekly report indicates that CCP team members will require additional training when that revision is promulgated. Mr. Quamme stated that the revision will be completed by January 15th. Special instructions have been issued to cover people who have to be put in the field before that date.
- Mr. Harrison asked if a procedure covers the routing of nonconformances when they are returned from Ann Arbor since an item in a CIO weekly report states that the nonconformances are being returned directly to the initiator bypassing the formal routing sequence. Mr. Wells stated that the comment in the CIO report referred to coordination needed in the routing process with CCP teams. A discussion on whether the routing problem was a nonconformance ensued, and the CIO was asked to resolve the issue.

- Mr. Gardner asked for clarification on why the CIO had delayed the review of field change documents that had been processed under the field change review program. Mr. Amoruso stated that the CIO review had been originally scheduled before the verification by the Quality Assurance Department. The review was rescheduled after the verification. This change was considered consistent with the CIO objective of ensuring that the Quality Assurance Department carries out their responsibilities properly.
- Mr. Harrison stated that a protocol infraction by the CIO had been outlined in a CIO weekly report. The infraction involved sending a copy of the transcript of the last meeting to CPCo and Bechtel but not to the NRC. Corrective action was considered appropriate.
- Mr. Harrison asked for clarification of a statement in a CIO weekly report that Groups I and II were not preparing for status assessment in the same way Group III was. Mr. S. W. Baranow, S&W, stated that Group III had been undergoing mockup training to standardize assessment terminology. A later report mentions that Groups I and II have since conducted similar training.
- o Mr. Harrison asked what was going to be done with field control changes since an item in a CIO weekly report stated that field control notices would no longer be used for safety related work. Mr. Wells stated that initially after lifting stop-work orders, there would be no field control notices for safety related work. Later, after the change process has been reviewed by project engineering, a new program will be developed. This program will be more limited as to when a field change notice can be used and will only require approval of project field engineering.

Of Mr. Harrison asked about the walkdown of systems to identify low alloy quenched and tempered steel (LAQTS) bolts. Mr. Wells stated that the effort to identify LAQTS bolts has been ongoing for over a year. The bolts have to be checked for hardness because of an industrial problem involving the control of hardness testing. Since all the LAQTS bolts in the plant may not have been located, statusing will be used to assist in that effort.

Action Items

- ° CIO resolve whether CCP teams are having a problem receiving the dispositions of nonconformances and, if a problem does exist, whether the cause is one of routing, coordination, or a procedural noncompliance.
- CPCo present at the January meeting the background on training level codes used in construction training matrices.



P.O. Box 2325, Boston, Massachusetts 02107

December 14, 1983

Mr. D. L.Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640 PRINCIPAL STAFF

RA DPRP

D/RA DE

A/RA DRMSP

RC DRMA

PAO SCS

SGA ML

TNF FILE

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-004

Phase I and Phase II reviews of the Architectural FCR/FCNs have been completed and considered acceptable by CIO as meeting the requirements of FID-2.400 Rev. 3, Review and Resolution Program.

Sampling was performed on the MPQAD 100% verification of line 9 Phase I activity and of 100% MPQAD verifications of line 15 Phase II activity of the Generic Schedule for Resolving Stop Work Orders.

Sampling inspections were performed of controlled stick drawings at Stations 14, 48 a, b and d and 55. They were considered satisfactory and acceptable.

The Hold Point established by CIO for completion of Phase II activities in the Architectural discipline has been lifted.

This letter lifting the Hold Point, confirms my conversation with Mr. N. Riechel, CPCo, on December 13, 1983.

Very truly yours,

S. W. Baranow Program Manager

SWB/fs

JGKeppler, US NRC Glen Ellyn, IL
JHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso S&W

SB10180175



Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

December 13, 1983

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640 PRINCIPAL STAFF

RA DPRP

D/RA DE

A/AA DRMSP

RC DRMA

PAO SCS

SGA ML

File L

MIDLAND ENERGY CENTER GWO 7020 CIO OBSERVATIONS 36 AND 37

File: Bl.1.7, 0655 UFI: 53*50*04, 99*08 Serial: CSC-7081

Attached is our partial response to observations 36 and 37 which were identified in your Report No. 24. As indicated, further information will be provided on these issues.

DLQ/DDJ/klp

cc: RAWells, MPQAD w/a
NIReichel, MEC w/a
BHPeck, MEC w/a
RJCook, NRC w/a
JGKeppler, NRC w/a
JJHarrison, NRC w/a

831228.0376

660 19 1983


CONSUMERS POWER CO

DEC 0 - 1983

Site Mgr. Midlend Project

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme



Bechtel Power Corporation

Post Office Box 2167 Midland, Michigan 48640



December 9, 1903

Job 7220 Midland Project
CONSTRUCTION REVIEW OF STONE &
WEBSTER'S CCP OVERVIEW REPORT
NO. 24
ECCC-8802

Dear Mr. Quamme:

Construction's review of Stone & Webster's Overview Report No. 24 identified two (2) open (Construction) action items, specifically Nos. 36 and 37.

Detailed below is our partial response to the subject observations.

Obs. No. 36

Discussion between Construction's Site Quality Department, Stone & Webster and CPCo SMO has revealed that this observation as written is incorrect.

Per Stone & Webster's J. Barr on December 9, 1983, this observation will be revised and resubmitted in S&W's report No. 26.

Construction will address the revised observation upon receipt of S&W's report No. 26.

Obs. No. 37

NCR C00925 referred in this observation has been dispositioned. The disposition is in the process of being implemented. Please note that the as stated condition in S&W report No. 24 is not the same as the condition stated in the NCR.

Disposition implementation is projected for completion on or before December 14, 1983. Further correspondence onthis subject will be forwarded to you on or before December 2', 1983.

. In reference to the above NCR, T.C. Valenzano issued the attached memo $(0-6866,\, \text{dated}\,\, 12/7/83)$ directing the field for strict adherence to housekeeping procedure.

D.L. Quamme BCCC-8802 Page 2

If you have any questions concerning the above, please contact B.T. Foote at Ext. 7507.

Very truly yours,

G.A Hierzen

Site Manager

GAH/MAD/BTF/1cc

Attachment: Stone & Webster's Observations

Bechtel Power Corporation

Ichalemano. c. valenzano

Inter-office Memorandum

All Superintendents/General To

Foremen

Job 7220 Midland Project Subject

GENERAL HOUSEKEEPING

0-6866

Distribution Copies to

December 7, 1983 Date

T. C. Valenzano From

Field Construction Of

Midland, Michigan

Recently, an NCR (#C00925) was written because two (2) boards with protruding nails were found lying in a "Q" cable tray. This condition resulted in damage to the "Q" cable in the tray.

Through various means of communications such as memos, tool box meetings, training and superintendent/general foremen meetings, housekeeping is continually stressed. Therefore, there is no excuse for the neglectful condition that initiated NCR #C00925.

In order to prevent damage to plant equipment, it is essential that we maintain good housekeeping. This practice is the responsibility of everyone on the project. As supervisors, it is your responsibility to make sure that the people under your supervision are conforming to housekeeping procedures.

Your cooperation and immediate attention to this concern will be appreciated.

TCV/FEH/Ijg

Distribution:

G. Hierzer

R. Cote

M. Dietrich

F. Haluska

T. Robertson

S. Estlack

J. Reinsch

STONE & WEDSTER MICHIGAN, INC. MIDLAND NUCLEAR COGENERATION PLANT CIO OBSERVATIONS

servation Number	Observations	Originating Document/Date	CPCo Response Document/Date	.Status Open/Closed	Close-Out Document/Date
034	NIR 008 issued on November 14, 1983 to address five unsatisfactory conditions observed during the review of 50 training	Report No. 22 11/14/83		Open '	
C .	levels assignments in the System Team Training Matrix of the Construction. Training Program.	-, -,			
035	ClO observed that dielectric isolation spacers for galvanic protection of copper	Report No. 22 11/14/83		Open	
	pipe to galvanized steel pipe supports were missing in some areas on this system. Small Bore (Instrument Air) KAC Systems. drawing FSK-J-30-0220 Sheet 2 Rev. 7.				
036	At team meeting of teams 26 and 27 held on November 22, 1983, a decision that FCNs would no longer be issued for "non-Q"	Rdport No. 24 11/29/83		Open	
	items was discussed. The method for con- trolling changes has not been finalized.			*	
037	CIO observed that two boards with pro- truding nails lying in Cable Tray 1AKA019	Report No. 24 11/29/83		0pen	
	of a "Q" cable. The cable is Q-channel A. 480V. MCC. NCR C00925 was issued by MPQAD on November 22, 1983. CIO will track this				
	(repair) has been performed to approved procedures.	1-1-1			
037	C10 observed that two boards with protruding nails lying in Cable Tray 1AKA019 (Q Tray) had punctured the cable jacket of a "Q" cable. The cable is Q-channel A, 480V. MCC. NCR C00925 was issued by MPQAD on November 22, 1983. C10 will track this item to assure that corrective action (repair) has been performed to approved	11/29/83		Open	



Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

December 13, 1983

Mr Stan Baranow Stone and Webster Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF PQCIs FILE 24.2 SERIAL 27235

This will confirm the transmittal of reference copies of the following document to Stone and Webster, as listed below:

C-8.51 Rev 4 CN#AA-00128 Revised Effectivity Date C-8.51 Rev 4 CN#AA-00131 C-8.51 Rev 4 CN#AA-00133 C-8.50 Rev 13 CN#AA-00132 C-8.50 Rev 13 CN#AA-00134

of a Pure / law

G F Ewert, Division Head Quality Services Midland Project Quality Assurance

GFE/JAP/djh

CC JRKeppler, NRC Region III Administrator DLQuamme, SMO RAWells, MPQAD

8312280206

fele



Dean L Quamma Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

December 13, 1983

Mr S Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

MIDLAND ENERGY CENTER GWO 7020

S & W REPORT NO. 20 FILE: B1.1.7 UFI: M-151 99*08, 10400(s), 53*52*04

SERIAL: CSC-7086

Your report No. 20 has an error on page four, item two, RPT 8318-8319. It should read:

Sixty-eight (68) HVAC material samples were selected by the NRC and subsequently tested for chemical and physical properties which include chemical analysis, hardness, tensile, bend, and macroscopic examination of specimens.

Should you have any questions do not hesitate to contact J.G. Balazer at 6511.

Additionally, a copy of the materials testing report has been received from the NRC and does show favorable results.

DLQ/JGB/sc

cc: JLWood, P14-416 RAWells, MPQAD RJCook, NRC JJHarrison, NRC JGKeppler, NRC NIReichel, MEC BHPeck, MEC DDJohnson, MEC

831278014

DEC 1 9 1983



P.O. Box 2325, Boston, Massachusetts 02107

December 13, 1983

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48240

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-001

	1				
J	PR PR	INCIP	AL ST	AFF	
•	D/RA	N-	DE		
	A/RA		DRMSP		
	RC		DRMA		1 2
	PAO		SCS	V	oug+2
	SGA		ML	-1	. 0
	ENF		File	R	

Sample inspections of controlled stick drawings and FCR/FCN attachments were performed by CIO at the Document Control Stations Number 14, located in the Support Service Building, and Stations 48 a, b and d, located in the Area Teams 25 through 29 Building. The review was considered acceptable as meeting the requirements of FID-2.400 Rev. 3, Review and Resolution Program. Stations 14 and 48 a, b and d are considered satisfactory for start of QVP activities and Status Assessment.

NIR 009 was issued December 12, 1983, for rejection of the lot of drawings at Station 55. Corrective action had been accomplished by MPQAD. CIO verified that the missing drawing had been added to the controlled stick drawings, and performed a sample inspection of the drawings at this station. The review was considered to be satisfactory and acceptable in meeting the requirements of FID-2.400 Rev. 3, Review and Resolution Program.

As the corrective action had been completed on December 12, 1983, CIO will issue NIR 009 as closed on December 13, 1983.

Station 55 is considered satisfactory for start of Status Assessment, and QVP QC.

Very truly yours,

S. W. Baranow Program Manager

SWB/fs

CC: ✓OGKeppler, US NRC Glen Ellyn, IL JJHarrison, US NRC Glen Ellyn, IL RJCook, US NRC Midland (site) RAWells, CPCo Midland (site) RBKelly, S&W APAmoruso, S&W

8312280301

060 10 to



P.O. BOX 2325, BOSTON, MASSACHUSETTS 02107

December 13, 1983

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Subject:

Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-002

PRINC	DPRP	
D/RA	DE	
A/RA	DRMSP	
RC	DRMA	Variat:
PAO	SCS	yougt-
SGA	ML ·	
ENF	File	lev

This letter supersedes my letter dated December 12, 1983, which was inadvertently addressed to Mr. G. A. Hierzer.

We have reviewed the records of Steve Babb and Pete Zagorin and find them to be acceptable for Status Assessment, subject to the conditions described below:

The Bechtel I.O.M. dated December 9, 1983, subject - "Statement of Policy, Training Records" is revised to reflect agreements reached with Bechtel personnel, to reflect Bechtel record keeping.

A draft of the policy as understood by Stone & Webster is attached to this letter.

If you concur with this draft, please formally issue it and upon receipt by C.I.O. we will release our hold on training with regard to the above named individuals.

If your understanding is different to ours, please contact S. Baranow in order that a meeting can be established and agreement reached.

Very truly yours,

S. W. Baranow Program Manager

SWB/fs Enclosure

JGKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

MEC , 9 MA

8312780365



P.O. Box 2325, Boston, Massachusetts 02107

PRINCIPAL STAFF

DRMSP

SCS

ML

A/RA

PAO

SGA

ENF

December 13, 1983

Mr. D. L. Quamme Consumers Power Company Midland Nuclear Plant 3500 E. Miller Road Midland, Michigan 48640

Subject: Docket No. 50-329/330

Midland Plant - Units 1 and 2 Overview of the Construction

Completion Program Serial No. SWMCP-003

Re:

CPC Letter Serial #CSC 7080

Bechtel Power Company Training Records

Policy Statement

CIO has reviewed the subject policy statement, considers it satisfactory and in total agreement with the commitment made in a meeting held with representatives of CPCo, BPCo and CIO on December 6, 1983.

Very truly yours,

S. W. Baranow Program Manager

SWB/fs

JGKeppler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
RJCook, US NRC Midland (site)
RAWells, CPCo Midland (site)
RBKelly, S&W
APAmoruso, S&W

8812280168

90-329/330	PRINCIPAL STAFF A AMOPRP D/RA DE A/RA DRMSP	P.O. BOX 1963, MIDLA	R MICHIGAN, INC. AND, MICHIGAN 48640
VIA F	PAO SCS VOLID 12 SGA ML ENF FILE MA	DEAR SIRS:	P. O. NO. N/A LTR. NO. 83-0002 REF. N/A PACHED: SENT SEPARATELY:
Nuclear Regul 799 Roosevelt	Administrator, Region III atory Commission Road Ilinois 60137	COPIES PRINTS	REPRODUCIBLES MICROFILM APERTURE CARDS EACH OF SPECIFICATIONS NOTES OF CONFERENCE
FINAL PELIMINARY NO COMMENT SUGGESTIONS AS NOTED	STATUS APPROVED APPROVED AS REVISED IN SPECIFICATION UNACCEPTABLE	PLEASE OTE REVISIONS OMISSIONS ADDITIONS CORRECTIONS COMMENTS N/A	SENT FOR YOUR APPROVAL COMMENT USE INFORMATION PILES CONCURRENCE
YOUR ATTENTION RELEASED FOR:	PARTICATION THE FOLLOWING PARTICATION PARTICATION PARTICAL PRINTS REPRODUCIBLES MICRO PARTICAL OF THIS MATERIAL SEARING YOUR APPRODUCIBLES OF THIS MATERIAL SY SIGNING AND RETURN RECEIPT OF THIS MATERIAL SY SIGNING AND RETURN RECEIPT OF THIS MATERIAL SY SIGNING AND RETURN RECEIPT OF THIS MATERIAL SY SIGNING AND RETURN RETURN RECEIPT OF THIS MATERIAL SY SIGNING AND RECEIPT OF THE THIS MATERIAL	MICROFILM APERTURE CARDS. OFILM APERTURE CARDS OF 00000	MENTS DRAWINGS SHOP DETAIL

CIO NIRs 002, 003, 004 and 009 the attached NIRs have been closed out

S. W. Baranow Program Manager

8312280461

DEC 19 88

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

PAGE 1 OF 3 NIR NUMBER DATE OF NONCONFORMANCE: 002 SEPTEMBER 27, 1983 IDENTIFICATION/LOCATION OF ITEMS: MPOAD - RECORDS FILE SECTION DESCRIPTION OF NONCONFORMANCE: During a sample inspection of 6 of 45 MPQAD Personnel Training Records, discrepancies were observed in the use of forms to document training activities. It was observed that forms from both B-3M and B3M-1 Procedures were utilized. Forms as found in B-3M-1 are the appropriate ones. See attached list of discrepant items: DATE September 27, 1983 CORRECTIVE ACTION BY: MPOAD OAR NO. RT00005 & RT 00010 IDENTIFY ORGANIZATION TAKING CORRECTIVE ACTION All training records that were listed on forms not reflected by the requirements. of B3M-1 were accepted since the incorrect forms had all the information required with one exception. The one exception does not apply to the electrical inspectors checked in this sample. This problem is addressed by MPQAD in QAR-RT-00010 with a completion date of December 16, 1983. All of the forms required by MPQAD Procedure B3M-1 will be utilized starting October 17, 1983. CIO performed a sampling inspection of the training records of 39 MPQAD personnel.

VERIFICATION SAT V UNSAT

INITIATOR Walter H. Sienkieures

DATE 12-9-83

NEW NIR# ~//N

PROGRAM MGR. Subsanael

DATE DATE NORMAN 12, 1983

A sample size of 50 records representing a lot size of 312 records were selected,

examined and were found to be in compliance with Procedure B3M-1.

REMARKS

PERSONNEL

- 1) B. E. FREIMARK 365-64-4818
 - 1) Vision Examination Record Form QA-14-2 used in lieu of QA-115-0
 - 2) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0
- 2. T. G. NELSON 276-56-6857
 - 1) Vision Examination Record Form QA-14-2 used in lieu of QA-115-0
 - 2) Personnel Certification Form QA-37-0 used in lieu of QA-37-1
 - 3) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0
- 3. S. REVICH 379-84-0876
 - Inspection Test Personnel Qualification Questionnaire Form QA-12-2 used in lieu of QA-117-0 and QA-118-0
 - 2) Vision Examination Record Form QA-14-2 used in lieu of QA-115-0
 - Personnel Certification Form QA-37-0 used in lieu of QA-37-1,
 Also a revision was not listed on the form.
 - 4) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0
- 4) D. W. GASKILL 278-54-0575
 - 1) Vision Examination Record Form QA-14-2 used in lieu of QA-115-0
 - 2) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0
- 5) B. D. HINES 365-52-6895
 - Inspection Test Personnel Qualification Questionnaire Form QA-12-2 used in lieu of QA-117-0 and QA-118-0
 - 2) Vision Examination Record Form QA-14-2 used in lieu of QA-115-0
 - 3) Personnel Certification Form QA-37-0 used in lieu of QA-37-1
 - 4) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0

- 6) J. R. ADOMOWSKI 368-46-9164
 - 1) Vision Examination Record Form QA-14-3 used in lieu of QA-115-0
 - 2) Performance Demonstration Record Form QA-10-2 used in lieu of QA-114-0

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

		PAGE 1 OF 1
DATE OF NONCONFORMANCE:	SEPTEMBER 27, 1983	NIR NUMBER 003
IDENTIFICATION/LOCATION OF	ITEMS:	
MPQAD - RECORDS FILE SECT	ION	
DESCRIPTION OF NONCONFORMA	INCE:	
A check of MPQAD Personnel	Training Records ind	icated that the yearly Vision
Examination of B. D. Hines	was exceeded. The d	ue date for the Examination
was March 9, 1983. The da		
was march s, 1965. The do	to or the Examination	
71 AF 110 '	0	
Walter H. Sien	Roures	PROGRAM MGR SWEETEN
***************************************		DATE Colder 3, 483
DATE Soptember 3	17, 1983	DATE COLON 3, 483
CORRECTIVE ACTION BY:		
	MPQAD - QAR No.	RT 00006 & RT-00010
10	ENTIFY ORGANIZATION T	AKING CORRECTIVE ACTION
Verified that a letter wr	itten by D. D. Cochra	n, QA Level III on October 11, 198
		Brian D. Hines. The letter
stated that since he pass	ed the latest test he	is considered to have adequate
vision acuity to perform	inspection functions	during the period of no valid
eye examination.		
c) c cyaminacion:		

INITIATOR Walter H. Sienkieweg DATE December 12, 1983 NEW NIR#

DATE

PROGRAM MGR

DATE Rampher 12, 1983

REMARKS

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

DATE OF NONCONFORMANCE: SEPTEMBER 27	, 1983	NIR NUMBER	004
IDENTIFICATION/LOCATION OF ITEMS:			
MPQAD - RECORDS FILE SECTION DESCRIPTION OF NONCONFORMANCE:			
During a sample inspection of 6 of 45 !	MPQAD Personnel T	Training Records	, the
following discrepancies were observed			
records as required in Deviation #99 to			
		1	,
Walter H. Sunkieures	PROGRAM	MGR Sussem	well
		-11	
DATE September 27, 1983	_ DATE_d	ELES 3, 198	3
CORRECTIVE ACTION BY:			
MPQAD	QAR NO. RT-000	0 7	
IDENTIFY ORGAN	IZATION TAKING CO	PRECTIVE ACTION	
All discrepancies were verified as be	ing corrected as	required on Page	es 1 & 3
of this NIR. 1) B. E. Freimark			
Verified that on-the-job training	record E-6.0 equi	ipment installat	ion had
Rev. 15 per initials dated October	18, 1983.		
2) T. G. Nelson			
Verified letter dated October 18,	1983 From E. L.	Jones, QA Level	111.
VERIFICATION SAT VUNSAT	NEW NIR# N/A	T col	NCURRENCE
INITIATOR Walter H. Sunkieuier	1		7
The state of the s		PROGRAM MGR	Warmer!
DATE /2-9-83	DATE		Cember 9, 92

REMARKS

PERSONNEL

- 1) B. E. FREIMARK 365-64-4818
 - 1) There was no revision number listed on the OJT training record
- 2) T. G. NELSON 276-56-6857
 - 1) The difference training record was not available in the records file, but the above individual was certified to PQCI-E-6.0 Rev. 15
- 3) S. REVICH 379-84-0876
 - 1) The on-the-job training record was not available in the records file, but the above individual was certified to PQCI-E-6.0 with no revision listed
- 4) D. W. GASKILL 278-54-0575
 - 1) No revision number was listed on the on-the-job training record
 - 5) B. D. HINES 365-52-6895
 - The title of the PQCI was not listed on the on-the-job training record.

- continued - from PAGE 1

Which stated that T. Nelson received adequate on-the-job training prior to his performance demonstration.

3) S. Revich

- 1) Verified that individual certification for PQCI E-6.0 was corrected by writing in Rev. 12, initialed and dated October 11, 1983 by D. Cochran. Level III. The limitations were also corrected to state corrective lenses.
- 2) Verified that a letter was entered into the personnel record files stating that S. Revich received adequate on-the-job training prior to his performance demonstration from E. L. Jones, QA Level III.

4) D. W. Gaskill

Verified that on-the-job training record was corrected to include Rev. 15 initialed and dated November 5, 1983.

5) B. D. Hines

Verified that the title was entered in the on-the-job training record.

CIO performed a sampling inspection of the training records of 39 MPQAD personnel. A sample size of 50 records representing à lot size of 312 records were selected. examined and were found to be in compliance with Procedure B3M-1.

STONE AND WEBSTER ENGINEERING CORPORATION NONCONFORMANCE IDENTIFICATION REPORT

QCI 15.01 Attachment 4.1 Revision 2

IDENTIFICATION/LOCATION OF ITEMS: Support Services Building Q.C. Station #55					
DESCRIPTION OF NONCONFORMANCE: A sample inspection was performed of controlled Architechural drawings at Q.C. Station No. 55. A sample size of 50 drawings representing a lot size of 224 drawings was selected. Accept/Reject criteria is; Accept 0 Reject 1. Drawing No. A-213 was missing from Station 55 control drawing sticks. As a result, the entire lot of the 224 drawings has been rejected. This NIR describes a deficiency against the Document Control Center. A check of the Control Card for drawing A-213 does not show any FCR/FCNs as being applicable.					
DATE 12/12/23 DATE MISS 12, 1903					
CORRECTIVE ACTION BY:					
IDENTIFY ORGANIZATION TAKING CORRECTIVE ACTION					
Corrective action had been accomplished by MPQAD. CIO verified that the missing dwgs had been added to the controlled stick dwgs and performed a sample inspection of the drawings at this station. The review was considered to be satisfactory and acceptable in meeting the requirements of FID-2.400 Rev. 3, Review and Resolution Program. Corrective Action completed on December 12, 1983.					
VERIFICATION SAT UNSAT NEW NIR# CONQUERENCE					
DATE 12 13 83 DATE PROGRAM MGRANDER					
REMARKS This NIR as issued is closed as corrective action has been completed.					



P.O. Box 2325, Boston, Massachusetts 02107

December 12, 1983

Mr. G. A. Hierzer, Site Manager Bechtel Power Corporation 3500 E. Miller Road Midland, Michigan 48640

Dear Mr: Hierzer:

We have reviewed the records of Steve Babb and Pete Zagdrin and find them to be acceptable for Status Assessment, subject to the conditions described below:

The Bechtel I.O.M. dated December 9, 1983, subject - "Statement of Policy, Training Records" is revised to reflect agreements reached with Bechtel personnel, to reflect Bechtel record keeping.

A draft of the policy as understood by Stone & Webster is attached to this letter.

If you concur with this draft, please formally issue it and upon receipt by C.I.O. we will release our hold on training with regard to the above named individuals.

If your understanding is different to ours, please contact S. Baranow in order that a meeting can be established and agreement reached.

Very truly yours,

S. W. Baranow Program Manager

SWB/fs Enclosure

CC:

JJHarrison, US NRC Glen Ellyn, IL

RJCook, US NRC Midland (site)

DLQuamme, CPCo Midland (site)

RAWells, CPCo Midland (site)

APAmoruso, S&W

83+2280427

PRINCIPAL STAFF

DRMSP

DRMA

SCSV

ML

File

D/RA

A/RA

RC

PAQ

SGA

NF

ju




Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 . (517) 631-8650

December 12, 1983

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640



MIDLAND ENERGY CENTER GWO 7020

MANAGEMENT POLICY ON MAINTENANCE OF TRAINING RECORDS

File: 0400.2, Bl.1.7 UFI: 07*, 99*08 Serial: CSC-7080

Attached is a copy of the revised Bechtel Management Policy addressed to E H Pillsbury, the Training Task Force Leader. The policy reflects Stone & Webster's comments of 12/12/83.

W DLQ/NIR/klp

cc: RAWells, MPQAD
BHFeck, MEC
DDJohnson, MEC
RJCook, NRC
JGKeppler, NRC
JJHarrison, NRC

831250456

Bechter Power Corporation

Post Office Box 2167 Midland, Michigan 48640



December 12, 1983

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme

Job 7220 Midland Project
MANAGEMENT POLICY ON MAINTENANCE
OF TRAINING RECORDS
BCCC-8815

Dear Mr. Quamme:

Attached is a copy of the revised Management Policy addressed to E.H. Pillsbury, the Training Task Force Leader. The policy reflects Stone & Webster's comments of 12/12/83.

Very truly yours,

G.A. Hierzer Site Manager

GAH/EJR/EHP/1cc

Attachment: Revised Management Policy

CC: N. Reichel

Written Response Requested: No

Bechtel Power Corporation

Inter-office Memorandum

To E.H. Pillsbury Date December 12, 1983

G.A. Hierzer

Subject

Job 7220 Midland Project STATEMENT OF POLICY TRAINING RECORDS

Of Construction

From

0-6896

Copies to

Midland, MI Ext. 7200 At

A recent audit of the Training Department by Stone and Webster has uncovered several concerns. The following Statement of Policy will clarify Bechtel's position and eliminate all concerns.

1. The CCP Training Program is a Familiarization Program based on the fact that all Bechtel personnel are technically qualified to do their job. The purpose of the CCP Training Program is to familiarize the construction personnel with the documents they will be using in completing their assigned tasks as required by the Midland Project. While it is readily admitted that accurate records are a necessity, it is also recognizable that all entries on a training record, i.e., pagination, time of instruction, location of instruction, etc., are not required to establish objective evidence of training. If all of the following essential information is on a training record, the record shall be accepted as objective evidence that the person has received the training, regardless of the format.

*Formal Instruction

All class attendance rosters prior to September 28, 1983 will have the following minimum information.

- °Subject of Class
- *Reference Documents (as taken from Training Matrix)
- CAttendee's Name
- "Instructor's Signature
- Date of Instruction
- Authenticating Signature of Training Group

*Reading Reports

- Name of Employee
- *Appropriate Identification of Level of Reading or Exemption
- *Reference Documents
- Signature of Supervisor an Date
- "Signature of Employee and Date

^{*}As an exception to the above, any class roster prior to September 28, 1983 for:

E.H. Pillsbury 0-6896 Page 2

Bechtel Power Corporation

Interoffice Memorandum

- (1) Safety Orientation (FIS-1.200, FIS-2.100, FPS-3.000, FPS-6.000)
- (2) BPC Quality Orientation (NQAM, BQAM)

will be accepted, as long as they contain any objective evidence that the training was completed.

- Series Drawing: See T.C. Valenzano/J.T. Minor IOM 0-6879 dated 12/8/83, Training Records Recording of Revisions On Series Documents.
- 3. White out (opaque) and correction tape: All members of the Construction Training Group have been instructed that the only acceptable method of correcting a training record is:
 - a. A permanent line out of the entry
 - b. Date and initial the line out

Level 1, 2, and 3 supervisors have been instructed that any record received with white-out corrections or correction tape will be returned to the originator. They have been furnished the proper reading form and instructed to dispose of all previous revisions of the form.

All records from September 28. 1983 to date, that have white out or taped-over corrections will be revalidated by lining out, dating and initialing. If the trainee's supervisor who originally signed the form is not available, the present supervisor may be used. Records prior to September 28, 1983 with white out or taped-on corrections will be utilized as is.

- 4. The individual training files are the official record as specified in paragraph 9 to FPG-2.000.
- 5. Illegible Documents: A document will be considered illegible if any of the essential information listed in paragraph 1 above is not readable. In this case, the Records Group will make an effort to secure a better copy. If they are unsuccessful, the document will be forwarded to the Curricula Committee to determine if credit should be given or not.
- Retrofit of Records: Retrofit of attendance rosters prior to September 28, 1983 is neither warranted or practical.

E.H. Pillsbury 0-6896 Page 3

Bechtel Power Corporation

Interoffice Memorandum

 All Class Attendance Rosters from September 28, 1983 to date will be completed in accordance with the latest revision of FPG-2.000.

This policy is not intended to reduce the quality requirements of the Training Records. Our policy has always been and will continue to be:

*Quality is the individual responsibility

Again, accurate and complete records are mandatory and care should be taken with them. At the same time remember that the form and the manner which it is completed is secondary to assuring that the essential elements are included in the form, substantiating that training requirement has been met.

G:A. Hierzer Site Manager

GAH/EJR/1cc

^{*}Do it right the first time



Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

LAB 146-83

December 12, 1983

Mr Stan Baranow Stone & Webster Engineering Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDIAND ENERGY CENTER PROJECT -TRANSMITTAL OF (3) COMPUTER PRINTS

This will confirm the transmittal of three computer printouts containing information on MPQAD (BOP) Inspector records. These prints cover all training, exams, performance demos, certifications, etc.

GFEwert/LABotimer

cc: JHarrison, NRC

DLQuamme, Site Mgr

RAWells

8312280158



PRINCIPAL STAFF

D/RA DE

A/RA DRISH

RC DRISH

PAO SCSA SIGH3

ENF FILE

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

December 9, 1983

Mr Stan Baranow Stone and Webster Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF VOL I & II FILE 24.2 SERIAL 27232

This will confirm that Stone and Webster CIO is on controlled distribution for the following documents:

Controlled copy #13 of CP Co Topical Report CP Co IA Controlled copy #37 of CP Co QA Program Procedures

Updates of these manuals will be forwarded directly to you by the controlling organization using document transmittal acknowledg@ment forms rather than by letter.

Gary F Ewert, Division Head

Quality Services

Midland Project QA Department

GFE/kw

CC SHoward, JSC-222

JRKeppler, NRC Region III Administrator
DLQuamme, SMC
RAWells, MPQAD

8312200094



Midland Project: PO Box 1963, Midland, Mi 48640 • (517) 631-8650

December 9, 1983

Mr Stan Baranow Stone and Webster Midland Nuclear Plant Project Trailer 186 3500 E Miller Road Midland, MI 48640

MIDLAND ENERGY CENTER PROJECT -TRANSMITTAL OF QAR FILE 24.2 SERIAL 27231

This will confirm the transmittal of QAR RT 00015. This has been written based on concern of visual exams identified by Stone and Webster.

Cary F Ewert, Division Head

Quality Services

Midland Project QA Department

CFE/kw

CC JRKeppler, NRC Region III Administrator DLQuamme, SMO RAWells, MPQAD



Dean L Quamme Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

December 9, 1983

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640 PRINCIPAL STAFF

RA DPRP

D/RA DE

A/R/ DRMSP

RO DRMA

PAO SOS OUG/3

SGA ML

ENF FILE

MIDLAND ENERGY CENTER GWO 7020

MANAGEMENT POLICY IN MAINTENANCE OF TRAINING RECORDS

File: 0400.2, Bl.1.7 UFI: 07*, 99*08 Serial: CSC-7076

In accordance with a recent commitment, attached is Bechtel's management policy on maintenance of training records.

DLQ/DDJ/klp

cc: RAWells, MFQAD w/a
NIReichel, MFC w/a
BHPeck, MEC w/a
RJCook, NRC w/a
JGKeppler, NRC w/a
JJHarrison, NRC w/a

DEC 1 9 1983

-83121802H

Bechte, Power Corporation

Post Office Box 2167 Micland, Michigan 48640



December 9, 1983

Consumers Power Company P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme

Job 7220 Midland Project
MANAGEMENT POLICY ON MAINTENANCE
OF TRAINING RECORDS
BCCC- 8805

Dear Mr. Quamme:

In the course of recent audits of Construction Training Records by Stone & Webster several issues regarding content of the records have arisen. These issues were discussed with Stone & Webster and Consumers Power during two separate meetings.

Attached is a copy of a management policy addressed to E.H. Pillsbury, the Training Task Force Leader. The policy is to provide direction to the Training Records Group and others involved with Training Records. It should also serve to settle any issues still unresolved and obviate the necessity of tringing up such issues during future audits.

I know we share equal concern to ensure that only fully trained personnel are assigned to status assessment and to Construction Completion. There are essential elements to the program and these must be fully documented. The policy will provide the necessary guidance and direction to those involved in maintenance of training records assuring that the espential elements are documented.

Very truly yours,

Site Manager

GAH MAD EHP /1cc

Attachment: Statement of Policy - Training Records with the attachments

CC: N. Reichel

Bechtel Power Corporation

Inter-office Memorandum

December 9, 1983

To E. H Pillsbury

Subject Midland Plant Units 1 & 2

Bechtel Job 7220 STATEMENT OF POLICY TRAINING RECORDS

Copies to 0-6887

From G.A. Hierzer

of Construction

At Midland, MI

A recent audit of the Training Department by Stone and Webster has uncovered several concerns. The following Statement of Policy will clarify Bechtel's position and eliminate all concerns.

1. The CCP Training Program is a Familiarization Program based on the fact that all Bechtel personnel are technically qualified to do their job. The purpose of the CCP Training Program is to familiarize the construction personnel with the documents they will be using in completing their assigned tasks as required by the Midland Project. While it is readily admitted that accurate records are a necessity, it is also recognizable that all entries on a training record, i.e., pagination, time of instruction, location of instruction, etc., are not required to establish objective evidence of training. If all of the following essential information is on a training record, the record shall be accepted as objective evidence that the person has received the training, regardless of the format.

*Formal Instruction.

- Training Program Identification "CCP"
- reference documents (as taken from Training Matrix)
- ° attendee's name
- ° instructor's name
- o date of instruction
- · authenticating signature of Training Group

*Reading Reports

- o name of employee
- appropriate identification of level of reading or exemption
- o reference documents
- e signature of supervisor

Sechtel Power Corporation December 9, 1983 Page 2 0-6887

*As an exception to the above, any class roster prior to September 28, 1983 for:

- Safety Orientation (FIS 1.200, FIS 2.100, FPS 3.000, FPS 6.000)
- · BPC Quality Orientation (NQAM, BQAM)

will be accepted, as long as they contain any objective evidence that the training was completed.

- Series Drawing: Revisions to the series drawings (i.e., M-400's & M-600's, etc.) will not be required on the class attendance rosters or the reading sheets. We have prepared a memo describing the training objectives for those series of drawings, that do not have a lesson plan. (See Attachment A)
- 3. White out (opaque) and correction tape: All members of the Construction Training Group have been instructed that the only acceptable method of correcting a training record is:
 - a. A permanent line out of the entryb. Date and initial the line out

Level 1, 2, and 3 supervisors have been instructed that any record received with white out corrections or correction tape will be returned to the originator. They have been furnished the proper reading form and instructed to dispose of all previous revisions of the form.

All records from September 28, 1983 to date, that have white out or taped over corrections will be revalidated by lining out, dating and initialing. If the trainee's supervisor who originally signed the form is not available, the present supervisor may be used. Records prior to September 28, 1983 with white out or taped on corrections will be utilized as is.

- The individual training files are the official record as specified in paragraph 9 to FPG 2.000.
- 5. Illegible Documents: A document will be considered illegible if any of the essential information listed in paragraph I above is not readable. In this case, the Records Group will make an effort to secure a better copy. If they are unsuccessful, the document will be forwarded to the Curricula Committee to determine if credit should be given or not.
- Retrofit of Records: Retrofit of attendance rosters prior to September 28, 1983 is neither warranted or practical.

Bechtel Power Corporation December 9, 1983 Page 3 0-6887

This policy is not intended to reduce the quality requirements of the Training Records. Our policy has always been and will continue to be:

· Quality is the individual responsibility

° Do it right the first time

Again, accurate and complete records are mandatory and care should be taken with them. At the same time remember that the form and the manner which it is completed is secondary to assuring that the essential elements are included in the form, substantiating that training requirement has been met.

for G.A. Hierzer Site Manager

GAH/JMM/naw

Attachments: (A)

Bechtel Power Corporation

Inter-office Memorandum

To

Subject

Distribution

Job 7220 Midland Project

TRAINING RECORDS

RECORDING OF REVISIONS

ON SERIES DOCUMENTS

Copies to 0-

0-6879

Date 12-08-83

From

T. C. Valenzano/J. T. Minor

Of

Supervision/Field Engineering

At

Midland, MI

This is to clarify the requirements for documenting individual sheet revision for training to series type documents such as Drawings C480-C489, C2060-C2072, C140-C148 and C122-C131.

Individual document revision numbers for series type documents are not required to be recorded. Documents which require revision numbers to be individually tracked will be entered into the Training Matrix as individual documents not as a series.

Knowledge of and/or training to a particular revision of series documents is not a training objective. Importance of this training is based on knowledge of the source of information, not the technical details contained therein. This clarification is to be included in the next revision of FPG-2.000.

T. C. Valenzaro

A T Minor

TCV/JTM/jkc

Written Response Requested: No

file




Deen L Quemme Site Manager Midland Project

Midland Project: PC Box 1963, Midland, MI 48640 + (517) 631-8650

December 9, 1983

Mr S W Baranow Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640



MIDLAND ENERGY CENTER GWO 7020 NIR 006 AND 007 File: 0655, Bl.1.7 UFI: 99*08 Serial: CSC-7077

Attached is our complete response to NIR 006 and 007. Please advise if these commitments are acceptable to resolve these NIR's.

DLQ/DDJ/klp

NIReichel, MEC w/a
BHPack, MEC w/a
RJCook, NRC w/a
JGKeppler, NRC w/a
JJHarrison, NRC w/a

8312280205

DEC 19 1983

Bechte, Power Corporation

Post Office Box 2167 Midland, Michigan 48640



December 9, 1983

P.O. Box 1963 Midland, MI 48640

Attention: D.L. Quamme

Job 7220 Midland Project CONSTRUCTION REIVEW OF STONE & WEBSTER'S NIRS 006 & 007 BCCC-8804

Dear Mr. Quamme:

Reference: CPCo Ltr. D.L. Quamme to G.A. Hierzer dated December 7, 1983 .

Serial No. CSC-7069

Outlined below is Construction's complete response and proposed corrective action for the subject NIRs.

- The discrepancies listed for the class attendance roster are acknowledged. The use of the class attendance rosters was effective on September 28, 1983. Each roster since that date will be reviewed and corrected in conformance with Attachment D to FPG-2.000.
- 2. (Reading Records)
 - A. Illegibility occurs when the preparers run copies from poor masters instead of obtaining copies from the Training Department.
 - B. As noted on Attachment C, the format may vary as long as all information is included.
 - C. There is only one official training record and that is stipulated in paragraph 9 of FPG-2.000. The Team Record and the Team Status Report (TSR) are informal management tools and are not official records. The TSR is being replaced by the Training Exception Report Printout (TERP).

Addressing the two specifics listed.

- *Krantzfelder Completed FPD-2.000 at Level 5 on 8/18/83.
 Paragraph 6.3, FPG-2.000 applies.
- "Hull Spec. M-204 appears on the latest TERP (attached). This means he has not received the required training.

D.L. Quamme BCCC-8804 Page 2

- 3. (Inconsistencies)
 - A. FPG-2.00Q is being revised to stipulate that all corrections will be a line out in ink The corrector will initial and date.
 - B. All entries will be made in ink.
 - C. Review specified in para. 1 above will include the listing of all applicable documents on the class attendance resters.
 - D. See para. 1 above.
 - E. The Course Roster form is now furnished to the instructor with his copy of the Training Schedule to assure that the proper form is used.
- 4. The referenced letter stated that our original response regarding the Training Records Group review of a 10% random sample of the training files is unacceptable. We concur that a 10% sample is inadequate and regret the choice of words. In fact over 100% verification takes place. When training records indicate an individual is 100% complete a verification of the record takes place. This may occur long before the individual is assigned to status assessment. In addition, the supervisor is provided with an exception report showing the training requirements outstanding. Discrepancies between records which may be maintained by the supervisor and the Training Records Group are reconciled on a continuous basis using this management tool. Requirements, therefore, are documented in the exception report.

An additional 100% verification of records is made prior to an individual actually being assigned to status assessment by the Training Records Group. This occurs when the supervisor presents a listing of individuals to be assigned.

If you have any questions regarding the above, please contact E.H. Pillsbury at Ext. 7507.

Very truly yours,

GAH/MAD/BTF/1cc

Written Response Requested: No

Attachment: S&W NIRs (Nonconformance Identification Report) Nos.

006 & 007

CC: N. Reichel

NONCONFORMANCE IDENTIFICATION REPORT

Attackment 4.1 Revision 2 Page 1 of 2

DATE OF NONCONFORMANCE: Novembe	r 7, 1983	NIR NUMBER 007	
IDENTIFICATION/LOCATION OF ITEMS:		***	
DESCRIPTION OF NONCONFORMANCE:			
During the review of 834 non-manu			
of discrepancies were observed wh	ich were not in	compliance with the requir	ements
of FPG-2.000 Rev. 5, "Training of	Construction P	ersonnel." (The following	Teams
were evaluated #24, Field Procure			
and CGSO.			
(See attached for descriptions for	Discrepancies)		
		one alexandro	~
1 -> 0- 1		PROGRAM MGR Les Bucano	
7. Letter H. Sinking			
		DATE Francis 7,1903	
DATE NOVEMBER 7, 1983			1123
CORRECTIVE ACTION BY:	Alia Maria		
. IDENTIFY	ORGANIZATION TAI	KING CORRECTIVE ACTION	
WEDLESCATION FAT . UNFAT		T coursus	
VERIFICATION SAL UNSAL	NEW NIR#	CONCURR	RENCE
VERIFICATION SAT UNSAT	_ NEW NIR#	PROGRAM MGR	RENCE
VERIFICATION SAT UNSAT	_ NEW NIR# DATE		RENCE

REMARKS .

1) Course Rosters Attac. Int D to FPG-2000 exhibited he or more of the following discrepancies.

BLOCK NO.	ENTRY REQUIRED	- ENTRY RECORDED
1	CCP	DWG. No. Fig.
2 :	(a) Name of lesson (b) Procedures (c) Revision	Either a, b, or c missing
6	Location of Session	Bechtel
	In addition some entries were left blank	

- 2) In addition to these violations, inconsistencies were noted in 6 areas:
 - (1) Modification to records, some lined through, signed and dated and others simply lined through. (2) Some entries on course register are completed using pencil while most are in ink. (3) Difficulty is experienced in determining the accuracy of records where attendance at a course carries credit for several others. (4) Some entries carried the revision number to procedures and some omitted the revision. (5) Proper "Course Roster Form" as listed in Procedure FPG-2.000 were not utilized. (6) Some courses on Rosters contain information not identical to matrix listing.

It is recommended that the disposition to this NIR include a committment to verify training records of each individual prior to status assessment assignment. 11.22

STON .ND WEBSTER ENGINEERING CORPO TON NON WEGRMANCE IDENTIFICATION REF .T

OCI 15.01 Attachment 4.1

PAGE 1 OF 2

	~-	יייייייייייייייייייייייייייייייייייייי	
Unit	Ut	NONCONFORMANCE:	

. OCTOBER 27, 1983

NIR NUMBER

006

IDENTIFICATION/LOCATION OF ITEMS:

BECHTEL DOCUMENT CONTROL CENTER

DESCRIPTION OF NONCONFORMANCE:

During the review of 2054 non-manual Construction Training Records, three areas of discrepancies were observed which were not in compliance with the requirements of FFG-2.000 Rev. 5, "Training of Construction Personnel." (The following Teams were evaluated #5, 6, 8, 9, 12, 13, 16, 17, 19, 20, 25, 26, (27/28), 29, 30,31, 32/33), BHO Team Staff.

(See attached for descriptions of Discrepancies)

Walter H. Seenkieure

PROGRAM MGR Sulcanes

DATE 05tober 28 1983

DATE Gorales 28, 1983

CORRECTIVE ACTION BY:

IDENTIFY ORGANIZATION TAKING CORRECTIVE ACTION

NEW KIR#	; CONCURRENCE	
	PROGRAM MGR	
DATE	DATE	

REMARKS

1) Course Rosters Attachment D to FPG-2.000 exhibited one or more of the following discrepancies.

BLOCK NO.	ENTRY RECUIRED	ENTRY RECORDED
1 2	(a) Name of lesson (b) Procedures	DWG. No. FIG. No. Either ab, or c missing
6 10 5	(c) Revision Location of Session (a) Signature (b) Print Last Name Instructor Name	Bechtel Either a or b missing Instructor Department
	In addition many entries were left blank	1

2) Reading Records Attachment C to FPG-2.000 exhibited one or more of the following discrepancies:

Reading Record

- 1) The department and or assignment lines are illegible or incomplete.
- Assigned reading performed on October 11, 1983 and September 29, 1983 were not documented on Reading Form Attachment C, Rev. 5.
- 3) Team Records and TSR (Training Status Report) show training completed Document Control Files showed no record of training. For example:

NAME	TEAM #	TRAINING REQUIREMENT .			DIS	DISCREFANCY		
Kranzfelder J. Hull	Management 32/33	FPD-2.000 M-204	Code			Record Record		A CONTRACTOR OF THE PARTY OF TH

In addition to these violations, inconsistency was noted in 4 areas:

(1) Modification to records, some lined through, signed and dated and others simply lined through. (2) Some entries on course register are completed using pencil while most are in ink. (3) Difficulty is experienced in determining the accuracy of records where attendance at a course carries credit for several others. (4) Some entries carried the revision number to procedures and some omitted the revision. (5) Proper "Course Roster form as listed in Procedure FPG-2.000 were not utilized. (6) Some courses on Rosters contain information not identical to matrix listing.

It is recommended that the disposition to this NIR include a committment to verify training records of each individual prior to status assessment assignment.



Dean L Quamme Sile Manager Midland Project

Midland Project: PO 8ox 1963, Midland, MI 48640 + (517) 631-8650

December 7,1983

Mr S W Baranow, Program Manager Stone & Webster Michigan, Inc P O Box 1963 Midland, MI 48640

PRINC	The second secon	AFF	
RA -	-PRP		
D/RA	OE	-	
A/RA	DRMSF	-	
RC	DR'A	-	Youa+
PAD	508	V	Jours.
SGA	ML	1	1 0
ENF	File	1	1

MIDLAND ENERGY CENTER GWO 7020
RESPONSE TO OPEN ITEMS
File: B1.1.7, 0655 UFI: 53*50*04, 99*08 Serial: CSC-7060

Attached is our partial response to NIR-008. Please advise us of any comments you may have on the proposed action to close this NIR.

Man Damme

DLQ/DDJ/klp

cc: RAWells, MPQAD w/o attachments
BHPeck, MMC w/o attachments
NIReichel, MEC with attachments
RJCook, NRC w/a
JGKeppler, NRC w/a
JJHarrison, NRC w/a

DEC 1 9 1983

8312280375

CONSUMERS DY'ER CO. REGERER

DEC 02 1983

Site Mgr. Midland Project

Consumers Power Company P.O. Box 1963 Midland, Ml 48640

Attention: D.L. Quamme

Bech Power Corporation

Post Office Box 2167 Midland, Michigan 48640



013

November 30, 1983

Control of the Contro	And in case of the latest terms of the latest
Jir	1
11:2	
VAC	i
7.17	1
la K	1
Milia	
1.176	1
0.615	1

MR

1377-UF/

FIELD

Job 7220 Midland Project CONSTRUCTION REVIEW OF STONE & WEBSTER'S CCP OVERVIEW REPORT NO. 22

BCCC-8751

Dear Mr. Quamme:

Construction's review of Stone & Webster's Overview Report No. 22 identified one (1) open (Construction) action item (specifically S&W NIR No. 008).

Outlined below is Construction's partial response and proposed corrective action for the subject NIR.

The documents listed in the subject NIR will be incorporated into Rev. 3 to the Construction Training Matrices of the System Teams. Additionally, the Curriculum Committee is establishing a subcommittee to do a total review of all of the Training Matrices to verify their adequacy.

As an interim measure and to assure that the training is accomplished for those personnel currently assigned to the teams a memorandum was issued on November 29, 1983, requiring immediate training for those affected team personnel.

Construction's forecast for Rev. 3 to the Construction Training Matrices of the System Teams is January 15, 1984. Further correspondence on this subject will be forwarded to you at that time.

If you have any questions concerning the above, please contact B.T. Foote at Ext. 7567.

Very truly yours,

G.A. Hierzer

Site Manager

Attachment: S&W NIR No. 008

CC: N. Reichel

Written Response Requested: No

STONE AND WEBSTER ENGINEERING CORPORATION . NO! "NEORMANCE IDENTIFICATION RE" "RT

QCI 15.01 Attachment 4. Revision 2

			PAGE 1 OF 2	
DATE OF NONCONFORMANCE: NOVEMBER	8, 1983		NIR NUMBER	008
IDENTIFICATION/LOCATION OF ITEMS:				
SYSTEM TEAM TRAINING MATRIX, REV. 1	. DATED JULY	20, 1983		
DESCRIPTION OF NONCONFORMANCE:			•	
During the review of the adequacy	of the constru	ction tr	aining matrice	s,a sampl
size of 50 training level assignment	ents, represent	ing a lo	t size of 318	essignmer
five unsatisfactory conditions wer	re observed in	the trai	ning level ass	ignments.
The System Team Training Matrix of	the Construct	ion Trai	ning Program w	as utiliz
to perform the review.				
See the attached for unsatisfactor conditions reported represents a n				
INITIATOR - 1/9/83		PROGRAM I	retaber 10, 90	23
CORRECTIVE ACTION BY:				
IDENTIFY O	RGANIZATION TAN	CING CORP	RECTIVE ACTION	
VERIFICATION SAT UNSAT	NEW KIR#		CO	NCURRENCE
INITIATOR :			PROGRAM MGR	
DATE	DATE	1.7	21-5	

REMARKS

1. *FPG 9.700, "System Team Charter"

FPG 9.700 appears on the "System Team Training Matrix" as a Level "O" (no training required) for the system team field engineer, mechanical. Paragraph 5.2.7 of this procedure identifies the job responsibilities and reporting relationships for the system team field engineers. As such, a level of training of "O" (no training) is not satisfactory.

2. FPO 1.201, "Bechtel Assigned Post Turnover (PTO) Work".

FPO 1.201 appears on the "System Team Training Matrix" as a Level "O" (no training required) for the system team field engineer, mechanical. In discussion with the Team #5 supervisor, it was noted that the Team members do get involved in Post Turnover Work. Because of this involvement by the Team members, a level of training of "O" (no training) is not satisfactory.

3. FIG 1.400 "Preparation, Review and Routing of Field Engineer's Reports."

FIG 1.400 includes responsibilities for several disciplines, ie; mechanical civil, welding, and instrumentation as well as including responsibilities for the electrical discipline. The following conditions were noted as being unsatisfactory:

- (a) The "System Team Training Matrix" under the column entitled "Responsible Discipline" shows this procedure to be an electrical discipline—procedure.
- (b) The "System Team Training Matrix" requires the field engineers of the mechanical and the instrumentation disciplines to receive a level "2" training whereas the field engineers of the electrical and welding disciplines receive a level "3" training. There is an inconsistancy of training levels being assigned.
- 4. Specification M-214, "Piping System Erection Fit-up Control Requirements."

M-214 appears on the "System Team Training Matrix" as a level "O", (no training required) for the system team field engineer, welding. Specification pages 3, 5; 7B and 8 address welding. Also, weld fit-ups are addressed throughout this specification. As such, a level of training of "O" (no training) is not satisfactory.

5. Drawing E-039 -: "Seismic Wireway Supports."

E-039 appears on the "System Team Training Matrix," as a level "0" (no training required) for the system team field engineer, welding. This drawing contains weld sizes and weld symbols for typical wireway supports. As such, a level of training of "0" (no training) is not satisfactory.

It is recommended that the disposition to this NIR include a committment to verify the adequacy of all training matrices.