Thomas J. Martin
Vice President
Engineering and Construction

Public Service Electric and Gas Company 80 Park Plaza Newark, N.J. 07101 201/430-8316

May 25, 1984

Dr. Thomas E. Murley, Administrator U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Dr. Murley:

POTENTIAL CONSTRUCTION DEFICIENCY DEFECTS IN LUBE OIL PUMP DISCHARGE NOZZLES HOPE CREEK GENERATING STATION

On April 25, 1984, a verbal report was made to Region I, Office of Inspection and Enforcement representative, Mr. E. C. McCabe, advising of a potential ficant construction deficiency regarding cracked our diesel generator lube oil pump discharge nor and following interim report is provided in action with 10CFR50.55(e).

Colt Industries submitted art 21 Report to Region III concerning a broken boss on a lube oil pump discharge nozzle discovered during factory testing of a diesel generator set. A second lube oil pump was examined and the boss area was found to be cracked. Colt reported that the noted conditions significantly reduce the sealing area between the pump and the threaded adapter.

Our Architect/Engineer and Constructor, Bechtel, inspected the identical components on our diesel generator sets and found cracks and casting discrepancies at the boss connections. Bechtel has issued Nonconformance Report No. 3826 to document and control the hardware.

8406120456 840523 PDR ADDCK 05000354 S PDR Dr. T. E. Murley 2 5/25/84

A report conveying the requisite safety analysis and full details concerning our corrective actions will be submitted to your office by July 13, 1984.

Very truly yours,

C Office of Inspection and Enforcement Division of Reactor Construction Inspection

NRC Resident Inspector - Hope Creek P. O. Box 241 Hancocks Bridge, NJ 08038

Washington, D. C. 20555

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339

SECTION AND AND AND AND