NRC Form (9-83)	366						ıc	ENSE	E EVE	NT RE	PORT	(LER)			U.S.	AP		ED O	MB NO.	8Y COM 3150-0	MISSION 104
										DOC	DOCKET NUMBER (2)						PAGE (3)				
										0 15 1				101	0	0	31	218	1 0	0 12	
TITLE (4		,													_					-	
Re	acto	r Tr	ip																		
EVE	NT DATE	(5)	T	L	ER NUMBER	(3)		RE	PORT DA	TE (7)		ОТНЕ	RFA	CILIT	IES IN	VOL	VED (8)			
MONTH DAY YE		YEAR	YE	EAR SEQUENTIAL RE			RE VISION	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)						
0.00																	0 15	5 10	0 10	0	1.1
0 5	1 9	814	8	4	0 0 8	- 0	0	0 6	1 5	8 4							0 15	5 0	010	01	1.1
OPE	RATING		THIS	REPORT	IS SUSMITTI	ED PURSUA	NT T	O THE R	EQUIREM	ENTE OF 1	0 CHR \$: 15	Check one or mo	re of t	he foi	owing	_	_				-
MODE (9)				20.402(b)				20.405(c)			X	X 50.73(a)(2)(iv)			T	73,71(b)					
POWER LEVEL (10) 0 3 0				20.406(a)(1)(i) 20.406(a)(1)(ii)				50.36(c)(1) 50.36(c)(2)				50.73(a)(2)(v) 50.73(a)(2)(vii)			1	73.71(e)					
																	OTHER (Specify in Abstract				
				20.406()(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(vi	H)(A)					366A		reat, Nr	C Form
				20.405(a)(1)(lv)				50.73(e)(2)(ii)			50.73(a)(2)(viii)(B)										
20.406(a)(1)(v)					i)(1)(v)	2 1		50,73(a)(2)(iii)			50.73(e)(2)(x)										
							L	ICENSEE	CONTACT	FOR THIS	LER (12)			_							
NAME														AREA CODE							
CI	onn l	e v	i wle	Con	plianc	o Snot	io	n Er	oinec					6		5	8,7	7	0 -	6	1.6
(3.)	emi i	D. K.	LIK	, Con			-	-	-						1	7	01	1	L	9	1410
	-				COMPLETE	ONE LINE	FOR	EACH C	DMFONER	T FAILURE	DESCRIBE	D IN THIS REP	ORT (13)		_	_	_	100		
CAUSE	SYSTEM	СОМР	COMPONENT		TURER		REPORTABLE TO NPROS			CAUSE	SYSTEM	COMPONENT		MANUFAC- TURER		C-	REPORTABLE TO NPRDS				
	1													1	L	_					
		1										111		1	1	1					
SUPPLEMENTAL R. PORT EXPECTED (14)											EXPECTED SUBMISSION DATE (15)				DAY	YEAR					
YES (If ves. complete EXPECTED SUBMISSION DATE)																					

On 05/19/84, unit 2 was in mode 1 (556 degrees F, 2235 psig) at 30% reactor power with various maintenance activities underway while the unit was at reduced power. A reactor trip occurred at 1157 CST when the balance of plant reactor operator intended to stop the 2B main feedwater pump oil pumps but inadvertently stopped the 2A main feedwater pump oil pumps. This event resulted in a reactor trip on low-low steam generator level.

8406190307 840615 PDR ADDCK 05000328 S PDR

ABSTRACT (Limit to 1400 spaces, i.e., episroximately fifteen single-space typewritter lines) (16)

IEZZ/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

FACILITY NAME (1)	DOCKET NUMBER (2)	T	LE	R NUMBER (6)	PAGE (3)				
		YEAR		SEQUENTIAL NUMBER		REVISION MREA			
Sequoyah, Unit 2	0 5 0 0 0 3 2 8	8 4	_	0 0 8	_	010	0 2	OF	0 2

EXT III more space is required, use additional NRC Form 366A's) (17)

Unit 2 had been reduced to 30% reactor power for addition of oil to reactor coolant pumps. During the reduced power level condition, various maintenance activities were being performed which included repairing oil leaks on both the 2A and 2B main feedwater pumps. The 2A main feedwater pump was removed from service, all of its oil pumps stopped, and the leaks repaired. The 2A main feedwater pump was returned to service and the 2B main feedwater pump removed from service. When it came time to stop the 2B main feedwater pump oil pumps, the balance of plant reactor operator inadvertently stopped the 2A main feedwater pump oil pumps. This action caused the 2A main feedwater pump to trip resulting in a subsequent reactor trip on lowlow level in the number ? steam generator. Unit 2 was in mode 1 (556 degrees F, 2235 psig) at 30% reactor power just prior to the reactor trip which occurred at 1157 CST on 05/19/84.

With exception of an excessive packing leak on the loop 3 feedwater isolation valve, all other personnel and equipment performed as expected during the event. The event was discussed thouroughly with the operator involved and the cause of the event was confirmed to be a personnel error.

There was no effect on public health or safety. Although there have been several reactor trips on unit 1 during 1984, this was the first reactor trip (both units) initiated by inadvertent tripping of a main feedwacer pump due to a personnel error.

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant Post Office Box 2000 Soddy Daisy, Tennessee 37379

June 15, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE REPORT SQRO-50-328/84008

The enclosed licensee event report provides details concerning a reactor trip from 30% reactor power. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.iv.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

P. R. Wallace Plant Manager

P.R. Wall

Enclosure cc (Enclosure):

> James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30303

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

IE22