

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company  
Turkey Point 3

Docket No. 50-250  
License No. DPR-31

The following violation was identified during an inspection conducted on April 9-12, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion V as implemented by paragraph 5.1 of the accepted quality assurance program requires activities affecting quality to be accomplished in accordance with procedures. FP&L Turkey Point Maintenance Procedure MP 1107.3 "Reactor Coolant Pump Impeller Removal and Replacement" all revisions to and including September 2, 1982, Steps 9.10 and 9.93 require Fel-Pro-C5A Lubricant be used to Lubricate reactor coolant pump studs prior to installation.

Contrary to the above, activities affecting quality were not accomplished in accordance with procedures in that the 3A reactor coolant pump studs were lubricated with Fel-Pro-N-5000.

This is a Severity Level V Violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

**APR 26 1984**

Date: \_\_\_\_\_

8406210541 840608  
PDR ADOCK 05000250  
G PDR