

10CFR50.55(g)(5)

Pilgrim Nuclear Power Station Rocky Hill Road Plymouth, Massachusetts 02360

E. T. Boulette, PhD

Senior Vice Fraidont - Nuclear

August 31 , 1995 BECo 95089

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

> License DPR-35 Docket 50-293

Report of Pilgrim Nuclear Power Station (PNPS) Inservice Inspections
Conducted During Refueling Outage (RFO) 10
and Mid-Cycle Outage (MCO) 10

The enclosed raports provide results of the inservice inspections conducted at PNPS during RFO#10 and MCO #10.

This submittal fulfills the requirements of the XI, 1980 Edition, Winter 1980 Addenda, Para h IWA-6230, and is in compliance with 10CFR50.55(g)(5) requirements.

E. T. Boulette, PhD

GGW/ /RFO10ISI

Enclosures:

- Boston Edison RFO # 10 ISI Summary Report.
- 2) General Electric Co. Report of RFO # 10 Inservice Inspections
- 3) General Electric Co. Report of MCO # 10 Inservice Inspections
- 4) ABB RFO # 10 Inservice Inspection Final Report to Boston Ecison (5 Volumes)

cc: see next page

7509140227 750831 PDR ADOCK 05000293 Limited Distribution

AOH!

BOSTON EDISON COMPANY

U. S. Nuclear Regulatory Commission

Page 2

cc: w/Enclosures:

Mr. John McCabe
Supervising District Engineering Inspector
Division of Inspection
Department of Public Safety
1 Ashburton Place
Room 1301
Boston, MA 02108

cc: w/o Enclosures

Mr. R. Eaton, Project Manager
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
Mail Stop: 14D1
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U. S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406

Senior NRC Resident Inspector Pilgrim Nuclear Power Station

Mr. V. Iyer Authorized Nuclear Inservice Inspector (ANII) Pilgrim Nuclear Power Station