

NOTICE OF VIOLATION

Commonwealth Edison Company  
Braidwood Nuclear Generating Station

Docket Nos. 50-456; 50-457  
License Nos. NPF-72; NPF-77

During an NRC inspection conducted on January 13-17, 1992, two violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions", (10 CFR Part 2, Appendix C (1991)), the violations are listed below:

1. 10 CFR Part 50.54(q) requires that a licensee authorized to possess and operate a nuclear power reactor shall follow and maintain in effect emergency plans which meet the standards in 10 CFR Part 50.47(b) and the requirements of Appendix E to 10 CFR Part 50. The Generating Station Emergency Plan (GSEP), Section 8.5.7, states that Emergency Plan Implementing Procedures and corresponding lesson plans shall be developed consistent with the GSEP within 4 months of any GSEP revision.

Contrary to the above, lesson plans corresponding to the GSEP were not revised within four months of the revision of the GSEP. The GSEP was revised in March 1991, and, as of January 1992, relevant lesson plans had not been revised to be consistent with the current GSEP revision.

This is a Severity Level IV violation (Supplement VIII).

2. 10 CFR Part 50.54(q) requires that a licensee authorized to possess and operate a nuclear power reactor shall follow and maintain in effect emergency plans which meet the standards in 10 CFR Part 50.47(b) and the requirements of Appendix E to 10 CFR Part 50. Appendix E states that the emergency plan will provide a description of the specialized training which emergency response personnel assigned to repair and damage control teams will receive. The GSEP, Section 8.2.1, states that emergency response personnel assigned to repair and damage control teams will perform emergency response activities as an extension of their normal duties and will be trained each year as part of their duty specific training.

Contrary to the above, emergency response personnel assigned to repair and damage control teams did not receive specialized emergency preparedness training, relevant to their role in the emergency response organization, each year as part of their duty specific training.


This is a Severity Level IV violation (Supplement VIII).

Pursuant to the provisions of 10 CFR Part 2.201, Commonwealth Edison Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington D.C. 20555 with a copy to the U.S. Nuclear Regulatory Commission, Region III, 799 Roosevelt Road, Glen Ellyn, Illinois, 60137, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation. This reply should be clearly marked as a "Reply to a Notice of Violation" and should

FEB 07 1992

include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Glen Ellyn, Illinois  
this 7<sup>th</sup> day of February 1992

  
L. Robert Greger, Chief  
Reactor Programs Branch