

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PDR

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-77-01	IE BULLETIN	C	R210	C		PNEUMATIC TIME DELAY SET POINT DRIFT
	IR-77-02	IE BULLETIN	C	R210	C		POT FAILURE MECHANISM IN CERTAIN W AR-RELAYS W/LATCH ATTACHMENTS
	IR-77-03	IE BULLETIN	C	R329	C		ONLINE TESTING OF W SOLID STATE PROTECTION SYSTEM
	IR-77-04	IE BULLETIN	C	R210	C		CALC ERROR-DESIGN PERFORMANCE SYS CONTRLG PM CONT BUMP
	IR-77-05	IE BULLETIN	C		C		WATER FOL LOCA FLFC 'C CONNECTOR ASC PLIES
		IE BULLETIN	C	R210	C		SUPPLEMENT A
	IR-77-07	IE BULLETIN	C	R210	C		CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IR-77-08	IE BULLETIN	C	R210	C		SAFEGUARDS LOCKING SYSTEM
	IR-78-01	IE BULLETIN	C	R210	C		FLAMMABLE CONTACT-ARM RETAIN GE CR120A RELAYS
	IR-78-02	IE BULLETIN	C	R210	C		TERMINAL BLOCK QUALIFICATION
	IR-78-04	IE BULLETIN	C	R210	C		ENVIRONMENTAL QUALIF CERTAIN STEM MOUNTED LIMIT SWITCH INSIDE REACTOR CONTAINMENT

8406230218 840612
PDR ADOCK 05000530
PDR

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-76-05	IE BULLETIN	C	8210	C		HALF FUNCTION CIRCUIT BRKR AUX CONTACT MECHANISM-GENERAL MODEL CR105X
	IR-78-06	IE BULLETIN	C	8210	C		DEFECTIVE CUTLER HAMER TYPE M RELAYS WITH DC COILS
	IR-78-10	IE BULLETIN	C	8210	C		BERGEN-PATTERSON HYDRAULIC SHOCK SUPPRESSOR ACCUMULATOR SPRING COILS
	IR-78-12	IE BULLETIN	C	8210	C		ALSO 78-12 AND 78-12B ATYPICAL WELD MATERIAL IN RV-SPLMTS ARB
	IR-79-01	IE BULLETIN	C	8320	C		ENVIRONMENTAL QUALIFICATION OF CLASS IE EQUIPMENT-SPLMTS ARB
	IR-79-02	IE BULLETIN	C	8231	C		PIPE SUP BASE PLT DSGN USING CONCRETE EXP ANCHOR BOLTS LATEST EFFECTIVE REV: 2/SUP: 1
	IR-79-03	IE BULLETIN	C	8231	C		LONGITUDINAL WELD DEFECTS IN ASPE SA-312 TYPE 304 STAINLESS STEEL PIPE-REV. A
	IR-79-04	IE BULLETIN	C	8231	C		INCORRECT WEIGHTS FOR SWING CHECK VALVES MANUFACTURED BY VELAN ENG.
	IR-79-07	IE BULLETIN	C	8231	C		SEISMIC STRESS ANALYSIS OF SAFETY RELATED PIPING
	IR-79-09	IE BULLETIN	C	8231	O		FAILURES OF GE TYPE AK-2 CIRCUIT BREAKER IN SAFETY RELATED SYSTEMS
	IR-79-11	IE BULLETIN	C	8231	C		FAULTY OVERCURRENT TRIP DEVICE IN CIRCUIT BREAKERS IN ENG SAFETY SYSTEM

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 3

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-79-14	IE BULLETIN	C	8231	0		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/8HP1-2
	IR-79-15	IE BULLETIN	C	8231	C		MATL DEFS IN INGER-RAND PUMPS USED FOR HI/LO PRESS CORE SPRAY & PWR PP
	IR-79-21	IE BULLETIN	C	8308	0		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IR-79-23	IE BULLETIN	C	8308	C		POTENTIAL FAILURE OF EMERG DIESEL GEN-FIELD EXCITER TRANSFORMER
	IR-79-24	IE BULLETIN	C	8311	C		FROZEN LINES SAFETY RELATED
	IR-79-25	IE BULLETIN	C	8308	C		FAILURES OF WESTINGHOUSE RFD RELAYS IN SAFETY RELATED SYSTEMS
	IR-79-28	IE BULLETIN	C	8308	C		POSS MALFCON OF NAMCO MODEL EA180 LIMIT SWITCHES AT ELEVATED TEMPS
	IR-80-03	IE BULLETIN	M	8021	C		LOSS OF CHARCOAL FROM TRAY ABSORBER CELLS-RESPOND BY MAR 31, 1980
	IR-80-05	IE BULLETIN	C	8311	C		VACUUM COND RESULTING IN DAMAGE TO HOLDUP TANKS RESPOND BY JUN 28, 1980
	IR-80-06	IE BULLETIN	C		0		ESF RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IR-80-08	IE BULLETIN	C		0		EXAM OF CONTAINMENT LINER PENETRATION WELDS - RESPOND BY JUL 16, 1980

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 4

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IR-80-09	IE BULLETIN	C		0		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980
	IR-80-11	IE BULLETIN	C	R311	C		MASONARY BLOCK WALLS
	IR-80-12	IE BULLETIN	C	R121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	IR-80-16	IE BULLETIN	C	R121	0		POTENTIAL MISAPPLICATION OF ROBERT 1151 & 1152 PRESSURE TRANSMITTERS-REP BY 9-5-80
		IE BULLETIN	C	R308	0		
	IR-80-18	IE BULLETIN	C		0		MAINT OF ADEQUATE FLOW THRU CCP'S AFTER SECONDARY BREAK-NO REPLY REQD
	IR-80-19	IE BULLETIN	C	R308	C		FAILURE OF MERCURY WETTED RELAYS IN RPS-REPLY BY 11-05-80
	IR-80-20	IE BULLETIN	C	R308	C		WESTINGHOUSE TYPE W-2 CONTROL SWITCH-REPLY BY 9-21-80
	IR-80-21	IE BULLETIN	C	R308	C		VALVE YOKES SUPPLIED BY MALCOM FOUNDRY CO. CRACK FAILURE
	IR-80-23	IE BULLETIN	C	R308	C		FAILURE OF SOLENOID VALVES MFG BY VALCOR ENG CORP
	IR-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNUBBERS-INSPECT ACCESSABLE WITHIN 30 DAYS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IB-81-02	IE BULLETIN	C	A234	0		POW INSULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST
		IE BULLETIN	C	A305	0		
	IB-81-03	IE BULLETIN	C		0		CLAM INFESTATIONS OF WATER SYSTEMS & RESULTANT FOULING-90 DAY RPT FOR CONST.
	IB-82-01	IE BULLETIN	C		0		ALTERATION OF RADIOGRAPHS OF WELDS IN PIPING SUBASSEMBLIES
	IB-82-02	IE BULLETIN	C		0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARY
	IB-82-03	IE BULLETIN	C		0		STRESS CORROSION CRACKING IN THICKWALL LARGE-DIAMETER STAINLESS RECIR
	IB-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IB-83-02	IE BULLETIN	C		0		STRESS CORROSION CRACKING IN LARGE DIAMETER STAINLESS STEEL RECIR
	IB-83-03	IE BULLETIN	C		0		CHECK VALVE FAILURES IN RAW WATER COOLING SYSTEMS OF DG
	IB-83-04	IE BULLETIN	C		0		FAILURE OF UV TRIP FUNCTION OF REACTOR TRIP BREAKERS
	IB-83-05	IE BULLETIN	C		0		PUMPS AND PARTS BY HAYWARD TYLER

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 6

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	10-83-06	IE BULLETIN	C		0		NO MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLAND CITY HOUSTON
	10-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDULENT PRODUCTS SOLD BY RAY MILLER, INC
	10-83-08	IE BULLETIN	0		0		C/R'S WITH UV TRIP ON SAFETY RELATED SYSTEMS OTHER THAN REACTOR TRIP SYSTEM
	10-84-02	IE BULLETIN	0		0		FAILURE OF GE TYPE MFA RELAYS USED IN CLASS 1E SAFETY SYSTEMS

06/12/80

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 7

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-76-01	IE CIRCULAR	C	8210	C		CIRCUIT MODS ON CRANE HOIST CONTROLS
	IC-76-02	IE CIRCULAR	C	8210	C		RELAY FAILURES-W/BF(AC) & BFD(DC) RELAYS
	IC-76-05	IE CIRCULAR	C	8210	C		HYDRAULIC SHOCK & SWAY SUPPRESSORS MFG BY ITT-GRINNELL
	IC-77-01	IE CIRCULAR	C	8210	C		MALFUNCTIONS OF LIMITORQUE VALVE OPERATORS
	IC-77-03	IE CIRCULAR	C	8210	C		FIRE INSIDE A MOTOR CONTROL CENTER
	IC-77-05	IE CIRCULAR	C	8210	C		LIQUID ENTRAPMENT IN VALVE RONNETS
	IC-77-06	IE CIRCULAR	C	8210	C		EFFECTS OF HYDRAULIC FLUID ON ELECTRICAL CABLE
	IC-77-14	IE CIRCULAR	C	7807	C		SEPARATION CONTAMINATED WATER SYS FROM NONCONTAMINATED PLANT SYSTEM
	IC-78-02	IE CIRCULAR	C	8210	C		PROPER LUBRICATING OIL FOR TERRY TURBINES
	IC-78-04	IE CIRCULAR	C	8210	C		INSTALLATION ERROR THAT COULD PREVENT CLOSING OF FIRE DOORS
	IC-78-05	IE CIRCULAR	C	8210	C		INADVERTENT SAFETY INJECTION DURING COOLDOWN

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-78-06	IE CIRCULAR	C	8210	C		POT COMMON MODE FLOODING OF ECCS EQUIP RMS AT RWR FACILITIES
	IC-78-07	IE CIRCULAR	C	8210	C		DAMAGED COMPONENTS OF BERGEN-PATTERSON 25000 HYDRAULIC TEST STAND
	IC-78-08	IE CIRCULAR	C	8210	C		ARCING OF GE CO-SIZE 2 CONTRACTORS
	IC-78-13	IE CIRCULAR	C	8210	C		INOPERABILITY OF MULT SERVICE WATER PUMPS
	IC-78-15	IE CIRCULAR	C	8210	C		CHECKVALVES FAIL TO CLOSE IN VERT POSITION
	IC-78-16	IE CIRCULAR	C	8210	C		LIMITORQUE VALVE ACTUATORS
	IC-78-18	IE CIRCULAR	C	8210	C		UL FIRE TEST
	IC-78-19	IE CIRCULAR	C	8210	C		MANUAL OVERRIDE OF SAFETY SYS ACTUATOR SIGNALS
	IC-79-02	IE CIRCULAR	C	8231	C		FAILURE OF 120 VOLT VITAL AC POWER SUPPLIES
	IC-79-04	IE CIRCULAR	C	8231	C		LOOSE LOCKING NUT ON LIMITORQUE VALVE OPERATORS
	IC-79-05	IE CIRCULAR	C	8231	C		MOISTURE LEAKAGE IN STRANDED WIPE CONNECTORS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-05	IE CIRCULAR	C	R231	C		
	IC-79-08	IE CIRCULAR	C	R231	C		NO DESCRIPTIVE TITLE
	IC-79-10	IE CIRCULAR	C	R231	C		NO DESCRIPTIVE TITLE
	IC-79-11	IE CIRCULAR	C	R231	C		DESIGN/CONSTR PROB=MISORIENTED RX VESSELS OR THEIR SUPPORTS
	IC-79-13	IE CIRCULAR	C	R231	C		REPLACEMENT OF DIESEL FIRE PUMP STARTING CONTACTORS
	IC-79-17	IE CIRCULAR	C	R231	O		CONTACT PROBLEM IN SR-12 SWITCHES ON GE METALCLAD CIRCUIT BREAKERS
	IC-79-18	IE CIRCULAR	C	R231	C		PROPER INSTALLATION OF TARGET ROCK SAFETY-RELIEF VALVES
	IC-79-19	IE CIRCULAR	C	R231	C		LOOSE IMPELLAR LOCKING DEVICES ON INGERSOLL-RAND PUMPS
	IC-79-20	IE CIRCULAR	C	R231	C		FAILURE OF GTE SYLVANIA RELAYS
	IC-79-21	IE CIRCULAR	H	R021	C		PREVENTION OF UNPLANNED RELEASES OF RADIOACTIVITY
		IE CIRCULAR	C	R231	O		

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 10

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-79-22	IE CIRCULAR	C	8231	C		STROKE TIMES FOR POWER OPERATED RELIEF VALVES (PORV'S)
	IC-79-23	IE CIRCULAR	C	8231	C		MOTOR STARTERS AND CONTACTORS FAILED TO OPERATE
	IC-79-25	IE CIRCULAR	C	8231	C		SHOCK ARRESTOR STRUT ASSEMBLY INTERFERENCE; LATEST EFFECTIVE IS SUP A
	IC-80-01	IE CIRCULAR	C	8308	O		GE INDUCTION RELAYS
	IC-80-03	IE CIRCULAR	C	8308	C		TOXIC GAS
	IC-80-04	IE CIRCULAR	C	8308	C		SECURING OF THREADED LOCKING DEVICES ON SAFETY-RELATED EQUIPMENT
	IC-80-05	IE CIRCULAR	C	8308	O		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-07	IE CIRCULAR	C	8308	C		TURBINE OIL PROBLEMS
	IC-80-09	IE CIRCULAR	C	8308	O		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
	IC-80-10	IE CIRCULAR	C	8308	O		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT
	IC-80-11	IE CIRCULAR	C	8308	C		EMERGENCY DIESEL GENERATOR LUBE OIL COOLER FAILURES

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 11

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-80-12	IE CIRCULAR	C	8308	C		BETTIS/PRATT VALVE ACTUATOR SHAFT KEY ORIENTATION
	IC-80-14	IE CIRCULAR	C	8311	O		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
	IC-80-16	IE CIRCULAR	C	8311	O		DEFICIENCIES IN ROSEMOUNT 510DU TRIP UNITS & 1152 PRESS. XMTS
	IC-80-17	IE CIRCULAR	C	8311	C		FUEL PIN DAMAGE FROM WATER JET BAFFLE PLATE CORNER
	IC-80-18	IE CIRCULAR	M	8021	C		50,59 SAFETY EVALUATIONS FOR CHANGES TO RAWASTE SYSTEMS
	IC-80-22	IE CIRCULAR	C	8311	C		CONFIRMATION OF EMPLOYEE QUALIFICATIONS PROGRAM
	IC-80-23	IE CIRCULAR	C	8311	C		DEFECTS IN BELOIT POWER SYSTEMS EMERGENCY GENERATORS COUPLED TO DIESELS
	IC-81-01	IE CIRCULAR	C	8319	C		MECHANICAL MALFUNCTION OF HONEYWELL PB INDICATING SWITCHES AT SAN ONOFRE
	IC-81-02	IE CIRCULAR	O		O		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY
	IC-81-03	IE CIRCULAR	O		O		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	O		O		ROLE OF STAFF & IMPORTANCE OF LER'S

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 12

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IC-81-05	IE CIRCULAR	C	8311	C		SELF-ALIGNING ROD END BUSHINGS FOR PIPE SUPPORTS
	IC-81-06	IE CIRCULAR	C	8311	C		ENVIRONMENTAL QUAL FAILURE OF FOXBORO 10-50 MA XMITTERS
	IC-81-07	IE CIRCULAR	M		C		CONTROL OF RADIOACTIVELY CONTAMINATED MATERIAL
		IE CIRCULAR	M	8224	C		SEE 50-528/82-24
	IC-81-08	IE CIRCULAR	C	8311	C		INSUFFICIENT COMPACTION OF BACKFILL MATERIALS DURING CONSTRUCTION
	IC-81-09	IE CIRCULAR	C	8311	C		UNMONITORED CONTAINMENT EFFLUENT BYPASS
	IC-81-10	IE CIRCULAR	O		O		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-12	IE CIRCULAR	O		O		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-81-13	IE CIRCULAR	C	8311	C		TORQUE SWITCH ELECTRICAL BYPASS-CKT MISSING ON SAFEGUARD VALVE MOTORS
	IC-81-14	IE CIRCULAR	C	8311	O		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS
	83-01-03	IE CIRCULAR	C		O		ORIENTATION OF DUAL AIR START CHECK VALVES

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 13

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
--------	----------	------	--------------------	------------------------	--------	-------------	----------------------

50530	80-16-01	INSP RPT (ENF)	C	0212	C		CLEANLINESS INSP PRIOR TO CONCRETE PLACEMENT
	84-03-01	INSP RPT (ENF)	C		0		STORAGE OF 480 V. MCC IN LEVEL D STORAGE

06/12/64

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 14

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
-----------------	------	--------------------	------------------------	--------	-------------	----------------------

50530	82-09-01	INSP RPT (FOLLOWUP)	C	A323	C	REMOVAL OF CONSTRUCTION AIDS
-------	----------	---------------------	---	------	---	------------------------------

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 15

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-81-36	INFO NOTICE	M		C		CLARIFICATION OF PLACEMENT OF PERSONNEL MONITORING DEVICES FOR EXTERNAL USE
		INFO NOTICE	M	8224	C		SEE 50-528/82-24
	IN-82-05	INFO NOTICE	S		O		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		O		SCREENING OF ONSITE PERSONNEL
	IN-82-31	INFO NOTICE	M		C		OVEREXPOSURE OF DIVER DURING WORK IN FUEL STORAGE POOL
		INFO NOTICE	M	8224	C		SEE 50-528/82-24
	IN-82-36	INFO NOTICE	M		C		RESPIRATOR USERS WARNING FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
		INFO NOTICE	M	8224	C		SEE 50-528/82-24
	IN-82-49	INFO NOTICE	M		C		CORRECTION FOR SAMPLE CONDITIONS AIR & GAS MONITORS
		INFO NOTICE	M	8312	C		SEE REPORT 50-528/83-12
	IN-82-51	INFO NOTICE	M		C		OVEREXPOSURE IN PWR CAVITIES

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 16

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-82-51	INFO NOTICE	M	8312	C		SEE REPORT 50-528/83-12
	IN-83-10	INFO NOTICE	M		C		INFO NOTICE CLARIFICATION FOR USE OF NRC CERTIFIED TRANSPORT PACKAGES
		INFO NOTICE	M	8312	C		SEE REPORT 50-528/83-12
	IN-83-14	INFO NOTICE	M		C		INFO NOTICE EXOTHERMIC REACTION IN RESINS
		INFO NOTICE	M	8312	C		SEE REPORT 50-528/83-12
	IN-83-21	INFO NOTICE	M	8313	C		DEFECTIVE EMERGENCY USE RESPIRATOR BIOPAK 60
	IN-83-27	INFO NOTICE	S		O		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S 8 0)
	IN-83-28	INFO NOTICE	S		O		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-33	INFO NOTICE	M	8313	C		SAMPLING OF CONTAMINATED OIL
	IN-83-36	INFO NOTICE	S		O		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-83-52	INFO NOTICE	M	8313	C		RADWASTE GAS EVENTS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 17

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-15	INFO NOTICE	M		0		INFO NOTICE-REPORTING OF RADIOLOGICAL RELEASES
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-8CBA 4500 PSI LUXFER CYLINDERS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 18

DOCKET	ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	FW-06-16	OTHER	M		C		IE NOTICE 82-16-ASSMT. OF INTAKES OF RADMATERIAL BY WORKERS
		OTHER	M	8224	C		SEE 50-528/82-24
	FW-11-16	OTHER	M		C		IE NOTICE 82-43-DEFICIENCIES IN VENTILATION SYSTEMS
		OTHER	M	8312	C		SEE REPORT 50-528/83-12

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 19

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN-LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-08	TEMP INSTR (TI)	C	8311	C		TI FOR IER 81-08 SOILS AND BACKFILL
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IER 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-37	TEMP INSTR (TI)	C	8311	C		IE BULLETIN FOLLUP 80-11 MASONARY WALLS IN PROXIMITY TO SAFETY SYSTEMS
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT ROOMS HP & EMERGENCY PLANNING-REV. 2
	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION ROOMS FOR SYSTEM ROOMS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 20

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY R2
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82
	TI-15-60	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 7/82

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 21

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	82-09-02	INSP RPT (UNR)	C		0		FLARE VEVEL WELDS
	83-03-02	INSP RPT (UNR)	C	8311	0	0303	WATER USED TO COOL STAINLESS STEEL WELDS
		INSP RPT (UNR)	C	8317	0		
		INSP RPT (UNR)	C	8329	0		

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 3

PAGE 22

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50530	83-01-28	50.55E RPT	0		0	0228	50.55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
	83-04-06	50.55E PPT	0		0	0505	50.55E-APS STARTUP QC NOT QUALIFIED-DER 8320
	83-04-07	50.55E RPT	0		0	0505	50.55E-LP61 PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-07-C	50.55E PPT	C		0		50.55(E): BORG WARNER VALVE STEM EXTENSIONS-REFERENCE PREVIOUS DER 80-21-FINL RPT EXP 6/1/84