



Commonwealth Edison  
1400 Opus Place  
Downers Grove, Illinois 60515

February 10, 1992

Dr. Thomas E. Murley, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Braidwood Station, Unit 2  
Inservice Inspection Report for  
Interval 1, Period 1, Refuel Outage 2  
NRC Docket Nos. 50-457

Reference:(a) December 15, 1988, S.C. Hunsader to letter  
to T. E. Murley

Dear Dr. Murley:

Reference (a) provided the complete Braidwood Station Units 1 and 2 Inservice Inspection (ISI) program for NRC review that is currently being implemented at the station. In accordance with the requirements of this program and Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code (1983 Edition through and including the Summer, 1983 Addenda) Commonwealth Edison is submitting the report of the ISI performed at Unit 2 from May 28, 1990 through November 26, 1991. This report is required to be submitted within 90 days of the completion of a refueling outage. The Unit 2 refueling outage was completed on November 26, 1991.

Please address any questions regarding this submittal to this office.

Very truly yours,

*Terrence W. Simpkin*

T.W. Simpkin  
Nuclear Licensing Administrator

180116

cc: R.M. Pulsifer - NRR w/o attachment  
B. Clayton - RIII w/o attachment  
Braidwood Resident Inspector w/o attachment

ZNLD/968/8

9202190346 920210  
PDR ADUCK 05000457  
G PDR

AD47,1