

ENCLOSURE 1

NOTICE OF VIOLATION

Georgia Power Company
Hatch

Docket Nos. 50-321 and 50-366
License Nos. DPR-57 and NPF-5

The following violations were identified during an inspection conducted on February 21-23, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B Criterion V, requires that activities affecting quality be prescribed by documented instructions procedures or drawings and be accomplished in accordance with these instructions, procedures or drawings. Georgia Power Procedure HNP-821 requires that safety-related plant modifications be inspected to verify that the work is completed in accordance with details on the design documents.

Contrary to the above, during inspection of masonry wall modifications, quality control inspectors failed to detect that the welding used in connections of the flanges of W8 x 35 steel member was not accomplished in accordance with the details shown on the design documents.

This is a Severity Level V (Supplement I) Violation.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAR 15 1984

8406230530 840604
PDR ADOCK 05000321
Q PDR