

FEB 10 1992

Docket No. 50-334  
50-412

Mr. J. D. Sieber  
Vice President  
Nuclear Group  
Duquesne Light Company  
P.O. Box 4  
Shippingport, Pennsylvania 15077

Dear Mr. Sieber

Subject: Inspection No. 91-23

This refers to your letter dated January 21, 1992, in response to our letter dated December 24, 1991.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By

Edward C. Wenzinger, Chief  
Projects Branch No. 4  
Division of Reactor Projects

cc w/o cy of licensee ltr:  
G. S. Thomas, General Manager, Corporate Nuclear Services  
N. R. Tonet, Manager, Nuclear Safety  
T. P. Noonan, General Manager, Nuclear Operations  
K. D. Grada, Manager, Quality Service Unit

cc w/cy of licensee ltr:  
H. R. Caldwell, General Superintendent, Nuclear Operations  
K. Abraham, PAO (2)  
Public Document Room (PDR)  
Local Public Document Room (LPDR)  
Nuclear Safety Information Center (NSIC)  
NRC Resident Inspector  
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL BV 91-23 - 0001.0.0  
02/05/92

9202210009 920210  
PDR ADOCK 05000334  
G PDR

JED 1

bcc w/o cy of licensee's letter:  
Region I Docket Room (w/concurrences)  
Management Assistant, DRMA

bcc w/cy of licensee's letter:  
J. Joyner, DRSS  
W. Ruland, DRP  
E. Wenzinger, DRP  
D. Vito, SRI, Oyster Creek  
J. Shedlosky, SRI, Haddam Neck  
F. Young, SRI, Three Mile Island  
A. DeAgazio, NRR/PB 1-4  
R. Lobel, OEDO

RI:DRP  
Kaufman/gcb

02/ /92

RI:DRP  
Ruland

02/10/92  
OFFICIAL RECORD COPY

RL BV 91-23 - 0002.0.0  
02/05/92

**Duquesne Light Company**

Beaver Valley Power Station  
P.O. Box 4  
Shippingport, PA 15077-0004  
(412) 393-5255

JOHN D. SIEBER  
Vice President - Nuclear Group

January 21, 1992

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

**Subject: Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334, License No. DPR-66  
Inspection Report 50-334/91-23**

In response to NRC correspondence dated December 24, 1991 and in accordance with 10 CFR 2.201, the attached reply addresses the Notice of Violation transmitted with the referenced inspection report.

If there are any questions concerning this response, please contact Mr. K. L. Ostrowski at (412) 393-5104.


Sincerely,

*J. D. Sieber*  
J. D. Sieber

Attachment

cc: Mr. J. Beall, Sr., Resident Inspector  
Mr. T. T. Martin, NRC Region I Administrator  
Mr. E. C. Wenzinger, Chief, Projects Branch No. 4  
Division of Reactor Projects, Region I  
Mr. A. W. DeAgazio, Project Manager  
Mr. M. L. Bowling (VEPCO)

9202040464



Action Taken to Prevent Recurrence

The circumstances surrounding this violation will be reviewed with emphasis on procedure compliance and log keeping in Module 3 of Unit 1 and 2 License Retraining.

A Human Performance Enhancement System evaluation has been initiated on the event associated with this violation. Additional corrective actions may be initiated based on the evaluation. This evaluation will be complete by April 3, 1992.

The procedure step to start the main feedwater pump will be evaluated to determine if the pump should be started earlier in the heatup. This evaluation will be completed by April 3, 1992.

A precaution will be added to the start-up procedure to provide additional information concerning the shutoff head of the condensate pumps. This action will be completed by April 3, 1992.

An Operating Manual Deficiency Report has been written on Operating Manual 1.24.4.P. "Steam Generator 1A(1B)(1C) Level Low". The alarm response will be evaluated to determine if additional steps are necessary to address restoration of feedwater and isolation of blowdown.

Date of Full Compliance

The station is in full compliance at this time.

Module 3 of Unit 1 and 2 License Retraining will be completed by June 26, 1992.

The Human Performance Enhancement System Evaluation will be completed by April 3, 1992.

All procedure changes addressing this violation will be evaluated by April 3, 1992.

DUQUESNE LIGHT COMPANY  
Nuclear Group  
Beaver Valley Power Station, Unit No. 1

Reply to Notice of Violation

Combined Inspection Report 50-334/91-23 and 50-412/91-22  
Letter dated December 24, 1991

VIOLATION (Severity Level IV; Supplement I)

Description of Violation (50-334/91-23-01)

Technical Specification 6.8.1.a, requires that written procedures be established, implemented, and maintained, covering activities listed in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Contrary to the above, on November 6, 1991, operators failed to follow the procedures contained in the Operating Manual as evidenced by the following two examples.

- (1) Operating Manual 1.24.4.P, "Steam Generator 1A(1B)(1C) Level Low", Issue 2, Revision 35, required that action be taken to restore low steam generator level to normal. Operators failed to restore Steam Generator 1A Level to normal, following receipt of the low level alarm. Operators initiated steam generator blowdown, further reducing steam generator level, which resulted in automatic start of the auxiliary feed pump on low-low level.
- (2) Operating Manual 1/2.48.5.VI, "Conduct of Operation", Issue 3, Revision 4, required major equipment status changes be logged in the reactor operator log and the nuclear shift operating foreman log. The initiation of steam generator blowdown was not documented in either of the above logs.

Reason for the Violation

This violation occurred because control room operators did not maintain complete awareness of plant conditions in that they initiated blowdown flow, thus reducing steam generator level, at a steam pressure where the ability to replenish steam generator level using the condensate pumps was limited.

Failure to log initiation of blowdown flow occurred because the crew believed it was a routine evolution.

Corrective Action Taken

At the time of the event, operations personnel stabilized steam generator levels and secured the auxiliary feedwater pump.

Operations shift crews were briefed on the event during shift meetings.