APPENDIX A

NOTICE OF VIOLATION

Boston Edison Company Pilgrim Nuclear Power Station Docket No. 50-293 License No. DPR-35

As a result of the inspection conducted on April 23-27, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

A. Pilgrim Nuclear Power Station Technical Specification 6.8.A states in part: "Written procedures and administrative policies shall be established, implemented and maintained that meet or exceed the requirement and recommendations of ... Appendix "A" of USNRC Regulatory Guide 1.33". This appendix includes procedures for modification.

Station Procedure 1.5.5, "Cutting, Welding and Hot Work", requires: "Measures shall be established to contain falling slag", during welding.

Contrary to the above, on April 26, 1984, the welding activities for the rigging lugs located at elevation 41' and azimuth 180°, were conducted without establishing measures to contain falling slag.

This is a Severity Level IV violation (Supplement I) applicable to DPR-35.

Pursuant to the provisions of 10 CFR 2.201, Boston Edison Company is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8406260410 840606 PDR ADOCK 05000293 Q PDR

OFFICIAL RECORD COPY

DL50-293/84-11 - 0003.0.0 05/11/84