TENNESSEE VALLEY AUTHORITY

GHATTANOOGA. TENNESSEE 37401
400 Chestnut Street Tower, JI

June 13, 1984 AlD: 23

BLRD-50-438/81-13 BLRD-50-439/81-13

U.S. Nuclear Regulatory Commission Region II Attn: Mr. James P. O'Reilly, Regional Administrator 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - UNACCEPTABLE PIPE BREAK INTERACTIONS - BLRD-50-438/81-13, BLRD-50-439/81-13 - SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on January 27, 1981, in accordance with 10 CFR 50.55(e) as NCR BLN BLP 8003. This was followed by our interim reports dated February 24, April 27, and December 22, 1981 and May 24, and August 23, 1982, and our final report dated March 16, 1983. Below is our supplemental report.

As discussed with NRC-OIE Inspector R. Carroll on May 30, 1984, the date of June 1, 1984 for completion of corrective actions indicated in our final report on this matter would not be met. Modifications identified on ECNs 1211 and 1831 are complete, but work outlined in ECNs 1044 and 1212 concerning spray shields, drain pans, and deluge valves is ongoing. The corrective action on this matter will be completed by March 30, 1985 for unit 1 and March 30, 1987 for unit 2.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

OFFICIAL COPY.