

(2)

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

June 26, 1984

DOCKETED  
USNRC

84 JUN 29 A10:38

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

Glenn O. Bright  
Dr. James H. Carpenter  
James L. Kelley, Chairman

OFFICE OF SECRETARY  
DOCKETING & SERV.  
BRANCH

In the Matter of

CAROLINA POWER AND LIGHT CO. et al.  
(Shearon Harris Nuclear Power Plant,  
Unit 1)

Docket 50-400 OL

ASLBP No. 82-468-01  
OL

Cover Letter for Documents  
Supporting Stokes Affidavit on Eddleman 65  
(Defective Concrete)

Dear Administrative Judges:

Enclosed are copies for you and all parties of the selected sample of documents illustrating facts cited in the affidavit of Charles Stokes filed June 14 in this proceeding. By arrangement, Charles Barth of NRC Staff will receive a copy of the entire set of CP&L pour packages reviewed by Stokes. I also possess copies of the other 95% of the pour packages as copied for me by CP&L; if anyone wishes to examine them, please contact me at 919-286-3076. This letter will briefly describe the enclosures and the part(s) of the Stokes affidavit of 11 June 1984 which each relates to.

The first enclosure is from pour ICBXW290001 of 7/23/82, (Stokes affidavit pp 5-7, starting low on page 5). This includes the Ebasco concrete specification Stokes refers to on his page 6 and the related concrete strength reports.

The next is from pour LCBSL216002, Beginning with the Field Inspection Report sheet on "Accidental Burning of Waterproof Membrane" which is the Water stop referred to by Stokes on pp 9 & 10.

8406290358 840626  
05000400 PDR  
ADOCK

DS03

The third enclosure is also from ICBSL216002 in the base mat, and it shows the concrete slump in the "SLUMP (in.)" column, fifth from the left, and the slump specification as "Slump required" ( $4 \pm 1$  in.) below the ~~the~~ table. The table continues on later pages. These are the out-of-specification slumps in this pour as cited by Stokes on page 9.

The fourth enclosure includes the cover sheet of the ICBSL216-002 Concrete Placement Report. It documents the hot weather, (1st page, "Anticipated Special Weather Precautions", and reproduces pages indicating repair work not completed (not covered by Stokes) on the waterstop 7-27-78, and also the last page has the note on clearance between asbestos board and cadweld under 1/2 inch. This clearance problem is mentioned by Stokes on p.9 and is the same one he mentions on p.8 as appearing with the same "never again" language ("Future clearance to be 1/2 in minimum) on several other pours in the early going, i.e. ICBSL216001,-004 and 005).

The fifth enclosure is the concrete strength information from ICBX# 308001 of 8-29-83, a single sheet. (Stokes, p.7) Note the reference to 9% air in pretest under "remarks".

The sixth enclosure is the entire package for ICB SL 216001. It documents the slump, waterstop and vibration problems (Stokes, pp 8-9) and also the asbestos board problem, e.g. on 216004 sheet 1 of 4, Field inspection Report, and likewise 216005, sheet 1 of 3, re clearance to asbestos board. This package is as it came to me from CP&L except reproduced on front-and-back of pages to save paper, to the best of my knowledge.


The seventh enclosure is the concrete repairs report on the large void in~~m~~ pour ICBSL 216002 (Stokes, pp 9-10).

The eighth enclosure is from pour ICBXW219001 (Stokes pp 3-4) including the strength data on cylinders (last page of enclosure). Note the approvals on the next-to-last sheet in spite of the problems noted by Stokes. The comments on exposed aggregate are on the front sheet under "comment & Clarification to Proposed Methods", upper right quadrant of the sheet.

I am leaving blank space in case I have another enclosure to describe when I get this to the printers.

The ninth enclosure is from pour ICBXW 256004, showing the statements (2d page) about "a most difficult placement" and warning workers about vibration.  
(Stokes, pp. 4-5)

If there is further information I can supply, please do not hesitate to contact me, preferably on or before 29 June.

  
Wells Eddleman

Wells Eddleman

CC w/enclosures: Charles Stokes.

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

In the matter of CAROLINA POWER & LIGHT CO. Et al.  
Shearon Harris Nuclear Power Plant, Unit 1

Docket 50-400  
C.L.

CERTIFICATE OF SERVICE

I hereby certify that copies of Letter of 6-2x6-84 to Board  
with Enclosures re Concrete Pour Packages and Stokes Affidavit on E-65

HAVE been served this 26 day of June 1984, by deposit in  
the US Mail, first-class postage prepaid, upon all parties whose  
names are listed below, except those whose names are marked with  
an asterisk, for whom service was accomplished by Including  
one copy of the entire 5% sample of pour packages reviewed

by Charles Stokes.

Judges James Kelley, Glenn Bright and James Carpenter (1 copy each)  
Atomic Safety and Licensing Board  
US Nuclear Regulatory Commission  
Washington DC 20555

George F. Trowbridge (attorney for Applicants)

Shaw, Pittman, Potts & Trowbridge  
1800 M St. NW  
Washington, DC 20036

Ruthanne G. Miller  
ASLB Panel  
USNRC Washington DC 20555

\* Office of the Executive Legal Director  
Attn Dockets 50-400/401 O.L.  
USNRC  
Washington DC 20555

E Spence W. Perry  
PLA/IV FEMA- Room 840  
OWWW 500 C St SW  
Washington DC 20740

Docketing and Service Section (3x)  
Attn Dockets 50-400/401 O.L.  
Office of the Secretary  
USNRC  
Washington DC 20555

Dan Read  
CHANGE/FIP  
5707 Wavcross  
Raleigh, NC 27606

Dr. Linda W. Little  
Governor's Waste Mgt. Bd.  
513 Albemarle Bldg.  
325 N. Salisbury St.  
Raleigh, NC 27611

John Runkle  
CCNC  
307 Granville Rd  
Chapel Hill NC 27514

Bradley W. Jones  
USNRC Region II  
101 Marietta St.  
Atlanta GA 30303

Travis Payne Robert Gruber  
Edelstein & Payne Exec. Director  
Box 12607 Public Staff  
Raleigh NC 27605 Box 991  
Raleigh NC 27602

Richard Wilson, M.D.  
729 Hunter St.  
Apex NC 27502

Certified by

W.D. Eddleman

CONCRETE  
PLACEMENT  
REPORT

CP&amp;I

SHNPP

Exhibit 1

WP-05

FILE

LOCATION (INCLUDE ELEV. IF IN BLDG.)

CONTAINMENT #1 EL 290

PLACEMENT NUMBER

1CBXW290101

SCHEDULED DATE

7/23/82

TYPE PLACEMENT

ESTIMATED QUANTITY

CART. WITH C.

35 cu.

TIME UNIT (CUBE CY.)

50 cu. ft.

LEVELING CLASS I

YES NO

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

## TRANSPORTING

## PLACING

## VIBRATION

## FINISHING

## FORMED SURF.

UNFORMED SURF.  
WATER

BUGGY

 CHUTE INTERNAL STEEL TROWEL FORMS ALONE NET BURLAP

BUCKET

 TREMIE FORM WOOD FLOAT TARPS POLYETHYLENE

CONVEYOR

 DROP HAIR BRUSH INSULATION CURING COMPOUND

PUMP

 BROOM FINISH FORMS & WATER KUREZ

TRUCK

 RUBBER FLOAT NUTEC 10

SERVICE, COND.

MILD

ANTICIPATED WEATHER  
CONDITIONS: HOT

PROTECTION EXTENDED

PRIMARY MASONRY DWG. NO.  
2167-C-0631R-7RATE OF RISE  
2 1/4"DES. STRENGTH  
5.0KSIDESIGN MIX CODE  
M-172

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

EXT. WALL FLOOR A=270' TO 300' CEC  
236.8370 ZEP P.R. 25. RD

GALLONS REQUIRED

NAME, TITLE PERSON SUBMITTING ALL THE ABOVE  
BY: *Russell J. Breddone* TITLE: A.E. DATE: 7/16/82

PRE-PLACEMENT DATA BY PLACEMENT ORGANIZATION

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR			CONST. INSPECTION		QUALITY ASSURANCE	
	REF. PROC.	CRAFT SUPT.	FIELD ENG.	DATE	INSPECTOR	H.Q.C. SIGNOFF	DATE Q.A. SIGNOFF
1 CONTACT SURFACES	WP-205	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
2 FORMS	WP-22	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
3 REINFORCING STEEL	WP-11	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
4 EMBEDS				7-23	R. Breddone	7-23	7-23 10:00AM
5 MECHANICAL PIPE	WP-102	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
6 ELECTRICAL	WP-201	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
7 CADWELDS	WP-01	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
8 BOP WELDING				7-23	R. Breddone	7-23	7-23 10:00AM
9 CODE/SEISMIC WELDING						7-23	7-23 10:00AM
10 CLEAN-UP	WP-05	R. Breddone	12/10/81	7-23	R. Breddone	7-23	7-23 10:00AM
11							
12							

CONSTRUCTOR SIGNOFF (AREA SUPT.)

TIME:

C.L. SIGNOFF

TIME: 10:00AM

DATE: 7-23-82

SIGNED: *J. Breddone*

DATE: 7-23-82

DESIGN APPROVAL

TIME OF START

DATE: 7-23-82 10:30

DATE PLACED

07-23-82

YDS. CONCRETE  
DELIVEREDYDS PLACED IN  
THIS PLACEMENT

42

YARDS WASTED

CONCRETE 1 10'2"  
GROUT 1 10'2"YARDS GROUT  
DELIVERED

CONCRETE

1 10'

YARDS PLACED ELSEWHERE

CONCRETE 1 10'  
GROUT 1 10'

GROUT

1 10'

ELSEWHERE

GROUT 1 10'

ACCEPTANCE OF PLACEMENT METHODS &amp; COMPLETENESS OF ABOVE INFORMATION

NAME: *Russell J. Breddone*

TITLE: 7-23-82 C.I.

DATE: 7-23-82

REMARKS (ATTACH RELEVANT REPORTS)

+ Reinforcing shifted for access - 6 #18's 240° to 300° - Required 8 #18's R.L. 7-26-82

000566

#### .4 Number of Test Cylinders

The number of test cylinders to be made under various conditions shall be as follows:

	Min No. of Cylinders	Test Breaks				Extra
		3 Day	7 Day	28 Day		
Until final determination of each design mix for each class of concrete placed in any one day.*					—	
Each 100 cu yd or fraction thereof	14	4	4	4	2	
For each class of concrete of determined mix placed in any one day.						
Each 100 cu yd or fraction thereof (or a minimum of one set per day)	4	-	1	2	1	R4

\* This is intended to cover only those new design mixes, created by modification of determined design mixes, which have not been proven by the test lab prior to their placement. When 100 or more test cylinders for a new design mix has proven the mix to be acceptable to the Engineer, the number of test cylinders required for each 100 cu yd or fraction thereof may be reduced to a minimum of 4.

The extra cylinders will only be tested if it is necessary to substantiate 7 or 28 day test results.

#### .5 Evaluation of Strength Tests

The concrete cylinders shall be tested for compressive strength in accordance with ASTM C39. The strength level of the concrete shall be considered satisfactory if:

- a - No individual strength test results falls more than 500 psi below the required class strength at 28 days.
- b - The averages of all sets of three consecutive strength test results equal or exceed the required class strength at 28 days.

- 21 -

Ebasco S.H.  
Concrete  
Specification  
PP 21-22

Concrete Materials and Mixes  
Concrete Mixing and Transportation  
and Concrete Testing

#### 13. SAMPLING AND TESTING (Cont'd)

##### .5 (Cont'd)

Each 28 day strength test result shall be the average of two cylinders from the same sample. The variation between the two cylinders shall be not more than five (5) percent of their average. A greater variation shall require testing of the third (spare) cylinder to determine the average strength. If the third cylinder strength "variation" is also greater than five (5) percent from the average, the Owner shall determine the reason for such a wide variation in test results and rectify it.

The coefficient of variation for the tests on each mix as determined in accordance with ACI 214, shall not be greater than fifteen (15) percent. A greater variation will require a review of concrete batching, mixing and transporting facilities and procedures to assure a reduction in this coefficient to the required fifteen (15) percent or lower. Refer to ACI 214 for correlation between the coefficient of variation and the average compressive strength requirements.

#### .6 Test for Entrained Air and Consistency

Rev. 9  
7/82

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
POST PLACEMENT CHECKLIST

Exhibit 2  
TP-15

PLACEMENT NO. 108XW290001

LOCATION Conf. #1 Ext. W. Wall

PLACED 7-23-82

SURFACE AREA N/A

END OF CURE 7-30-82

CURE COMPOUND (AMOUNT) N/A

CURE/PROTECTION REQUIREMENTS Special Lining / Extended Protection 17 days moist cure

CHECKLIST	REMARKS	INITIALS
<u>FINISH</u>		
A. Steel Trowel	N/A	RAB
B. Wood Float	N/A	RAB
C. Broom	N/A	RAB
D. Hair Brush	N/A	RAB
E. Rubber Float	N/A	RAB
F. Keyways Installed	N/A	RAB
<u>FORMS</u>		
Form & Shoring Removal	Complete except for seismic gap	RAB
<u>REPAIRS</u>		
Type of Repair Required	<input checked="" type="checkbox"/> Cosmetic <input type="checkbox"/> Structural <input checked="" type="checkbox"/> Forms Still In Place in seismic gap	RAB
<u>EMBED PLATES W/SCREW-IN-STUDS</u>		
Thread Engagement	N/A	RAB
<u>SEISMIC GAP</u>		
Proper Gap Maintained	Forms still in place in gap	RAB
CURING/PROTECTION	EXTENSIONS	REMARKS
A. Water	/ N/A	Set - 7 days moist cure
B. Curing Compound	N/A	N/A
C. Ponding	N/A	N/A
D. Burlap	N/A	N/A
E. Wet Sand	N/A	N/A
F. Polyethylene	N/A	N/A
G. Temperature	/ N/A	Set - 7 days, ≥ 50°F

COMMENTS:

CONSTRUCTION INSPECTOR

Russell J. Breedlove DATE 8-16-82

CONSTRUCTION INSPECTION SUPERVISOR

Dee L. Taylor DATE 8-21-82

8-24-82    CORPORATE QUALITY ASSURANCE DEPARTMENT  
CONCRETE TEST REPORT  
(Procedure CQC-11)

CONCRETE TEST REPORT

PLACEMENT NO. 1CBXW-29000Y DATE 2-23-82

**LOCATION** South of Waste Processing

**WEATHER:** ( ) CLEAR ( ) OVERCAST ( ) RAIN ( ) OTHER —  
 ( ) HAZY ( ) FOG ( ) P. CLOUDY

DESIGN MIX // 101

FIELD INSPECTOR Rick Shulman DATE 7-23-82  
QA/QC

DESIGN STRENGTH 5000 PSF

### **LAB QA/QC INSPECTOR**

DATE 8-23-82

APP-C 1  
Rev. 1b  
2/4/82

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD CHANGE REQUEST/PERMANENT WAIVER

AP-IX-05  
Exhibit 1

-P/N -C- 37159

Page 1 of 2 10/1/82

Type of Request:

- Permanent Waiver to "use-as-is"  
 Field Change  
 See Recommended Action

- Non-ASME  
 ASME Section III Division 1  
 ASME Section III Division 2  
 Q       Non-Q

Nonconformance  No  Yes Report No. NCR-C-508

ORIGINAL

Identification of Area and Item: Low Concrete Compression Cylinder Breaker  
for placement 1CBxW290 001

Conflict/Condition

Reference Documents or Attachment

CAR-SH-CH-6 Sect. I Para. 13.5 a. Rev. 10

The only production set of cylinders cast for placement 1CBxW290 001 failed to achieve the required minimum 28 day concrete compressive strength of 5000 psi. This placement is located on the containment exterior wall from azimuth 240° to azimuth 300° between elevations 286.33' to el. 289.83'. The actual average 28 day cylinder strength (laboratory moist cured) for this placement was 4965 psi. See attached Concrete test report.

Recommended Action:

- Please Investigate and Resolve  
 Please Resolve as Follows

Accept the placement as-is.

RECEIVED  
DOCUMENT CONTROL

SEP 17 1983

SHEARON HARRIS N.P.P.

Justification: The reserve "D" cylinder was retained and continually moist cured in the laboratory for a total of 90 days. At this time the cylinder was compression tested and found to have a strength of 5660 psi. This is in excess of the 5000 psi design requirement. There is not a trend developing for low breakers in M-72 power block concrete.

Requested by:

W.C. Priden  
Discipline Engineer

12/1/82  
Date

Site Approval: CATEGORY I

Bill Shuler for INFT 12/1/82  
Senior Resident Engineer Date

RR/PW - C - 3769

Page 2 of 2

Design Organization Approval  AE  NSSS  NPED Only  Other

Telephone Resolution  Yes  No

Approved as Recommended

Design Organization Attachments  Yes  No

Rejected

Conditional Approval

This change requires the following Document(s) (Specification, Drawing, SAR, etc.)  
to be changed

Comments:

Signature	Title	Date	Signature	Title	Date
-----------	-------	------	-----------	-------	------

MINOR CHANGE, NO CP&L Harris Plant Engineering Approval  
VERIFICATION NEEDED

HPES Attachments  Yes  No

Approved as Recommended

Rejected

Conditional Approval

TEST BREAKS ARE ATTACHED.

*Bob Sloan*

7/16/83

Discipline Engineer

Date

*Ronald R. Pfeifer* 9/16/83

MHPE or PPE

Date

Site Concurrence: Recommend  Implementation

Alternate Resolution

Rejected

*N/A Per AP IX-05 Rev 28*

Senior Resident Engineer Date

Distribution:

(Original) Document Control

(Copy)

(Copy) W. O. Friedman

(Copy)

(Copy) S. R. Holmes

(Copy)

Implementation Completed as Approved?

Yes

No

Comments:

*James R. Paul*

9/21/83

Discipline Engineer

Date

Final Distribution:

(Original) File in Doc. Control

(Copy)

(Copy)

(Copy)

(Copy)

(Copy)

26  
101  
IV. 0

DOCUMENT NO. 1C BXW 29004 DATE 7-23-82

LOCATION South of Waste Processing

HOME OF PLACEMENT

7-23-82

WEATHER: ( ) CLEAR ( ) OVERCAST ( ) RAIN ( ) FOG ( ) HAZY ( ) CLOUDY

Pecuaria

1

352

PLATE 310.9 Sheet 3 of 4

Simplifying requirements for min.

DESIGN MIX / 0250-22

64

ATE 7-

8.

٢٧

AIR REQUIREMENT

LECTURE 5000 POST

DESIGN STRENGTH

ATE

16

4

PW-C-3769 sheet 4 of 4

COMPRESSIVE STRENGTH EVALUATION

PLACEMENT = 1CBXWZ90001

MIX #72, 5000 PSI

LAB #	AVERAGE 28 DAY STRENGTH, PSI	RUNNING AVERAGE OF THREE, PSI
8176	5635	5180
8381	5040	4670
[9265]	[4865]	[4790]
9323	4105	-
9397	5400	-

EVALUATION: IN ACCORDANCE WITH CAR-SH-CH-6

- ① THE 28 DAY TESTS ARE NOT 500 PSI OR MORE BELOW THE REQUIRED STRENGTH.
- ② THE RUNNING AVERAGE OF ALL GROUPS OF THREE CONSECUTIVE TEST AVERAGES ABOVE THE REQUIRED STRENGTH OF 5000 PSI.
- ③ THE 28 DAY STRENGTH IS CONSIDERED A FAILURE FOR NOT MEETING CRITERION NUMBER TWO.

H PES ATTACHMENT  
TO PW-C-3769

PAGE 1 OF 2

CAROLINA POWER & LIGHT COMPANY -  
SHEARON HARRIS NUCLEAR POWER PLANT

Date Placed 7-23-82

Placement No. ICBXW290001

## TEST RESULTS

Compression Machine C&L M-43105

**REMARKS**

LAB INSPECTOR Wendy J. West DATE 8-8-83  
QA SPECIALIST Donald D. Sugg DATE 8-8-83

H PES ATTACHMENT

TO PW-C-3769

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

PAGE 2 OF 2

Date Placed \_\_\_\_\_

Placement No. ICBXW290001

## TEST RESULTS

Compression Machine CR&LM-4310S

## REMARKS

**LAB INSPECTOR**

LAB INSPECTOR Wendy Dr. Wett

DATE 8-23-33

QA SPECIALIST

Albert C. L.

DATE 8-28-33


(2)

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

## FIELD INSPECTION REPORT

Date 7/26/78Spec. No. WP-02Location Unit No 1Inspector Randy G. GodwinElevation Containment Bldg.Shift DayPlacement No. ICBSL 216002 Weather Sunny, MildCOMMENTAccidental Burning of Waterproof Membrane

During a daily inspection of the waterproof membrane and waterstop on the Fuel Handling Building wall, the above inspector noticed an area of waterproof membrane burned by cadweld operations. The Area Superintendent and General Foreman were notified of this problem and in turn we were informed that it would be corrected.



cc: Jim Nevill  
Charles Hall  
Ken Fuller  
Jim Lothan

BROWN PRINTING, INC., RALEIGH, N.C.

INSPECTOR Randy D. Godwin  
QA REVIEW Eugene Kelly 9/21/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFINGPlacement No. ICB5L216002Sheet 1 of 2Location Unit No. 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Vinaliner Inspection using Holiday Detector From 115° to 180° Fuel Handling Wall Between Reglets and End of membrane to waterstop.	Several Holidays Detected and patched in accordance with WP-02	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: Stanley Carter  Date 6/8/78
2	Repair of Waterstop Fuel Handling Wall Top Waterstop Repaired with Sikastix Epoxy Cement	<u>None</u>	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: N/A  Date 5/24/78
3	Repair of Vinaliner Membrane Six accidental holes drilled on 204 Elevation. (0° - 270°)	<u>None</u> <u>N/A</u>	<u>None</u> <u>N/A</u>	<u>Satisfactory</u> Area patched and new concrete replaced	Randy G. Godwin  Individual Notified: Jim Lathan  Date 7/12/78
4	Repair of Waterstop Azimuth 225° ± Elevation 204 Waterstop burned during Cadweld operation.	Area was chipped out and waterstop replaced, chucked 7/14/78 P.G.B.	<u>None</u> Not Applicable	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Lathan  Date 7/14/78
5	Waterstop Butt Splices 200° ± 215° ±	<u>None</u> All Splices made in accordance with WP-12.	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: J. C. Hyatt  Date 7/21/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. 1CB5L216 002

Sheet 2 of 2

Location Unit No 1 Containment Blg

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Waterstop - Waterprooing Azimuth 180° Accidental Burning by Cadweld	<u>None</u>  Patching in progress. by Carpenters and Painters (Completed Satisfactory 7/28/78)	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: J.C. Hyatt  Date 7/28/78
2	Waterstop Alignment Inspection 151-50" to 208-1"	Two violations noted. Reported to Foreman and Corrected.	<u>None</u>  All req'd. waterstop is place. Needs to be tied down prior to Concrete Placement.	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: J.C. Hyatt  Date 8/2/78
3	Waterstop Entire Placement 151-50" to 208-1" with WP-02	<u>None</u>  All work performed is accordance with WP-02.	Final check Completed 8/15/78	<u>Satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Cathan  Date 8/15/78
4					Individual Notified:  Date
5					Individual Notified:  Date

SPK

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. ICB3L216.002

Sheet 1 of 4

Location Unit No 1 Containment Building

Drawings CAR-2167-G-0610, 0611, 0612, 0613, 0614, 0617

INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	INSPECTOR
1 Elevation 198 ft. Bottom Reinforcing North-South Bars	<u>None</u> All reg'd. bars in place.	Two bars checked out of tolerance, but checked out upon correction by field.	<u>Satisfactory</u>	Frank Collins General Foreman Individual Notified: <u>5/2/78</u> Date Randy D. Collier
2 Elevation 198 ft. Bottom Reinforcing North-South Bars East-West Bars	<u>None</u> All reg'd. bars in place.	Clearance between Asbestos board and cadweld was under <u>satisfactory</u> $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ inch min.		Frank Collins General Foreman Individual Notified: <u>5/5/78</u> Date Randy S. Collier
3 Elevation 198 ft. Bottom Reinforcing East-West Bars	<u>None</u> All reg'd. bars in place.	Five clearance and spacing violations were noted and corrected.	<u>satisfactory</u>	Frank Collins <u>Satisfactory</u> Individual Notified: <u>5/8/78</u> Date Randy S. Collier
4 Elevation 204 ft. Bottom Reinforcing Circumferential Bars	<u>None</u> All reg'd. bars in place.	Problem with Spacing Tolerance at Cadweld Joint of bars (QA Hold) Corrected AM 6/1/78	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: <u>6/6/78</u> Date Randy S. Collier
5 Elevation 201 ft. 4 Bars in Key Way between Containment and Fuel Handling Building	<u>None</u> All reg'd. bars in place.	Spacing tolerance and location out on North-South Bars. Problem corrected PM 6/4/78	<u>satisfactory</u>	Randy S. Collier Individual Notified: Frank Collins Date <u>6/6/78</u>

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CB3LZ1002

Sheet 2 of 4

Location Unit No 1 Containment Building

Drawings CAR-2167-G- 0610, 0611, 0612, 0613, 0614, 0617

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTOR
1	Elevation 204 Bottom Mat Circular Bars Radial Bars Const. Joint between 151°-50' to 180° Drug. 0618	To be checked at later date quantity Not complete 6/8/78	outside circular bars, out of tolerance in several areas. Notified <u>Foreman</u>	Satisfactory	Randy G. Godwin  Individual Notified: Stan Warmbird Date 6/8/78
2	Elevation 204 Bottom Mat Circular Bars Radial Bars Const. Joint between 151°-50' and 180° (Lower Layer of) Lower Mat	None	Several violations noted and corrected 6/12/78.	Satisfactory	Randy G. Godwin  Individual Notified: Frank Collins Date 6/12/78
3	Elevation 204 Bottom Mat Circular Bars Radial Bars Const. Joint between 151°-50' and 180° Lower Layer of Lower Mat	None	All spacing violations corrected and checked out. 6/13/78	Satisfactory	Randy G. Godwin  Individual Notified: Frank Collins -GF Date 6/13/78
4	Elevation 204 Bottom Mat Bottom Layer Circum. Bar (0° - 22°)	None	Several areas spacing out of tolerance, reported to Foreman.	Satisfactory	Randy G. Godwin  Individual Notified: Jim Elliott Date 7/12/78
5	Elevation 204 Bottom Mat Bottom Layer Circular Bars (151°-50' - 208° 10')	All reg'd. bars in place.	Several bars marked which did not meet spacing tolerances. Foreman notified and corrections in progress.	Satisfactory	Randy G. Godwin  Individual Notified: Frank Collins Date 7/19/78

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CTBSL 216002Location Unit No 1 Containment BuildingDrawings CAR-2167-G- 0610, 0611, 0612, 0613, 0614, 0617Sheet 3 of 4

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	Elevation 204 Bottom Mat Bottom Layer Radials (180° - 208° 10')	Several bars not placed as of 7/21/78 <u>Work in Progress</u>	Several areas noted. General Foreman informed	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 7/21/78
2	Elevation 204 Bottom Mat Lower & Upper Layers Circular Radials (151° 50' - 208° 10')	None All req'd bars in place.	Several areas need to be lined up and tied down. It was assured by General Foreman that this would be complete prior to concrete placement.	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 7/28/78
3	Elevation 210 #18 bars in Reactor Vessel Faces Area North-South Bars East-West Bars (151° 50' - 208° 10')	None All req'd bars in place. 1 additional cadweld needed to eliminate problem with survey stand.	Several areas noted and reported to General Foreman for corrections.	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 7/28/78
4	Elevation 216 Top Mat Bottom Layer Radials, Circulars (151° 50' - 208° 10')	Several bars left out to accommodate wall dowel installation. To be replaced after wall Dowels are set.	Areas need to be lined up and tied down. Reported to General Foreman.	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 8/2/78
5	Elevation 216 Top Mat Upper & Lower Layers Radials, Circulars (151° 50' - 208° 10')	see above (4)	Spacing tolerances are not being met. Reported to Superintendent and General Foreman. Not corrected as of 8/8/78.	satisfactory	Randy G. Godwin Individual Notified: Jim Lashka Date 8/8/78

Exhibit 1  
100-111

CAROLINA POWER & LIGHT  
SHEARON HARTIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CT5L216002

Sheet 4 of 4

Location Unit No. 1 - Containment Bldg.

Drawings CAR-2167-G- 0610, 0611, 0612, 0613, 0614, 0617

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	Elevation 216 Top Mat Radials, Circum, Wall Dowels 151-50' to 208-10'	<u>None</u> All areas checked, and corrections verified.	Several areas noted and reported to General Foreman. These were corrected.	<u>Satisfactory</u> <u>FINAL CHECK</u> <u>8/18/78</u>	Randy G Corwin Individual Notified: Frank Calfee Date <u>8/18/78</u>
2					Individual Notified: Date
3					Individual Notified: Date
4					Individual Notified: Date
5					Individual Notified: Date <i>SPK</i>

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. 1C05L216003Sheet 1 of 12Location Unit No. 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Repair of Waterstop</u> ① Azimuth $270^{\circ} \pm$ ② Azimuth $320^{\circ} \pm$ Elevation $204^{\circ}$ Waterstop burned during cadweld operation.	Areas are to be chipped out and waterstop replaced by patching.  <u>Work Not completed</u> 7/19/78			Randy G. Godwin  Individual Notified: Jim Lathan  Date 7/19/78
2	<u>Waterstop</u> Butt Splices <del>325</del> <del>245</del> $\pm$ <del>340</del> $\pm$ <del>275</del> $\pm$	<u>None</u> All splices made in accordance with WP-12.	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: J. C. Hyatt  Date 7/21/78
3	<u>Waterstop</u> Alignment Inspection $270^{\circ} - 320^{\circ}$	one area burned by cadwelding. Reported to Superintendent and corrected.	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: J. C. Hyatt  Date 8/2/78
4	<u>Waterstop</u> $244^{\circ} \text{ ENE}$ Accidental burning by cadweld operation. $280^{\circ} \pm$	Area corrected on 8/8/78.		<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Lathan  Date 8/8/78
5	<u>Waterstop</u> Entire Placement $270^{\circ} - 303^{\circ}$	<u>None</u> All work performed in accordance with WP-02.	Final check completed 8/15/78	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Lathan  Date 8/15/78

SPH

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CB5L 211,005

Location Unit No. 1 Containment Building

Drawings CAR-21167-0-0610 0611 0612 0613 0614 0617

Sheet 1 of 3

INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTOR
Elevation 198 ft. Bottom Reinforcing 1 North - South Bars	<u>None</u> All req'd. bars in place.	Two bars checked out of tolerance but checked out upon correction by field.	<u>satisfactory</u>	Frank Collin General Foreman Individual Notified: Date 5/2/78 Randy G. Godwin
Elevation 198 ft. Bottom Reinforcing 2 North - South Bars East - West Bars	<u>None</u> All req'd. bars in place.	Clearance between asbestos board and cadweld was under $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ inch min.	<u>satisfactory</u>	Frank Collin General Foreman Individual Notified: Date 5/5/78 Randy G. Godwin
Elevation 198 ft. Bottom Reinf. North - South Bars 3 East - West Bars (Reactor Vessel) Recess Area	<u>None</u> All req'd. bars in place	A final re-bar inspection was made and all violations corrected.	<u>satisfactory</u>	Frank Collin General Foreman Individual Notified: Date 6/6/78 Randy G. Godwin
Elevation 204 ft. Bottom Reinforcing Circular Bars Lower Layer of Lower Mat $270^\circ$ - $360^\circ$	<u>None</u> All req'd. bars in place	Several violations noted and foreman notified.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Date 6/15/78 Wardrobe
Elevation 201° Shear Key - U Bars 5 $(305^\circ$ - $270^\circ$ )	<u>None</u> All req'd. bars in place.	Bars not completely tied down. Awaiting circular and radial bar installation.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Date 7/6/78 ETK

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CB5L 216003Location Unit No 1 Containment BuildingDrawings CAR-2167-G- 0610, 0611, 0612, 0613, 0614, 0617Sheet 2 of 3

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	Elevation 204 Bottom Mat Bottom Layer Circular Bars (270° - 0°)	<u>None</u> All req'd bars in place.	Several bars marked which did not meet spacing tolerances. Foreman notified and corrections in progress.	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Frank Collins Date 7/19/78
2	Elevation 204 Bottom Mat Bottom Layer Radials (270° - 330°)	Several bars not placed as of 7/21/78 <u>Work in Progress</u>	Several areas noted. General Foreman informed.	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Frank Collins Date 7/21/78
3	ELEVATION 204 Bottom Mat Reinforcing around Valve Chambers at Azimuths 315°	<u>None</u> All req'd bars in place.	Several bars violate spacing tolerances. General Foreman was notified.	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Frank Collins Date 7/26/78
4	Elevation 204 Bottom Mat Lower & Upper Layers Circum & Radials (270° - 360°)	<u>None</u> All req'd bars in place.	Several areas need to be lined up and tied down. I was assured by General Foreman that this would be complete prior to concrete placement	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Frank Collins Date 7/25/78
5	Elevation 210 #10 bars in Reactor Vessel Rebar Area North - South Bars East - West Bars (270° - 360°)	<u>None</u> All req'd. bars in place. I additional cadweld needed to eliminate problem with Survey Stand.	Several areas noted and reported to General Foreman for corrections.	<u>satisfactory</u>  SFH Date 7/28/78	Randy G. Godwin  Individual Notified: Frank Collins Date 7/28/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. ICB5L 216003Sheet 3 of 3Location Unit No. 1 Containment Bldg.Drawings CAR-2167-G- 0610, 0611 0612 0613 0614 0617

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Elevation 216</u> Top Mat Upper 3 Lower Layers Radials & Circulars (27° - 303°)	Some bars left out to accommodate wall Dowel installation.	Spacing tolerance are not being met. Reported to Superintendent and General Foreman. Not corrected as of 8/8/78	satisfactory	Randy G. Godwin Individual Notified: Tim Cather Date 8/8/78
2	<u>Elevation 216</u> Cylinder Wall Dowels All Rows 27° - 303°	<u>None</u> All bars in place.	Some spacing violations noted. Reported to General Foreman 8/15/78	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 8/15/78
3	<u>Elevation 216</u> Shear Truss Bars 27° - 303°	Several bars found to be left out because of support steel. Replaced	<u>None</u> All spacing meets tolerance.	satisfactory	Randy G. Godwin Individual Notified: JIM Elliott Date 8/15/78
4	<u>Elevation 216</u> Top Mat Radials, Circum. & Wall Dowels 27° - 303°	<u>None</u> All areas checked and corrective verified.	Several areas noted and reported to General Foreman. These were corrected. <u>FINAL CHECK</u> 8/18/78	satisfactory	Randy G. Godwin Individual Notified: Frank Collins Date 8/18/78
5					Individual Notified: Date 8/18/78

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. 1CB5L216006Sheet 1 of 2Location Unit No. 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Waterstop</u> <u>Butt Splices</u> $215^\circ \pm$ $270^\circ \pm$	<u>None</u> All splices made in accordance with WP-12.	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin Individual Notified: J.C. Hyatt Date 7/21/78
2	<u>Waterstop</u> <u>Alignment inspection</u> $270^\circ - 320^\circ$ $208-11^\circ - 270^\circ$	One area rejected because of minimum 18-inch splice being performed. Reported to General Foreman and Superintendent and corrected.		<u>satisfactory</u>	Randy G. Godwin Individual Notified: Jim Lathan Date 8/2/78
3	<u>Waterstop</u> Elev. 204 <u>Accidental burning by Cadweld operations</u> $250^\circ \pm$	Area corrected on 8/8/78		<u>satisfactory</u>	Randy G. Godwin Individual Notified: Jim Lathan Date 8/8/78
4	<u>Waterstop</u> Entire Placement $208-10^\circ - 270^\circ$	<u>None</u> All worked performed in accordance with WP-02.	Final check completed 8/15/78	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Jim Lathan Date 8/15/78
5					SGH Individual Notified: Date

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CB5L 216006

Sheet 1 of 3

Location Unit No. 1 Containment Building

Drawings CAR-2167-G-0610 0611 0612 0613 0614 0617

No.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	Elevation 198 ft. Bottom Reinforcing North-South Bars	<u>None</u> All req'd. bars in place.	Two bars checked out of tolerance, but checked out upon correction by field.	<u>Satisfactory</u>	Frank Collins General Foreman Individual Notified: <u>5/2/78</u> Randy G. Godwin
2	Elevation 198 ft. Bottom Reinforcing North-South Bars East-West Bars	<u>None</u> All req'd. bars in place.	Clearance between Asbestos board and cadweld was under $\frac{1}{2}$ ". Discussed with <u>satisfactory</u> Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ " min.	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: <u>5/5/78</u> Randy G. Godwin
3	Elevation 198 ft. Bottom Reinf. North-South Bars East-West Bars (Reactor Vessel) Recess Area	<u>None</u> All req'd. bars in place.	A final re-bar inspection was made and all violations corrected.	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: <u>6/6/78</u> Randy G. Godwin
4	Elevation 204 Ft. Bottom Reinforcing Circular Bars Lower Layer of Lower Mat $250^\circ - 310^\circ$	<u>None</u> All req'd. bars in place.	Several violations noted and Foreman notified	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Stan Wamboldt Date <u>6/15/78</u>
5	Elevation 201 Shear Key - U Bars $(270^\circ - 191^\circ)$	<u>None</u> All req'd. bars in place.	Bars not completely tied down. Awaiting circular and radial bar installation.	<u>satisfactory</u> EPK	Randy G. Godwin Individual Notified: Jim Elliot Date <u>7/6/78</u>

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CB5L 216 006

Location Unit No. 1 Containment Building

Drawings CAR-2167-G- 0610, 0611, 0612, 0613, 0614, 0617

Sheet 2 of 3

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Elevation 204</u> Bottom Mat Bottom Layer Circular Bars (208°10' - 270°)	<u>None</u> All Reg'd. bars in place.	Several bars marked which did not meet spacing tolerances. Foreman notified and corrections in progress.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 7/17/78
2	<u>Elevation 204</u> Bottom Mat Bottom Layer Radials (208°10' - 270°)	Several bars not placed as of 7/21/78. <u>Work in Progress</u>	Several areas noted. General Foreman informed.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date
3	<u>Elevation 204</u> Bottom Mat Reinforcing around Vehic Chambers at Azimuth 225°	<u>None</u> All Reg'd. bars in place.	Several bars violate spacing tolerance. General Foreman was notified.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 7/26/78
4	<u>Elevation 204</u> Bottom Mat Lower & Upper Layers Circum's Radials (208°10' - 270°)	<u>None</u> All reg'd bars in place.	Several areas need to be lined up and tied down. I was assured by General Foreman that this would be complete prior to concrete placement.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 7/23/78
5	<u>Elevation 210</u> #18 bars in Reactor Vessel Recess Area North-South Bars East-West Bars (208°10' - 270°)	<u>None</u> All Reg'd. bar in place. Additional #18 Cadweld needed to eliminate problem with survey stand.	Several areas noted and reported to General Foreman for corrections.	<u>satisfactory</u>  EKF	Randy G. Godwin Individual Notified: Frank Collins Date 7/28/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1 CTB5L 216 006

Sheet 3 of 3

Location Unit No. 1 Containment Building

Drawings CAR-2167-G-0610, 0611, 0612, 0613, 0614, 0617

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	Elevation 216 Top Mat layers Upper / Lower Mat Radials & Circulars (208'-10" - 270")	Some bars left out spacing tolerance to accommodate wall Dowel installations.	are not being met. Reported to Superintendent and General Foreman. Not corrected as of 8/8/78	satisfactory	Randy G Godwin Individual Notified: Jim Lath Date 8/8/78
2	Elevation 216 Shear Truss Bars 208'-10" - 270"	Several bars found to be left out because of support steel Replaced 8/15/78	None All spacing meets tolerance.	satisfactory	Randy G Godwin Individual Notified: Jim Elliott Date 8/15/78
3	Elevation 216 Cylinder Wall Dowels All Rows 208'-10" - 270"	Several bars found None All bars in place.	Some spacing violations noted. Reported to General Foreman 8/15/78	satisfactory	Randy G Godwin Individual Notified: Frank Collins Date 8/15/78
4	Elevation 216 Top Mat Radials, Circum, & Wall Dowels 208'-10" to 270"	None All areas checked and corrections verified	Several areas noted and reported to General Foreman. There were corrected. <u>FINAL CHECK</u> 8/17/78	satisfactory	Randy G Godwin Individual Notified: Frank Collins Date 8/18/78
5					Individual Notified: Date 8/22/78

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
POST PLACEMENT CHECKLIST

TP-15  
Exhibit 3

PLACEMENT NO. ICBSL216 002

LOCATION Unit # 1

Containment Building

CHECKLIST	REMARKS	INITIALS
Defects Repaired (OA notified)	(Being Patched) Large Cavity at most north V.C.	TGG
Anchor Holes Grouted	Satisfactory	TGG
<u>CURING</u>		
A. Water	✓ Satisfactory	TGG
B. Curing Compound		
C. Ponding	✓ Satisfactory	TGG
D. Burlap (Wet)	✓ Satisfactory	TGG
E. Wet Sand		
F. Polyethylene		
G. Temperature	✓ Satisfactory	TGG
<u>FINISH</u>		
A. Steel Trowel		
B. Wood Float (Bull)	✓ Satisfactory	TGG
C. Broom		
D. Hair Brush		
E. Rubber Float		
Exposed Aggregate	Satisfactory	TGG

QC INSPECTOR

Randy S. Edwars DATE 9/18/78

PRINCIPAL SITE CIVIL ENGINEER

Franklin S.R.

DATE

9/18/78

THE CLOTHES LINE  
BY MARY HARRIS WELCH

101 - 9

(2) DATE 8/17/72 (Procedure C.P.-1)  
 LAB AT H.O.T. H / Convenience Bldg. (pump discharge)  
 ATM (H.O.T.) : (✓) CLOUDY ( ) OVERCAST ( ) RAIN  
 ( ) HAZY ( ) FOG ( ) P. CLOUDY  
 AMBIENT TEMP. 78 °F  
 THERMOMETER H.O. 75.506

THE JOURNAL OF CLIMATE

Ergonomics in Design 11

卷之三

THE EAST ASIAN ECONOMY

constant 2.16 — — —  
(pump discharge)

( ) P. Cloudy ( ) P. Partly Cloudy

ASBESTOS FIBR.  $\frac{1}{6}$  o<sub>p</sub>  
THERMOMETER.  $\frac{1}{6}$  o<sub>diss</sub>

卷之三

**W. T. DODGE & COMPANY**, CINCINNATI, OHIO, MANUFACTURERS OF LIGHT COTTON AND COTTON CLOTHS.

THE AMERICAN HERITAGE® HOMOLOGUE

CHIROPRACTIC THERAPY

卷之三

Procedure. (See § 110)

卷之三

113

Chancery D. 55 1986

EINHEIT

OVERCAST       RAIN       OTHER  
 FOG       HAIL       CLOUDY

AMBIENT TEMP. 74 °F.

TEST NO.	TEST	ITEM	INDIVIDUAL		CONC. (%)	TEMP. (°F)	THERM. NO.	AIR METER NO. (#)	UNIT WT.	UNIT WT.	WATER ADDED
			BUCKET NO.	BUCKET NO.							
21	3.2	API	225	416	24.6	74	24	24	0	0	0
22	3.2	API	227	417	24.6	74	24	24	0	0	0
23	3.2	API	228	418	24.6	74	24	24	0	0	0
24	3.2	API	229	419	24.6	74	24	24	0	0	0
25	3.2	API	230	420	24.6	74	24	24	0	0	0
26	3.2	API	231	421	24.6	74	24	24	0	0	0
27	3.2	API	232	422	24.6	74	24	24	0	0	0
28	3.2	API	233	423	24.6	74	24	24	0	0	0
29	3.2	API	234	424	24.6	74	24	24	0	0	0
30	3.2	API	235	425	24.6	74	24	24	0	0	0
31	3.2	API	236	426	24.6	74	24	24	0	0	0
32	3.2	API	237	427	24.6	74	24	24	0	0	0
33	3.2	API	238	428	24.6	74	24	24	0	0	0
34	3.2	API	239	429	24.6	74	24	24	0	0	0
35	3.2	API	240	430	24.6	74	24	24	0	0	0
36	3.2	API	241	431	24.6	74	24	24	0	0	0
37	3.2	API	242	432	24.6	74	24	24	0	0	0
38	3.2	API	243	433	24.6	74	24	24	0	0	0
39	3.2	API	244	434	24.6	74	24	24	0	0	0
40	3.2	API	245	435	24.6	74	24	24	0	0	0
41	3.2	API	246	436	24.6	74	24	24	0	0	0
42	3.2	API	247	437	24.6	74	24	24	0	0	0
43	3.2	API	248	438	24.6	74	24	24	0	0	0
44	3.2	API	249	439	24.6	74	24	24	0	0	0
45	3.2	API	250	440	24.6	74	24	24	0	0	0
46	3.2	API	251	441	24.6	74	24	24	0	0	0
47	3.2	API	252	442	24.6	74	24	24	0	0	0
48	3.2	API	253	443	24.6	74	24	24	0	0	0
49	3.2	API	254	444	24.6	74	24	24	0	0	0
50	3.2	API	255	445	24.6	74	24	24	0	0	0
51	3.2	API	256	446	24.6	74	24	24	0	0	0
52	3.2	API	257	447	24.6	74	24	24	0	0	0
53	3.2	API	258	448	24.6	74	24	24	0	0	0
54	3.2	API	259	449	24.6	74	24	24	0	0	0
55	3.2	API	260	450	24.6	74	24	24	0	0	0
56	3.2	API	261	451	24.6	74	24	24	0	0	0
57	3.2	API	262	452	24.6	74	24	24	0	0	0
58	3.2	API	263	453	24.6	74	24	24	0	0	0
59	3.2	API	264	454	24.6	74	24	24	0	0	0
60	3.2	API	265	455	24.6	74	24	24	0	0	0
61	3.2	API	266	456	24.6	74	24	24	0	0	0
62	3.2	API	267	457	24.6	74	24	24	0	0	0
63	3.2	API	268	458	24.6	74	24	24	0	0	0
64	3.2	API	269	459	24.6	74	24	24	0	0	0
65	3.2	API	270	460	24.6	74	24	24	0	0	0
66	3.2	API	271	461	24.6	74	24	24	0	0	0
67	3.2	API	272	462	24.6	74	24	24	0	0	0
68	3.2	API	273	463	24.6	74	24	24	0	0	0
69	3.2	API	274	464	24.6	74	24	24	0	0	0
70	3.2	API	275	465	24.6	74	24	24	0	0	0
71	3.2	API	276	466	24.6	74	24	24	0	0	0
72	3.2	API	277	467	24.6	74	24	24	0	0	0
73	3.2	API	278	468	24.6	74	24	24	0	0	0
74	3.2	API	279	469	24.6	74	24	24	0	0	0
75	3.2	API	280	470	24.6	74	24	24	0	0	0
76	3.2	API	281	471	24.6	74	24	24	0	0	0
77	3.2	API	282	472	24.6	74	24	24	0	0	0
78	3.2	API	283	473	24.6	74	24	24	0	0	0
79	3.2	API	284	474	24.6	74	24	24	0	0	0
80	3.2	API	285	475	24.6	74	24	24	0	0	0
81	3.2	API	286	476	24.6	74	24	24	0	0	0
82	3.2	API	287	477	24.6	74	24	24	0	0	0
83	3.2	API	288	478	24.6	74	24	24	0	0	0
84	3.2	API	289	479	24.6	74	24	24	0	0	0
85	3.2	API	290	480	24.6	74	24	24	0	0	0
86	3.2	API	291	481	24.6	74	24	24	0	0	0
87	3.2	API	292	482	24.6	74	24	24	0	0	0
88	3.2	API	293	483	24.6	74	24	24	0	0	0
89	3.2	API	294	484	24.6	74	24	24	0	0	0
90	3.2	API	295	485	24.6	74	24	24	0	0	0
91	3.2	API	296	486	24.6	74	24	24	0	0	0
92	3.2	API	297	487	24.6	74	24	24	0	0	0
93	3.2	API	298	488	24.6	74	24	24	0	0	0
94	3.2	API	299	489	24.6	74	24	24	0	0	0
95	3.2	API	300	490	24.6	74	24	24	0	0	0
96	3.2	API	301	491	24.6	74	24	24	0	0	0
97	3.2	API	302	492	24.6	74	24	24	0	0	0
98	3.2	API	303	493	24.6	74	24	24	0	0	0
99	3.2	API	304	494	24.6	74	24	24	0	0	0
100	3.2	API	305	495	24.6	74	24	24	0	0	0
101	3.2	API	306	496	24.6	74	24	24	0	0	0
102	3.2	API	307	497	24.6	74	24	24	0	0	0
103	3.2	API	308	498	24.6	74	24	24	0	0	0
104	3.2	API	309	499	24.6	74	24	24	0	0	0
105	3.2	API	310	500	24.6	74	24	24	0	0	0
106	3.2	API	311	501	24.6	74	24	24	0	0	0
107	3.2	API	312	502	24.6	74	24	24	0	0	0
108	3.2	API	313	503	24.6	74	24	24	0	0	0
109	3.2	API	314	504	24.6	74	24	24	0	0	0
110	3.2	API	315	505	24.6	74	24	24	0	0	0
111	3.2	API	316	506	24.6	74	24	24	0	0	0
112	3.2	API	317	507	24.6	74	24	24	0	0	0
113	3.2	API	318	508	24.6	74	24	24	0	0	0
114	3.2	API	319	509	24.6	74	24	24	0	0	0
115	3.2	API	320	510	24.6	74	24	24	0	0	0
116	3.2	API	321	511	24.6	74	24	24	0	0	0
117	3.2	API	322	512	24.6	74	24	24	0	0	0
118	3.2	API	323	513	24.6	74	24	24	0	0	0
119	3.2	API	324	514	24.6	74	24	24	0	0	0
120	3.2	API	325	515	24.6	74	24	24	0	0	0
121	3.2	API	326	516	24.6	74	24	24	0	0	0
122	3.2	API	327	517	24.6	74	24	24	0	0	0
123	3.2	API	328	518	24.6	74	24	24	0	0	0
124	3.2	API	329	519	24.6	74	24	24	0	0	0
125	3.2	API	330	520	24.6	74	24	24	0	0	0
126	3.2	API	331	521	24.6	74	24	24	0	0	0
127	3.2	API	332	522	24.6	74	24	24	0	0	0
128	3.2	API	333	523	24.6	74	24	24	0	0	0
129	3.2	API	334	524	24.6	74	24	24	0	0	0
130	3.2	API	335	525	24.6	74	24	24	0	0	0
131	3.2	API	336	526	24.6	74	24	24	0	0	0
132	3.2	API	337	527	24.6	74	24	24	0	0	0
133	3.2	API	338	528	24.6	74	24	24	0	0	0
134	3.2	API	339	529	24.6	74	24	24	0	0	0
135	3.2	API	340	530	24.6	74	24	24	0	0	0
136	3.2	API	341	531	24.6	74	24	24	0	0	0
137	3.2	API	342	532	24.6	74	24	24	0	0	0
138	3.2	API	343	533	24.6	74	24	24	0	0	0
139	3.2	API	344	534	24.6	74	24	24	0	0	0
140	3.2	API	345	535	24.6	74	24	24	0	0	0
141	3.2	API	346	536	24.6	74	24	24	0	0	0
142	3.2	API	347	537	24.6	74	24	24	0	0	0
143	3.2	API	348	538	24.6	74	24	24	0	0	0
144	3.2	API	349	539	24.6	74	24	24	0	0	0
145	3.2	API	350	540	24.6	74	24	24	0	0	0
146	3.2	API	351	541	24.6	74	24	24	0	0	0
147	3.2	API	352	542	24.6	74	24	24	0	0	0
148	3.2	API	353	543	24.6	74	24	24	0	0	0
149	3.2	API	354	544	24.6	74	24	24	0	0	0
150	3.2	API	355	545	24.6	74	24	24	0	0	0
151	3.2	API									

330 AVEO HARRIS HIGHTECH POKER PLANT  
CONCRETE TEST REPORT

卷之三

卷之三

1000 *Environ Biol Fish* (2006) 77:993–1000

TABLE 2

7) *university*      ( ) *university*      ( ) *overseas*, *overseas*      ( ) *rain*      ( ) *other*

AMBIENT TEMP.          °F  
THERMOMETER NO.

TIME NO.	TEST NO.	CROWN SAMPLED	THICK- NESS IN.	PICKET no.	STOKE (in.)	CONG. TEMP. (°F)	THERM. NO.	AIR METER (in.)	UNIT WT. WT.	WATER ADDED BUCKET	TEST CYLINDER			REMARKS
											7 DAY RESULTS	14 DAY RESULTS	21 DAY RESULTS	
2.2	2.1	2.1	.10	101	1 1/4	56	142.1	142.1	0	4740	6380	6010	311	1583
2.2	2.2	2.1	.10	101	1 3/8	56	142.1	142.1	0	4740	6380	6010	312	1584
2.2	2.3	2.1	.10	101	2 1/8	56	142.1	142.1	0	4670	6190	6340	313	1585
2.2	2.4	2.1	.10	101	2 1/2	56	142.1	142.1	0	4670	6190	6340	314	1586
2.2	2.5	2.1	.10	101	3 0	56	142.1	142.1	0	3610	5410	5450	315	1587
2.2	2.6	2.1	.10	101	2 1/2	54	142.1	142.1	0	4490	6050	6300	316	1588
2.2	2.7	2.1	.10	101	2 1/2	52	142.1	142.1	0	4170	6050	5660	317	1589
2.2	2.8	2.1	.10	101	2 1/2	50	142.1	142.1	0	4100	5530	5860	318	1590
2.2	2.9	2.1	.10	101	2 1/2	48	142.1	142.1	0	4100	5530	5860	319	1591

1448 R.J. de Bruin

**WATER REQUIRED** =  $\frac{1}{2} \times 2 = \frac{1}{2}$

DESIGN MIX #

LAB QC INSPECTOR Cathy Vacca Strom DATE 9-14-78

POLYGRAPH TESTIMONY

QA SPECIALIST

1948-8-10-75

1/1/78  
Rev. 1

## CONCRETE TEST REPORT

CAROLINA POWER & LIGHT COMPANY  
SHELTON HARRIS NUCLEAR POWER PLANT

## CONCRETE TEST REPORT

(Procedure CGC-1D)

TESTMENT NO. PL6052DATE 8-18-78LOCATION Site 4

(PUMP DISCHARGE)

WEATHER: ( ) CLOUDY ( ) OVERCAST ( ) RAIN ( ) OTHER  
( ) FOG ( ) P. CLOUDYPage 5 of 9AMBIENT TEMP. 62 °F  
THERMOMETER NO. 11-3507

BLOCK NO.	TEST SAMPLED	INDIVIDUAL TYPE SAMPLE	TICKET NO.	SLUMP (in.)	CONC. TEMP. (°F)	THERM. NO.	AIR METER NO.	UNIT WT.	UNIT WT. BUCKET	WATER ADDED	TEST CYLINDERS				REMARKS	
											RESULTS					
											7 DAY	DAY	DAY	DAY		
25	AM	AM	1605	3 1/2	80	1142	144.1	145.2	145.2	0	3750	5270	5270	5270	317 1589	
24	AM	AM	16050	3 3/4	80	44				0						
25	AM	AM	16052	4.0	82	20		146.0	146.0	0	4030	5410	5590	5590	318 1590	
23	AM	AM	16050	3 3/4	80	66				0						
30	AM	AM	16051	4.0	87	89		143.1	143.1	0	3820	5660	5660	5660	319 1591	
26	AM	AM	16050	2 1/2	86	42		143.2	143.2	0	4560	6240	6150	6150	320 1592	
30	AM	AM	16052	2 1/2	85	42				0						
26	AM	AM	16052	2 1/4	80	42		143.2	143.2	0	4560	6240	6150	6150	321 1592	
27	AM	AM	16051	3 1/2	86	46		144.1	144.1	0	3890	5660	5550	5550	321 1593	
29	AM	AM	16050	3 1/2	80	24				0						
28	AM	AM	16051	3 1/2	82	66		143.1	143.1	0	3680	5380	5620	5620	322 1594	
30	AM	AM	16052	3 1/2	84	66	66			0						

SLUMP REQUIRED 2 1/2 in.FIELD QC INSPECTOR Ricky Strickland DATE 8-18-78AIR REQUIRED 1 1/2 %LAB QC INSPECTOR Cathy Youngstrom DATE 9-14-78

DESIGN MIX #

DESIGN STRENGTH 4000 psiQA SPECIALIST Eugene Kelly DATE 9-19-78

**THE CROWN COLLECTOR'S QUARTERLY** is a monthly magazine of light reading, and may be had at \$1.00 per volume.

THE WOOD HARBOR MECHANICAL POWER PLANT

CONTINENTAL RECOVERY

- Procedure (part 1)

FEDERAL BUREAU OF INVESTIGATION

With the exception of the first two, all the remaining species have been described from the Malabar coast.

**AMERICAN TRIP.** — o<sub>p</sub>  
INTERVIEW WITH

Ergonomics in Design

$$\text{AIR REQUIRED} = \frac{1}{2} \frac{n}{\rho}$$

DESIGN MIX #

FIELD QC INSPECTOR *Sabey & Blackland* DATE *8-18-21*

LAB QC INSPECTOR Cotton 1/2 DATE 2-11-18

~~1945~~ 1946

DATE 9-19-27

**CONCRETE INFORMATION FORM**

P. v. 1

500 cu. yds. LIGHT CONCRETE  
500 cu. yds. BARET : MORTAR, PLASTER

CONCRETE TEST REQUEST  
(Procedure No. 1)

DATE 8/22/78  
PART 2

OUTSIDE ( ) COLD  
( ) HOT  
( ) P. Cloudy  
( ) OTHER 2/2/78

AMBIENT TEMP.  
THERMOP. PER. NO. 2/2/78

TEST NO.	TIME AM.	TEST NO.	TEST NO.	SIGHT NO.	SIGHT NO.	CONE TEMP. (°F.)	CONE TEMP. (°F.)	CONE TEMP. (°F.)	AIR METER NO.	AIR METER NO.	UNIT WT. BUCKET	UNIT WT. BUCKET	WATER ADDED	TEST CYL. INDEXES			REMARKS	
														DAY	WEEK	MONTH		
201	8:30	401	401	1/2	84	104526	5.4	104529	142.5	104529	4006	5660	5770	39	34	37	1601	
202	8:30	402	402	2 1/2	84	104526	5.5	104529	142.5	104529	4070	5460	5770	39	34	37	1602	
301	9:10	401	401	2 1/2	86	104526	5.6	104529	142.5	104529	3780	5460	5770	39	34	38	1602	
302	9:10	402	402	2 1/2	87	104526	5.5	104529	142.5	104529	3710	5460	5770	39	34	38	1602	
203	9:20	401	401	2 1/2	86	104526	5.4	104529	143.1	104529	3700	5310	5460	31	34	37	1603	
204	9:20	402	402	2 1/2	82	104526	5.3	104529	143.1	104529	3710	5460	5770	39	34	37	1603	
205	9:20	401	401	2 1/2	82	104526	5.6	104529	143.1	104529	4100	5370	5800	5455	39	34	37	1604
206	9:20	402	402	2 1/2	82	104526	5.4	104529	143.1	104529	4100	5370	5800	5455	39	34	37	1604
207	9:20	401	401	2 1/2	84	104526	5.5	104529	143.1	104529	3750	5590	5770	39	34	37	1605	
208	9:20	402	402	2 1/2	84	104526	5.6	104529	143.1	104529	3780	5620	5850	31	34	37	1606	
209	9:20	401	401	2 1/2	80	104526	5.4	104529	143.1	104529	3750	5590	5770	39	34	37	1606	

SIGHT REQUIRED — 2/2 — 1/1 — in.

AIR REQUIRED — 4/4 — 1/1 — 2 —

DESIGN MIX # 3005

DESIGN STRNGHT 2000 psi

**Bracebridge**

FIELD QC INSPECTOR

DATE 8/19/78

LAB QC INSPECTOR

DATE 9-16-78

QA SPECIALIST Elaine Kelly

DATE 9-19-78

THE WOLF HARTZ'S ONE-YEAR POSITION PAPER

CONTINUOUS FLOW

WWE 2K12 (Procedure Cap)

C 42.

卷之三

卷之三

مکالمہ

) 1(m); ( ) P. Clarity

11

AMBIENT TEMP. 71 °F  
THERMOMETER NO. 2045525

**SLIP REQUIRED** =  $\frac{1}{2} \times \frac{1}{n}$

FIELD QC INSPECTOR

Benchwork DATE 8/19/78

LAB QC INSPECTOR *Bob Wright* DATE *9-16-78*

MESES EN MIX # 117 - 57

BY SPECIALIST Lynne Steel DATE 9-15-28

C

CAROLINA POWER & LIGHT COMPANY  
SHIAH-MORI HAERIS THREE-YEAR POWER PLANT

## CONCRETE TEST REPORT

(Procedure CQC-13)

TEST NO. 356246222 DATE 8/12/78

LOCATION H-1000-1000-1000-1000

WEATHER: ( ) CLEAR ( ) OVERCAST ( ) RAIN ( ) FOG ( ) CLOUDY  
( ) DRY ( ) WET ( ) HUMIDAMBIENT TEMP. 71 °F  
THERMOMETER NO. 84526

TEST CYLINDER SIZES

RESULTS

7 DAY

28 DAY

3840

5626

5450

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

5553

SLUMP REQUIRED 4 1/2 in.

AIR REQUIRED 6 1/2 in.

DESIGN MIX # 97-56

DESIGN STRENGTH 222 psi

FIELD QC INSPECTOR

LAB QC INSPECTOR

QA SPECIALIST

FIELD QC INSPECTOR

LAB QC INSPECTOR

QA SPECIALIST

DATE 8/12/78

DATE 9-14-78

DATE 9-19-78

DATE

DATE

DATE

CONCRETE  
PLACEMENT  
REPORT

LOCATION (INCLUDE ELEV. F.M.B.G.)

PLACEMENT NUMBER

1C85L216002

10' + 1 CB Fm. West - End 1 Side

SCHEDULED DATE

TYPE PLACEMENT

ESTIMATED QUANTITY

TYPE OF CONCRETE

Struct. Mat.

4709 yds

Segment 1-4" Design Class

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

TRANSPORTING	PLACING	VIBRATION	FINISHING	FORMED SURF.	UNFORMED SURF.
BUGGY	<input type="checkbox"/> CHUTE	<input type="checkbox"/> INTERNAL	<input checked="" type="checkbox"/> HAND SCREED	<input type="checkbox"/> FORMS ALONE	<input checked="" type="checkbox"/> WATER
BUCKET	<input checked="" type="checkbox"/> TREMIE	<input checked="" type="checkbox"/> FORM	<input type="checkbox"/> BULL FLOAT	<input type="checkbox"/> TARPS	<input type="checkbox"/> WET BURLAP
CONVEYOR	<input checked="" type="checkbox"/> DROP	<input type="checkbox"/>	<input type="checkbox"/> TROWEL MACH.	<input type="checkbox"/> INSULATION	<input type="checkbox"/> VAPOR BARRIER
PUMP	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> BROOM	<input type="checkbox"/> FORMS & WATER	<input type="checkbox"/> MEMBRANE
TRUCK	<input type="checkbox"/>	* Outside exterior wall * Rubber Float	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> NUCLEAR *
		Exposed Aggregate on remainder			<input type="checkbox"/> NON-NUCLEAR

## ANTICIPATED SPECIAL WEATHER PRECAUTIONS

Hot weather

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

\*\* Outside Exterior walls only  
(See action plan for this placement)

\*\*\* Outside edge of pit only

PRIMARY MASONRY DWG. NO.

2167-G-0610 RG

SPEC. FINISH

DES. STRENGTH

4000 psi

DESIGN MIX CODE

M56

NAME/TITLE, PERSON SUBMITTING ALL THE ABOVE

BY: Ken Fuller TITLE: Area Tech DATE: 7-20-78

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR			QUALITY CONTROL		QUALITY ASSURANCE			
	REF. PROC.	CRAFT SUPT	FIELD ENG.	DATE	INSPECTOR	H	REF. PROC.	DATE	INSPECTOR
1 CONTACT SURFACES	WP-5	J.EE		8/16	TGG				
2 FORMS	WP-22	J.EE		8/16	TGG				
3 REINFORCING STEEL	WP-11	J.C.		8/16	TGG				
4 EMBEDS	WP-18	J.EE		8/16	TGG				
5 MECHANICAL	NA			8-16	NA CSH	✓	NA	8/17	R. Fletcher
6 ELECTRICAL	NA	J.P.J.		8-16	NA CSH				
7 CADWELDS	WP-1	J.EE		8-16	L.F.A		CH-15	8/17	P. Brown
8 NDE	WP-5	NA		8/16	TGG				
9 CLEANUP	WP-5	J.EE		8/16	TGG				
10 WATERSTOP	WP-12	J.EE		8/16	TGG				
11									
12									
13									
14									

CONSTRUCTOR SIGNOFF (AREA SUPT)

QC. SIGNOFF

Q.A. SIGNOFF

S-15 FOR

DATE: 8/12/78

DATE: 8/12/78

DATE: 525PM

DATE: 8/12/78

TIME OF START

TIME OF START

TIME OF START

TIME OF START

DATE: 8/11/78

DATE: 8/11/78

DATE: 8/11/78

DATE: 8/11/78

DATE PLACED

DATE PLACED

DATE PLACED

DATE PLACED

08-17-78

08-17-78

08-17-78

08-17-78

YDS. CONCRETE

YDS. NOT PLACED IN

YDS. WASTED

YDS. WASTED

DELIVERED

THIS PLACEMENT

0.0

38.2

YARDS GROUT

THIS PLACEMENT

YARDS PLACED ELSEWHERE

0.0

6 YDS. PLACED IN

6 YDS. PLACED ELSEWHERE

0.0

ACCEPTANCE OF PLACEMENT METHODS &amp; COMPLETENESS OF ABOVE INFORMATION

NAME: John L. Frank

TITLE: Construction Agent

DATE: 8/12/78

REMARKS (ATTACH RELEVANT REPORTS)

#6 bars in shear key to be installed immediately prior to placing  
\*\* Clean up to proceed from 9 AM Team prepared

100.561

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT


FIELD INSPECTION REPORT

Date 7/26/78 Spec No. WP-02  
Location Unit No 1 Inspector Randy G. Godwin  
Elevation Containment Bldg. Shift Day  
Placement No. ICBSL216002 Weather Sunny, Mild

COMMENT

Accidental Burning of Waterproof Membrane

During a daily inspection of the waterproof membrane and waterstop on the Fuel Handling Building wall, the above inspector noticed an area of waterproof membrane burned by radweld operations. The Area Superintendent and General Foreman were notified of this problem and in turn we were informed that it would be corrected.



cc: Jim Nevill  
Charles Nall  
Ken Fuller  
Jim Lathan

BURKE PRINTING, INC., RALEIGH, N.C.

INSPECTOR Randy D. Atkins  
Q A REVIEW Eugene Kelly 7/21/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFINGPlacement No. ICB5L216003Sheet 1 of 12Location Unit No. 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Repair of Waterstop ① Azimuth $270^\circ \pm$ ② Azimuth $320^\circ \pm$ Elevation $204^\circ$ Waterstop burned during cadweld operation.	Areas are to be chipped out and waterstop replaced by patching.  <u>Work Not completed</u> 7/19/78	-	Randy G. Godwin	Individual Notified: Jim Lathan Date 7/19/78
2	Waterstop Butt Splices <del>325</del> <del>-245</del> <del>340</del> <del>275</del> <del>±</del>	<u>None</u> All splices made in accordance with WP-12.	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: J.C. Hyatt Date 7/21/78
3	Waterstop Alignment Inspection $270^\circ - 320^\circ$	one area burned by cadwelding. Reported to Superintendent and corrected.	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: J.C. Hyatt Date 8/2/78
4	Waterstop $204^\circ \text{ E.W.}$ Accidental burning by cadweld operation. $280^\circ \pm$	Area corrected on 8/8/78.		<u>Satisfactory</u>	Randy G. Godwin Individual Notified: Jim Lathan Date 8/8/78
5	Waterstop Entire Placement $270^\circ - 303^\circ$	<u>None</u> All work performed in accordance with WP-02.	Final check completed 8/15/78	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: Jim Lathan Date 8/15/78

STK

CAROLINA POWER & LIGHT  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. LCBSL 211,005

Location Unit No. 1 Containment Building

Drawings CAR-2167-0- 0610 0611 0612 0613 0614 0617

Sheet 1 of 3

INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	NO INSPECTOR
1. Elevation 198 ft Bottom Reinforcing North - South Bars	<u>None</u> All req'd. bars in place.	Two bars checked out of tolerance but checked out upon correction by Field.	<u>satisfactory</u>	Frank Collier General Foreman Individual Notified: <u>5/2/78</u> Randy G. Godwin
2. Elevation 198 ft Bottom Reinforcing North - South Bars East - West Bars	<u>None</u> All req'd. bars in place.	Clearance between Asbestos board and cadweld was under <u>satisfactory</u> $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ inch min.		Frank Collier General Foreman Individual Notified: <u>5/5/78</u> Randy G. Godwin
3. Elevation 198 Ft. Bottom Reinf. North - South Bars East - West Bars (Reactor Vessel) Recess Area	<u>None</u> All req'd. bars in place	A final re-bar inspection was made and all violations corrected	<u>satisfactory</u>	Frank Collier General Foreman Individual Notified: <u>6/6/78</u> Randy G. Godwin
4. Elevation 204 Ft. Bottom Reinforcing Circular Bars Lower Layer of Lower Mat $270^\circ$ - $360^\circ$	<u>None</u> All req'd. bars in place	Several violations noted and Foreman notified <u>satisfactory</u>		Randy G. Godwin Individual Notified: Stan Warmbrod <u>6/15/78</u>
5. Elevation 201° Shear Key - U Bars ( $303^\circ$ - $377^\circ$ )	<u>None</u> All req'd. bars in place.	Bars not completely tied down. Awaiting circular and radial bar installation.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: JIM ELLIOTT <u>7/6/78</u>

PLACEMENT # 1CBXW308001  
M-80 5000 PSI

(2)

LAB NO.	AVG. 28-DAY STRENGTH	Avg. of three CONSECUTING TEST
10639	5275	5647
10654	6795	6040
10664	4870	5632
10685	6455	
10699	5570	

EVALUATION IN ACCORDANCE WITH CAR-SH-CH-6

- ① THE 28-DAY AVERAGE STRENGTH TESTS ARE NOT MORE THAN 500 PSI BELOW THE DESIGN STRENGTH OF 5000 PSI.
- ② THE AVERAGE OF ALL GROUPS OF THREE CONSECUTIVE TESTS ARE ABOVE THE DESIGN STRENGTH OF 5000 PSI.
- ③ THE 28-DAY STRENGTH TEST IS NOT CONSIDERED A FAILURE.

Guy C. 10-7-83

CAROLINA POWER & LIGHT COMPANY  
CORPORATE QUALITY ASSURANCE DEPARTMENT

## CONCRETE TEST REPORT (Procedure CC-11)

PLACEMENT NO. ICB KW 308001 DATE 8-29-83

LOCATION #/Cont. Bds

MODE OF PLACEMENT

WEATHER:  CLEAR  OVERCAST  RAIN  OTHER  
 HAZY  FOG  P. CLOUDY

SLUMP REQUIRED 0-8 IN. DESIGN MIX USED M-80

FIELD  
QA/QC INSPECTOR

LATE 5-22-83

AIR REQUIRED 1-8 %

DESIGN STRENGTH 5000 psi  
FOR PLACEMENT

FIELD  
QA/QC INSPECTOR J. Zoller DATE 5-22-83  
LAB QA/QC INSPECTOR Wendy Weller DATE 9-26-83  
QA/QC SPECIALIST Doreen L. Sarge DATE 10-4-87

CONCRETE  
PLACEMENT  
REPORT

CONCRETE PLACEMENT

CHNPP

FILE

PLACEMENT NUMBER

ICBSL216001

LOCATION (INCLUDE ELEV. &amp; IN BLDG)

SCHEDULED DATE

UNIT 1 C.B. BASE MAT - WEST SIDE

7-14-78

TYPE PLACEMENT

ESTIMATED QUANTITY

STRUCT. MAT

3020 YD<sup>3</sup>

90° ASCH. 1-4"

SECTION JOBSITE

X

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

TRANSPORTING	PLACING	VIBRATION	FINISHING	FORMED SURF.	UNFORMED SURF.	CURING
BUGGY	<input type="checkbox"/> CHUTE	<input type="checkbox"/> INTERNAL	X HAND SCREED	<input type="checkbox"/> FORMS ALONE	X WATER	<input type="checkbox"/>
BUCKET	X TREMIE	X FORM	<input type="checkbox"/> BULL FLOAT	<input type="checkbox"/> TARPS	<input type="checkbox"/> WET BURLAP	<input type="checkbox"/>
CONVEYOR	X DROP	<input type="checkbox"/>	<input type="checkbox"/> TROWEL MACH.	<input type="checkbox"/> INSULATION	<input type="checkbox"/> VAPOR BARRIER	<input checked="" type="checkbox"/> OR NUCLEAR 10' X 4' MEMBRANE
PUMP	X	<input type="checkbox"/>	* BROOM	<input type="checkbox"/> FORMS & WATER	<input type="checkbox"/>	<input type="checkbox"/> NUCLEAR *
TRUCK	<input type="checkbox"/> *OUTSIDE EXTERIOR WALL	RUBBER FLOAT X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> NON-NUCLEAR
	<input type="checkbox"/> EXPOSED AGGREGATE ON REMAINDER					

ANTICIPATED SPECIAL WEATHER PRECAUTIONS

HOT WEATHER

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

PRIMARY MASONRY DWG. NO.

CAR-2167-G-0610 R6

SPEC. FINISH

\* OUTSIDE EXTERIOR WALL ONLY

(SEE ACTIONS PLAN FOR THIS PLACEMENT)

DES. STRENGTH

4000 PSI

DESIGN MIX CODE

W44

T66

7/14/78

NAME/TITLE, PERSON SUBMITTING ALL THE A/E'S

By Charles H. Doherty

TITLE: A.E.

DATE 7/14/78

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR			QUALITY CONTROL		QUALITY ASSURANCE			
	REF. PROC	RAFT SUPT.	FIELD ENG.	DATE	INSPECTOR	H	REF. PROC	DATE	INSPECTOR
1 CONTACT SURFACES	WP-5	J.E.E.	J.E.E.	7/14/78	T66		WP-5	7-15-78	T66
2 FORMS	WP-12	J.E.E.	J.E.E.				N/A	-	A/E
3 REINFORCING STEEL	WP-11	J.C.	J.E.E.		T66		WP-11	7-15-78	T66
4 EMBEDS	NA	NA	NA		T66		N/A	-	-
5 MECHANICAL	N/A	S.G.H.	NA		NA T66 CSH		N/A	-	-
6 ELECTRICAL	NA	J.F.H.	NA		NA T66 CSH		N/A	-	-
7 CADWELDS	WP-1	J.C.	NA		T66	✓	CITIS	7/14	T. Conroy
8 NDE	NA	NA	NA	7/14/78	T66		N/A	-	-
9 CLEANUP	WP-5		NA	7/17/78	T66		WP-5	7-15	T66
10 WATERSTOP	WP-12	J.E.E.	NA	7/14/78	T66		WP-12	7-15	T66
11									
12									
13									
14									

CONSTRUCTOR SIGNOFF (AREA SUPT.)

T. H. Doherty

QC SIGNOFF

D. L. Wright

Q.A. SIGNOFF

DATE 7-14-78

DATE 7-14-78

DATE 7-15-78

DATE 7-15-78

DESIGN APPROVAL

K. J. Doherty

TIME OF START

DATE 7-15-78

DATE PLACED

07-18-78

YDS CONCRETE

DELIVERED

YDS NOT PLACED IN

THIS PLACEMENT

YARDS PLACED

YARDS PLACED ELSEWHERE

74

3070

76

62

YARDS CROUT

05

YDS PLACED IN

THIS PLACEMENT

YARDS PLACED ELSEWHERE

00

2999

YARDS PLACED ELSEWHERE

00

ACCEPTANCE OF PLACEMENT METHODS &amp; COMPLETENESS OF ABOVE INFORMATION

NAME

Tandy D. Doherty

TITLE Construction Inspector DATE 7/18/78

REMARKS (ATTACH RELEVANT REPORTS)

Hold on change until time of placement 7/17/78 7:00 AM  
Specified for Monday 7/17/78 7:00 AM  
Cleanup to continue ahead of placement 7/17/78 7:00 AM  
Nonstop

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. ICB5L 216001Location Unit No 1 Containment BuildingSheet 1 of 1

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Vinatliner Inspection using Holiday Detector From 65° to 115° Fuel Handling Wall Between Reglets and bond of membrane to waterstop.	Several Holidays Detected and patched in accordance with WP-02.	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin
2	Repair of Waterstop Fuel Handling Wall Top Waterstop Repaired with Sikastix Epoxy Cement	<u>None</u>	<u>None</u>	<u>satisfactory</u>	Individual Notified: Stanley Carter  Date 6/8/78
3	Waterstop Tie-in to existing Waterstop in Fuel Handling Bldg. Wall 0° and 180° (Top and Bottom)	<u>None</u>	<u>None</u> Butt-splice approved by FCR - 180	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: J. C. Hyatt  Date 5/24/78
4	Waterstop Fuel Handling Wall Top Layer (0° - 151 - 50°)	<u>Waterstop needs to be</u> <u>tied up to eliminate</u> <u>possibility of bending down</u> <u>when concrete is placed.</u> <u>Not completed</u>	<u>7/13/78</u>	<u>satisfactory</u> <u>Completed</u> <u>7/14/78</u> <u>3:30 PM</u>	Randy G. Godwin  Individual Notified: J. C. Hyatt  Date 7/13/78
5	Waterstop Fuel Handling Wall Top Layer Bottom Layer (0° - 151 50')	<u>None</u> All work under Item 4 above completed in accordance with specifications.	<u>Final check</u> was made prior to concrete placement 6:00 AM <u>7/17/78</u>	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Lathen  Date 7/17/78

SPK

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

INFORMATION ONLY

Placement No. ICB5L216001

Sheet 1 of

4

Location Unit No. 1 Containment Building

Drawings CAR-2167-6-0612, 0613, 0614, 0615, 0616, 0617, 0618 & 0619

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTOR
1	Elevation 198 ft. Bottom Reinforcing North - South Bars	None All req'd. bars in place	Two bars checked out of tolerance but checked out upon correction by field	Satisfactory	Frank Collins General Foreman Individual Notified: 5/2/78 Date Randy D. Galewitz
2	Elevation 198 ft. Bottom Reinforcing North - South Bars East - West Bars	None All req'd. bars in place	Clearance between Asbestos board and cadweld was under $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ in. min.	Satisfactory	Frank Collins General Foreman Individual Notified: 5/5/78 Date Randy D. Galewitz
3	Elevation 198 ft. Bottom Reinf. North - South Bars	None All req'd. bars in place.	Five spacing violations were noted and corrected.	Satisfactory	Frank Collins General Foreman Individual Notified: 5/8/78 Date Randy G. Galewitz
4	Elevation 198 ft. Bottom Reinf. North - South Bars East - West Bars (Reactor Vessel) Access Area	None All req'd. bars in place	A final re-bar inspection was made and all violations corrected	Satisfactory	Frank Collins General Foreman Individual Notified: 6/6/78 Date Randy G. Galewitz
5	Elevation 204 ft. Bottom Mat Circular Bars Radial Bars Cent. Joint between 90° and 30°-10° (Lower Layer of) Lower Mat	None All req'd. bars in place	All violations corrected and checked out	Satisfactory	Randy G. Galewitz Individual Notified: Frank Collins Date 6/14/78 6/14/78 S.E.H.

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

DO NOT USE ONLY

Placement No. ICBSL 216001

Sheet 2 of 4

Location Unit No 1 Containment Building

Drawings CAR-2167-G-0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Elevation 207</u> Bottom Mat Circular Bars Radial Bars Const. Joint between 90° - 30° - 10° (Top Layer of) Lower Mat	<u>None</u> All req'd. bars in place.	All violations corrected and checked out 6/20/78	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 6/20/78
2	<u>Elevation 201</u> <u>SHEAR KEY</u> U Bars Between 90° - 30° - 10°	<u>None</u> All req'd. bars in place.	Bars checked. Will have to be moved around several times to accommodate wall Dowel installation. To be rechecked prior to concrete placement.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 6/22/78
3	<u>Elevation 216</u> Top Mat Bottom Layer Radial Bars 90° - 30° - 10°	<u>None</u> All req'd. bars in place.	All bars met tolerance. By using plumb bob able to see several bars not plumb with bottom Mat. Informed Foreman and General Foreman.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 6/22/78
4	<u>Elevation 216</u> Top Mat Upper Layer Circular and Radial Bars 90° - 30° - 10°	<u>None</u> All req'd. bars in place.	Several areas need to be plumbed and tied down. Foreman was informed and stated that this would be done prior to wall Dowel installation.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Stan Warming Date 6/29/78
5	<u>Elevation 204</u> <u>SHEAR TRUSS</u> BARS	Not Complete as of 7/5/78	-	Work in progress	Randy G. Godwin Individual Notified: - Date 7/5/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

CONFIDENTIAL INFORMATION ONLY

Placement No. ICB5L216001

Location Unit No 1 Containment Building

Drawings CAP-2167-0- 0612, CG13, 0614, 0615, 0616, 0617, 0618 & 0619

Sheet 3 of 4

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTOR
1	<u>Elevation 216</u> <u>Cylinder Wall</u> Dowels - 1 <sup>st</sup> R.w. (90° = 30°-10°)	<u>None</u> All req'd. bars in place.	Numerous bars out of tolerance as far as spacing. Quality was unsatisfactory. Superintendent and General Foreman notified. Both agreed that tolerances would be met and quality re-established.	Randy G. Godwin	Individual Notified: FRANK COLLINS J M Lathen Date 7/6/78
2	<u>Elevation 216</u> <u>Cylinder Wall</u> Dowels - 2 <sup>nd</sup> R.w. 3 <sup>rd</sup> R.w., 5 <sup>th</sup> R.w. (30°-10° - 151-50°)	<u>None</u> Areas complete, <u>No violations</u> , Work not complete as of 7/11/78.	several violations noted and reported to General Foreman	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: FRANK COLLINS Date 7/11/78
3	<u>Elevation 204</u> <u>Shear Truss Bars</u>	Not complete as of 7/12/78	Several bars left out need to be corrected	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: FRANK COLLINS Date 7/12/78
4	<u>Elevation 216</u> <u>Cylinder Wall</u> Dowels, all Rows including Vertical and Horizontal Bars.	<u>None</u> All req'd. bars in place.	several areas flagged for spacing violations. General Foreman was notified Not corrected	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: FRANK COLLINS Date 7/13/78
5	<u>Elevation 216</u> <u>Shear Truss</u> <u>Bars</u> 21 quantity bars and 6 bars in key way.	<u>None</u> All req'd bars in place. (Reference Item 3)	All areas corrected	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: FRANK COLLINS Date 7/13/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CTB5L 216 001

Location Unit No. 1 Containment Building

Drawings CAR-2167-G- 0612, 0613, 0614, 0615, 0616, 0617, 0618, & 0619

Show 4 of 4

ITEM	INSPECTION LOCATION	QUANTITY VIOLATIONS	STAGING VIOLATIONS	QUALITY	PC INSPECTOR
1	<u>Elevation 198</u> <u>Reactor Vessel Recess</u>	<u>None</u>	Tolerances need to be met between bars and slope wall in several areas.	<u>Satisfactory</u>	Randy G Godwin
1	<u>Vertical Bars adjacent to slope Wall</u>	All req'd bars in place.	Not completed 7/13/78 4:00 PM	-	Individual Notified: Frank Collins Date 7/13/78
2	<u>Elevation 216</u> <u>Bottom Mat</u> <u>Top Mat</u> <u>Upper 3 lower layers</u> <u>Radial and Circular Bars</u>	<u>None</u> All req'd bars in place.	Several bars had to be moved to accommodate concrete placement. Top To be corrected prior to tipping out of concrete.	<u>Satisfactory</u>	Randy G Godwin Individual Notified: Frank Collins Date 7/13/78
	<u>FINAL CHECK</u>				
3	<u>Elevation 216</u> <u>Shear Keys at Radius 44'-9"</u> <u>Steel - see Detail "Z" - Dug</u> <u>2167-G-0613</u>	<u>None</u> All bars in place in 7 keys located in placement.	All errors noted in work.	<u>Satisfactory</u> N/A	Randy G Godwin Individual Notified: Date 7/13/78
4	<u>Elevation 216</u> <u>Reinf. around Bulkhead at Reactor Vessel Recess.</u> <u>3 #18 @ 12"</u>	<u>None</u> All bars in place.	Area correctly installed.	<u>Satisfactory</u> N/A	Randy G Godwin Individual Notified: Date 7/13/78
5	<u>Elevation 204 ft. 216</u> <u>Final visual inspection made on entire placement.</u> <u>(0° - 151 51')</u>	<u>None</u> All req'd bars in place. All work performed in accordance with WP-11.	All areas which were flagged have been corrected. 6:00 AM 7/12/78	<u>Satisfactory</u> ERK	Randy G Godwin Individual Notified: Frank Collins Date 7/12/78

CAROLINA POWER & LIGHT FOR INFORMATION ONLY  
 SHEARON HARRIS NUCLEAR POWER PLANT  
 FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. 1CTB-L216 Out

Sheet 1 of

1

Location Unit No. 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Vinaliner Inspection using Holiday Detector  From 65° to 115° Fuel Handling Wall Between Reglets and bond of Membrane to waterstop.	Several Holidays Detected and patched in accordance with WP-02.	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Stanley Carter  Date 6/5/78
2	Repair of Waterstop  Fuel Handling Wall Top Waterstop Repaired with Si-Kastfix Epoxy Cement	<u>None</u>	<u>None</u>	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: N/A  Date 5/24/78
3	Accidental Burning of Waterstop  Location ± 100° concr. Joint  Area to be cut out and patched.	  Not corrected as of Pn 6/21/78.  Area not as bad as anticipated. Corrected	  7/6/78	  —	Randy G. Godwin  Individual Notified: Jim Lathan  Date 6/21/78
4	Waterstop  Fuel Handling Wall Top Layer (90° - 151'-50")	Waterstop needs to be tied up to eliminate possibility of bending down when concrete is placed.	  <u>satisfactory</u> Complete 7/14/78		Randy G. Godwin  Individual Notified: J.C. Hyatt  Date 7/13/78
5	Waterstop  Fuel Handling Wall Top Layer Bottom Layer (90° - 151'-50")	<u>None</u>  All work under Item 4 above completed in accordance with specification	<u>Final check</u> was made prior to concrete placement. 6:00 AM 7/17/78	<u>satisfactory</u>	Randy G. Godwin  Individual Notified: Jim Lathan  Date 7/17/78

EFK

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. ICB5L216004

*NO. 1*  
*CONT.*  
*CONT.*

Location Unit No. 1 Containment Building

Sheet 1 of 4

Drawings CAR-2167-6- 0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

INSPECTION LOCATION	QUANTITY VIOLATIONS	STRUCTURE VIOLATIONS	QUALITY	QC INSPECTOR
1. Elevation 198 ft. Bottom Reinforcing North - South Bars	<u>None</u> All req'd. bars in place.	Two bars checked out of tolerance, but checked out upon correction by field.	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: 5/2/78 Date: 8. Randy G. Godwin
2. Elevation 198 ft. Bottom Reinforcing North-South Bars East-West Bars	<u>None</u> All req'd. bars in place.	Clearance between Asbestos board and cadweld was under <u>satisfactory</u> $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ " min.	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: 5/5/78 Date: 8. Randy G. Godwin
3. Elevation 198 ft. Bottom Reinf. North - South Bars East - West Bars (Reactor Vessel) Recess Area	<u>None</u> All req'd. bars in place.	A final re-bar inspection was made and all violations corrected.	<u>satisfactory</u>	Frank Collins General Foreman Individual Notified: 6/6/78 Date: 8. Randy G. Godwin
4. Elevation 204 Ft. Bottom Mat Circular Bars Radial Bars Const. Joint between 151-50' and 90' (Lower Layer of) Lower Mat	<u>None</u> All req'd. bars in place.	Several violations noted and discussed with General Foreman	<u>satisfactory</u>	Stan Warmke Foreman Individual Notified: 6/12/78 Date: 8. Randy G. Godwin
5. Elevation 204 Ft. Bottom Mat Circular Bars Radial Bars Const. Joint between 151-50' and 90' (Lower Layer of) Lower Mat	<u>None</u> All req'd. bars in place.	All violations corrected and checked out.	<u>satisfactory</u>	T. Dugay Randy G. Godwin Individual Notified: Frank Collins Date 6/13/78 EFF

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. ICB5L216004Sheet 2 of 4Location Unit No. 1 Containment BuildingDrawings CAR-2167-G- 0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Elevation 204 Ft.</u> <u>Bottom Mat</u> <u>Upper layer of</u> <u>Lower Mat</u> <u>Circular Bars</u>	<u>Various Areas</u> <u>checked</u> <u>(None)</u>	<u>None</u> <u>No difficulty in</u> <u>placing bars directly</u> <u>over bars in</u> <u>lower layer.</u>	<u>satisfactory</u>	Randy G. Godwin Notified: Frank Collins Date 6/15/78
2	<u>Elevation 204</u> <u>No clearance between</u> <u>cadweld and</u> <u>concrete on lower</u> <u>mat.</u> <u>Location - 55° ±</u>	—	<u>Not corrected</u> <u>as of PM 6/21/78</u> <u>corrected</u> <u>6/23/78</u>	—	Randy G. Godwin Individual Notified: Frank Collins Date 6/21/78
3	<u>Elevation 216 Ft.</u> <u>Top Mat</u> <u>Radial Bars</u> <u>Bottom Layer</u> <u>Const. Joint</u> <u>Entire Placement</u>	<u>None</u> <u>All req'd. bars</u> <u>in place</u>	<u>All bar mat</u> <u>tolerance. By using</u> <u>plumb bob. Able to</u> <u>see several bars</u> <u>not plumb with</u> <u>bottom layer. Informed</u> <u>Foreman and General</u> <u>Foreman.</u>	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 6/22/78
4	<u>Elevation 216 Ft.</u> <u>Top Mat</u> <u>Radial Bars</u> <u>Bottom Layer</u> <u>Entire Placement</u>	<u>None</u> <u>All req'd. bars</u> <u>in place.</u>	<u>Tails of bars not</u> <u>aligned with</u> <u>tails of other layer.</u> <u>Informed Foreman</u> <u>and corrected</u> <u>PM 6/23/78</u>	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Stan Warmbrod Date 6/23/78
5	<u>Elevation 198 Ft.</u> <u>Bottom Reinforcing</u> <u>North-South Bars</u> <u>East-West Bars</u> <u>(Reactor Vessel)</u> <u>Recess Area</u>	<u>None</u> <u>All req'd. bars</u> <u>in place.</u>	<u>A final re-bar</u> <u>inspection was</u> <u>made and all</u> <u>violations corrected.</u>	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Collins Date 6/6/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

NOV 1978 CSM 10

Placement No. 1CB5L216004

Sheet 3 of 4

Location Unit No. 1 Containment Building

Drawings CAR-2167-0- 0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	RANDY G. INSPECTION
<u>Elevation 216</u>	<u>None</u>			Randy G. Godwin
1 Top Mat Upper Layer Radial Bars Circular Bars (90° - 151° - 50°)	All req'd. bars in place.	Several areas need to be plumped and tied down. Foreman was informed and stated that this would be done prior to Wall Dowel installation.	<u>satisfactory</u>	Individual Notified: <u>Frank Collins</u> Date 7/6/78
<u>Elevation 201</u>	<u>None</u>	Bars checked. Will have to be moved around several times to accommodate Wall Dowel installation. To be rechecked prior to Concrete placement.	<u>satisfactory</u>	Randy G Godwin Individual Notified: <u>Frank</u> Collins Date 6/22/78
<u>Elevation 204</u>	Not complete as of 7/5/78		Work in progress	Randy G. Godwin Individual Notified: — Date 7/5/78
<u>Elevation 216</u>	<u>None</u>	Numerous bars out of tolerance as far as spacing. quality was unsatisfactory. Superintendent and General Foreman notified. Both agreed that tolerances would be met and quality re-established.		Randy G. Godwin Individual Notified: <u>Frank Collins</u> <u>Jim Lathan</u> Date 7/6/78
4 Cylinder Wall Dowels - 1 <sup>st</sup> row (90° - 151° - 50°)	All req'd. bars in place.			

5 References Items Nos. 1, 2, 3 and 4 on Sheet 4 of Placement No. 1CB5L216001. These Items <del>5</del> are for Isometric Nos. 1CB5L216001, 004 and 005.	Randy G. Godwin Individual Notified: — Date 7/14/78
--	---

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. ICBSL 216 004

Sheet 4 of 4

Location Unit No. 1 Containment Building

Drawings CAR-2167-3- 0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTION
2.	Elevation 204 to 216	None	None		Randy G. Godwin
1.	Final visual inspection made on entire placement. (0° - 151° 50')	All req'd bars in place. All work performed in accordance with WP-11.	All areas which were flagged have been corrected.	satisfactory	Individual Notified: Frank Collins Date 7/17/78
2					Individual Notified:  Date
3				-	Individual Notified:  Date
4				-	Individual Notified:  Date
					Individual Notified:  Date

SPK

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR WATERSTOP AND WATERPROOFING

Placement No. 1CB5L-216005

Sheet 1 of 1

Location Unit # 1 Containment Building

NO.	INSPECTION LOCATION	SPLICING VIOLATIONS OR HOLIDAYS	INSTALLATION VIOLATIONS	QUALITY	QC INSPECTOR
1	Vinyliner Inspection using Holiday Detector <u>From 0° to 65° Fuel Handling Wall Between Raglets and bond of Membrane to waterstop.</u>	Several Holidays Detected and patched in accordance with WIP-02.	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: Stanley Carter Date 6/5/78
2	Repair of Waterstop <u>Fuel Handling Wall Top Waterstop Repaired with Sikostik Epoxy Cement</u>	<u>None</u>	<u>None</u>	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: N/A Date 5/24/78
3	Accidental Burning of Waterstop. <u>Location at 30°-10° const. Joint.</u> <u>Area to be cut out and patched.</u>	Not corrected as of PM 6/2/78.	—	—	Randy G. Godwin Individual Notified: Jim Cotten Date 6/21/78
4	Waterstop <u>Fuel Handling Wall Top Layer (0° - 30°-10°)</u>	Waterstop needs to be tied up to eliminate possibility of bending down when concrete is placed.	<u>satisfactory</u> Complete 7/14/78	—	Randy G. Godwin Individual Notified: J.C. Hyatt Date 7/13/78
5	Waterstop <u>Fuel Handling Wall Top Layer Bottom Layer (0° - 30°-10°)</u>	<u>None</u> All work under Item 4 above completed in accordance with specification.	Final check was made prior to concrete placement. 6:00 AM 7/17/78	<u>Satisfactory</u>	Randy G. Godwin Individual Notified: Jim Cotten Date 7/17/78

SPK

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. LCB5L216005

Sheet 1 of 3

Location Unit No. 1 Containment Building

Drawings CAR-2167-6 0612 0613 0614 0615 0616 0617 0618 0619

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	PC INSPECTOR
1	Elevation 198 ft. Bottom Reinforcing North - South Bars	<u>None</u> All reg'd. bars in place.	Two bars checked out of tolerance, but checked out upon correction by field.	<u>satisfactory</u>	Frank Cullis General Foreman Individual Notified:  5/2/78 Date Randy G. Godwin
2	Elevation 198 ft. Bottom Reinforcing North - South Bars East - West Bars	<u>None</u> All reg'd. bars in place.	Clearance between Asbestos board and cadweld was under $\frac{1}{2}$ ". Discussed with Area Engineer decided to tolerate $\frac{1}{2}$ " or more. Future clearance to be $\frac{1}{2}$ " min.	<u>satisfactory</u>	Frank Cullis General Foreman Individual Notified:  5/5/78 Date Randy G. Godwin
3	Elevation 198 ft. Bottom Reinf. North - South Bars	<u>None</u> All reg'd. bars in place.	Three violations were noted and corrected.	<u>satisfactory</u>	Frank Cullis General Foreman Individual Notified:  5/8/78 Date Randy G. Godwin
	Elevation 204 FT Bottom Mat Circular Bars Radial Bars Const. Joint between 0° and 30° - 10° (Lower Layer of Lower Mat)	<u>None</u> All reg'd. bars in place	All violations corrected and checked out	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Frank Cullis Date 6/14/78
5	Elevation 204 FT Bottom Reinforcing Circular Bars Lower Layer of Lower Mat 340° - 0°	<u>None</u> All reg'd. bars in place	Several violations noted and Foreman notified.	<u>satisfactory</u>	Randy G. Godwin Individual Notified: Stan Wambold Date 6/15/78

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEELPlacement No. 1CB5L216005Sheet 2 of 3Location Unit No. 1 Containment BuildingDrawings CAR-2167-G- 0612 0613 0614 0615 0616 0617 0618 7' 0619

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	QC INSPECTOR
1	<u>Elevation 204</u> No clearance between cadweld and concrete on lower mat. Location - 55° ft-	—	Not corrected as of TM 6/21/78	—	Randy G Godwin
2	<u>Elevation 198</u> Bottom Reinf. North-South Bars East-West Bars (Reactor Vessel) (Recess Area)	<u>None</u> All req'd. bars in place.	Corrected 7/6/78 by use of sh.m.	satisfactory	Randy G Godwin
3	<u>Elevation 204</u> Bottom Mat Upper Layer Radial and Circular Bars (0° - 30°-10')	<u>None</u> All req'd. bars in place.	Several areas to be plumbed and tied down. Foreman Notified.	satisfactory	Randy G Godwin
4	<u>Elevation 204</u> SHEAR TRUSS BARS	Not complete as of 7/5/78	—	work in progress	Randy G Godwin
5	<u>Elevation 201</u> SHEAR KEY U Bars Between <del>—</del> 0° - 30°-10'	<u>None</u> All req'd. bars in place.	Bars checked. Will have to be moved around several times to accommodate wall dowel installation. To be rechecked prior to concrete placement.	satisfactory	Randy G Godwin

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1 CBSL 216 005

Location Unit No. 1 Containment Building

Drawings CAR-2167-C-0612, 0613, 0614, 0615, 0616, 0617, 0618, 0619

Sheet 3 of 3

INSPECTION LOCATION	QUANTITY VIOLATIONS	STAGING VIOLATIONS	QUALITY	PC INSPECTOR
Elevation 216	None	All bars met tolerance. By using plumb bob able to see several bars not plumb with bottom Mat. Informed Foreman and General Foreman.	satisfactory	Randy G Godwin
1 Top Mat Bottom Layer Radial Bars (0° - 30°-10')	All req'd. bars in place.			Individual Notified: Frank Collins Date 6/22/78
Elevation 216	None	Several areas need to be plumbed and tied down. Foreman was informed and stated that this would be done prior to Wall Dowel installation.	satisfactory	Randy G Godwin
2 Top Mat Upper Layer Circular and Radial Bars (0° - 30°-10')	All req'd. bars in place.			Individual Notified: Stan Warmbold Date 6/29/78
Elevation 216	None	One bar to be moved to clear waterstop in Bulkhead. Foreman notified.	satisfactory	Randy G Godwin
3 Cylinder Wall Dowels - 1 <sup>st</sup> Row (0° - 30°-10')	All req'd. bars in place.			Individual Notified: Stan Warmbold Date 7/6/78
Reference Item Nos. 1, 2, 3 and 4 on Sheet 4 of Placement Report No. 1 CBSL 216 001. These Items are for Isometric Nos. 1 CBSL 216 001, 004 and 005.				Randy G Godwin Individual Notified: N/A Date 7/14/78
Elevation 204 ft. 216	None	None		Randy G Godwin
Final visual inspection made on entire placement in accordance (0° - 151°50')	All req'd. bars in place. All work performed with WP-11.	All areas which were flagged have been corrected.	satisfactory 6:00 AM 7/17/78	Individual Notified: Frank Collins Date 7/17/78

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

POST PLACEMENT CHECKLIST

TP-715  
Exhibit 2

PLACEMENT NO. ICBSL 216001

LOCATION Unit No 1

Containment Building

CHECKLIST	REMARKS	INITIALS
Defects Repaired	✓ Satisfactory	TGG
Anchor Holes Grouted	N/A	TGG
<u>CURING</u>		
A. Water	✓ Satisfactory	TGG
B. Curing Compound	✓ Satisfactory	TGG
C. Ponding	✓ Satisfactory	TGG
D. Burlap		
E. Wet Sand		
F. Polyethylene		
G. Temperature		
<u>FINISH</u>		
A. Steel Trowel	✓ Satisfactory	TGG
B. Wood Float	✓ Satisfactory	TGG
C. Broom		
D. Hair Brush		
E. Rubber Float		
<u>Expoed Aggregate</u>	Satisfactory	TGG

QC INSPECTOR

Rand, D. Brown

DATE

7/25/78

PRINCIPAL SITE CIVIL ENGINEER

L. P. Shultz

DATE

7/25/78



CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
CONCRETE TEST REPORT

PLACEMENT NO. 1CB5A316001

DATE 7-17-78

LOCATION # / Containment Bldg

1-11-18  
(pump discharge) Test pt. 2

WEATHER:  CLEAR  OVERCAST  RAIN  
 HAZY  FOG  P. CLOUDY

Page 2 of 2

FOR INFORMATION ONLY

AMBIENT TEMP. 82 °F  
THERMOMETER NO. m4507

SLEEP REQUIRED 4 1/2 hr.

**FIELD QC INSPECTOR**

DATE 7/18/78

AIR FLOWED 6 ± 2 %

### **LAB QC INSPECTOR**

DATE 8-14-78

DESIGN HIC # m-45- M-56 GMW  
8-16-74

DESIGN STRENGTH 4000 psi

QA SPECIALIST

Eugene Keeg

Date 8-15-78





12/77

112 / 77

CAROLINA POWER & LIGHT COMPANY  
SHEAHER HARRIS FOR FEAR POWERED BY AIR

PLACE/MN# No. ICBSR216001  
LOCATION # 1 Containment Bl

DATA REDUCTION

(pump discharge) Test pt. I

AMBIENT TEMP.  $\frac{71}{\text{THERMOMETER NO. } 19507}$  °F

FOR INFORMATION ONLY

FOR INFORMATION ONLY

National Curriculum Framework for School Education

(C)  $\text{V}_{\text{P}, \text{AIS}}$       (C)  $\text{W} + \text{F}(\text{CAS})$       (C) RAIN  
 (C)  $\text{H}_2\text{O}$       (C)  $\text{FHG}$       (C) P: Cl.O



QA-3  
3/77  
Rev. 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
QUALITY CONTROL FIELD REPORT

(2)


Subject

Concrete Repairs  
KBSL 216002.

Date 9-13-78  
Page 1 of 1  
Report No. C-160

Inspection Details

The area on the east wall of containment bldg I. was found to have a large void in the concrete.




The extent of the void from (north to south) cannot be determined until chipping operations are completed.

Several rebar in the vicinity of the void were found to be very close to the previous formwork.

Chipping operations were started in this area today.

Q A RECORDS



SHNPP CONSTR. Q A UNIT

DO NOT USE UNLESS

000583

J. L. Wright

QC Inspector

ER 9-13-78

9-13-78

Date

ICB-KBSL 216002

QA-3  
3/77  
Rev. 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

QUALITY CONTROL FIELD REPORT

Subject

Concrete Patchwork  
Placer # 14.BSL 216002.

Date 7-25-73


Page 1 of 1

Report No. 132

Inspection Details

The area located above the center valve chamber vessel on the east side of containment bldg #1 was approved for patching after the area was satisfactorily chipped out to expose the honey-combed area.

Note: the area with the #18 rebar exposed was not approved. area =  $\approx 5 \text{ ft}^2$



CONFIDENTIAL

J.L. Waynfitt  
QC Inspector

9-25-73  
Date

EK 9/25/78

-CE-14.BSL 216002

CONCRETE  
PLACEMENT  
REPORTFILE *SK*

TCBSL 216002-1

PLACEMENT NUMBER

10-03-78

PRE-CHECKOUT DATA BY PLACING ORGANIZATION

LOCATION INCLUDE ELEV. & FLOOR  
*2nd fl (North side)*

10-2-78

THE PLACEMENT  
*Grout Patch*

2cy

*soil*

N/A

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

TRANSPORTING	PLACING	VIBRATION	FINISHING	FORMS & WATER	INSULATION	EMBEDDING
BUGGY	<input type="checkbox"/> CHUTE	<input type="checkbox"/> INTERNAL	<input type="checkbox"/> HAND SCREED	<input checked="" type="checkbox"/> FORMS ALONE	<input checked="" type="checkbox"/> WATER	
BUCKET	<input checked="" type="checkbox"/> TREMIE	<input type="checkbox"/> FORM	<input type="checkbox"/> BULL FLOAT	<input type="checkbox"/> TARPS	<input type="checkbox"/> NET SURF.	
CONVEYOR	<input type="checkbox"/> DROP	<input checked="" type="checkbox"/> Strap	<input checked="" type="checkbox"/> TROWEL MACH.	<input type="checkbox"/> INSULATION	<input type="checkbox"/> VAPOR BARRIER	
PUMP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> BROOM	<input type="checkbox"/> FORMS & WATER	<input type="checkbox"/> MEMBRANE	
TRUCK	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> N/A	<input checked="" type="checkbox"/>	<input type="checkbox"/> NUCLEAR	
	<input type="checkbox"/>	<input type="checkbox"/>				

## ANTICIPATED SPECIAL WEATHER PRECAUTIONS

*N/A*

## COMMENT &amp; CLARIFICATION TO PROPOSED

*Spray with epoxy bonding agent before placing (Q=Grout)*

PRIMARY MASONRY DWG. NO.

2167-G-610

SPEC. FINISH

*N/A*

DES. STRENGTH

4000 psi

DESIGN MIX CODE

Same as Grout

Under Shear Key Pans

NAME/TITLE, PERSON SUBMITTING

BY Ken Fisher TITLE Area Eng

10-2-78

H REF. PROC. DATE

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR		QUALITY CONTROL		QUALITY ASSISTANCE	
	REF. PROC.	GRAFT SUPT	FIELD ENG.	DATE	INSPECTOR	H REF. PROC.
1 CONTACT SURFACES	WP. 5	JRL	<i>JRL</i>			
2 FORMS	WP-22	JRL	<i>JRL</i>			
3 REINFORCING STEEL	NA	NA	NA			
4 EMBEDS	NA	NA	NA			
5 MECHANICAL	NA	<i>CK</i>	NA			
6 ELECTRICAL	NA	<i>CK</i>	NA			
7 CADWELDS	NA	NA	NA			
8 N.C.E	NA	NA	NA			
9 CLEANUP	WP. 5	JRL	NA			
10 PLACEMENT	WP-27	JRL	NA			
11						
12						
13						
14						

CONSTRUCTOR SIGNOFF (AREA SUPT)

*M. L. Dutton*

QC. SIGNOFF

QA. SIGNOFF

DATE 20-07-78 SEE ABOVE

DATE

*H. L. Dutton*

DATE 10-2-78

DESIGN APPROVAL

TIME OF START

DATE PLACED

*1/17**1/17*

10-03-78

YDS CONCRETE  
DELIVERED

CS NOT PLACED IN

AFCS 100-707

THIS PLACEMENT

YARDS GROUT

CS PLACED IN

YARDS PLACED ELSEWHERE

THIS PLACEMENT

YARDS PLACED ELSEWHERE

NAME

*M. L.*

TITLE

*M. L.*DATE *10-03-78*

REMARKS (ATTACH RELEVANT REPORTS)

*ICBSL 216002-p**ICBSL 216002-p**SPK*

QA-3  
3/77  
Rev. 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
QUALITY CONTROL FIELD REPORT

Subject: Patchwork Inspection

ICBSL204012

Reference Placement No. ICBSL 216002

Date 10-4-78

Page 1 of 1


Report No. C-212

Inspection Details

The above area in the 26.1 Containment Bldge above the northern most valve chamber was inspected before during and after placement of the grout patch.

The patching was in accordance with FCR # 292.

The remaining portion of the void will be patched using the replacement concrete method.



ICBSL 216002 FK  
ICBSL 204012 BK  
ICBSL 204012

H.L. Wright

QC Inspector

10-4-78

FK 2/16/78 Date

QA-3  
3/77  
Rev. 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
QUALITY CONTROL FIELD REPORT

Subject:


Concrete Patchwork Inspection  
ICBSL 216002

Date 10-6-78  
Page 1 of 1  
Report No. 221

Inspection Details


The area to be patched in the above placement is located above the northern-most valve chamber in containment bldg No. 1.

The area to be patched was approved for patching using the "replacement concrete" method.



NOTE: This inspection is for the second portion of the patchwork. The first portion was accomplished using the "replacement mortar" method.

QA RECORDS



1-CB-ICBSL 216002

H.L. Wright

QC Inspector

10-6-78

PL 2/10/77 Date

CONCRETE  
PLACEMENT  
REPORT

CP3J

SHNPP

FILE

LOCATION (INCLUDE ELEV. IF IN BLDG.)

Northern part value charged (Elev 204) Cont #1

PLACEMENT NUMBER

1C8SL216002

TYPE PLACEMENT  
POURING  
CONCRETE

ESTIMATED QUANTITY

1yd

SCHEDULED DATE:

10-3-78

P

TEMP LIMIT  
50°  
plowSLUMP LIMIT  
4"

SEISMIC CLASS I

YES NO

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

TRANSPORTING	PLACING	VIBRATION	FINISHING	FORMED SURF	UNFORMED SURF
BUGGY	<input type="checkbox"/> CHUTE	<input type="checkbox"/> INTERNAL	<input checked="" type="checkbox"/> HAND SCREED	<input type="checkbox"/> FORMS ALONE	<input checked="" type="checkbox"/> WATER
BUCKET	<input checked="" type="checkbox"/> TREMIE	<input type="checkbox"/> FORM	<input type="checkbox"/> BULL FLOAT	<input type="checkbox"/> TARPS	<input type="checkbox"/> WET BURLAP
CONVEYOR	<input type="checkbox"/> DROP	<input checked="" type="checkbox"/>	<input type="checkbox"/> TROWEL MACH.	<input type="checkbox"/> INSULATION	<input type="checkbox"/> VAPOR SARRIER
PUMP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> BROOM	<input type="checkbox"/> FORMS & WATER	<input type="checkbox"/> MEMBRANE
TRUCK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Form	<input type="checkbox"/>	<input type="checkbox"/> NUCLEAR
	<input type="checkbox"/>				<input type="checkbox"/> NON-NUCLEAR

ANTICIPATED SPECIAL WEATHER PRECAUTIONS

No

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

apply epoxy bonding compound prior to placing concrete

PRIMARY MASONRY DWG. NO.

SPEC. FINISH

2167-G-610

ATA

DES. STRENGTH

4000 psi

DESIGN MIX CODE

M56

NAME/TITLE, PERSON SUBMITTING ALL THE ABOVE  
BY Ken Fuller TITLE: Area Eng DATE 10-3-78

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR			QUALITY CONTROL	QUALITY ASSURANCE				
	REF. PROC.	CRAFT SUPT	FIELD ENG						
1. CONTACT SURFACES	WP-5	JRL							
2. FORMS	WP-22								
3. REINFORCING STEEL	NA	NA	NA						
4. EMBEDS	NA	NA	NA						
5. MECHANICAL	NA	BP	NA	10-3 C.S.H. int					
6. ELECTRICAL	NA	BP	NA	10-3 C.S.H. int					
7. CADWELDS	NA	NA	NA						
8. N.D.E.	NA	NA	NA						
9. CLEANUP	WP-5		NA						
10. PLACEMENT	WP-27		NA						
11.									
12.									
13.									
14.									

CONSTRUCTOR SIGN-OFF (AREA SUPER) Q.C. SIGN-OFF WA PER GELD WA SIGN-OFF WA PER LEE

DATE 9 OCT 78 SIGN-OFF 20078 DATE WA SIGN-OFF 9 OCT 78

DESIGN APPROVAL

Ken Fuller

DATE 10-3-78

TIME OF START

DATE PLACED

10-3-78

YDS. CONCRETE  
DELIVEREDYDS. NOT PLACED IN  
THIS PLACEMENT

YARDS WASTED

YARDS GROUT

YDS. PLACED IN  
THIS PLACEMENT

YARDS PLACED ELSEWHERE

ACCEPTANCE OF PLACEMENT METHODS &amp; ACCURACY OF ABOVE INFORMATION

NAME

REMARKS (ATTACH RELEVANT REPORTS)

Patchwork only

DATE

QA-3  
3/77  
Rev. 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
QUALITY CONTROL FIELD REPORT


Object

Concrete Patchwork Inspection  
1 C BSL 216002

Date 11-6-78  
Page 1 of 1  
Report No. 5-313

Inspection Details

The above area was patched in accordance with applicable specifications and FCR-288. The patched area is located in Unit 1 Containment above the valve chamber in the northeast quadrant.



A.L. Wright  
QC Inspector

11-6-78  
Date

1-CB-1C BSL 216002

E.L. 2/16/79

APP-001  
Rev. 9

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

AP-17-03  
Exhibit 1

2/78

FIELD CHANGE REQUEST/PERMITTING WAIVER

Page 1 of 2

Type of Request:  Permanent Waiver to "use-as-is"

Field Change

See Enclosure A Section

TECH/PK 288

Identification of Area and Item:  Unit 1 Containment Rebar Minimum Concrete Coverage Violation

Specifications/Documents:

CAR - 2167-G-0561 Rev. 2

Conflict/Condition:

See attached sheet 2

Recommended Action:  Please Investigate and Resolve  Please Resolve as Follows DOCUMENT CONTROL

"Use "as is"

RECOMMENDED  
OCT 19 1978

Justification: By Ebasco. THE PROPOSED CONCRETE COVER MEETS THE REQUIREMENTS OF ASCE/IRC 1975 SECTION CC-3534.1 FOR THIS REINFORCEMENT. THAIS N. P. P.

Requested by:

N. S. Prilgen A Eng. 1/25/78

Signature & Title

Site Approval

AM Lauer 9/26/78  
Project Engineer - Date

Design Engineering Approval (AE) (XSSS)

Telephone Resolution  
 Yes  No

Approved as Recommended

Rejected

Conditional Approval

This change requires the following Document(s) (Specification, Drawing, SAE, etc.) to be changed SHOW ON AS-BUILT DWG.

Comments:

Mario S. Verdadero SE ENG. 10/2/78

Signature

Title

Date

Michael J. Hart PE 10/26/78

Title

Date

CP&L Engineering Tool Approval

Telephone Resolution  
 Yes  No

Approved as Recommended

Rejected

Conditional Approval

FOR INFORMATION ONLY

10-6-78

J. R. Dugay Discipline Engineer

Date

PIP or PIP

Site Concurrence: Recommend

Implementation

Alternate Resolution

G. M. Lauer 10-19-78

Attachment to FCR-C-238

CACHELA POINT AND LIGHT CONCRETE  
SHENANDOAH VALLEY PROJECT

FCR-20 CONCRETE SHEET

21-2-1  
EXHIBIT 1

Page 2

Conflict/Condition:

Upon raking the forms off the cl. 216' Containment 1 placement, two reinforcing bars were visible at the vertical concrete surface. These bars are:

- 1) A CA 49 #11 shear truss reinforcing bar
- 2) A C 64 #18 bar (the tail portion)

These bars were too close to the formed surface thus violating the  $-1\frac{1}{2}$ " coverage tolerance.

After required chipping and patching operations around the affected areas are completed, there will be approximate 1" of concrete cover over the bars.

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD CHANGE REQUEST/PERMANENT WAIVER  
CLOSE OUT\*

\*Note: This form is to be used to document implementation of FCR/PW's written prior to revision 12 of Exhibit 1.


FCR/PW C-288

Implementation Completed as Approved?

Yes

No

Comments:



Bill Stiles  
Discipline Engineer

Final Distribution  
(Original) File in Document Control  
(Copy) Ebasco  
(Copy) PPED  
(Copy) Principal QA Specialist

I-CB-SL-216-002

APP-001  
Rev. 10CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANTAP-IX-05  
Exhibit 1

9/78

## FIELD CHANGE REQUEST/PERMANENT WAIVER

Page 1 of 3

Type of Request:	<input type="checkbox"/> Permanent Waiver to "use-as-is" <input checked="" type="checkbox"/> Field Change <input type="checkbox"/> See Recommended Action	FCR/EN C-272
Identification of Area and Item:	<input checked="" type="checkbox"/> Q <input checked="" type="checkbox"/> ASME Section III <input type="checkbox"/> Non-Q <input type="checkbox"/> Non-ASME Section III	
Specifications/Documents:	DOCUMENT CONTROL CAR-SH-CH-06	
Conflict/Condition:	SAME AS FCR-C-278 (ATTACHED) OCT 17 1978	
FOR INFORMATION ONLY		
Recommended Action: <input type="checkbox"/> Please Investigate and Resolve <input checked="" type="checkbox"/> Please Resolve as Follows: SAME AS FCR-C-278 - HOWEVER, AN EPOXY BONDING COMPOUND SHALL BE USED AS A BONDING MEDIUM (SEE FCR-C-096 FOR APPROVED EPOXY)		
Justification: By EBASCO THE RECOMMENDED REPAIR PROCEDURE IS SATISFACTORY TO INSURE PROPER BONDING IN ALL THE Affected AREAS.		
Requested by: <u>Charles J. Miller, Jr.</u> Discipline Engineer	Site Approval: <u>AM Lucy</u> Resident Engineer - Project	9/27/78 Date
Design Engineering Approval: (AE) (NSES)	Telephone Resolution <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<input checked="" type="checkbox"/> Approved as Recommended <input type="checkbox"/> Rejected <input type="checkbox"/> Conditional Approval		
This change requires the following Document(s) (Specification, Drawing, SAR, etc.) to be changed <u>NONE</u>		
Comments: <u>Mario S. Verchillo</u> 9/27/78 <u>Michael U. Tate</u> 9/27/78		
Signature	Title	Date
CP&L Engineering Pool Approval		
<input checked="" type="checkbox"/> Approved as Recommended In accordance with EBASCO Comments on FCR-C-278	Telephone Resolution <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<u>J. R. Tenggara</u> Discipline Engineer	10-4-78 5:04-13 Date	<u>G. G. Smith</u> 10-5-78 Date
Site Concurrence: Recommend	<input checked="" type="checkbox"/> Implementation <input type="checkbox"/> Alternate Resolution	<u>AM Lucy</u> 10-16-78 Date

APF-001  
Rev. 9

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

AP-IX-05  
Exhibit 1

2/78

FIELD CHANGE REQUEST/PERMANENT WAIVER

Page 1 of 2

Type of Request:  Permanent Waiver to "use-as-is"

Field Change


See Recommended Action

FORM # C-271

Identification of Area and Item:  Q  Non-Q

UNIT 1 CONTAINMENT MAT - HONEYCOMB AREA

Specifications/Documents:

  
CAR-SH-CH-06

Conflict/Condition: A HONEYCOMB WAS FOUND IN THE UNIT 1 CONTAINMENT MAT AT ELEV. 204, DIRECTLY ABOVE THE NORTHERN MOST VALUE CHAMBER. ALL LOOSE CONCRETE WAS CHIPPED OUT AND THE RESULTING VOID AREA IS AS SHOWN ON THE ATTACHED SKETCH. CONFIGURATION OF THE VOID IS SUCH THAT REPAIR BY METHODS OUTLINED IN CH-6 WOULD BE DIFFICULT.

Recommended Action:  Please Investigate and Resolve  Please Resolve as Follows:  
ALLOW THE CONSTRUCTOR TO PLACE A FORM AS SHOWN ON THE ATTACHED SKETCH AND POUR GROUT INTO THE INDICATED AREA. THE REMAINDER OF THE VOID AREA WOULD THEN BE FORMED AND FILLED WITH CONCRETE DESIGN MIX NO. M-56

Justification: THIS METHOD WOULD ASSURE THAT ALL THE VOID AREA WOULD BE FILLED.

Requested by:

Kenneth Fuller Rev Eng 9-19-78  
Signature & Title

Date

Site Approval:

Charles D. King FOR AMI 9/19/78  
Resident Engineer - Project Date

Design Engineering Approval

(AE) (XSSS)

Telephone Resolution

Yes  No


Approved as Recommended

Rejected

Conditional Approval

This change requires the following Document(s) (Specification, Drawing, SAR, etc.) to be changed

Comments:

Signature	Title	Date	Signature	Title	Date	
CP&L Engineering Pool Approval				Telephone Resolution <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
<input type="checkbox"/> Approved as Recommended			<input type="checkbox"/> Conditional Approval			
			SHEARON HARRIS N. P. P.			
Discipline Engineer	Date	MEP or PPT	Date			
Site Concurrence: Recommend			<input type="checkbox"/> Implementation	<input type="checkbox"/> Alternate Resolution	For instant implementation Date	

FOR ADDITIONAL COPY

PAGE  
NO.  
4  
1

CONTAINMENT  
BLDG. WALL

T/BASE SLAB MAT  
EL. 216.00'

PROVIDE EMBEDDED P  
FOR EQUIP HANDLING  
FACILITY (TYP OF 4)

PROVIDE EMBEDDED P  
FOR HOOK - FOR LIFTING  
CHAMBER COVER & INSIDE  
VALVE (TYP OF 4)

CUT OUT FOR ELEC BOX  
(SECT C-C ONLY)


EL. 195.42

B/MAT  
EL. 180.00'


WORK SLAB  
& POROUS CONC. CHANNEL  
REACTOR AUX. BLDG.  
FOR CONTINUATION  
SEE DWG G-1150A

SECT. C-C (J6,L12) G-0610  
SECT. C-C (J6,L11) G-0610

S. CALC. No.



DOCUMENT CONTROL  
REF ID: A64715  
SEP 21 1978  
RUGETTE  
SHEARON HARRIS N. P. P.



Value Chamber  
(Northern most value chamber in unit #1)  
 $\approx 218^\circ$

FOR INFORMATION ONLY

Drawing Not to Scale

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD CHANGE REQUEST/PERMANENT WAIVER  
CLOSE OUT\*

\*Note: This form is to be used to document implementation of FCR/PW's written prior to revision 12 of Exhibit 1.

FCR/~~12~~ C-292

Implementation Completed as Approved?

Yes

No


Comments:

QA RECORDS

RECEIVED MAR 27 1979

Bill Sylva  
Discipline Engineer

Final Distribution  
(Original) File in Document Control  
(Copy) Ebasco  
(Copy) PPED  
(Copy) Principal QA Specialist



CONCRETE  
PLACEMENT  
REPORT

PRECHECKOUT DATA BY PLACING ORGANIZATION

LOCATION (INCLUDE ELEV. IF IN BLDG.)

Unit #1 C.B. Estorios wall Elev 28.5

PLACEMENT NUMBER

1CBXW219001

SCHEDULED DATE:

12/2/78

TYPE PLACEMENT

Exterior Wall

ESTIMATED QUANTITY

230 yds<sup>as placed</sup>

TEMP LIMIT

55°

SLUMP LIMIT

4"

SEISMIC CLASS I

YES NO

PROPOSED PLACEMENT METHODS (CHECK APPLICABLE SPACES)

				CURING	
TRANSPORTING	PLACING	VIBRATION	FINISHING	FORMED SURF	UNFORMED SURF
BUGGY	<input type="checkbox"/> CHUTE	<input type="checkbox"/> INTERNAL	<input checked="" type="checkbox"/> HAND SCREED	<input type="checkbox"/> FORMS ALONE	<input checked="" type="checkbox"/> WATER
BUCKET	<input type="checkbox"/> TREMIE	<input checked="" type="checkbox"/> FORM	<input type="checkbox"/> BULL FLOAT	<input type="checkbox"/> TARPS	<input type="checkbox"/> WET BURLAP
CONVEYOR	<input type="checkbox"/> DROP	<input type="checkbox"/>	<input type="checkbox"/> TROWEL MACH.	<input type="checkbox"/> INSULATION	<input type="checkbox"/> VAPOR BARRIER
PUMP	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> BROOM	<input type="checkbox"/> FORMS & WATER	<input type="checkbox"/> MEMBRANE
TRUCK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>Exposed Agg.</i> <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> NUCLEAR** <input checked="" type="checkbox"/>
					<input type="checkbox"/> NON-NUCLEAR

\* \* Nurac 10 on Ext wall face

NON-NUCLEAR

ANTICIPATED SPECIAL WEATHER PRECAUTIONS

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

PRIMARY MASONRY DWG. NO.

2167-G-0610

SPEC. FINISH

Exposed Aggregate

At C.S. the concrete must be free of  
dust and roughened until the aggregate  
is exposed for a depth of  $\frac{1}{2}$ "

DES. STRENGTH

5000 psi

DESIGN MIX CODE

M172

NAME/TITLE, PERSON SUBMITTING ALL THE ABOVE

BY Ken Fuller TITLE Area Tech DATE 10-23

PRE-PLACEMENT CHECKOUT	CONSTRUCTOR			QUALITY CONTROL		QUALITY ASSURANCE			
	REF PROC	CRAFT SUPT	FIELD ENG	DATE	INSPECTOR	H	REF PROC	DATE	INSPECTOR
1 CONTACT SURFACES	WP-5	J. E. B.	J. E.	12/2	GFF				
2 FORMS	WP-22	J. R. B.	J. D.	12/2	GFF				
3 REINFORCING STEEL	WP-11	J. C.	J. D.	12/2	GFF				
4 EMBEDS	N/A	N/A	N/A	12/2	GFF				
5 MECHANICAL	N/A	J. P. J.	N/A	11/16	S.A. 77% done				
6 ELECTRICAL	N/A	J. P. J.	N/A	11/21	Q. S. Bell				
7 CADWELDS	WP-1	J. C.	N/A	12/2	GFF				
8 N.D.E	N/A	N/A	N/A	12/2	GFF				
9 CLEANUP	WP-5	JRL	N/A	12/4	* GFF				
10 Bend breaker	GEN 550-112	JRL	N/A	12/2	GFF				
11									
12									
13									
14									

CONSTRUCTOR SIGNOFF (AREA SUPT)

*R. J. Fuller*

CC. SIGNOFF

*John S. French*

12/4/78

J.A. SIGNOFF

*Bill Wright*

DATE 12-4-78

DESIGN APPROVAL

Ken Fuller

DATE

TIME OF START

0930

DATE PLACED

12-06-78

YDS. CONCRETE

DELIVERED

0237

YDS. NOT PLACED IN  
THIS PLACEMENT

14

YARDS WASTED

0.5

YARDS GROUT

02

YDS. PLACED IN  
THIS PLACEMENT

0225

YARDS PLACED ELSEWHERE\*\*

0.9

ACCEPTANCE OF PLACEMENT METHODS &amp; COMPLETENESS OF ABOVE INFORMATION

NAME

*John S. French*

TITLE

*Construction Inspector*

DATE 12/4/78

REMARKS (ATTACH RELEVANT REPORTS)

Delivery to contours just prior to the placement of concrete.

\*\* WAREHOUSE #3

*JK*

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

PLACEMENT CHECKLIST

PLACEMENT NO. 1C01120001

LOCATION Unit #1 Civil City  
EL 819

CHECKLIST	REMARKS	INITIALS
Free Fall Height	Sat	G/H
Rate of Placement	Sat	G/H
Hot Weather Conditions	N/A	G/H
Cold Weather Conditions	N/A	G/H
Layer Thickness	Sat	G/H
Use of Placing Equipment	Sat	G/H
Consolidation	Sat	G/H
Embedded Items	N/A	G/H
Forms	Sat	G/H

QC INSPECTOR

*John Stank* DATE 11/12/82

PRINCIPAL SITE CIVIL ENGINEER

DATE

100-11111

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CBAND19001

Sheet 1 of 1

Location Unit #1 Cyl. Bldg. Exterior Wall

Drawings CAR-2167-G-

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	OC INSPECTOR
1	Shear tie bars E1.216 to E1.217 exterior wall	Approximately 200 bars missing	Numerous spacing violations due to missing shear tie bars	Sat.	C.A. Stark INDIVIDUAL Notified <u>J. Williams</u> Date <u>Nov. 27, 1982</u>
2	Ditto Iron #1 (E16)	None	None	Sat	C.A. Stark INDIVIDUAL Notified <u>Nov. 27, 1982</u> <u>ABD</u>
3					
4					
5					

CAROLINA POWER & LIGHT  
SHEARON HARRIS NUCLEAR POWER PLANT  
FIELD INSPECTION REPORT FOR REINFORCING STEEL

Placement No. 1CBXW219001Sheet 1 of 1Location Unit #1 Cont. Bldg. Exterior Wall from EL. 216 to 218.5Drawings CAR-2167-G- 0632 - 0633 - 0651

NO.	INSPECTION LOCATION	QUANTITY VIOLATIONS	SPACING VIOLATIONS	QUALITY	OC INSPECTOR
1	216 EL to 218.5 EL Horizontal rebar 0° to 360°	None	None	Sat	CJ Farn Individual Notified: _____ Date <u>12/1/78</u>
2	216 EL to 218.5 EL Shear tie bars 0° to 360	Approx. 150 shear tie bars missing	None	Sat	CJ Farn Individual Notified: J. Jathman _____ Date <u>12/1/78</u>
3	Item #2	None <u>All of the shear tie bars in place</u>	None	Sat	CJ Farn Individual Notified: _____ Date <u>12/4/78</u>
4					Individual Notified: _____ Date
5					Individual Notified: _____ Date

*SHK*

CAROLINA POWER & LIGHT CO., ANY  
SHEARON HARRIS NUCLEAR POWER PLANT

TP-15  
Exhibit 3

POST PLACEMENT CHECKLIST

PLACEMENT NO. 1CBXW219001

LOCATION Unit #1, Containment  
Bldg E1 219 Exterior Wall

CHECKLIST	REMARKS	INITIALS
Defects Repaired	N/A	CH
Anchor Holes Grouted	N/A	CH
<u>CURING</u>		
A. Water	Sat	CH
E. Curing Compound	N/A	CH
C. Ponding	N/A	CH
D. Burlap	Sat	CH
E. Wet Sand	N/A	CH
F. Polyethylene	N/A	CH
G. Temperature	Sat	CH
<u>FINISH</u>		
A. Steel Trowel	N/A	CH
B. Wood Float	N/A	CH
C. Broom	N/A	CH
D. Hair Brush	N/A	CH
E. Rubber Float	N/A	CH
F. Exposed Agg.	Sat	CH

CONSTRUCTION INSPECTOR

*John S. Frank*

DATE 12/19/28

PRINCIPAL SITE CIVIL ENGINEER

*J. H. Field Jr.*

DATE 12-20-20

QA-24  
11-01-78  
Rev. 2

CAROLINA POW & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT  
CONCRETE TEST REPORT  
(Procedure CQC-13)

Page 1

PLACEMENT NO. IC BX WZ19001 DATE 12-6-78

AMBIENT TEMP. 46 °F

LOCATION #1 Containment Bldg. (pump discharge)

THERMOMETER NO. 4553

WEATHER:  CLEAR  OVERCAST  RAIN  OTHER  
 HAZY  FOG  P. CLOUDY

TRUCK NO.	TIME SAMPLED	TRUCK YARDS	TICKET NO.	SLUMP (IN.)	TEMP. (°F)	THERM. NO.	AIR (%)	AIR METER NO.	UNIT WT.	UNIT BUCKET	SCALE NO.	WATER ADDED	TEST CYLINDERS				SET NO.	REMARKS
													DAY 3	DAY 4	DAY 28	DAY 28		
29	10:20 AM	5	23588	2 3/4	63	4553	4.6	4508A				+7						
29	11:00 PM	5	23589	1 1/2	65	4553	4.0	4508A				+9						
28	1:05 PM	8	23597	2 1/2	66	4553	5.6	4508A	141.9	4508A	04530	+6	3860	5060	7150	7220	1	1/6 Field/curemate 2507
28	2:05 PM	8	23603	3 1/2	68	4553	5.0	4508A										
30	3:00 PM	8	23608	4	68	4553	6.2	4508A	144.9	4508A	04530	+180	4780	6330	6470	2	2508	
29	4:00 PM	8	23615	3	70	4553	5.4	4508A	141.4	4508A	04530	+640	5380	7000	7250	3	2509	
	: AM																	
	: PM																	
	: AM																	
	: PM																	
	: AM																	
	: PM																	
	: AM																	
	: PM																	
	: AM																	
	: PM																	
	: AM																	
	: PM																	
	: AM																	
	: PM																	

SLUMP REQUIRED 4 ± 1 in.

DESIGN MIX # M - 72

FIELD QC INSPECTOR Ricky Strubbed DATE 12-6-78

AIR REQUIRED 4 - 8 %

DESIGN STRENGTH 5000 psi

LAB QC INSPECTOR Lthy Ytron DATE 1-3-79

QA SPECIALIST Eugene Keele DATE 1-4-79

CONCRETE  
PLACEMENT  
REPORT**CP&L****SHNPP**Exhibit 1  
WP-05

000564

FILE

LOCATION (INCLUDE ELEV. IF IN BLDG.)

Cont. #1 EXT. WALL AT 9' PER AIR LOCK

PLACEMENT NUMBER

1K18xW256004

TYPE PLACEMENT

ESTIMATED QUANTITY

EXT. WALL

67 C.Y.

SCHEDULED DATE:

8/11/81

TEMP. LIMIT

SLUMP LIMIT

50°-90° 8" max

SEISMIC CLASS I

YES NO

PROPOSED PLACEMENT METHODS: (CHECK APPLICABLE SPACES)

## TRANSPORTING

## PLACING

## VIBRATION

## CURING

BUGGY

 CHUTE INTERNAL HAND SCREED FORMS ALONE WATER

BUCKET

 TREMIE FORM BULL FLOAT TARPS WET BURLAP

CONVEYOR

 DROP PNEUM TROWEL MACH. INSULATION VAPOR BARRIER

PUMP

 BROOM FORMS & WATER MEMBRANE

TRUCK

 EXA AGG WATER NUCLEAR

SERVICE COND

SPECIAL NOTES

 NOTE: *Exp. Agg.* Forms removed NON-NUCLEARANTICIPATED WEATHER  
CONDITIONS: *HOT*PROTECTION *CIRNOOT*CURE(DAYS) *7*PRIMARY MASONRY DWG. NO. *2167-G-0831 R-11*SPEC. FINISH *Exp. Agg.*DES. STRENGTH *5.0KSI*DESIGN MIX CODE *M-80*

COMMENT &amp; CLARIFICATION TO PROPOSED METHODS

*RATE OF RISE - 2'/HR**USE M-12 Pump agent*

NAME/TITLE, PERSON SUBMITTING ALL THE ABOVE

BY: *Dave L. By* TITLE: *Area E* DATE: *8/11/81*

## PRE-PLACEMENT

## CHECKOUT

## CONSTRUCTOR

## CONST. INSPECTION

## QUALITY ASSURANCE

REF PROC

CRAFT SUPT.

DATE

INSPECTOR

H

Q.C. SIGNOFF

DATE

1 CONTACT SURFACES

J. P. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

2 FORMS

J. C. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

3 REINFORCING STEEL

T. L. Hyatt

8/11

R. Breedlove

8/11/81

*Hyatt*

4 EMBEDS

J. C. Hyatt

8/11

R. Breedlove

8/11/81

*Hyatt*

5 MECHANICAL

EMBEDS

8/10

R. Breedlove

8/11/81

*Breedlove*

PIPE

J. C. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

6 ELECTRICAL

J. C. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

7 CADWELDS

T. L. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

8 BOP WELDING

T. L. Hyatt

8/10

R. Breedlove

8/11/81

*Hyatt*

9 CODE/SEISMIC WELDING

10 CLEAN-UP

J. C. Hyatt

8/11

R. Breedlove

8/11/81

*Hyatt*

11

12

CONSTRUCTOR SIGNOFF (AREA SUPT.)

TIME: 7:15

C.I. SIGNOFF

TIME: 8:05AM

*J. C. Hyatt* 98-299

DATE: 8-11-81

*Russell L. Breedlove*

DATE: 8-11-81

DESIGN APPROVAL

TIME OF START

DATE PLACED

*Dave L. By*

DATE: 8/11/81

8:30

DATE PLACED

08-11-81

YDS. CONCRETE

YDS. NOT PLACED IN

YARDS WASTED

DELIVERED

67

0.5

0.5

YARDS GROUT

YDS. PLACED IN

YARDS PLACED ELSEWHERE

11

66.5

10

ACCEPTANCE OF PLACEMENT METHODS &amp; COMPLETENESS OF ABOVE INFORMATION

NAME: *Russell L. Breedlove* TITLE: C.I.

DATE: 8-11-81

REMARKS (ATTACH RELEVANT REPORTS)

*\* Some rebar shifted for access-flaged; Replaced @ completion RLB 8-11-81*

Rev. 7  
4/81

Exhibit 1  
TP-15

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

PLACEMENT CHECKLIST

PLACEMENT NO. 1CBXW256004

LOCATION Cont. #1 Ext. Wall

A2. 315° to 16°, el. 251' to 256'

CHECKLIST	REMARKS	INITIALS
Free Fall Height	Sat.	R&B
Rate of Rise	Sat.	R&B
Hot Weather Conditions	Sat.	R&B
Cold Weather Conditions	N/A	R&B
Layer Thickness	Sat.	R&B
Use of Placing Equipment	Sat.	R&B
Consolidation	Sat. *	R&B
Embedded Items	Sat.	R&B
Forms	Sat.	R&B
Cleanup Maintained	Sat.	R&B
Mixing To Placing Intervals	Sat.	R&B
Shifted/Removed Rebar Replaced	Sat.	R&B

COMMENTS \* Workers warned about vibration techniques; both under- and over-vibration. A most difficult placement.

CONSTRUCTION INSPECTOR

Russell L. Breckenridge DATE 8-11-81

CONSTRUCTION INSPECTION SUPERVISOR

M.D. Sealsby DATE 8-11-81

FOR INFORMATION ONLY

## CAROLINA POWER &amp; LIGHT COMPANY

## SHEARON HARRIS NUCLEAR POWER PLANT

FIELD INSPECTION REPORT FOR REINFORCING STEEL-  
REQUIRED DRAWINGSPlacement Number CBXW256004Coordinates A2. 315° to 16°Elevation 251.0' to 256.0'C.I. Review Russell S. BrescianoArea Engineer Review John R. Key

Drawings Required/Revision:

✓ Masonry ✓ CAR-2167-G-0630(R7)  
 ✓ -0631(R7)

✓ Reinforcing ✓ CAR-2167-G-0618(R6)  
 ✓ -0619(R6)  
 ✓ -0636(R4)  
 ✓ -0637(R4)  
 ✓ -0764(R3)  
 ✓ -0767(R2)  
 ✓ -0632(R3)  
 ✓ -0633(R3)  
 ✓ (cont.)

✓ Embeds ✓ CAR-2167-G-0631(R7)

✓ Penetrations ✓ CAR-2167-G-0630(R7)  
 ✓ -0631(R7)  
 ✓ (cont.)

✓ Dowels ✓ CAR-2167-G-0618(R6)  
 ✓ -0619(R6)

✓ Bar Bending ✓ CAR-2167-B-9005-5,6,7,8,9,3

Affecting Documents \*

- ✓ FCR-C-7116 (Tolerance on Shell Liner)
- ✓ FCR-C-2324 (Excess clearance in blister area)
- ✓ FCR-C-2556 (Interference CC 906/5-57 stud)
- ✓ FCR-C-2557 (No clearance on cadwelds @ 16°)
- ✓ FCR-C-2558 (Change C.J. @ A2. 315°)
- ✓ PW-C-2089 (8<sup>th</sup> Row As-Built)
- ✓ PW-C-2333 (Form and Probe Vibrators)
- ✓ PW-C-1370 (Omitted 8<sup>th</sup> Row Dowels)
- ✓ PW-C-2495 (Radial Bars misfabbed)
- ✓ PW-AS-685 (Bent Studs on penetrations)
- ✓ PW-AS-736 (Bent Studs on penetrations)
- ✓ FCN-550-805 ('Endos' 8<sup>th</sup> Row)
- ✓ RCI-C-625 (Add'l Temperature Steel)
- ✓ RCI-C-465 (Form Coatings)
- ✓ RCI-C-498 (ACI concrete cover minimums)
- ✓ RCI-C-535 (Acceptable 'Endo' lengths)
- ✓ RCI-C-589 (Conflicts between prints)
- ✓ RCI-C-598 (Conflicts between prints)
- ✓ RCI-C-599 (Liner plate tolerance clarification)
- ✓ RCI-C-555 (Shear Bolt Assemblies)
- ✓ RCI-C-600 (Design Drawings Clarification)

\* This placement has been checked with the computer printout and documents. Correct as of 8-8-81

Other \_\_\_\_\_

Russell S. Bresciano

## CAROLINA POWER &amp; LIGHT COMPANY

## SHEARON HARRIS NUCLEAR POWER PLANT

FIELD INSPECTION REPORT FOR REINFORCING STEEL-  
REQUIRED DRAWINGSPlacement Number ICBXW286004Coordinates A2. 315° to 16°Elevation 251.0' to 256.0'C.I. Review P. Bruegge

Area Engineer Review \_\_\_\_\_

Drawings Required/Revision:

809-9-8-81  
BridgesCAR-2167-G-0638(R3) ✓-0639(R5) ✓-0641(R4) ✓-0650(R4) ✓-0651(R4) ✓-0652(R6) ✓-0770(R1) ✓-0634(R3) ✓-0635(R3) ✓-0761(R4) ✓809-2168-G-601(R6)✓ -0229(R14)✓ -0230(R16)✓ -0231(R15)✓ -253501(R3)

Penetrations

✓ -253502(R4)✓ -253503(R3)✓ -253504(R3)✓ -253508(R2)

Bar Bending

Other

Bethlehem Steel Corporation Prints (Reinforcing)

✓ 8099-10(R1) ✓✓ -7(R2) ✓✓ -12(R6) ✓✓ -3(R2) ✓✓ -8(R4) ✓✓ -4(R1) ✓✓ -13(R2) ✓✓ -24(R3) ✓✓ -25(R4) ✓✓ -26(R3) ✓✓ -32(R3) ✓✓ -29(R2) ✓✓ -33(R3) ✓✓ -22(R4) ✓✓ -23(R3) ✓✓ -23A(R1) ✓

**CAROLINA POWER & LIGHT COMPANY,  
CORPORATE QUALITY AND SERVICE DEPARTMENT  
CONCRETE TEST REPORT**

DATE 8-11-81

WODE OF PLACEMENT Page

<u>LOCATION</u>	<u>Concordant Bldg #1</u>		
<u>WEATHER</u>	( <input type="checkbox"/> ) CLEAR	( <input checked="" type="checkbox"/> ) OVERCAST	( <input type="checkbox"/> ) RAIN
	( <input type="checkbox"/> ) HUMID	( <input type="checkbox"/> ) FOG	( <input type="checkbox"/> ) CLOUDY

AIR REQUIRED - 4 - 8 L

DESIGN MIX & USED M-20  
DESIGN STRENGTH 5000PSF

$q\bar{q}/qc$

DATE 8-11-81  
DATE 9-5-81  
DATE 9-9-81

John Kelly

FIELD QA/QC INSPECTOR  
LAB QA/QC INSPECTOR  
QA/QC SPECIALIST

Rev. 7  
4/81

TP-15  
Exhibit 2

CAROLINA POWER & LIGHT COMPANY  
SHEARON HARRIS NUCLEAR POWER PLANT

POST PLACEMENT CHECKLIST

PLACEMENT NO. 1CBXU2784004

LOCATION Coat. #1 Ext. Wall

PLACED 8/11/81

Az. 318° to 16°, el. 281' to 256'

END OF CURE 8/18/81

CURE/PROTECTION REQUIREMENTS Extended

CHECKLIST	REMARKS	INITIALS
Form & Shoring Removal	Forms removed 8-25-81	RLB
Concrete Repairs Required	Cosmetic Only	RLB
<u>CURING/PROTECTION</u>		
A. Water	Set.	RLB
B. Curing Compound	Set - Kurez confirmed 8-13-81	RLB
C. Bonding	N/A	RLB
D. Burlap	N/A	RLB
E. Wet Sand	N/A	RLB
F. Polyethylene	N/A	RLB
G. Temperature	Set - 7 days > 50°F	RLB
<u>EXTENSIONS (DR's, Speed Letters, Poor Practice Condition Reports)</u>		
A. Cure	N/A	RLB
B. Protection	N/A	RLB
<u>FINISH</u>		
A. Steel Trowel	N/A	RLB
B. Wood Float	N/A	RLB
C. Broom	N/A	RLB
D. Hair Brush	N/A	RLB
E. Rubber Float	N/A	RLB
F. Roughened Surface	Set	RLB

CONSTRUCTION INSPECTOR Ronell J. Breddow  
CONSTRUCTION INSPECTION SUPERVISOR M.D. Seale

DATE 8-25-81  
DATE 8-25-81