| | PREVIOUS REPORT DATE 9/30/8 |
|---------|--|
| | CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 01 | N C B E P 2 2 0 0 - 0 0 9 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5 |
| CON'T | REPORT L 6 0 5 0 - 0 3 2 4 7 0 9 0 3 8 0 8 0 62 5 8 4 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During a reactor startup, following the completion of a routine refueling outage, it |
| 0 2 | |
| 0 3 | was discovered that control rod number 38-27 could not be withdrawn beyond position |
| 0 4 | ["46." The rod was then declared inoperative, and was fully inserted and electrically |
| 0 5 | disarmed as per technical specifications. This event did not affect the health |
| 06 | or safety of the public. |
| 07 | |
| 0 8 | Technical Specifications 3.1.36, 6.9.1.9b |
| 0 9 7 8 | SYSTEM CAUSE CAUSE SUBCODE SUB |
| | 17 REPORT 18 0 24 26 27 28 29 30 31 32 32 32 32 32 32 32 |
| 10 | Investigation revealed that the control rod had uncoupled from the control rod drive. |
| 111 | This was attributed to the inner filter being loose and dirty. The control rod drive |
| 1 2 | was rebuilt and the filter was replaced with a new one. No further action is planned |
| 13 | regarding this event. |
| 1 4 7 8 | 9 80 FACULTY (2) METHOD OF (2) |
| 1 5 | FACILITY STATUS OTHER STATUS (30) DISCOVERY DESCRIPTION (32) LC 28 0 0 0 0 29 NA A A A A A A A A A A A A A A A A A A |
| | ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA 44 45 LOCATION OF RELEASE 36 NA 44 45 |
| 17 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA 80 |
| 118 | PERSONNEL INJURIES NUMBER DESCRIPTION (41) |
| 19 | LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z 42 NA NA |
| 7 8 | PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA NA N |
| 7 8 | |
| | |

Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429 June 25, 198

FILE: B09-13510C SERIAL: BSEP/84-1481

Mr. James P. O'Reilly, Administrator U. S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street N.W. Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SUPPLEMENT TO LICENSEE EVENT REPORT 2-80-060

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical recifications for Brunswick Steam Electric Plant Unit 2, the enclosed suplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within 30 days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

Modul for C. R. Dietz, General Manager Brunswick Steam Electric Plant

RMP/sd1/LETPS1

Enclosure

cc: Mr. R. C. DeYoung

NRC Document Control Desk

OFFICIAL COPY

IE 22

//