

018



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555

OFFICE OF THE  
COMMISSIONER

June 21, 1984

DOCKETED  
USNRC

'84 JUL -3 A9:20

DOCKET NUMBER  
PROD. & UTIL. TAG... 50-3220L

OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

MEMORANDUM FOR: WILLIAM J. DIRCKS  
EXECUTIVE DIRECTOR FOR OPERATIONS  
SERVED JUL 3 1984

*Bill,*

SUBJECT: SHOREHAM ECCS

It has come to my attention that essentially all of the ECCS pumps at Shoreham are located next to one another on the bottom floor of the reactor building. Since there are no walls or dams to isolate the pumps, I am curious as to how the plant meets the Appendix R fire barrier requirements or General Design Criterion 35, 34, and 35 with respect to flooding induced by a single pipe failure. Has the staff made a finding that the ECCS pumps meet the regulations? I would appreciate a response by tomorrow evening if possible.

*Victor*  
Victor Gilinsky

cc: Chairman Palladino  
Commissioner Roberts  
Commissioner Asselstine  
Commissioner Bernthal  
SECY ✓

DS02

