

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company  
Shearon Harris Unit 1

Docket No. 50-400  
License No. CPPR-158

The following violation was identified during an inspection conducted on April 16 - 20, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.55(f)(1) requires CP&L to implement the quality assurance program described or referenced in the Preliminary Safety Analysis Report. Section 1.8.5.17 of the CP&L Quality Assurance Program requires QA records to be identifiable and retrievable.

Contrary to the above, on April 17, 1984, CP&L could not retrieve a QC inspection report (TP-28, Exhibit 6) for the work performed on Motor Control Center 1A34-SA to correct deficiencies identified on Deficiency and Disposition Report 1391.

This is a Severity Level V violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAY 16 1984