

OCT 3 1984

Docket No. 50-440  
Docket No. 50-441

The Cleveland Electric Illuminating  
Company

ATTN: Mr. Murray R. F...man  
Vice President  
Nuclear Group  
Post Office Box 5000  
Cleveland, OH 44101

Gentlemen:

Thank you for your letter dated September 13, 1984, informing us of the steps you have taken to correct the noncompliance which we brought to your attention in our letter dated August 14, 1984. Pending further inspection of the issues addressed in your September 13, 1984 response, the following is Region III's commentary on the identified item of your response letter:

- a. In your response to item 8d(4) you note that ECN 12734-33-2405, issued July 20, 1982, indicates a floating shield at TB-BB-3 in panel 1H22-P018. During our inspection no reference was given to this ECN on drawing D-209-055, Sheet 10, Revision C, which indicates that the shield is connected to TB-BB-3.

The technical aspects of the other areas of your response appear acceptable.

We will examine these matters during a subsequent inspection.

Sincerely,

*R. D. Walker*

W. S. Little, Chief  
Engineering Branch

cc w/ltr dtd 9/13/84:  
J. Waldron, Plant Manager  
L. Beck, General Supervisor  
Licensing and Fuels Management  
DMB/Document Control Desk (RIDS)  
Resident Inspector, RIII  
Harold W. Kohn, Ohio EPA  
Terry J. Lodge, Esq.  
James W. Harris, State of Ohio  
Robert H. Quillin, Ohio  
Department of Health

RIII <i>Cusick</i> Naidelic 10/1/84	RIII <i>Cusick</i> Falebits 10/2	RIII <i>Cusick</i> Gaufam 10/2	RIII <i>Cusick</i> Tan 10/2	RIII <i>Cusick</i> Chrisnot 10/2	RIII <i>Cusick</i> Williams 10/2	RIII RCK Knop	RIII <i>R. S. Little</i> Little 10-3-84
--	---	---	--------------------------------------	---	---	---------------------	--

B410100136 B41003  
PDR ADUCX 05000440  
Q PDR