

September 18, 1984

W3P84-2583 Q-3-A35.07.57 3-A1.01.04

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

REFERENCE: 1) LP&L letter W3K84-1218 dated May 22, 1984

2) NRR letter dated June 13, 1984 from Darrell G. Eisenhut to J.M. Cain

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Reopening of Significant Construction Deficiency No. 57

"Inadequate Instrumentation and Control Installations Turnover

Documentation"

Because of ongoing efforts associated with resolution of issues in reference 2, it may be necessary to modify reference 1. We therefore have elected to reopen SCD57 pending completion of those efforts. A final report will be issued upon completion of this effort which is currently scheduled for October 5, 1984.

Very truly yours,

K.W. Cook

Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410100319 840918 PDR ADDCK 05000382 S PDR 16-3I

Mr. John T. Collins W3P84-2583 Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Mr. W. A. Cross 7910 Woodmont Avenue Suite 1200 Betherda, Maryland 20814