

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

September 25, 1984

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station Unit 2
Docket No. 50-370
Report Due Date Extension

Gentlemen:

On August 26, 1984, the turbine-driven auxiliary feedwater pump (TDAFP) experienced a short period of reverse operation due to check valves sticking open. This event has subsequently been determined to be reportable pursuant to 10CFR 50.73 (a)(2)(vi). However, due to the lateness of the determination and the investigation involved, the LER cannot be submitted within the 30-day time limit. This report will be submitted by October 25, 1984.

Very truly yours,

H. B. Tucker

Hal B. Tucker

SAG/mjf

cc: Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission-Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30323

Mr. W. T. Orders
Senior Resident Inspector
McGuire Nuclear Station

8410100752 840925
PDR ADDCK 05000370
S PDR

IE22
1/0