

APPENDIX A

NOTICE OF VIOLATION

Baltimore Gas and Electric Company
Calvert Cliffs Unit 1 and 2

Docket/License: 50/317;DPR53
50/318;DPR69

As a result of the inspection conducted on June 12 - July 10, 1984 and in accordance with the NRC Enforcement Policy, (10 CFR2 Appendix C) the following violation was identified:

10 CFR 50.59 requires that the licensee make a determination that an unreviewed safety question does not exist for changes made to the facility which are described in the FSAR, and that a written Safety Evaluation be recorded which provides the basis for the determination that the change does not involve an unreviewed safety question.

Contrary to the above, on June 14, 1984, the licensee made a change to the facility which is described in the FSAR by placing the "swing" HPSI pump for unit in the "Pull to Lock" position changing the logic described in section 7.3.2.2 of the FSAR without performing a written safety evaluation documenting the basis that the change did not involve an unreviewed safety question.

This is a Severity Level V violation (Supplement I) applicable to DPR 53 and 69.

Pursuant to the provisions of 10 CFR2.201, Baltimore Gas and Electric Company is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including : (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

8410110033 840714
PDR ADOCK 05000317
Q PDR