

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH: AUGUST 1995

REVISION 1 October 9, 1995
 UNIT NAME: D.C. COOK UNIT 2
 DATE: September 11, 1995
 COMPLETED BY: G.F. Bussone
 TELEPHONE: 616-465-5901
 PAGE: Page 1 OF 1

NO.	DATE	TYPE ¹	DURATION HOURS	REASON ²	METHOD OF SHUTTING DOWN REACTOR ³	LICENSEE EVENT REPORT NO.	SYSTEM CODE ⁴	COMPONENT CODE ⁵	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
244	950824	S	N/A	B	N/A	N/A	N/A	N/A	Reactor power was reduced to 80% RTP on 082495 to remove the #21 Circulating Water Pump from service to support diving operations on Unit 1. Reactor power was returned to 100% RTP 082595.
245	950826	F	45.7	A*	3	95-004*	SB*	LS*	On 082695 the reactor tripped due to a turbine trip caused by an MSR drain tank extreme high-high level. The main generator was paralleled to the grid at 2232 EST on 082795.
246	950829	F	63.6	G*	3	95-005*	CD*	RG*	On 082995 the reactor tripped due to loss of both Control Rod Drive Power Supply MG sets.

* Data updated 10/9/95

1	2	3	4	5
F: Forced S: Scheduled	Reason: A: Equipment Failure (Explain) B: Maintenance or Test C: Refueling D: Regulatory Restriction E: Operator Training and License Examination F: Administrative G: Operational Error (Explain) H: Other (Explain)	Method: 1: Manual 2: Manual Scram 3: Automatic Scram 4: Other (Explain)	Exhibit G - Instructions for preparation of data entry sheets for Licensee Event Report (LER) File (NUREG 0161)	Exhibit I: Same Source

9510160279 951009
 PDR ADDCK 05000316
 PDR