

ENCLOSURE 2

NOTICE OF DEVIATION

Florida Power Corporation
Crystal River 3

Docket No. 50-302
License No. DPR-72

The following deviation was identified during an inspection conducted on February 28 - March 27, 1984.

Final Safety Analysis Report (FSAR) Section 9.7.2.1.g describes the operation of the control room emergency ventilation system and specifies that administrative controls "...to start this system within approximately ten minutes and to manually de-energize failed units and start standby units is satisfactory." These administrative controls are required to secure the normal running fans and start the emergency fans to provide flow through the emergency filter banks during an Engineered Safeguards System (ESS) actuation.

Contrary to the above, abnormal procedure AP-580 which provides administrative controls for an ESS actuation, does not direct securing of the normal running fans and starting of the emergency fans.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: APR 19 1984