
Public Service

of Colorado

16805 WCR 19 1/2, Platteville, Colorado 80651



Mr. John T. Collins Regional Administrator U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, TX 76011

ATTN: Eric Johnson

DOCKETED USNRC

SEP 2 1 1984 >

MAIL SECTION

DOCKET CLERK

September 7, 1984 Fort St. Vrain Unit #1 P-84341

SUBJECT: Existing Condition on the

Fort St. Vrain Refueling

Floor

Dear Mr. Johnson:

This letter is to provide you with a description of a situation at Fort St. Vrain that has temporarily delayed control rod drive refurbishing efforts. This situation was discussed with you and Phil Wagner during a telecon on September 4, 1984.

While removing a control rod drive and orifice assembly (CRDOA) from Region 7 for maintenance, a motor over-current condition on the auxiliary transfer cask (ATC) shutters occurred, preventing their full closure. Work was discontinued, and an investigation of the possible causes began.

The ATC shutters were opened, and an attempt to lower and reinstall the CRDOA into the core was made. The mechanism could not be completely seated in the penetration, so the CRDOA was again withdrawn from the core into the ATC. Once this was completed, a radiation survey was performed around the ATC. This indicated an abnormal radiation profile for a fully retracted control rod pair in the ATC, introducing the possibility that the control rod(s) were not fully retracted. The ATC shutter drive shafts were removed, and a borescope was inserted for visual examination. These examinations revealed that one of the two control rod strings was not fully retracted.

8410120216 840907 PDR ADDCK 05000267

ILL LALIVE 24164 A special test was conducted on September 5, 1984, with Messrs. Chaney and Plumlee of the NRC on-site and cognizant. This test involved lifting the ATC approximately 4 inches to verify borescope observations and to obtain radiation level data. Video tape taken during the test revealed that indeed only one control rod string was not fully retracted. Radiation levels at the circumference of the ATC were on the order of 5 R/hr. This corresponds to approximately 80 R/hr at one foot from the control rod string.

All CRDOA work has been discontinued until it is established that the CRDOA can be removed from the reactor in accordance with Fort St. Vrain licensing requirements and without causing unnecessary health hazards to plant personnel.

As always, Public Service Company will keep the Nuclear Regulatory Commission abreast of the existing conditions. If you have any questions please contact Mr. Chuck Fuller, of my staff, at (303) 785-2224, extension 202.

Sincerely,

J. W. Gahm

Manager, Nuclear Production

JWG/dkh

DOCKET NO.	50-261
CONTROL NO.	24164
DATE OF DOC.	09/07/84
DATE RCVD.	09/21/84
FCUF	PDR
FCAF	LPDR
WM	ISE REF.
WMUR	SAFEGUARDS
PCTC	OTHER
PASCRIPTION:	
Westing	Condition
on the	Fort St.
Wagin K	elueling.
Honry	of the same of the
72000	
19/2/184	TNITTAL CAR.

R4 A001 9/84	Date		/ / Date of	1/	1.1
Docket 50-267	Rece	eived 9	14/84 Document	: 7/7/	84
Title: OR Submittal: General Distribution			P-84341		
Document Control Desk Rids Code H005		(Region copy, NRC PDR, LPDR, NSIC, NTIS)			
	LTR.	ENCL.		LTR.	ENCL.
Region IV Internal: Region IV Supense Copy	1		Region IV External: State: COLORADO	1	
P. Wagner	(3)	(3)			
E. Haycraft					
RRI	/				
*Original sent to DMB					
REGION IV ROUTING:			NRR OVERSIGHT:		
R. Denise	/		NRR/ORB3/BC: J.R. Mill	er (7)	(7)
J. Collins			NRR/DL/DIR: D. Eisenh		(1)
P. Check			NRR/DSI/RAB:	1	
R. Bangart	The state of the s		NRR/DE/MTEB	/	
E. Johnson			NRR/DL/ORAB	/	
J. Jaudon			NRR/DSI/METB	1	
R. Ireland	S 100 - 101 T 11		The state of the s		
Do not Return to RIV File	Room				
Copies Required 29	_		Other ACRS	/ (6)	(6)
Letter only	_		ELD	1	
			REG FILE	1	
			ADM-LFMB	V (1)	(0)

^{*} One copy distributed unless otherwise indicated ()

^{*} Original file copy will be returned to RIV